

2019-01-01
2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

2019-01-01

Marcus
May chuan

REF: CS/FCI19005720/USD3⁷²

ASSIGNMENT (Office)

of FCI

Date/Time: 3:29pm @ 1/4/19

OD: TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No. FU3325L

Insured SHA 4170R

at Workshop n/z Erofa Motor

Tel 67527740

of 1 Kalci Bldg Ave 6 # 02-62

Policy No. Claim No. DI9002043MFSH

Sum Insured Excess.

Make of Vehr D.O.A. 24/3/2019
(Client's Record)

CA / REV / REP / REV 24 HRS

Date/Time: 4:30pm @ 1/4/19 Person Contacted: te he

H.O.D. Endorsement:
Vehicle: IN/OUT

Date/Time Action/Instruction (✓) Estimate

FU3325L - NBA/NCI4008052/84

D.O.A. 1/4/19

SHA 4170R - 03/16/16011970/Hua392

D.O.A. 23/6/2016

03/04/19 @ 17:27 p.m. send RA to May via email

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Order~~ / Jammed / Leaked / Burnt orBrake: ~~Order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/4/19 LTA 573
L/S \$1000 confirmed with AH Henry
(\$2,579.90 Red - 72%)

MV - \$4K

LTA - \$573

NLA - \$3,427.00

RECEIVED 15 APR 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

130

50

50

59

289

Report Format :

Lump Sum / I.B.I.: (\$ 1,000 / 45)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002043MFSH

Date: 03 April 2019

Our Ref: CS/FCI19005720/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FU 3325L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/04/2019 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,579.90</u>
Revised Estimate Amount	: S\$ <u>1,372.70</u>
"Check" Items Amount	: S\$ <u>175.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the n/s front portion & n/s body.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-03-2019	Our Ref No. D19002043MFSH
Accident Date	24-03-2019	Claim Type. Third Party
Insured Vehicle	SHA4170R	Third Party Vehicle. FU3325L
Survey Location	1 KAKI BUKIT AVE 6 #02-62	
Contact Person.	LEELEE TAN	
Contact No.	67527740/ 0	Fax No. 67528669
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EROFIA MOTOR TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Erofia Motor - LeeLee Tan

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: 01 April, 2019 10:18 AM
To: EROFIA@SINGNET.COM.SG
Cc: May Chua Hui Chin; May Chua Hui Chin
Subject: PRI REQUEST : FC REF: SHA4170R. (D19002043MFSH) & TP REF: FU3325L
(FU3325L) ACCIDENT ON 24-03-2019

Dear Sir,

Thank you for informing us of your choice **LKK AUTO CONSULTANTS PTE LTD**, the surveyor will be appointed within 2 working days of your email.

Thanks and Regrds
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 April 2019 5:27 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19002043MFSH/2
Attachments: FU 3325L - Preli Advise.pdf

Dear May,

Enclosed preliminary revised of vehicle FU 3325L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 1 April 2019 4:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002043MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 1 April 2019 3:29 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002043MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Model	Honda TA200 Phantom (/listing/usedbike/model/honda-ta200-phantom/)
Engine Capacity	197cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	27/11/2002
COE Expiry Date	26/11/2022 (3 years 7 months left)
Mileage	-
No. of owners	4
Type of Vehicle	Cruiser (/listing/usedbike/model/motorcycle-for-sale/cruiser/)

Price: ^{SGD}\$5400

DETAILS

NEA rebate of 3500. Road tax until November. Service done every 1500km. New chain and sprocket changed Jan 2019. Battery changed in Dec.

Accessories

Comes with a box.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/listing/usedbikes/listing/)



Honda TA200 Phantom

[\(/listing/usedbike/honda-honda-ta200-phantom/11877/\)](/listing/usedbike/honda-honda-ta200-phantom/11877/)



Honda TA200 Phantom

[\(/listing/usedbike/honda-honda-ta200-phantom/12049/\)](/listing/usedbike/honda-honda-ta200-phantom/12049/)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	6795A

Vehicle Details

Vehicle No.:	FU3325L
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	PHANTOM200
Primary Colour:	Black
Manufacturing Year:	2001
Engine No.:	TA200E0005472
Chassis No.:	TA2000005472
Maximum Power Output:	-
Open Market Value:	\$3,500.00
Original Registration Date:	02 Jan 2002
First Registration Date:	02 Jan 2002
Transfer Count:	3
Actual ARF Paid:	\$525.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Dec 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$2,087.00
COE Rebate Amount:	\$573.00
Total Rebate Amount:	\$573.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5029596213-10

Cover : Third Party

1. Index mark and Registration Number of Vehicle

FU3325L

Chassis Number

TA2000005472

2. Name of Policyholder

TEO KOK LEONG

3. Effective Date of Insurance

02 Jul 2018

4. Expiry Date of Insurance

01 Jul 2019

5. Persons or Classes of Persons entitled to drive#

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)

N/A

EXCESS (SECTION 2)

N/A

INSURE WITH CODE

N/A

NAMED DRIVER (1)

TEO KOK LEONG

NAMED DRIVER (2)

N/A

HIRE PURCHASE COMPANY

N/A

SUM INSURED

N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : THINK ONE AUTOMOBILE & TRADING PTE LTD (00000571089)

Date of Issue : 25 May 2018 09:02 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Think One Authorised Workshop

Accident No.: 9128 8488 / 6844 3300

18 Defu Avenue 2 S(539522)

Renewal No.: 6555 3300

20 Ubi Road 4, #02-03 S(408622)

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1666795A



TEO KOK LEONG

張國隆

Race
CHINESE

Date of birth
21-01-1964

Country/Place of birth
SINGAPORE

Sex
M



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1666795A

Name: TEO KOK LEONG

Birth Date: 21 Jan 1964

Issue Date: 04 Oct 2003

000874153H



6117364



NRIC No. S1666795A



Date of issue
01-02-2019

Address
APT BLK 69 REDHILL CLOSE
#29-80
SINGAPORE 150069

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles not exceeding 200 cc

PASS DATE
24 Dec 1987

NP 428A

Licence No: S1666795A



EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Teo Kok Leong

Accident Date : 24-Mar-19

Vehicle No : FU 3325 L

Vehicle Model : Honda TA 200

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 50.00 X
1	Headlamp	\$ 95.00
1	Headlamp bracket	\$ 30.00 X
1	Front sport rim	\$ 350.00 X
1	Front rim shaft	\$ 55.00 X
2	Fork inner tubes	\$ 370.00 X
2	Fork outer tubes	\$ 210.00 X
1	Front brake disc	\$ 125.00 X
1	Fork under bracket	\$ 145.00 X
1	Handle bar	\$ 95.00
1	Handle bar grip (1 set)	\$ 80.00
1	Side mirror -L/H	\$ 65.00
1	Clutch lever	\$ 18.00 X
2	Front signals	\$ 90.00 X
1	Front footrest -L/H	\$ 48.00
1	Front footrest bracket -L/H	\$ 35.00
1	Gear pedal	\$ 34.00 X
1	Crash bar (1 set)	\$ 200.00
1	Rear footrest -L/H	\$ 35.00
1	Rear footrest bracket -L/H	\$ 68.00 X
1	Rear signal -L/H	\$ 45.00 X
1	Side stand	\$ 58.00 X
		\$ 2,301.00
	Less 10%	\$ 230.10
		\$ 2,070.90

LUK Auto Consultants hence notify the Repairs of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

c/f: \$ 2,070.90

Special Nett Items

1	Number plate (1 set)	\$ 47	28.00	X
2	Fork oils	\$ 17	30.00	X
2	Fork oil seals	\$ 17	56.00	X
1	Steering cone (1 set)	\$ 17	75.00	X
1	Rear box	\$ 17	180.00	X
1	Rear box bracket	\$ 17	100.00	X
1	ERP IU	\$ 80	175.00	X
1	Side box (1 set)	\$ 647	360.00	350
		\$	1,004.00	

S/No. **Labour**

1	To provide towing service.	\$	45.00	35-
2	To check wiring and reset headlamp focusing	\$ 17	80.00	X
3	To provide labour.	\$	380.00	280
		\$	505.00	

1252.70

Grand Total **\$ 3,579.90**



EROFIA MOTOR TRADING PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005720/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4170R	Veh. Inspected	FU 3325L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002043MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	01/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA PHANTOM200	c.c	197	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	TA2000005472	Colour	BLACK	
Odometer	3033	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	100-90-17	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130-90-15	METZELER	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2019	Inspection Date	01/04/2019	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 3325L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	TO REPAIR SEE LABOUR	50.00	-
1	HEADLAMP	SCRATCHED	95.00	95.00
1	HEADLAMP BRACKET	NOT NECESSARY	30.00	-
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	350.00	-
1	FRONT RIM SHAFT	SERVICEABLE	55.00	-
2	FORK INNER TUBES	TO REPAIR SEE LABOUR	370.00	-
2	FORK OUTER TUBES	TO REPAIR SEE LABOUR	210.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	125.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	145.00	-
1	HANDLE BAR	BENT	95.00	95.00
1	SET HANDLE BAR GRIP	NECESSARY	80.00	80.00
1	SIDE MIRROR-L/H	CUT	65.00	65.00
1	CLUTCH LEVER	NOT NECESSARY	18.00	-
2	FRONT SIGNALS	NOT NECESSARY	90.00	-
1	FRONT FOOTREST-L/H	TORN	48.00	48.00
1	FRONT FOOTREST BRACKET-L/H	BENT	35.00	35.00
1	GEAR PEDAL	SERVICEABLE	34.00	-
1	SET CRASH BAR	SCRATCHED / BENT	200.00	200.00
1	REAR FOOTREST-L/H	CUT	35.00	35.00
1	REAR FOOTREST BRACKET-L/H	NOT NECESSARY	68.00	-
1	REAR SIGNAL-L/H	NOT NECESSARY	45.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	58.00	-
	LESS 10% DISCOUNT		-230.10	-65.30
			2,070.90	587.70
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-

Report Ref No. CS/FCI19005720/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	75.00	-
1	REAR BOX (SN)	NOT NECESSARY	180.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	100.00	-
1	ERP IU (SN)	SERVICEABLE	175.00	-
1	SET SIDE BOX (SN)	CUT	360.00	350.00
			1,004.00	350.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		45.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FENDER,FRONT SPORT RIM,FORK INNER TUBES,FORK OUTER TUBES AND SIDE STAND.		380.00	280.00
			505.00	315.00
	GRAND TOTAL		3,579.90	1,252.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/FCI19005720/Usd3n2

MARKET VALUE: \$4,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$573.00=NETT VALUE: \$3,427.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.