

22/03/2019

ASS. REC. BY:

REF: CS/FCI 1900 57n/ JV d30/ Special Instruction:

Surveyor: Hwa Jie

(WS)

ASSIGNMENT (Office)From (Person): Henry Kaoof FCIDate/Time: 29.3.2019

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: VN8487Insured: SHC 786 DCat Workshop m/s CARZ AUTO SERVICES Pte LTDTel: 8322 7418of NO 61 Woodlands Industrial Park E9, #04-04, E9 premium

Policy No: _____

Claim No: D19002164 MFSH

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 28.3.20192.4.2019

CA / REV / REP. / REV 24 HRS "WR"

H.O.D. Endorsement: _____

Date/Time: 1.4.19 4.48 p.mPerson Contacted: Jeslyn ChuaVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	VN8487 - X	
	SHC 786 DC - CS/FCI 18021233/ R1 + d 3e2	D.O.A - 21/11/2018
3/4/19	Email preli revised to FCI	

Gannett Hwee Jie

REF: FCI

ASSIGNMENT

From

Date:

2/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

VN 8487

at Workshop m/s

Carz Auto Services

of

No. 61 Woodlands Ind. Park E9 #0404

Insured:

E9 premium

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Jesuying 8322 7418

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1 imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

VN 8487

Yr Regn:

17

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C. 1498

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

110032

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMHFC16206D402242

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Bm / STD A/Rim or

Tyre Size:

F: 215 / 50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/3/19

D.O.A.

2/4/19

Survey held at

Carz Auto

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Hwee Jie,

Pls check repair margin.

MV-RM 90,000

RECEIVED 02 MAY 2019

2/5/19 Confirmed LS \$6800 for 10 days of repair.
(Red 5178.68, 4390)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

15 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$) :

6800/2

Days Of Repair:

10

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Other

TOTAL

170419
50
50490
110
445

MOTOR SURVEY ASSIGNMENT

Date	29-03-2019	Our Ref No. D19002164MFSH
Accident Date	28-03-2019	Claim Type. Third Party
Insured Vehicle	SHC7860C	Third Party Vehicle. VN8487
Survey Location	NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04, E9 PREMIUM, S(757047)	
Contact Person.	JESLYN CHUA	
Contact No.	83227418/ 83227418	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	2.4.2019
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CARZ AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 April 2019 2:22 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002164MFSH/1, VN 8487
Attachments: VN 8487 PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle VN 8487

Date of survey: 2/4/2019

Number of days : 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 1 April 2019 5:00 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002164MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 2/4/2019.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 1 April, 2019 3:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002164MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002164MFSH

Our ref: CS/FCI19005721/Jvd3

Date: 3/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. VN 8487


We thank for your instruction on 29/3/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle
on 2/4/2019 at the premises of M/s CARZ AUTO SERVICES PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$11,978.68
Revised Estimate Amount	: S\$7,155.96
"Check" Items Amount	: S\$2,260.72
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ONG HWEE JIE

Automotive Assessor



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

A6RREADB

No. Pendaftaran : VN8487
No. ID : 841207016613
Nama Pemunya Berdaftar : LEI HONG CHOON
Alamat : NO. 6 JALAN SEPAT TAMAN INDAH JAYA
86000 KLUANG JOHOR

No. Chasis/No. Enjin : PMHFC1620GD402242 / L15B72102206
Buatan/Name Model : HONDA / CIVIC 1.5 TC
Keupayaan Enjin : 1498
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2016
Tarikh Pendaftaran : 23/01/2017
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



SINGAPORE POLICE FORCE



T/20190328/2183

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20190328/2183

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2019 19:29	Vide Report No.:	Station Diary No.: 159
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: LEI HONG CHOON		Address: APT BLK 223 JURONG EAST STREET 21 #02-851 SINGAPORE 600223	
ID Type / ID No.: FIN NO / G3227775L		Contact No.: Home/Office: Mobile: 87187338	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 34	Date of Birth: 07/12/1984	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Sales executive		Driving Licence Information: Class: 2B,3 Date of Expiry: 07/12/2023	

General Information of the Accident				
Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 28/03/2019 17:00	Type of Location: Straight Road
Location: Along Road 1 JALAN AHMAD IBRAHIM Towards Tuas Checkpoint near Joo Koon Circle				
Weather: Heavy rain		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7860C	Taxi					0
VN8487	Car				Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190328/2183

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 3

Report No. T/20190328/2183

CONTINUATION OF REPORT

Driver				
Name	DHANABALAN S/O A GOPALKRISHNAN		ID No.	S6945259J
Related Vehicle	SHC7860C (Taxi)		Contact No.	86228841
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	LEI HONG CHOON		ID No.	G3227775L
Related Vehicle	VN8487 (Car)		Contact No.	87187338
Hospital/Clinic	NORTHEAST MEDICAL CENTRE		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: 07/12/2023
Date Treatment	28/03/2019		Date Discharge	28/03/2019
No. of Days granted Medical Leave	04		Degree of Injury	Slight

Brief Details.

On 28.03.2019 at about 1700hrs, I drove a car, VN8487 along Jalan Ahmad Ibrahim towards Tuas Checkpoint on 1st lane. The rain was very heavy. While I was driving along the said road, one unknown car overtook my car on the 2nd lane and thus caused some water on the road to splash over onto my car. I then slowed down my car. But suddenly a taxi, SHC7860C hit the rear of the car. The impact was so hard that caused my car to move forward and also pain at my back and neck. But I was not conveyed to hospital and we just exchanged our particulars. I am no longer staying at the above address as I have moved out to Gelang Patah, Johor but I am still working at Chee Fatt Co. Pte Ltd which is located at 54 Tanjong Penjuru Singapore 609035.



**SINGAPORE
POLICE FORCE**



T/20190328/2183

3 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20190328/2183

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt ABDUL RAHMAN BIN ABDUL MALIK

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

28/03/2019 19:29

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH

Contact No.: 65476204

SN 114

Authentication Stamp

NP168

Classification Of Case:



MSIG Certificate of Insurance

Road Transport Act, 1987 (Malaysia)
 The Motor Vehicle (Third Party Risks) Rules, 1959 (Malaysia)
 The Motor Vehicle (Third Party Risks And Compensation) Act (Cap 189) Republic of Singapore
 The Motor Vehicle (Third Party Risks And Compensation) Rules 1960 (Republic of Singapore)
 The Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Certificate No. 79144514

Private Car - Individual

1. Index Mark and Registration
 Number of Vehicle: VN8487
 Make of Vehicle :HONDA CIVIC 1.5 TC
2. Name of Policy Holder: LEI HONG CHOON
3. Effective date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment: 23/01/2019
4. Date of Expiry of Insurance: 22/01/2020
5. Persons or Classes of Persons entitled to drive*
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitation as to use*
 Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for the hire or reward, racing, pacemaking, reliability trial speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.

"I/WE HEREBY certify that the Policy to which this Certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam."

Approved Insurer

RTD-32

This Certificate is not transferable to a new owner of the vehicle.

If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Compulsory Third Party Insurance Legislation.

The Certificate must be returned if the Insurance is suspended during its currency.

Important Notice

If you are involved in an accident causing injury to any person or damage to any property or other vehicle you must:-

- (a) Try to obtain names and addresses of any witness to the accident.
- (b) Report to the Company immediately.
- (c) Refer to the Company immediately all communications received from the Police authorities.
- (d) Send to the Company immediately all letters received from third parties unanswered.
- (e) Not pay money to any party involved in the accident without the Company's written permission.

KUALA LUMPUR TEL: 03-20508228 FAX: 03-20268086	PETALING JAYA TEL: 03-79544208 FAX: 03-79544202	IPOH TEL: 05-2551319 FAX: 05-2537979	KUANTAN TEL: 09-5157501 FAX: 09-5157502	MIRI TEL: 09-7481280 FAX: 09-7483509	KLANG TEL: 03-33436691 FAX: 03-33422571	SIBU TEL: 084-323890 / 084-347008
JOHOR BHARU TEL: 07-2763100 FAX: 07-2763800	MELAKA TEL: 06-2831335 FAX: 06-2840331	PENANG TEL: 04-219 0800 FAX: 04-219 0999	KUCHING TEL: 082-255901/082-259204 FAX: 082-427612	SEREMBAN TEL: 06-6013501 FAX: 06-6013503	SUNGAI PETANI TEL: 04-4244180 FAX: 04-4234513	084-314558
KOTA KINABALU TEL: 088-233030 FAX: 088-235110	TAWAU TEL: 089-771051 FAX: 089-764079	SANDAKAN TEL: 089-217388 FAX: 089-215388	KOTA BHARU TEL: 09-7481280 FAX: 09-7483509	BATU PAHAT TEL: 07-4336808 FAX: 07-4337808	ALOR SETAR TEL: 04-7722266/00 FAX: 04-7722255	KLUANG TEL: 07-7726502 / 07-7745701 FAX: 07-7745702



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMISES)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: MS FIRST CAPITAL INSURANCE

Address: 36 Robinson Road #16-01 City House, Singapore 068877

Telephone: 6507 3848

Fax: 6507 3849

Email:

Make/ Model : HONDA CIVIC

Date: 29/3/2019

Chassis No :

Vehicle No: VN 8487

Date/Time of Accident : 28/3/2019 17:00

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BOOTLID BUC ✓	1	\$ 582.20	20%	\$ 465.76
2	BOOTLID TOP LOCK Jam ✓	1	\$ 115.30	20%	\$ 92.24
3	BOOTLID HINGE BT ✓	2	\$ 131.40	20%	\$ 105.12
4	BOOTLID REFLECTOR ? CRA ✓	2	\$ 377.80	20%	\$ 302.24
5	BOOTLID INSULATOR DEF ✓	1	\$ 155.60	20%	\$ 124.48
6	BOOTLID WEATHERSTRIP DEF ✓	1	\$ 98.60	20%	\$ 78.88
7	BOOTLID LOGO nec ✓	1	\$ 29.90	20%	\$ 23.92
8	BOOTLID LOGO GARNISH CRA ✓	1	\$ 191.20	20%	\$ 152.96
9	BOOTLID EMBLEM CIVIC nec ✓	1	\$ 29.90	20%	\$ 23.92
10	BOOTLID EMBLEM VTEC nec ✓	1	\$ 32.10	20%	\$ 25.68
11	BOOTLID SENSOR ? Shorted ✓	1	\$ 145.20	20%	\$ 116.16
12	REAR BUMPER DEF ✓	1	\$ 671.20	20%	\$ 536.96
13	REAR BUMPER REVERSE SENSOR Shorted ✓	1	\$ 653.60	20%	\$ 522.88
14	REAR BUMPER SENSOR WIRE ?	1	\$ 99.30	20%	\$ 79.44
15	REAR BUMPER REINFORCEMENT BT ✓	1	\$ 180.90	20%	\$ 144.72
16	REAR BUMPER SIDE RETAINER nec ✓	2	\$ 45.20	20%	\$ 36.16
17	REAR BUMPER LOWER GARNISH DEF ✓	1	\$ 115.50	20%	\$ 92.40
18	REAR BUMPER REFLECTOR ?	2	\$ 78.40	20%	\$ 62.72
19	REAR BUMPER REFLECTOR GARNISH SCR ✓	2	\$ 64.20	20%	\$ 51.36
20	REAR BUMPER REFLECTOR CHROME nec ✓	2	\$ 160.60	20%	\$ 128.48
21	REAR BUMPER BRACKET mis ✓	2	\$ 56.20	20%	\$ 44.96
22	REAR BUMPER TOW COVER SCR ✓	1	\$ 18.60	20%	\$ 14.88
23	REAR BUMPER EXHAUST GARNISH CRA-LH ✓	12	\$ 79.00	20%	\$ 63.20
24	REAR TAIL LAMP CRA ✓	2	\$ 599.60	20%	\$ 479.68
25	REAR TAIL LAMP PANEL ?	2	\$ 221.20	20%	\$ 176.96
26	REAR TAIL LAMP LOWER BRACKET ?	2	\$ 79.40	20%	\$ 63.52
27	REAR END PANEL BUC ✓	1	\$ 298.30	20%	\$ 238.64
28	REAR END PANEL TOP GARNISH CRA ✓	1	\$ 89.20	20%	\$ 71.36
29	REAR FLOOR PANEL BUC ✓	1	\$ 399.30	20%	\$ 319.44
30	REAR FLOOR PANEL TOP BOARD CRA ✓	1	\$ 178.60	20%	\$ 142.88
31	REAR FLOOR PANEL SIDE LH BUC ✓	1	\$ 89.10	20%	\$ 71.28
32	REAR CHASSIS MEMBER EXTANSION LH ?	1	\$ 682.70	20%	\$ 546.16
33	REAR FENDER LH Repair X	1	\$ 855.90	20%	\$ 684.72

34	REAR FENDER INNER TRIM LH	BUC ✓	1	\$	197.60	20%	\$	158.08
35	REAR FENDER AIR VENT LH	?	1	\$	39.50	20%	\$	31.60
36	REAR FENDER AIR VENT PANEL LH	?	1	\$	105.30	20%	\$	84.24
37	REAR WINDSCREEN MOULDING	nnx	1	\$	82.10	20%	\$	65.68
38	REAR FENDER SPLASHIELD LH	?	1	\$	93.70	20%	\$	74.96
39	REAR SILENCER BOX LH	?	1	\$	688.50	20%	\$	550.80
40	REAR SILENCER BOX MOUNTING LH	?	2	\$	57.40	20%	\$	45.92
41	REAR SILENCER BOX INSULATOR LH	?	1	\$	85.30	20%	\$	68.24

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	BOOTLID INSULATOR CLIP	10	\$ 50.00	\$ 15 50.00
2	BOOTLID LOGO GARNISH CLIP	10	\$ 50.00	\$ 15 50.00
3	REAR BUMPER EXHAUST GARNISH CLIP	4	\$ 20.00	\$ 15 20.00
4	REAR BUMPER CLIP	10	\$ 50.00	\$ 30 50.00
5	REAR TAIL LAMP CLIP	4	\$ 20.00	\$ 15 20.00
6	REAR END PANEL TOP GARNISH CLIP	5	\$ 25.00	\$ 25.00
7	REAR FLOOR PANEL INSULATOR	1	\$ 150.00	\$ 60 150.00
8	REAR FENDER INNER TRIM CLIP LH	8	\$ 40.00	\$ 15 40.00
9	REAR WINDSCREEN SEALANT	1	\$ 60.00	\$ 60.00
10	REAR FENDER SPLASHIELD CLIP LH	8	\$ 40.00	\$ 40.00
11	REAR SILENCER BOX CHROME PIPE LH	1	\$ 200.00	\$ 200.00
12	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
Total Special Items Cost				\$ 7,918.68

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 1,800.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TOWING	\$ 60.00
TO REMOVE & REFIX REAR WINDSCREEN	\$ 120.00
TO TUFFCOAT AFFECTED AREA	\$ 80 250.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 50 150.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 40 60.00
TO REMOVE/ REPLACE REAR SILENCER BOX	\$ 120.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 30 100.00
Total Others Cost	\$ 860.00
GRAND TOTAL	\$ 11,978.68




CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Account Assistant
Mobile: 65 8322 7418
Email: jeslyn@carzauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3/4/19
Hase Jie-LKK
2/4/19
L/S 10days.
ey



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: MS FIRST CAPITAL INSURANCE

Address: 36 Robinson Road #16-01 City House, Singapore 068877

Telephone: 6507 3848

Fax: 6507 3849

Email:

Make/ Model : HONDA CIVIC

Date: 29/3/2019

Chassis No :

Vehicle No: VN 8487

Date/Time of Accident : 28/3/2019 17:00

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BOOTLID BUC ✓	1	\$ 582.20	20%	\$ 465.76
2	BOOTLID TOP LOCK Jam ✓	1	\$ 115.30	20%	\$ 92.24
3	BOOTLID HINGE BT ✓	2	\$ 131.40	20%	\$ 105.12
4	BOOTLID REFLECTOR ? CRA ✓	2	\$ 377.80	20%	\$ 302.24
5	BOOTLID INSULATOR DEF ✓	1	\$ 155.60	20%	\$ 124.48
6	BOOTLID WEATHERSTRIP DEF ✓	1	\$ 98.60	20%	\$ 78.88
7	BOOTLID LOGO nec ✓	1	\$ 29.90	20%	\$ 23.92
8	BOOTLID LOGO GARNISH CRA ✓	1	\$ 191.20	20%	\$ 152.96
9	BOOTLID EMBLEM CIVIC nec ✓	1	\$ 29.90	20%	\$ 23.92
10	BOOTLID EMBLEM VTEC nec ✓	1	\$ 32.10	20%	\$ 25.68
11	BOOTLID SENSOR ? Shorted CRA ✓	1	\$ 145.20	20%	\$ 116.16
12	REAR BUMPER DEF ✓	1	\$ 671.20	20%	\$ 536.96
13	REAR BUMPER REVERSE SENSOR Shorted ✓	4	\$ 653.60	20%	\$ 522.88
14	REAR BUMPER SENSOR WIRE ? CUT ✓	1	\$ 99.30	20%	\$ 79.44
15	REAR BUMPER REINFORCEMENT BT ✓	1	\$ 180.90	20%	\$ 144.72
16	REAR BUMPER SIDE RETAINER nec ✓	2	\$ 45.20	20%	\$ 36.16
17	REAR BUMPER LOWER GARNISH DEF ✓	1	\$ 115.50	20%	\$ 92.40
18	REAR BUMPER REFLECTOR ? CRA ✓	2	\$ 78.40	20%	\$ 62.72
19	REAR BUMPER REFLECTOR GARNISH SCR ✓	2	\$ 64.20	20%	\$ 51.36
20	REAR BUMPER REFLECTOR CHROME nec ✓	2	\$ 160.60	20%	\$ 128.48
21	REAR BUMPER BRACKET mis ✓	2	\$ 56.20	20%	\$ 44.96
22	REAR BUMPER TOW COVER SCR ✓	1	\$ 18.60	20%	\$ 14.88
23	REAR BUMPER EXHAUST GARNISH CRA-LH ✓	12	\$ 39.50 79.00	20%	\$ 63.20
24	REAR TAIL LAMP CRA ✓	2	\$ 599.60	20%	\$ 479.68
25	REAR TAIL LAMP PANEL ? BUC ✓	2	\$ 221.20	20%	\$ 176.96
26	REAR TAIL LAMP LOWER BRACKET ? CRA ✓	2	\$ 79.40	20%	\$ 63.52
27	REAR END PANEL BUC ✓	1	\$ 298.30	20%	\$ 238.64
28	REAR END PANEL TOP GARNISH CRA ✓	1	\$ 89.20	20%	\$ 71.36
29	REAR FLOOR PANEL BUC ✓	1	\$ 399.30	20%	\$ 319.44
30	REAR FLOOR PANEL TOP BOARD CRA ✓	1	\$ 178.60	20%	\$ 142.88
31	REAR FLOOR PANEL SIDE LH BUC ✓	1	\$ 89.10	20%	\$ 71.28
32	REAR CHASSIS MEMBER EXTENSION LH ? Repair X	1	\$ 682.70	20%	\$ 546.16
33	REAR FENDER LH Repair X	1	\$ 855.90	20%	\$ 684.72

34	REAR FENDER INNER TRIM LH	BUC ✓	1	\$	197.60	20%	\$	158.08
35	REAR FENDER AIR VENT LH	? CRA ✓	1	\$	39.50	20%	\$	31.60
36	REAR FENDER AIR VENT PANEL LH	? Repair X	1	\$	105.30	20%	\$	84.24
37	REAR WINDSCREEN MOULDING	nux	1	\$	82.10	20%	\$	65.68
38	REAR FENDER SPLASHIELD LH	? CUT ✓	1	\$	93.70	20%	\$	74.96
39	REAR SILENCER BOX LH	? DD ✓	1	\$	688.50	20%	\$	550.80
40	REAR SILENCER BOX MOUNTING LH	? CUT ✓	2	\$	57.40	20%	\$	45.92
41	REAR SILENCER BOX INSULATOR LH	? BUC ✓	1	\$	85.30	20%	\$	68.24

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	BOOTLID INSULATOR CLIP	10	\$ 50.00	\$ 15 50.00
2	BOOTLID LOGO GARNISH CLIP	10	\$ 50.00	\$ 15 50.00
3	REAR BUMPER EXHAUST GARNISH CLIP	4	\$ 20.00	\$ 15 20.00
4	REAR BUMPER CLIP	10	\$ 50.00	\$ 30 50.00
5	REAR TAIL LAMP CLIP	4	\$ 20.00	\$ 15 20.00
6	REAR END PANEL TOP GARNISH CLIP	5	\$ 25.00	\$ 25.00
7	REAR FLOOR PANEL INSULATOR	1	\$ 150.00	\$ 60 150.00
8	REAR FENDER INNER TRIM CLIP LH	8	\$ 40.00	\$ 15 40.00
9	REAR WINDSCREEN SEALANT	1	\$ 60.00	\$ 60.00
10	REAR FENDER SPLASHIELD CLIP LH	8	\$ 40.00	\$ 15 40.00
11	REAR SILENCER BOX CHROME PIPE LH	1	\$ 200.00	\$ 80 200.00
12	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
Total Special Items Cost				\$ 7,918.68

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 1,800.00
1200	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00
1000	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TOWING	\$ 60.00 ✓
TO REMOVE & REFIX REAR WINDSCREEN	\$ 120.00 X
TO TUFFCOAT AFFECTED AREA	\$ 80 250.00 ✓
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 50 150.00 ✓
TO REMOVE/ REFIT WIRING CHECKS	\$ 40 60.00 ✓
TO REMOVE/ REPLACE REAR SILENCER BOX	\$ 40 120.00 ?
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 30 100.00 ✓
Total Others Cost	\$ 860.00
GRAND TOTAL	
	\$ 11,978.68

[Signature]



CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Account Assistant
Mobile: 65 8322 7418
Email: jeslyn@carzauto.com.sg

Total - \$6800/-

[Signature]
2/5/19

Three Jie-LKK
2/4/19
L/S 10days.


[Signature]

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005721/Jvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7860C	Veh. Inspected	VN 8487	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002164MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	29/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	PMHFC1620GD402242	Colour	WHITE	
Odometer	110032	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/50 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/03/2019	Inspection Date	02/04/2019	
Survey held at	NO61 WOODLANDS INDUSTRIAL PARK E9,#04-04,E9			
Repairer	CARZ AUTO SERVICES PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. VN 8487

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	BUCKLED	582.20	582.20
1	BOOTLID TOP LOCK	JAMMED	115.30	115.30
2	BOOTLID HINGE	BENT	131.40	131.40
2	BOOTLID REFLECTOR	CRACKED	377.80	377.80
1	BOOTLID INSULATOR	DEFORMED	155.60	155.60
1	BOOTLID WEATHERSTRIP	DEFORMED	98.60	98.60
1	BOOTLID LOGO	NECESSARY	29.90	29.90
1	BOOTLID LOGO GARNISH	CRACKED	191.20	191.20
1	BOOTLID EMBLEM CIVIC	NECESSARY	29.90	29.90
1	BOOTLID EMBLEM VTEC	NECESSARY	32.10	32.10
1	BOOTLID SENSOR	CRACKED	145.20	145.20
1	REAR BUMPER	DEFORMED	671.20	671.20
4	REAR BUMPER REVERSE SENSOR	SHORTED	653.60	653.60
1	REAR BUMPER SENSOR WIRE	CUT	99.30	99.30
1	REAR BUMPER REINFORCEMENT	BENT	180.90	180.90
2	REAR BUMPER SIDE RETAINER	NECESSARY	45.20	45.20
1	REAR BUMPER LOWER GARNISH	DEFORMED	115.50	115.50
2	REAR BUMPER REFLECTOR	CRACKED	78.40	78.40
2	REAR BUMPER REFLECTOR GARNISH	SCRATCHED	64.20	64.20
2	REAR BUMPER REFLECTOR CHROME	NECESSARY	160.60	160.60
2	REAR BUMPER BRACKET	MISSING	56.20	56.20
1	REAR BUMPER TOW COVER	SCRATCHED	18.60	18.60
2	REAR BUMPER EXHAUST GARNISH	N/S CRACKED	79.00	39.50
2	REAR TAIL LAMP	CRACKED	599.60	599.60
2	REAR TAIL LAMP PANEL	NECESSARY	221.20	221.20
2	REAR TAIL LAMP LOWER BRACKET	CRACKED	79.40	79.40
1	REAR END PANEL	BUCKLED	298.30	298.30
1	REAR END PANEL TOP GARNISH	CRACKED	89.20	89.20
1	REAR FLOOR PANEL	BUCKLED	399.30	399.30
1	REAR FLOOR PANEL TOP BOARD	CRACKED	178.60	178.60
1	REAR FLOOR PANEL SIDE LH	BUCKLED	89.10	89.10

Report Ref No. CS/FCI19005721/Jvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CHASSIS MEMBER EXTANSION LH	TO REPAIR SEE LABOUR	682.70	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	855.90	-
1	REAR FENDER INNER TRIM LH	BUCKLED	197.60	197.60
1	REAR FENDER AIR VENT LH	CRACKED	39.50	39.50
1	REAR FENDER AIR VENT PANEL LH	TO REPAIR SEE LABOUR	105.30	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	82.10	-
1	REAR FENDER SPLASHIELD LH	CUT	93.70	93.70
1	REAR SILENCER BOX LH	DENTED	688.50	688.50
2	REAR SILENCER BOX MOUNTING LH	CUT	57.40	57.40
1	REAR SILENCER BOX INSULATOR LH	BUCKLED	85.30	85.30
	LESS 20% DISCOUNT		-1,790.92	-1,437.82
			7,163.68	5,751.28
	<u>SPECIAL NETT ITEMS</u>			
10	BOOTLID INSULATOR CLIP (SN)	NECESSARY	50.00	15.00
10	BOOTLID LOGO GARNISH CLIP (SN)	NECESSARY	50.00	15.00
4	REAR BUMPER EXHAUST GARNISH CLIP (SN)	NECESSARY	20.00	15.00
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
4	REAR TAIL LAMP CLIP (SN)	NECESSARY	20.00	15.00
5	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	25.00	-
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	150.00	60.00
8	REAR FENDER INNER TRIM CLIP LH (SN)	NECESSARY	40.00	15.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
8	REAR FENDER SPLASHIELD CLIP LH (SN)	NECESSARY	40.00	15.00
1	REAR SILENCER BOX CHROME PIPE LH (SN)	DENTED	200.00	80.00
1	REAR NUMBER PLATE (SN)	CRACKED	50.00	50.00
			755.00	310.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR CHASSIS MEMBER EXTANSION LH, REAR FENDER LH AND REAR FENDER AIR VENT PANEL LH.		1,800.00	1,200.00

Report Ref No. CS/FCI19005721/Jvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY AFFECTED AREAS.	NOT NECESSARY	1,400.00	1,000.00
	TOWING.		60.00	60.00
	TO REMOVE & REFIX REAR WINDSCREEN.		120.00	-
	TO TUFFCOAT AFFECTED AREA.		250.00	80.00
	TO REMOVE / REFIT INTERIOR UPHOLSTERY.		150.00	50.00
	TO REMOVE / REFIT WIRING CHECKS.		60.00	40.00
	TO REMOVE / REPLACE REAR SILENCER BOX.		120.00	40.00
	TO REMOVE / REPLACE REVERSE SENSORS.		100.00	30.00
			4,060.00	2,500.00
GRAND TOTAL			11,978.68	8,561.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CS/FC119005721/Jvd3e2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.