

ASS. REC. BY:

REF: CS/MSG 1905727/Agg 4307

Special Instruction:

Surveyor: Adrian

Minimum

ASSIGNMENT (Office)

From (Person): Fierei Foo Winyao of MSG

Date/Time: 01 Apr. 2019 16:49 P.M.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JRM 976

Insured: SMF 1849B

at Workshop m/s Hua Mung Spray Painting

Tel: 67478064 / 67465519 Jingling

of MOI Kaki Bukit 6, #01-61

Policy No: 29114729 am y

Claim No: 587230

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9.3.2019

CA / REV / REP. / REV 24 HRS

"W"

2.4.2019

H.O.D. Endorsement:

Date/Time: 01.04.2019 5:06 p.m.

Person Contacted: Jure

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	JRM 976-X	
	SMF 1849B - CV1 / VAL 19004524 / CV	D.O.A - 09/03/2019
31/4/2019 @ 17:05 pm-	compose mail to firei foo pending estimate.	
26/7/19 @ 12:05 pm	revised to firei foo via Minimum.	
	US \$2200, 5 days (Red \$3494, 61%)	

REF: MSIG

ASSIGNMENT

From: Date: 2/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JRM 976

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: JRM 976 Yr Regn: 2016 / April

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Y15ZR

c.c

150

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMYU6051060023374

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80/90 R17. Mic.

R:

110/70 R17. Maxxis

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

02/04/19.

Survey held at

Hua Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[Signature]
2/8/2019

RECEIVED 05 AUG 2019

Date / Time

Action / Instruction

TPM816.

MV: 7000RM ≈ \$2.4K.

PV: 200

Nett: 2.2K.

Date/Time, File Pass to?

☐

Preli. Report

1) 05/8/2019

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

N

161

Report Format:

MER-TP

Lump Sum / I.B.I. (\$)

2200

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Mar 2019		01 Apr 2019 16:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ZHANG TAO, ID: S8367459H, Tel: +6591597669, Email: TONYZHANGTHU@GMAIL.COM			[Created by insurer]						
Main Claimant: LAI KHANG WHI, ID: NA									
Vehicle Reg. No.: JRM976			Date of Loss: 09/03/2019 12:00 - :59						
Claim Type: TP / 587230			Policy/Cover Note No.: 29114729QMY (Comprehensive) Coverage: 31/01/2019 - 30/01/2020						
Vehicle Reg. No. (Insured): SMF1849B			Policy No. (Claimant):						
			Excess: S\$500.00						
Repairer: Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/04/2019]									
Driver/Custodian (Insured): ZHANG TAO (36 / Male), NRIC: S8367459H, Tel: +6591597669 Email: TONYZHANGTHU@GMAIL.COM									
Adj Asg. Remarks: SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100% CONTACT: JUNE 6747 8064/6746 5519. on WP. Car In.									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.			View All Compose Case Mail						
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

P: June

E:

V: in

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyao

Date: 26 Jul 2019

Preliminary Advice

Insured Vehicle No	: SMF1849B	Accident Date	: 09/03/2019
TP Vehicle No	: JRM976	Assignment Date	: 01/04/2019
Make	: ADIVA AD1 200	Est. Duration of Repair	: 5.00
Date of Inspection	: 02/04/2019		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,635.00
Revised Amount	:S\$	3,704.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,704.70

Lump Sum Repair	:S\$	2,200.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. Kindly assist to amend the make & model of JRM 976 to YAMAHA Y152R (150cc) instead of ADIVA AD1 200 190cc 3W in Merimen System.

View Sent Message

This mail is associated with :

***JRM976 (587230)**

[SMF1849B]

TP

LAI KHANG WHI

Mar 9 2019 12:00PM

[ZHANG TAO]

Hua Meng Spray Painting Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 03/04/2019 17:05 PM.

To fievel_foo@sg.msg-asia.com

Subject JRM976 (587230) [SMF1849B] TP

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JRM 976 on 02/04/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.



**SINGAPORE
POLICE FORCE**



T/20190311/2139

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20190311/2139

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/03/2019 16:14	Vide Report No.:	Station Diary No.: 112
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: LAI KHANG WUI		Address: APT BLK 180 YUNG SHENG ROAD #15-105 SINGAPORE 610180	
ID Type / ID No.: FIN NO / G7476805P		Contact No.: Home/Office: Mobile: 84358938	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 35	Date of Birth: 25/08/1983	Type of Informant: Rider
Race: Chinese		Language:	Institution / School Name:
Occupation: COOKER		Driving Licence Information: Class: 2B Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 09/03/2019 11:00	Type of Location: Straight Road
Location: Along Road 1 JURONG GATEWAY ROAD BOON LAY WAY ALONG JURONG GATEWAY TOWARDS BOON LAY WAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRM976	Motorcycle				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190311/2139

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

2 of 3

Report No. T/20190311/2139

CONTINUATION OF REPORT

Rider			
Name	LAI KHANG WUI	ID No.	G7476805P
Related Vehicle	JRM976 (Motorcycle)	Contact No.	84358938
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	09/03/2019	Date Discharge	11/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

On 09/03/2019 at 1100hrs, I was riding my motorcycle (JRM976) along Jurong Gateway Road towards Boon Lay Way direction. I stopped my motorcycle at the traffic light junction. Upon seeing the traffic light turn 'Green', I proceed to move ahead and a vehicle suddenly came out from the left side and hit onto the front side of my motorcycle which cause my motorcycle and myself to skid. I then lost conscious and was aided by some passer by who witness the accident. They then called the ambulance and I was subsequently conveyed to Ng Teng Fong Hospital.

I sustained fractures on my right arm, cuts and acrasion on my left upper eye, both hands and bruises on my whole body. I was given 3 days MC by the doctor and was discharge on 11/03/2019. I appointed to go to Ng Teng Fong General Hospital to proceed with my surgery on the 13/03/2019. The front side of my motorcycle was slightly damaged.

This is the first time it had happened to me. I did not take down the vehicle plate number who bang into me. I am unsure if there's CCTV at the vicinity.



**SINGAPORE
POLICE FORCE**



T/20190311/2139

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3

Report No. T/20190311/2139

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 CHONG SHAO XUAN, VANESSA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH

Contact No.: 65476204

Authentication Stamp

NP168 POLICE FORCE

Signature Of Informant:

Date/Time:

11/03/2019 16:14

Classification Of Case:



T/20190327/2117

1 of 3

Report No. T/20190327/2117

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No T/20190311/2139

Report Number T/20190327/2117

Vide Report Number

Date/Time of Report Made 27/03/2019 15:57

Place Report Lodged Traffic Police

Type of Informant Rider

Name of Informant LAI KHANG WUI

ID Type / ID No. FIN NO / G7476805P

Home/Office 84358938

Mobile 84358938

Email

Type of Accident Injury / Conveyed By Ambulance

Drink Drive No

Anyone conveyed by
ambulance Yes

Date/Time of Accident 09/03/2019 11:00

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRM976	Motorcycle				Slightly Damaged	0
SMF1849B	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20190327/2117

2 of 3

Report No. T/20190327/2117

Continuation of CSF For NP168

Rider			
Name	LAI KHANG WUI	ID No.	G7476805P
Related Vehicle	JRM976 (Motorcycle)	Contact No.	84358938
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	09/03/2019	Date Discharge	11/03/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Facts.

ON THE ABOVE MENTION THE DATE, TIME AND LOCATION.
I WAS RIDING ALONG THE LEFT LAND OF JURONG GATEWAY ROAD TOWARDS THE DIRECTION OF BOON LAY WAY. AS THE TRAFFIC LIGHT WAS GREEN IN MY FAVOUR, I CONTINUED TO RIDE ON WHEN THE MOTOR VEHICLE NO. SMF1849B CAME FROM THE OPPOSITE DIRECTION TO MAKE THE RIGHT TURN WITHOUT GIVING WAY TO MY MOTORCYCLE. I WAS NOT ABLE TO STOP IN TIME AND COLLIDED INTO THE FRONT LEFT PORTION OF THE MOTOR VEHICLE.
THAT'S ALL



T/20190327/2117

3 of 3

Report No. T/20190327/2117

Continuation of CSF For NP168

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity No

Officer-In-Charge of Case TP / GIT /
MARIAH BINTE ZAKARIA

Classification of Case 1) INJURY / CONVEYED BY AMBULANCE



A handwritten signature in black ink, consisting of a large, stylized loop followed by a series of smaller, connected strokes.



Zurich General Insurance Malaysia Berhad (1249518-V)
11th Floor, Menara Zurich, No. 12, Jalan Dewan Bahasa, 50460 Kuala Lumpur, Malaysia
Tel: 03-2146 8000 Fax: 03-2144 1622 Call Center: 1-300-888-622

MOTORCYCLE MOTORSIKAL

THE SCHEDULE

ORIGINAL COPY

JADUAL

SALINAN ASAL

Agent Code (Kod Ejen)	: D14093-000 (JOHOR BHARU) CHOO SWEE HWA	Date (Tarikh)	: 03 APR 2018			
Replacing Cover Note No. (Menggantikan Nota Lindung No.)	: D14093-18000625	Receipt No. (No. Resit)	:			
Policy No. (No. Polisi)	: 501600053893-02	ACT (ACT)	: RM 47.18			
The Policyholder (Yang Diinsuranskan)	: LAI KHANG WUI	Basic Premium	: RM 208.71			
Address (Alamat)	: 116, JLN RAWA 1, TMN PERLING, 81200 TAMPOI, JOHOR DARUL TAKZIM	All Riders	: RM 104.36			
Business Reg. No. (No. Sykt.)	:	NCD: 25.00%	: RM 78.27			
I/C No. New (No. K/P Baru)	: 830825-13-5667 Old I/C No. (No. K/P Lama) :	Extra Cover	: RM 0.00			
Business / Profession (Perniagaan / Pekerjaan)	: OTHERS	Gross Premium	: RM 234.80			
Hire Purchase Owners (Pemilik Sewa Beli)	: -	GST: 6.00%	: RM 14.09			
Employer / Lessors (Majikan / Pemajak)	:	Stamp Duty (DUTI SETEM)	: RM 10.00			
Period of Insurance (Tempoh Insurans)	(a) From (Dari) : 27 APR 2018 To (Hingga) : 26 APR 2019 Termasuk kedua-dua Time (Masa) : 12:01AM To (Hingga) : 11.59PM tarikh dan masa (b) Any subsequent period for which you shall pay and we shall agree to accept a renewal premium Sebarang tempoh selanjutnya untuk mana anda membayar dan kami bersetuju menerima premium pembaharuan	Total Premium (JUMLAH)	: RM 258.89			
The Motor Vehicle	Any of the following (Mana - mana daripada yang berikut):	Kenderaan Motor				
Registration No. No. Pendaftaran	Make Buatan & Jenis Badan	Type of Body Jenis Badan	Cubic Capacity Keupayaan Enjin	Year of Manufacture Tahun Diperbuat	Seating Capacity Including Driver Muatan Tempat Duduk termasuk Pemandu	Your Estimate of Value Including Accessories Nilai Anggaran Anda termasuk Aksesori
JRM976	YAMAHA Y15ZR	MOTORCYCLE	150.00 CC	2016	2	RM6,500.00
Date of Signature of Proposal and Declaration Tarikh Cadangan dan Perakuan Dandatangani		EXCESS : All Claims : RM 100.00 (LEBIHAN)		Engine (Enjin) : G3D3E-022455 CHASSIS (CASIS) : PMYUG0510G0023374		
Subject to the terms and conditions of the Policy and endorsement as numbered below : Tertakluk kepada peraturan - peraturan dan syarat - syarat Polisi dan pengendoursan seperti disenaraikan di bawah :						
Named Driver : 1) ALL RIDERS						
Include Endorsement No : 03, 94, 107, FINANCIALSERVICESACT2013						
Additional Extra Coverage/Endorsements :-						
Code Description		Value		Premium		
03 ALL RIDERS		0.00		104.36		

LEGISLATION:-

Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore Motor Vehicles (Third Party Risks and Compensation) Rules (Republic of Singapore) Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery" is limited to Section 94, 95 and 96 of the Road Transport Act 1987 (Malaysia) Section 7, 8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

UNDANG - UNDANG:-

Akta Pengangkutan Jalan Raya, 1987 Malaysia, Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, Peraturan Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) 1960 Republik Singapura, Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam (rujukan kepada undang - undang di bawah tajuk "Pengelakan Peraturan - Peraturan Dan Hak Tuntutan Tertentu" adalah terhad kepada Seksyen 94, 95 dan 96 Akta Pengangkutan Jalan Raya, 1987 Malaysia. Seksyen 7, 8 dan 9 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, dan Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam).

Limits of Liability:-

Had Tanggungan:

Limit of the amount of the Company's Liability under Section 1-3	RM50.00
Had jumlah tanggungan Syarikat di bawah Seksyen 1-3	
Limit of the amount of the Company's Liability under Section 11-1(a)	Unlimited
Had jumlah tanggungan Syarikat di bawah Seksyen 11-1(a)	
Limit of the amount of the Company's Liability under Section 11-1(b)	RM3,000,000.00
Had jumlah tanggungan Syarikat di bawah Seksyen 11-1(b)	

For and on behalf of / Untuk dan bagi pihak
Zurich General Insurance Malaysia Berhad

Limitation as to Use
Had Penggunaan

: As shown in the Certificate of Insurance
: Seperti ditunjukkan dalam Sijil Insurans

Geographical Area
Had Wilayah

: Malaysia, Republic of Singapore and Negara Brunei Darussalam
: Malaysia, Republik Singapura dan Negara Brunei Darussalam

Authorised Driver
Pemandu Yang Dibenarkan

: As shown in the Certificate of Insurance
: Seperti ditunjukkan dalam Sijil Insurans

David Fike
Chief Executive Officer

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: **JRM976**

No. Siri B **9687421**
9KQF3DS4

Nama Pemunya : **LAI KHANG WUI**
Berdaftar

830825135667
[MAL]

Alamat : **116, JLN RAWA 1, TMN PERLING,
81200 JOHOR BAHRU JOHOR**

No. Enjin	: G3D3E-022455	B.D.M/B.G.K	: -
No. Casis	: PMYUG0510G0023374	B.T.T.	: -
Buatan	: YAMAHA	Berat Kerb	: -
Nama Model	: YAMAHA Y15ZR	B.T.M.	: -
Keupayaan Enjin	: 150 S.P	B.G.1	: -
Bahan Bakar	: PETROL	B.G.2	: -
Warna	: BIRU	B.G.3	: -
Kelas Kegunaan	: MOTOSIKAL	B.G.4	: -
Jenis Badan	: MOTOSIKAL	B.G.5	: -
Tahun Dibuat	: 2016	B.G.6	: -
Tarikh Pendaftaran	: 27/04/2016	B.G.7	: -
Status Pemunya	: PERSENDIRIAN	B.G.8	: -
Muatan Tempat		B.G.9	: -
Duduk	: 2	B.G.10	: -
Kadar Lesen		B.G.11	: -
Kenderaan Motor	: 6 bulan RM2.00	B.G.12	: -
	: 12 bulan RM2.00		

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan
oleh Pengarah JPJ Negeri **JPJ NEGERI JOHOR**

PEMASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

1.
2.
3.
4.
5.
6.
7.
8.
9.
0.
1.
2.
3.

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
- Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaharui lesen 60 hari sebelum tempohnya tamat.
- Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
- Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
- Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

TPMS/G.
Xiao Chen,

JRM976 2016 April
Yamaha Y15ZR. 150 cc.
PmyUG0510G0023374

Nett. Value: 21C

Front Tyre.	new	150 (SN) X
Front Wheel Rim.	ut	280 (SN) 180 (SN)
Front Fender	ut	90 ✓
Front Number Plate Sticker	new	10 (SN) ✓
Front Cowling.	cracked	95 ✓
Front Cowling Base.	Cracked	85 ✓
Front Cowling Lamp x 02	cracked	80 x 2 = 160 ✓
Headlamp	cracked	185 ✓
Headlamp Cowling.	cracked	105 ✓
Front Windshield	new	28 X
Front Windshield Number Plate Sticker	new	10 (SN) X.
Handle Bar	Bent	75 ✓
Balancer LH.	ut	25 ✓
Handle Grip LH	new	20 X.
Front wing Mirror LH.	cracked	48 ✓
Front Fork Assy	Bent	640 ✓
Front Fork Top Bracket	} Bent	95 ✓
Front Fork Under Bracket		185 ✓
Front Fork Oil	} new	30 ✓
Front Fork Oil Seal		40 ✓
Radiator	new new	430 X

JRM 976

Side Fairing (Silver) x 02	crushed	90 x 2 = 180.	✓
Front LH Footrest.	new	35	x
Front Basket.	crushed	60	✓
Horn.	new	30	+
Speedometer	crushed	350	✓
Signal Lamp x 02	crushed	65 x 2 = 130	✓
Side Fairing (Blue) x 02	new	50 x 2 = 100	x
Side Fairing Centre Garnish.	new	45	x
Rear Footrest LH	new	35	+
Rear Footrest Bracket LH.	new	78	+
Rear Seat Side Garnish LH. LH		75	✓
Rear Box	missing	250 200 (SN)	
Rear Box Bracket	best	150	✓
Stickers.	new	100 50	
Clutch Lever.	crushed	30	✓

2883 S.N. 380.

2594.70

JRM 976.

Labour
Spray Painting
Wiring.
To straighten chassis Member.
Towing Fees

~~400~~ 250
~~400~~ 200
~~50~~ 30
~~250~~ 200
~~60~~ 40
720.

total: 3694.70

H/S: 2.2K.

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5694

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Mar 2019		01 Apr 2019 16:49 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ZHANG TAO , ID: S8367459H, Tel: +6591597669, Email: TONYZHANGTHU@GMAIL.COM									
Main Claimant: LAI KHANG WHI , ID: NA									
Vehicle Reg. No.: JRM976		Date of Loss: 09/03/2019 12:00 - :59 [34 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 587230		Policy/Cover Note No.: 29114729QMY (Comprehensive) Coverage: 31/01/2019 - 30/01/2020							
Vehicle Reg. No. (Insured): SMF1849B		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/05/2019]									
Driver/Custodian (Insured): ZHANG TAO (36 / Male) , NRIC: S8367459H, Tel: +6591597669 Email: TONYZHANGTHU@GMAIL.COM									
Adj Asg. Remarks: SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100% CONTACT: JUNE 6747 8064/6746 5519. on WP. Car in.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JRM976 (587230)**
[SMF1849B]
TP
LAI KHANG WHI
Mar 9 2019 12:00PM
[ZHANG TAO]
Hua Meng Spray Painting Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/04/19 14:29	Accident Statement From:OD - Reg. No: SMF1849B, Claimant: ZHANG TAO	Load HTM	
2	01/04/19 14:29	Addendum Sheet From:OD - Reg. No: SMF1849B, Claimant: ZHANG TAO	Load JPG	☒
3	01/04/19 14:29	Accident Statement Addm. #1 From:OD - Reg. No: SMF1849B, Claimant: ZHANG TAO	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 12:05	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 11:43	General View	Load JPG	☒
2	26/07/19 11:43	General View	Load JPG	☒
3	26/07/19 11:43	General View	Load JPG	☒
4	26/07/19 11:43	General View	Load JPG	☒
5	26/07/19 11:43	General View	Load JPG	☒
6	26/07/19 11:43	General View	Load JPG	☒
7	26/07/19 11:43	General View	Load JPG	☒
8	26/07/19 11:43	General View	Load JPG	☒
9	26/07/19 11:43	General View	Load JPG	☒
10	26/07/19 11:43	General View	Load JPG	☒
11	26/07/19 11:43	General View	Load JPG	☒
12	26/07/19 11:43	General View	Load JPG	☒
13	26/07/19 11:43	General View	Load JPG	☒
14	26/07/19 11:43	General View	Load JPG	☒
15	26/07/19 11:43	General View	Load JPG	☒
16	26/07/19 11:43	General View	Load JPG	☒
17	26/07/19 11:43	General View	Load JPG	☒
18	26/07/19 11:43	General View	Load JPG	☒
19	26/07/19 11:43	General View	Load JPG	☒
20	26/07/19 11:43	General View	Load JPG	☒
21	26/07/19 11:43	General View	Load JPG	☒
22	26/07/19 11:43	General View	Load JPG	☒
23	26/07/19 11:43	General View	Load JPG	☒
24	26/07/19 11:43	General View	Load JPG	☒
25	26/07/19 11:43	General View	Load JPG	☒
26	26/07/19 11:43	General View	Load JPG	☒
27	26/07/19 11:43	General View	Load JPG	☒
28	26/07/19 11:43	General View	Load JPG	☒
29	26/07/19 11:43	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	26/07/19 11:43	General View	 Load JPG	☒
31	26/07/19 11:43	General View	 Load JPG	☒
32	26/07/19 11:43	General View	 Load JPG	☒
33	26/07/19 11:43	General View	 Load JPG	☒
34	26/07/19 11:43	General View	 Load JPG	☒
35	26/07/19 11:43	General View	 Load JPG	☒
36	26/07/19 11:43	General View	 Load JPG	☒
37	26/07/19 11:43	General View	 Load JPG	☒
38	26/07/19 11:43	General View	 Load JPG	☒
39	26/07/19 11:43	General View	 Load JPG	☒
40	26/07/19 11:43	General View	 Load JPG	☒
41	26/07/19 11:43	General View	 Load JPG	☒
42	26/07/19 11:43	General View	 Load JPG	☒
43	26/07/19 11:43	General View	 Load JPG	☒
44	26/07/19 11:43	General View	 Load JPG	☒
45	26/07/19 11:43	General View	 Load JPG	☒
46	26/07/19 11:43	General View	 Load JPG	☒
47	26/07/19 11:43	General View	 Load JPG	☒
48	26/07/19 11:43	General View	 Load JPG	☒
49	26/07/19 11:43	General View	 Load JPG	☒
50	26/07/19 11:43	General View	 Load JPG	☒
51	26/07/19 11:43	General View	 Load JPG	☒
52	26/07/19 11:43	General View	 Load JPG	☒
53	26/07/19 11:43	General View	 Load JPG	☒
54	26/07/19 11:43	General View	 Load JPG	☒
55	26/07/19 11:43	General View	 Load JPG	☒
56	26/07/19 11:43	General View	 Load JPG	☒
57	26/07/19 11:43	General View	 Load JPG	☒
58	26/07/19 11:43	General View	 Load JPG	☒
59	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
60	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
61	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
62	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
63	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
64	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
65	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
66	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
67	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
68	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
69	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
70	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
71	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
72	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
73	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
74	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
75	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
76	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
77	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
78	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
79	26/07/19 11:43	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
81	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
82	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
83	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
84	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
85	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
86	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
87	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
88	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
89	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
90	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
91	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
92	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
93	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
94	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
95	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
96	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
97	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
98	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
99	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
100	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
101	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
102	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
103	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
104	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
105	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
106	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
107	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
108	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
109	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
110	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
111	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
112	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
113	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
114	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
115	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
116	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
117	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
118	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
119	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
120	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
121	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
122	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
123	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
124	26/07/19 11:43	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/04/19 14:24	PRI - HUA MENG SPRAY PAINTING WORKSHOP	 Load PDF	
2	01/04/19 14:36	EMAIL FROM TP TO ARRANGE SURVEY	 Load PDF	
3	01/04/19 14:36	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	 Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
4	15/05/19 18:17	MSIG Insurance (Singapore) Pte. Ltd. (HQ) LOD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19005727/AGQD3E2

Date: 07/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114729QMY

Claimant Vehicle No : JRM976

Insured Vehicle No : SMF1849B

Date of Loss: 09/03/2019

Nature of Claim: TP

Claim No: 587230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JRM976

Make & Model: YAMAHA Y152R, 150cc

Engine No: G3D3E022455

Reg. Date: 27/04/2016 (Man. Year: 2016)

Chassis No: PMYUG0510G0023374

Colour: Blue

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90 R17

Rear Tyre Size: 110/70 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Maxxis 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,434.00	2,984.70	1,449.30	32.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	720.00	540.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,694.00	3,704.70	1,989.30	34.94
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	5,694.00	2,200.00	3,494.00	61.36

INSPECTION

Date of Assignment: 01/04/2019

Date Inspected: 02/04/2019 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Aug 2019)	
Parts:	N/A	YAMAHA Y152R 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JRM976)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	90.00 F	*90.00 FL
2	1		*FRONT COWLING	Cracked	95.00 F	*95.00 FL
3	1		*FRONT COWLING BASE	Cracked	85.00 F	*85.00 FL
4	2		*FRONT COWLING LAMP	Cracked	160.00 F	*160.00 FL
5	1		*HEADLAMP	Cracked	185.00 F	*185.00 FL
6	1		*HEADLAMP COWLING	Cracked	105.00 F	*105.00 FL
7	1		*FRONT WINDSHIELD	Not Necessary	28.00 F	*- FL
8	1		*HANDLE BAR	Bent	75.00 F	*75.00 FL
9	1		*BALANCER LH	Cut	25.00 F	*25.00 FL
10	1		*HANDLE GRIP LH	Not Necessary	20.00 F	*- FL
11	1		*FRONT WING MIRROR LH	Cracked	48.00 F	*48.00 FL
12	1		*FRONT FORK ASSY	Bent	640.00 F	*640.00 FL
13	1		*FRONT FORK TOP BRACKET	Bent	95.00 F	*95.00 FL
14	1		*FRONT FORK UNDER BRACKET	Bent	185.00 F	*185.00 FL
15	1		*FRONT FORK OIL	Necessary	30.00 F	*30.00 FL
16	1		*FRONT FORK OIL SEAL	Necessary	40.00 F	*40.00 FL
17	1		*RADIATOR	Not Necessary	430.00 F	*- FL
18	2		*SIDE FAIRING (SILVER)	Cracked	180.00 F	*180.00 FL
19	1		*FRONT LH FOOTREST	Not Necessary	35.00 F	*- FL
20	1		*FRONT BASKET	Cracked	60.00 F	*60.00 FL
21	1		*HORN	Not Necessary	30.00 F	*- FL
22	1		*SPEEDMETER	Cracked	350.00 F	*350.00 FL
23	2		*SIGNAL LAMP	Cracked	130.00 F	*130.00 FL
24	2		*SIDE FAIRING (BLUE)	Repair	100.00 F	*- FL
25	1		*SIDE FAIRING CENTRE GARNISH	Not Necessary	45.00 F	*- FL
26	1		*REAR FOOTREST LH	Not Necessary	35.00 F	*- FL
27	1		*REAR FOOTREST BRACKET LH	Not Necessary	78.00 F	*- FL
28	1		*REAR SEAT SIDE GARNISH LH	Cut	75.00 F	*75.00 FL
29	1		*REAR BOX BRACKET	Bent	150.00 F	*150.00 FL
30	1		*STICKERS	Necessary	100.00 F	*50.00 FL
31	1		*CLUTCH LEVER	Cracked	30.00 F	*30.00 FL
32	1		*FRONT TYRE	Not Necessary	150.00 FS	*- FS
33	1		*FRONT WHEEL RIM	Cut	280.00 FS	*180.00 FS
34	1		*FRONT NUMBER PLATE STICKER	Necessary	10.00 FS	*10.00 FS
35	1		*FRONT WINDSHIELD NUMBER PLATE STICKER	Not Necessary	10.00 FS	*- FS
36	1		*REAR BOX	Missing	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **4,434.00** **3,273.00**
- List Item Discount on L Items 0.00/10.00% (S\$) **0.00** **288.30**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	4,434.00	2,984.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	400.00	250.00
2	SPRAY PAINTING	New	400.00	200.00
3	WIRING	New	50.00	30.00
4	TO STRAIGHTEN CHASSIS MEMBER	New	350.00	200.00
5	TOWING FEES	New	60.00	40.00
Gross Labour Cost (S\$)			1,260.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >