

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBF5130U190322

Estimate**Customer**

Name: India International Insurance Pte Ltd

Address: Motor Claims Department

64 Cecil Street #04-00 & #05-00

IOB Building Singapore 049711

Date: 01-04-19

Vehicle No: GBF5130U

Model/Make: Fiat Doblo Cargo

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>20/22</i>	\$ 745.00	
2	Bumper Clips 1 set <i>new</i>	\$ 65.00	<i>SN</i>
3	Bumper Reinforcement <i>3rd</i>	\$ 475.30	<i>✓</i>
4	Bumper Reverse Sensor <i>5th</i>	\$ 220.00	<i>SN 200 S.N</i>
5	Bumper Side Holder 02 pcs (@ S\$35.60)	\$ 71.20	<i>X</i>
6	End Panel <i>n</i>	\$ 485.00	<i>X</i>
7	End Panel Top Rubber <i>11</i>	\$ 347.70	<i>X</i>
8	Tailgate "Professional" Emblem <i>new</i>	\$ 163.50	<i>SN</i>
9	Tailgate "70 KM/H" Sticker <i>new</i>	\$ 12.00	<i>SN 10 S.N</i>
10	Tailgate "6 PAX" Sticker <i>new</i>	\$ 12.00	<i>SN 10 S.N</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	<i>450</i>
	To putty & spray painting & including touch up paint on accident affected areas	\$ 500.00	<i>✓</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	<i>11X</i>
	To remove, replace and transfer <i>reverse sensor</i>	\$ 80.00	<i>50</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 3,856.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1448.80
1070
1303.92
2523

not Approved
new
2/3 2000/2
4th