

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 5590P

AAD1903-202

Not Authored
Resurvey By paint

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 5590P
 JTDKB3FU403076785
 TOYOTA
 PRIUS
 26.3.2019
ERGO
 15/11/2018

PART		LIST	
1	1 REAR BUMPER	\$	<i>B₁</i> 458.60 ✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>B₁</i> 318.80 ✓
3	1 REAR BUMPER TOWING COVER	\$	<i>Red Assy</i> 14.70 ✓
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>B₁</i> 552.60 ✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>D₁₇</i> 112.70 ✓
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>CM</i> 112.70 ✓
7	1 REAR TAILGATE	\$	<i>B₁</i> 1,547.27 ✓
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>CM</i> 905.10 ✓
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>S₁</i> 54.70 X
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>S₁</i> 54.70 X
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>S₁</i> 93.60 X
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>S₁</i> 93.60 X
13	1 BOARD ASSY, BACK DOOR TRIM	\$	254.40 ?
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>R</i> 51.20 X
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>Dis/Assy</i> 365.20 ✓
16	1 REAR END PANEL	\$	<i>B₁</i> 602.10 ✓
17	1 TAILLAMP LOWER RH	\$	548.40 ?
18	1 TAILLAMP UPPER RH	\$	<i>CM</i> 557.90 ✓
19	1 REAR BUMPER SIDE RH	\$	<i>mj/cm</i> 232.00 ✓
20	1 REAR BUMPER SIDE LH	\$	<i>mj/cm</i> 232.00 ✓
21	1 TAILLAMP LOWER LH	\$	548.40 ?
22	1 TAILLAMP UPPER LH	\$	<i>CM</i> 557.90 ✓
23	1 PAN, REAR FLOOR	\$	<i>B₁</i> 572.10 ✓
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	77.00 ?
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	192.90 ?
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	77.00 ?
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	192.90 ?
28	1 PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>R</i> 1,258.30 ?
29	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>R</i> 290.50 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5590P**AAD1903-202**

30	1 REAR FENDER LH	\$	<i>Bu</i>	817.50	✓
31	1 PANEL SUB-ASSY, REAR DOOR, RH	\$	<i>R</i>	1,258.30	X
32	1 REAR FENDER RH	\$	<i>n</i>	817.50	X
		\$		13,822.57	
		25% \$		3,455.64	
		\$		10,366.93	

Special Nett

1	1SET PARKING AID	\$	<i>Tn</i>	700.00	<i>2500n</i>
2	1SET REAR BUMPER CLIP	\$	<i>n</i>	22.00	✓
3	2 REAR WINDSCREEN SELANT	\$	<i>n</i>	80.00	✓
4	1 WINDSCREEN MOULDING	\$	<i>n</i>	100.00	✓
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i>	100.00	<i>300n</i>
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>n</i>	47.00	✓
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>n</i>	52.90	✓
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>n</i>	53.50	✓
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>n</i>	80.00	<i>300n</i>
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>n</i>	80.00	<i>300n</i>
11	1 REAR BUMPER PROTECTOR	\$	<i>n</i>	100.00	X
TOTAL		\$		1,415.40	
TOTAL PARTS		\$		11,782.33	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>2000 1320l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>2000l</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>120l</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>50l</i>

Trans-cab Auto Services Pte Ltd

AAD1903-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5590P

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	60%
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	} 60%
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120%
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	na 170.00	X

TOTAL \$ 10,150.00

Over All Total \$ 32,299.26

(PART-BY-PART) Repair Days

20 DAYS

15 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: