



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102197
INV Date 05/04/2021
Reference CC4/LPC19005754/Kba3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLW 5362J
Insured Veh. GBC 7592Y
Claim No. 18/19/19/VC05/021600
Policy No. Z18VC05000483
Accident Date 27/03/2019
Inspection Date 02/04/2019

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC19005754/Kba3q2

Date: 05/04/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 7592Y	Veh. Inspected	SLW 5362J
Policy No.	Z18VC05000483	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021600	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	01/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PICNIC (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTEGH23B100026621	Colour	METALLIC SILVER
Odometer	222921 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WANLI	9 mm
L/H Front Tyre	205/60 R16	WANLI	9 mm
R/H Rear Tyre	205/60 R16	MICHELIN	7 mm
L/H Rear Tyre	205/60 R16	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/03/2019	Inspection Date	02/04/2019
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 5362J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT	BENT	1,210.76	1,210.76
1	REAR BOOT EMBLEM -TOYOTA	NECESSARY	39.29	39.29
1	REAR BOOT EMBLEM -LOGO	NECESSARY	67.80	67.80
1	REAR BOOT EMBLEM -PICNIC	NECESSARY	45.00	45.00
1	REAR BOOT HANDLE	BENT	228.30	228.30
2	REAR NUMBER PLATE LAMP @\$85.20	SERVICEABLE	170.40	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	511.20	-
	LESS 25% DISCOUNT		-568.19	-397.79
			1,704.56	1,193.36
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	REVERSE SENSOR (SN)	DENTED	300.00	220.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			365.00	260.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		450.00	360.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		700.00	400.00
			1,270.00	880.00
GRAND TOTAL			3,339.56	2,333.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CC4/LPC19005754/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 5362J

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION JAPAN			
MODEL	ACV2003-ARSEK		
ENGINE	1AZ-FE	1998	ml
FRAME No.	JTEG-23B100026621		
COLOR	TRIM	PLANT	OPTION
ID4	EC07	C25	
TRG/ALF	U241E-01A		C80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 5362J

RE-INSPECTION

