

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0407/2019/DY/GW
Date : 30-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Seah Li-Yen Jocelynn
Address : 15 Bloxhome Drive
Singapore 559710
Telephone : 98750369
Type of Claim : Own Damage Claims
Policy No. : 1800098340
Vehicle No : **SKR 6778 A**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : 16/8/2018
Engine No : CVK 063933
Chassis No : WAUZZZF44JA188316
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Mar-19
Place of Accident : Upper Paya Lebar Rd Underpass

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/ ✓
2	To carry out first measurement on car-liner	\$ 800.00	/ ✓
3	To remove and renew front windscreen.	S/N \$ 360.00	/ 480
4	To remove and transfer, air con condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,000.00	P / ✓
5	To remove and transfer lhs front and rear door's multi locks systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 720.00	/ ✓
SUB-TOTAL LABOUR CHARGES		: \$ 3,360.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
6	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carperets, electronic components and fuse trays.	S/N \$ 1,400.00	/ ✓
7	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air baas and central protection.	S/N \$ 3,600.00	/ ✓
8	To renew passenger seat air bag and leather cover.	S/N \$ 800.00	/ ✓
9	To suspend engine, remove and reinstall front suspension for car -o-liner repairs. Inspect for damages and renew accordinqly.	S/N \$ 2,800.00	/ ✓
10	To remove and reinstall rear exhaust silencer assy, rear suspension assy and fuel tank, for car-o-liner repairs. Inspect for damages.	S/N \$ 2,800.00	/ ✓
SUB-TOTAL LABOUR CHARGES		: \$ 11,400.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
11	To place vehicle on car-o-liner.	S/N \$ 1,800.00	/ ✓
12	To dismantle front bumper, lhs front fender, lhs front and rear doors. Inspect lhs wheel house and floor pan for damages. Cut out and weld lhs A-pillar, inner reinforcements, sill panel and inner web plates. Renew front lock carrier. Renew all damaged panels. Reinstall all parts removed.	\$ 12,600.00	9500 10500 ✓
13	To respray front bumper, lhs front fender, bonnet, lhs front and rear doors, door handles, lhs A-pillar, sill panel, door entrances and inner reinforcements. To carry out joint sealer works and stone chip treatment.	\$ 6,500.00	4750 ✓
14	To renew lhs front and rear rims and lhs front tyre. To carry out wheel alignment.	S/N \$ 320.00	/ ✓
15	To carry out diagnostic check.	S/N \$ 576.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 36,556.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKR 6778 A

S/N	Parts Description		Damaged Par S/Nett	
1	FRONT BUMPER / Dis	\$	1,999.00 1599.00	
2	FRONT BUMPER SECURING STRIP /	2 \$	64.00 50.88	
3	FRONT BUMPER GUIDE SECTION-LH /	} MBL	\$ 33.00 26.08	
4	FRONT BUMPER GUIDE SECTION-RH /		\$ 34.00 27.12	
5	FRONT BUMPER GRILLE-CENTER X NN	\$	178.00 X	
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE / TN	\$	191.00 152.40	
7	FRONT AIR GUIDE-LH / misc. LH - misc	\$	56.00 44.40	
8	FRONT AIR GUIDE GRILLE-LH/RH < RH X NN	2 \$	246.00 98	
9	FRONT FENDER-LH / Dis	\$	700.00 559.60	
10	FRONT FENDER ATTACHMENT PARTS-LH /	} \$ Dis.	\$ 183.00 146.40	
11	FRONT FENDER BRACE-LH /		\$ 107.00 85.60	
12	FRONT FENDER END PLATE-LH /		\$ 45.00 36	
13	FRONT FENDER BRACKET-LH /		\$ 32.00 25.20	
14	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH /		\$ 45.00 35.60	
15	FRONT FENDER REAR BRACKET-LH /		\$ 29.00 22.64	
16	FRONT FENDER UPPER BRACKET-LH /		\$ 31.00 24.16	
17	FRONT FENDER CLOSING ELEMENT /		\$ 30.00 23.76	
18	FRONT FENDER PROTECTION FILM-LH X NN		\$	11.00 X
19	FRONT WHEEL HOUSING LINER-LH /		\$	223.00 178.40
20	FRONT WHEEL HOSUING LINER ATTACHEMENT PART-LH /	\$	82.00 65.52	
SUB FRONT SPARE PARTS			\$ 4,319.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER LINER LOWER COVER -LH / mis .	\$ 13.00	10.16
22	FRONT WHEEL ARC TRIM-LH / mis	\$ 66.00	52.32
23	FRONT FENDER MOLDING-LH = X NN	\$ 32.00	X
24	FRONT STONE CHIP GUARD-LH / MC	\$ 46.00	36.64
25	LED HEADLIGHT-LH / BS CRA .	\$ 7,087.00	5669.60
26	LED HEADLIGHT POWER MODULE-LH X NN	\$ 716.00	X
(27)	LED HEADLIGHT CONTROL UNIT-LH ✓ NN	\$ 685.00	548
28	LED HEADLIGHT DRAIN HOSE-LH X	\$ 32.00	X
29	LED HEADLIGHT COMPENSATING PIECE X } NN 2	\$ 77.00	X
30	LED HEADLIGHT ASSEMBLY SPACER X } 2	\$ 72.00	X
31	LED HEADLIGHT LIFT CYLINDER-LH / DM	\$ 192.00	153.00
32	LED HEADLIGHT LIFT CYLINDER BRACKET-LH / MC	\$ 6.00	4.24
33	FRONT DOOR-LH / BUC	\$ 2,152.00	1721.60
34	FRONT DOOR OUTER DOOR SEAL-LH / CL.	\$ 185.00	147.60
35	BONDNG AGENT /	\$ 45.00	36
36	CLEANING SOLUTION /	\$ 65.00	52
37	APPLICATOR X NN } MC	\$ 7.00	X
38	FRONT DOOR ATTACHMENT PARTS-LH /	\$ 488.00	390
39	FRONT DOOR HINGE HALF UPPER PART-LH UPPER /	\$ 41.00	32.08
40	FRONT DOOR HINGE HALVES-LH UPPER / } BT	\$ 42.00	33.04
SUB FRONT SPARE PARTS		\$ 12,049.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT DOOR HINGE HALF-LH LOWER	\$ 39.00	30.80
42	FRONT DOOR HINGE HALVES-LH LOWER	\$ 42.00	33.04
43	FRONT DOOR CATCH-LH	\$ 96.00	76.16
44	FRONT DOOR CATCH COVER-LH	\$ 13.00	10.40
45	FRONT DOOR SEAL INNET-LH	\$ 185.00	147.60
46	FRONT DOOR MOUNTING BAR-LH	\$ 149.00	118.80
47	FRONT DOOR HANDLE OUTSIDE GASKET-LH FRONT	\$ 4.00	3.20
48	FRONT DOOR HANDLE OUTSIDE GASKET-LH REAR	\$ 4.00	3.20
49	FRONT DOOR HANDLE EXTERIOR-LH	\$ 35.00	27.52
50	FRONT DOOR HANDLE SENSOR-LH	\$ 208.00	166.40
51	FRONT DOOR HANDLE TRIM PLATE-LH	\$ 80.00	63.52
52	FRONT DOOR HANDLE LOCK COVER-LH	\$ 6.00	4.08
53	FRONT DOOR LOCK-LH	\$ 394.00	314.80
54	FRONT DOOR INNER PANNEL COVER-LH	\$ 25.00	19.76
55	FRONT WINDOW GUIDIE-LH	\$ 412.00	329.20
56	FRONT WINDOW GUIDIE TRIM STRIP-LH	\$ 235.00	187.60
57	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH	\$ 280.00	224
58	FRONT B- PILLAR TRIM-LH	\$ 212.00	169.60
59	FRONT CONER TRIM-LH	\$ 41.00	32.80
60	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH	\$ 250.00	199.60
SUB FRONT SPARE PARTS		\$ 2,710.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	FRONT WINDOW REGULATOR-LH / Jm (photo)	\$ 278.00	222.40
62	FRONT EXTERIOR MIRROR MOUNTING-LH X } NN	\$ 999.00	X
63	FRONT MIRROR GLASS-LH X	\$ 1,553.00	X
64	FRONT MIRROR CAP-LH X repair.	\$ 220.00	175.60
65	FRONT TURN SIGNAL INDICATOR-LH ✓ NN	\$ 96.00	76.72
66	REAR DOOR-LH / OD.	\$ 2,152.00	1721.60
67	REAR OUTER DOOR SEAL-LH / MC	\$ 185.00	147.60
68	BONDING AGENT /	\$ 45.00	35.92
69	CLEANING SOLUTION /	\$ 65.00	51.68
70	APPLICATOR X NN	\$ 7.00	X
71	REAR DOOR SEALING STRIP-LH /	\$ 15.00	11.68
72	REAR DOOR ATTACHMENT PARTS-LH X NN	\$ 515.00	X
73	REAR DOOR CATCH-LH ✓ BT	\$ 109.00	87.20
74	REAR DOOR SEAL, INNER-LH X NN	\$ 201.00	X
75	REAR WINDOW SLOT SEAL WITH TRIM STRIP-LH / ant	\$ 335.00	267.60
76	REAR WINDOW GUIDE TRIM STRIP-LH X } NN	\$ 216.00	X
77	REAR B PILLAR TRIM-LH X	\$ 127.00	X
78	REAR DOOR WINDOW-LH X	\$ 265.00	X
79	FRONT LOCK CARRIER MOUNTING ✓ CRA	\$ 928.00	742
80	A/C DISCHARGE HOSE / BT.	\$ 310.00	248
SUB FRONT SPARE PARTS :		\$ 8,621.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	A/C RECEIVER DRIER	\$ 227.00	181.60
82	A/C COMPRESSOR HOSE	\$ 476.00	380.40
83	A/C HOSE AND TUBE ASSEMBLY		
84	A/C O-SEAL RING X		
85	A/C LINE O-RING X	\$ 21.00	X
86	FRONT FENDER PROTECTION FILM-LH X		
87	FRONT FENDER TOP LEDGE COVER-LH X	\$ 28.00	X
88	FRONT FENDER LEDGE COVER-LH X		
89	FRONT WIPER CROWL TRIM X	\$ 89.00	X
90	FRONT SECTIONAL PART-PILLAR A/B-LH	\$ 2,443.00	1954.40
91	FRONT A-PILLAR-LH OUTER	\$ 976.00	780.80
92	WEB PLATE FOR SIDE MEMBER-LH	\$ 134.00	107.20
93	REINFORCEMENT FOR LOWER SIDE MEMBER-LH	\$ 329.00	262.80
94	FRONT SENSOR-INNER/ OUTER	\$ 231.00	184.80
95	FROTNT BUMPER WIRING SET	\$ 470.00	376
96	FANFARE- HIGH TONE LH	\$ 37.00	29.20
97	FANFARE MOUNT BRACKET-LH	\$ 26.00	20.80
98	FRONT UNDERTRAY	\$ 520.00	416
99	REAR UNDERTRAY	\$ 358.00	286
100	FRONT UNDERBODY TRIM-LH	\$ 37.00	29.44
SUB FRONT SPARE PARTS		\$ 6,628.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
101	UNDERBODYTRIM-LH / <i>mis</i>	\$ 289.00	230.80
102	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	90.40
103	FRONT BUMPER CARRIER X <i>NN</i>	\$ 733.00	
104	FRONT BUMPER SUPPORT-LH/RH <i>✓ BR.</i> 2	\$ 52.00	40.64
105	FRONT LOCK CARRIER BRACKET <i>✓ CRA</i>	\$ 125.00	100
106	FRONT SCUFF PLATE-LH / <i>no</i>	\$ 109.00	87.20
107	FRONT SUSPENSION SUBFRAME <i>✓ BT</i>	\$ 1,726.00	1380.80
108	ENGINE BRACKET HOLDER <i>✓ CRA 22531</i>	\$ 430.00	343.60
109	FRONT LOWER CONTROL ARM-LH /	\$ 491.00	392.40
110	FRONT SUSPENSION GUIDE-LH /	\$ 861.00	688.40
111	FRONT UPPER CONTROL ARM-LH /	\$ 466.00	372.80
112	REAR UPPER CONTROL ARM-LH /	\$ 466.00	372.80
113	FRONT WHEEL BEARING HOUSING-LH / <i>BT</i>	\$ 884.00	707.20
114	FRONT SWIVEL JOINT-LH /	\$ 175.00	140
115	FRONT WHEEL HUB-LH /	\$ 451.00	360.40
116	FRONT WHEEL BEARING WITH ASSEMBLY PARTS-LH / 2	\$ 660.00	370.40
117	FRONT SUSPENSION FORKS-LH /	\$ 239.00	190.80
118	FRONT STABILIZER SWAT BAR END LINK-LH / 2	\$ 245.00	196
119	FRONT STABILIZER BAR /	\$ 397.00	317.60
120	FRONT STABILIZER BAR BUSHING /	\$ 20.00	15.76
SUB FRONT SPARE PARTS		\$ 8,932.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
121	FRONT STABILIZER BRACKET <i>X NN</i>	\$ 10.00	X
122	FRONT SUSPENSION SHOCK ABSORBER TOP MOUNTING-LH <i>BT</i>	\$ 84.00	66.80
123	FRONT SUSPENSION SPRING SUPPORT-LH <i>/</i>	\$ 56.00	44.56
124	FRONT SUSPENSION ABSORBER RUBBER STOP-LH <i>/ MC</i>	\$ 34.00	26.64
125	FRONT PROTECTIVE SLEEVE <i>/</i>	\$ 8.00	6.40
126	FRONT PROTECTIVE CAP <i>/</i>	\$ 4.00	3.20
127	FRONT SUSPENSION SHOCK SPACER-LH <i>/</i>	\$ 28.00	22.32
128	FRONT SUSPENSION SPRING DISC LOWER-LH <i>/ BT</i>	\$ 36.00	28.80
129	FRONT GAS SHOCK ABSORBER-LH <i>/ BT</i>	\$ 276.00	220.40
130	FRONT COIL SPRING-LH <i>X NN</i>	\$ 238.00	X
131	FRONT DRIVE SHAFT-LH <i>/ BT (photo)</i>	\$ 2,422.00	1937.60
132	FRONT WIRING SET FOR SPEED SENSOR-LH <i>/ Act</i>	\$ 224.00	178.80
133	FRONT HOSE BRAKE BRACKET-LH <i>X / NN</i>	\$ 25.00	X
134	FRONT BRAKE HOSE BRACKET-LH <i>X / NN</i>	\$ 25.00	X
122519 122520 135	FRONT BRAKE CALIPER HOUSING-LH <i>2 / BT</i>	\$ 246.00	340.40
136	FRONT BRAKE CALLIPER CARRIER-LH <i>2 / BT</i>	\$ 221.00	176.80
137	FRONT BRAKE PADS WITH WEAR INDICATOR-LH <i>2 / MC</i>	\$ 255.00	204
138	FRONT BRAKE DISC-LH <i>2 / BT</i>	\$ 219.00	175.20
139	FRONT BRAKE DISC COVER PLATE-LH <i>/ BT</i>	\$ 106.00	84.40
140	FRONT BRAKE HOSE-LH <i>2 / Twi</i>	\$ 70.00	55.84
SUB FRONT SPARE PARTS		\$ 4,587.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices		S/Nett	Remark
141	FRONT BRAKE HOSE CLIP-LH X NN	2	\$	4.00	X
142	FRONT BRAKE PIPE FROM HYDRAULICS TO BRAKE HOSE-LH ✓ BR ^{uni}			50.00	39.44
143	FRONT BRAKE FLUID 1.0 LTR / MC	2	\$	59.00	46.56
144	STEERING WHEEL AIR BAG UNIT /		\$	3,141.00	2512.80
145	FRONT DASHBOARD AIR BAG UNIT /		\$	4,019.00	3215.20
146	ROUND CONNECTOR HSD WITH CABLE / Act		\$	241.00	192.80
147	SIDE AIRBAG UNIT-LH /		\$	1,391.00	112.80
148	SIDE AIRBAG WIRING HARNESS-LH /		\$	190.00	151.60
149	HEAD AIRBAG UNIT-LH/RH /	2	\$	3,416.00	2732.80
150	AIR BAG CONTROL UNIT /		\$	1,927.00	1541.60
151	FRONT AIR BAG CRASH SENSOR /	3	\$	1,145.00	915.60
152	FRONT DASHBOARD WITH AIR DUCT / DM		\$	4,838.00	3870.40
153	FRONT CENTRAL CONSOLE TRIM PART X NN		\$	113.00	X
154	FRONT A-PILLAR TRIM-LH UPPR /RH UPPER ✓ MC		\$	374.00	298.40
155	FRONT GRAB HANDLE FOLDING-LH/RH ✓ BR	2	\$	258.00	103.20
156	REAR GRAB HANDLE FOLDING-LH/RH X NN	2	\$	258.00	X
157	MOULDED HEADLINING / MC		\$	1,751.00	1400.80
158	THREE POINT AUTOMATIC SEAT-LH/RH / Act	2	\$	2,010.00	1608
159	SEAT BEAT HEIGHT ADJUSTER / DM	2	\$	322.00	257.60
160	BACKREST COVER-RH LH - TN (photo)		\$	2,232.00	1785.60
SUB FRONT SPARE PARTS :				\$ 27,739.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

3.09.25

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
161	BACKREST FOR PADDING-RH <i>X NN</i>	TBC	X
162	FRONT WINDSCREEN <i>/ ACC.</i>	\$ 1,040.00	832
163	FRONT WINDSCREEN GEL FOIL FOR RAIN SENOR <i>/ ACC.</i>	\$ 128.00	10240
164	CENTRAL PROTECTION <i>/</i>	\$ 485.00	388
165	WINDSCREEN SEALANT <i>/</i>	S/N \$ 200.00	200
166	ACRYLIC SEALANT <i>/</i>	S.N \$ 360.00	360
167	CAVITY WAX <i>/</i>	S/N \$ 280.00	280
168	STONE CHIP <i>/</i>	S/N \$ 360.00	360
169	FRONT CAR PLATE NO. <i>X NN</i>	S/N \$ 25.00	X
170	SUNDRIES <i>/ ACC.</i>	\$ 2,000.00	64236
TOTAL SPARE PARTS		\$ 80,463.00	
TOTAL LABOUR CHARGES		\$ 36,556.00	
GRAND TOTAL		\$ 117,019.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Rim / DIS.

Tyre / DIS.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

28 - 32 Days.

[Handwritten signature]
24/19

Euro Qian - 82880222

before paint photos.

01/4/19.

Not Authorised.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant