

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 02 Apr 2019

Preliminary Advice

Vehicle No	: SKR6778A	Accident Date	: 28/03/2019
Make	: AUDI A4	Policy No.	: 1800098340
Assignment Date	: 02/04/2019	Excess	: S\$0.00
Date of Inspection	: 01/04/2019	Est. Duration of Repair	: 32.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and undercarriage. The chassis frame and body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	117,019.00
Revised Amount	:S\$	94,057.50
Check Items (Estimated)	:S\$	17,483.00
Total	:S\$	111,540.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	175,000.00
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	61,308.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	113,692.00
Margin for Repair (Pre-Accident Value)	:S\$	88,692.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please take note on the Margin for Repair New for Old Value and Pre-Accident Value. Kindly advised.