

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

28 - 32 Days.

[Handwritten signature]
2/4/19

Geo Aial - 8288022

before paint photos.

01/4/19.

Not Authorised.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



Audi

ETKA - Order Form

Order Form:

SKR6778A-ADD-PARTS

14:58

11.04.2019

Pls check with Kiam and Dennis. Before order.

Editor:

Supp parts \$40751

? items - \$10464

Item Description	Remark	Model	Qty	SGD	D
8W0 853 833 VIN: WAUZZZF44JA188316 Spoiler Location: PF03-D-2 Stock: +4.00	Supp left <i>(wheel housing liner)</i>		1	20,00 31,30	
7PF 941 572 AB Z00 VIN: WAUZZZF44JA188316 Power module for main light electronics Location: JJ04-D Stock: 0	Supp ? (26)		1	541,00 716,00	
4M0 907 397 AD VIN: WAUZZZF44JA188316 Control unit for light control system Location: JJ04-B Stock: 0	Supp ? (27)		1	634,00 685,00	
8W0 941 717 A VIN: WAUZZZF44JA188316 Hose Stock: 0	Supp left		1	28,30	
8P7 806 305 VIN: WAUZZZF44JA188316 Compensating piece For component strength: 0,8MM Location: CC09-B-5 Stock: 0	Supp		2	73,80	
8S0 806 305 VIN: WAUZZZF44JA188316 Compensating piece Location: CC09-C-4 Stock: +2.00	Supp		2	67,00	
4G8 806 305 VIN: WAUZZZF44JA188316 Compensating piece For component strength: 10MM Location: AA03-B-4 Stock: +2.00	Supp		2	67,00	
8W0 837 915 VIN: WAUZZZF44JA188316 cover for door inner panel	Supp ? (54) left		1	24,70	



Audi

ETKA - Order Form

Order Form: SKR6778A-ADD-PARTS

14:58

11.04.2019

Item Description	Remark	Model	Qty	SGD	D
8W0 837 461 VIN: WAUZZZF44JA188316 Window regulator without motor Location : 1D03-D-5 Stock : +1.00	-? (60) left		1	238,50 278,00	250,00
8W0 959 801 VIN: WAUZZZF44JA188316 Window regulator motor	-? (61) left		1	278,00	
8W0 805 594 VIN: WAUZZZF44JA188316 Lock carrier with mounting for coolant radiator Location : 1G01-B Stock : +3.00	-? (79)		1	878,00 928,00	
8W0 820 581 C VIN: WAUZZZF44JA188316 Cover D - 08.05.2017>> for fender	-supp left		1	27,80	
8W0 821 169 C VIN: WAUZZZF44JA188316 Cover D - 04.07.2016>> for fender	-supp left		1	51,20	
8W0 803 763 VIN: WAUZZZF44JA188316 Web plate for side member	-? (92) left		1	134,00	
8W0 802 845 VIN: WAUZZZF44JA188316 socket - jack	-supp left a. right		1	4,50	
8W0 809 755 VIN: WAUZZZF44JA188316 Reinforce. for lower side mem.	-? (93) left	PR-5C0	1	328,50	
8W0 951 223 VIN: WAUZZZF44JA188316 Fanfare Location : JJ10-D-6 Stock : +1.00	-? (96) high tone left	PR-8Y1	1	34,80 37,00	
8W6 951 229 VIN: WAUZZZF44JA188316 spring shackle D - 07.12.2015>>	-? (97) left		1	26,00	
8W0 863 821 D VIN: WAUZZZF44JA188316 Noise insulation	-? (98)		1	520,00	



Audi

ETKA - Order Form

Order Form:

SKR6778A-ADD-PARTS

14:58

11.04.2019

Item Description	Remark	Model	Qty	SGD	D
8K0 805 163 A VIN: WAUZZZF44JA188316 Clip D >> - 03.09.2018 Location : CC07-D-5 Stock : 0			3	6,90	
N 909 747 01 VIN: WAUZZZF44JA188316 Hexagon socket head panel bolt D >> - 03.09.2018 Location : K10-E-3 Stock : +126.00	5X16		1	0,50	
8K0 805 399 B VIN: WAUZZZF44JA188316 Hexagon socket head panel bolt Location : CC09-B-6 Stock : +15.00	7X22		4	5,60	
8N8 868 307 VIN: WAUZZZF44JA188316 Spreader rivet Stock : 0			2	3,40	
WHT 005 296 VIN: WAUZZZF44JA188316 Speed nut D - 10.04.2017>> Location : K08-F-2 Stock : +6.00	5MM		1	1,30	
8W0 863 822 B VIN: WAUZZZF44JA188316 Noise insulation D - 07.11.2016>>	rear	PR-B0A,B0L, B0M,B0N,B0R, B1C,B1D,B1F, B1Q,B1Z,B2E, B3D,B3E,B4G, B4K	1	358,00 331,50	
Stock : 0					
8K0 261 595 VIN: WAUZZZF44JA188316 Grommet Stock : 0	42,6MM	PR-9M0	1	2,50	
8W0 825 201 VIN: WAUZZZF44JA188316 Underbody trim Stock : 0	left front		1	34,00 37,00	
8W0 825 207 C VIN: WAUZZZF44JA188316 Underbody trim D - 15.01.2018>>	left		1	288,50	
N 912 724 01 VIN: WAUZZZF44JA188316 expanding nut D - 22.05.2017>>	5X16		7	11,90	



ETKA - Order Form

Order Form: SKR6778A-ADD-PARTS 14:58 11.04.2019

Item Description	Remark	Model	Qty	SGD	D
8W0 807 550 A VIN: WAUZZZF44JA188316 Foam filler piece D - 19.10.2015>> Location : IG05-C-1 Stock : +4.00	- supp ? (102)	PR-VL0+2K1, 2K3,2K5,2K6, 2K7+5C0+6W6	1	101,00 113,00	
8W0 807 113 VIN: WAUZZZF44JA188316 Bumper carrier Location : IG07-J-1 Stock : +5.00	- ? (103)		1	674,00 733,00	
N 100 362 03 VIN: WAUZZZF44JA188316 hexagon head bolt (combi) Location : K12-C-1 Stock : +12.00	supp M8X105		4	45,60	
N 023 003 11 VIN: WAUZZZF44JA188316 hexagon nut, self-locking Location : K08-C-5 Stock : +14.00	supp M8		4	1,60	
N 910 939 01 VIN: WAUZZZF44JA188316 Pop rivet Location : K06-B-4 Stock : +27.00	supp 6X16		4	2,40	
8W0 807 771 VIN: WAUZZZF44JA188316 Bracket lock carrier Location : J08-A Stock : +4.00	- ? (105)		1	111,50 125,00	
BW2 399 347 G VIN: WAUZZZF44JA188316 Assembly carrier D - 24.04.2017>>	- ? (107)	rhd	1	1726,00	
N 911 561 01 VIN: WAUZZZF44JA188316 Hexagon bolt D - 19.02.2018>> Location : K10-D-1 Stock : +6.00	supp M12X1,5X100		8	64,80	
N 904 560 02 VIN: WAUZZZF44JA188316 Hexagon collar nut Stock : 0	M6		4	3,60	
N 912 331 01 VIN: WAUZZZF44JA188316 hexagon head bolt (combi)	M8X55		2	6,60	



Audi

ETKA - Order Form

Order Form:	SKR6778A-ADD-PARTS	14:58	11.04.2019
-------------	--------------------	-------	------------

Item Description	Remark	Model	Qty	SGD	D
WHT 007 825 VIN: WAUZZZF44JA188316 Locating bolt Location : K04-F-2 Stock : +20.00	M12X1, 5X80		4	42,40	
N 912 189 01 VIN: WAUZZZF44JA188316 hexagon head bolt (combi) Location : X06-G-2 Stock : +20.00	M12X1, 5X50		4	21,60	
SWO 399 295 E VIN: WAUZZZF44JA188316 Console D - 07.09.2015>>	-? (108) left		1	429,50	
SWO 407 271 E VIN: WAUZZZF44JA188316 drive shaft with constant velocity joints	-? (131) tripodic		1	2422,00	
SWO 698 151 AF VIN: WAUZZZF44JA188316 1 set: brake pads with wear indicator for disc brake D - 26.09.2016>> Location : F11-B Stock : +5.00	-? (137) 314X25MM	PR-1LB	1	255,00 243,50	
SWO 615 301 T VIN: WAUZZZF44JA188316 Brake disc (vented) Stock : +2.00	-? (138)		1	219,00 209,00	
SWO 611 707 G VIN: WAUZZZF44JA188316 Brake hose	-? (140) M10X1X637MM left	PR-1LA, 1LB	1	69,80	
SKO 611 715 VIN: WAUZZZF44JA188316 retaining spring Location : F02-C-1 Stock : +7.00			2	3,00	
SWO 614 723 P VIN: WAUZZZF44JA188316 Brake pipe from hydraulics to brake hose	-? (142)		1	49,30	
SWO 611 845 S VIN: WAUZZZF44JA188316 Retainer for brake hose	- supp left		1	24,30	
SWO 863 187 A VIN: WAUZZZF44JA188316 cover for jointed shaft D - 19.10.2015>>	- supp left		1	33,60	



Audi

ETKA - Order Form

Order Form:

SKR6778A-ADD-PARTS

14:58

11.04.2019

Item Description	Remark	Model	Qty	SGD	D
N 907 579 01 VIN: WAUZZZF44JA188316 Hexagon collar nut Location : K06-C-2 Stock : +4.00	5		2	2,40	
8W0 857 511 9B9 VIN: WAUZZZF44JA188316 Interior mirror, automatic anti-dazzle Satin black	- SUPP	PR-4L6+8G0	1	983,50	
8W0 867 103 B WFA VIN: WAUZZZF44JA188316 Door trim (leatherette)	- SUPP left	PR-N1F+8RM, 9VD	1	1667,00	
soul (black) Stock : 0					
4M0 199 371 FC VIN: WAUZZZF44JA188316 engine mounting	- SUPP left electric	PR-G1C	1	377,00	
D - 07.11.2016>>					
4M0 199 307 CB VIN: WAUZZZF44JA188316 Support	- SUPP left		1	149,00	
D - 16.01.2017>>					
4M0 199 869 AM VIN: WAUZZZF44JA188316 Engine support bearing	- SUPP left		1	62,20	
D - 03.08.2015>>					
8W0 098 609 VIN: WAUZZZF44JA188316 1 set of fixing parts for engine and gearbox	- SUPP		1	128,00	
06L 103 598 R VIN: WAUZZZF44JA188316 oil sump-lower part	- SUPP		1	310,50	
06L 103 603 AT VIN: WAUZZZF44JA188316 Engine oil sump upper part	- SUPP		1	507,00	
N 103 472 04 VIN: WAUZZZF44JA188316 Hexagon socket head bolt, self-locking Location : K12-D-4 Stock : 0	- SUPP M6X25		17	15,30	
N 028 222 2 VIN: WAUZZZF44JA188316 seal ring Location : K07-D-3 Stock : +3.00	- SUPP 20X3,15		2	20,60	




Audi

ETKA - Order Form

Order Form:	SKR6778A-ADD-PARTS	14:58	11.04.2019
-------------	--------------------	-------	------------

Item Description	Remark	Model	Qty	SGD	D
N 015 082 10 VIN: WAUZZZF44JA188316 Hexagon collar nut Location : K08-B-5 Stock : +6.00	M6		3	2,70	
D 174 003 M2 Silicone sealant Location : H07-E-1 Stock : +9.00	supp 80ML		1	54,20	
06L 103 085 B VIN: WAUZZZF44JA188316 Shaft oil seal Location : A06-C-1 Stock : 0	supp 45X60X8		1	19,80	
G 052 167 M4 VIN: WAUZZZF44JA188316 High lubricity engine oil Location : 1A06-D Stock : +107.00	supp 5.0 Ltr.		1	180,00	
8W0 805 281 A VIN: WAUZZZF44JA188316 Cross member Wheel housing	supp left	PR-5C0	1	61,60	
8W0 806 289 VIN: WAUZZZF44JA188316 wheel housing length extension	supp left		1	277,00	
8W0 803 697 VIN: WAUZZZF44JA188316 Reinforcement	supp left		1	127,00	
8W0 802 171 A VIN: WAUZZZF44JA188316 Mounting plate	supp left		1	277,00	
0CK 300 044 P 001 VIN: WAUZZZF44JA188316 7-speed dual clutch gearbox 7-speed dual clutch gearbox with software:	→ supp Check with Dennis	SVN	1	27830,00	
G 055 529 A2 VIN: WAUZZZF44JA188316 Dual clutch transmission fluid atf (automatic transm. fluid) Location : H08-C Stock : +30.00	supp 1.0 Ltr.		1	121,50	
8W5 809 201 VIN: WAUZZZF44JA188316 a-pillar, outer	✓ also use:		1	976,00	
	left 8W0 810 949	PR-5C1	1		
8W0 802 111 VIN: WAUZZZF44JA188316 Closing element	left		1	6,70	



ETKA - Order Form

Order Form:

SKR6778A-ADD-PARTS

14:58

11.04.2019

Item Description	Remark	Model	Qty	SGD	D
4M0 907 129 HA VIN: WAUZZZF44JA188316 steering col. combi switch Location : RH01-B Stock : 0	-supp	PR-AV0,AV1+ 1XA,1XC,1KW, 2PF+6IO+8T6	1	871,50	
8W2 423 055 AE VIN: WAUZZZF44JA188316 Steering gear with int. track rod joint See parts bulletin: (9-97) D - 18.09.2017>>	-supp	rhd PR-QZ7	1	5939,00	
8W0 423 811 C VIN: WAUZZZF44JA188316 tie rod end Stock : 0	-supp		1	162,50	
N 011 164 17 VIN: WAUZZZF44JA188316 Hexagon nut Location : K08-F-3 Stock : +18.00	M16X1,5		1	3,00	
8W0 423 811 C VIN: WAUZZZF44JA188316 tie rod end Stock : 0	-supp		1	162,50	
WHT 006 151 VIN: WAUZZZF44JA188316 Hexagon collar nut self-locking Location : K08-G-5 Stock : +31.00			1	6,80	
4M0 927 803 C VIN: WAUZZZF44JA188316 speed sensor D - 25.04.2016>>	-supp front		1	89,80	
8W0 972 251 VIN: WAUZZZF44JA188316 Wiring set for speed sensor and brake wear indicator	left front		1	223,50	
8W0 601 025 EF VIN: WAUZZZF44JA188316 Aluminium rim	(after-market rim) rim change outside (8 rim and tyre)	7 JX16H2 ET35 PR-CX1 5/112 828	1	551,00	
Colour code:				53312,40 3731,87 57044,27	SGD
tyre 245/40 R18 YXL -supp +7.0% VAT					
General Altimax Sport - TBC.					

Labour SKR6778A

- | | | |
|--|-----------------|------|
| 1. To remove and reinstall dashboard inner frames, wire harness and all attachments. | s/n | 1800 |
| 2. To cut and weld lhs inner wheel house, floor pan, firewall lower section and reinforcements. | 4500
(9x500) | 5500 |
| 3. To reseal firewall and floor pan section, respray inner wheel house, floor pans and inner panels. | 2100 | 2600 |
| 4. To renew gearbox assy and carry out adaptation. | s/n | 1200 |

$$\begin{array}{r} \$40.7k \\ 32.8 \\ 9.6 \\ \hline 42.4 \end{array}$$

79104

\$85

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
101	UNDERBODYTRIM-LH	\$ 289.00	✓
102	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	X
103	FRONT BUMPER CARRIER	\$ 733.00	X
104	FRONT BUMPER SUPPORT-LH/RH <i>all</i>	2 \$ 52.00	?
105	FRONT LOCK CARRIER BRACKET	\$ 125.00	?
106	FRONT SCUFF PLATE-LH	\$ 109.00	✓
107	FRONT SUSPENSION SUBFRAME	\$ 1,726.00	?
108	ENGINE BRACKET HOLDER	\$ 430.00	?
109	FRONT LOWER CONTROL ARM-LH	\$ 491.00	✓
110	FRONT SUSPENSION GUIDE-LH	\$ 861.00	✓
111	FRONT UPPER CONTROL ARM-LH	\$ 466.00	✓
112	REAR UPPER CONTROL ARM-LH	\$ 466.00	✓
113	FRONT WHEEL BEARING HOUSING-LH	\$ 884.00	✓
114	FRONT SWIVEL JOINT-LH	\$ 175.00	✓
115	FRONT WHEEL HUB-LH	\$ 451.00	✓
116	FRONT WHEEL BEARING WITH ASSEMBLY PARTS-LH	2 \$ 660.00	✓
117	FRONT SUSPENSION FORKS-LH	\$ 239.00	✓
118	FRONT STABILIZER SWAT BAR END LINK-LH	2 \$ 245.00	✓
119	FRONT STABILIZER BAR	\$ 397.00	✓
120	FRONT STABILIZER BAR BUSHING	\$ 20.00	✓
SUB FRONT SPARE PARTS		\$ 8,932.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

①

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 1 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and reinstall dashboard inner frames, wire harness and all attachments. (S/N)	\$ 1,800.00	✓
2	To cut out and weld lhs inner wheel house, floor pan, fire wall lower section and reinforcements.	\$ 5,500.00	1500 ✓
3	To reseal fire wall and floor pan section, respray inner wheel house, floor pans and inner panels.	\$ 2,600.00	1650 ✓
④	To renew gear box assy and carry out adaptation. (S/N)	\$ 1,200.00	960 ✓
TOTAL LABOUR CHARGE		\$ 11,100.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Caro Corp.
 17/4/19.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

②

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0407/2019/DY/GW
 12-Apr-19
 George
 2 of 3
 SKR 6778 A
 A4 Sedan 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT FENDER END PLATE-LH / NGL	\$ 32.00	35.04
2	DRAIN HOSE FOR HEADLIGHT WASHER SYSTEM-LH / M's	\$ 29.00	35.36
3	HEADLIGHT COMPESATING ELEMENT-LH	2 \$ 67.00	53.60
4	HEADLIGHT RETAINER PLATE SPACER-LH / NGL	2 \$ 67.00	53.60
5	HEADLIGHT SCREW ASSEMBLY SPACE-LH	2 \$ 74.00	59.20
6	FRONT FENDER TOP COVER-LH / M's	\$ 28.00	33.24
7	FRONT FENDER LEDGE COVER-LH	\$ 52.00	41.52
8	SOCKET - JACK	\$ 5.00	33.40
9	HEXAGON HEAD BOLT	4 \$ 46.00	40.32
10	HEXAGON NUT	4 \$ 2.00	1.60
11	POP RIVET	4 \$ 3.00	2.58
12	HEXAGON BOLT	8 \$ 65.00	49.92
13	RETAINER FOR BRAKE HOSE-LH	\$ 25.00	19.40
14	JOINTED SHAFT-LH	\$ 34.00	26.58
15	REAR VIEW MIRROR - Dis	\$ 984.00	786.80
16	FRONT DOOR TRIM-LH - CRA	\$ 1,667.00	1503.40
17	ENGINE MOUNTING-LH - CRA BT	\$ 377.00	301.60
18	ENGINE MOUNTING BRACKET-LH - CRA	\$ 149.00	119.00
19	ENGINE MOUNTING HOLDER SUPPORT / NGL	\$ 63.00	49.76
20	ENGINE AND GEARBOX FIXING PARTS / NGL	\$ 128.00	103.40
SUB-TOTAL SPARE PARTS		\$ 3,897.00	

For Premium Automobiles Pte Ltd



3/16.12

Authorised Signature

23/7/12

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

3

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 3 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
21	ENGINE OIL SUMP-LOWER PART <i>2/4 ABC</i>	\$ 311.00	348.10
22	ENGINE OIL SUMP-UPPER PART	\$ 507.00	405.60
23	HEXAGON SOCKET HEADBOLT <i>x NN</i>	\$ 16.00	X
24	ENGINE OIL LEVEL SENSOR SEAL RING	2 \$ 21.00	17.60
25	SILICONE SEALANT	\$ 55.00	46.48
26	SHAFT OIL SEAL	\$ 20.00	16.40
27	HIGH LUBRICITY ENGINE OIL 5.0 LTR	1 \$ 180.00	215.60
28	CROSS MEMBER FOR WHEEL HOUSING LINER	\$ 62.00	49.28
29	WHEEL HOUSING LINER LENGTH EXTENSION-LH <i>mis</i>	\$ 277.00	221.60
30	FRONT FENDER REINFORCEMENT-LH	\$ 127.00	101.60
31	FRONT FENDER LOWER PLATE-LH	\$ 277.00	221.60
32	7 SPEED DUAL CLUTCH GEARBOX <i>x NN</i>	\$ 27,830.00	X
33	DUAL CLUTCH TRANSMISSION FLUID 1.0 LTR <i>Act</i>	1 \$ 122.00	97.60
34	FRONT A-PILLAR OUTER-LH <i>x Repeat</i>	\$ 976.00	X
35	STEERING COLUMN CRUISE CONTROL <i>Act</i>	\$ 872.00	752
36	STEERING GEAR <i>Act</i>	\$ 5,939.00	4751.20
37	FRONT TIE ROD END-LH <i>Act</i>	\$ 163.00	144
38	FRONT SPEED SENSOR <i>Act</i>	\$ 90.00	71.84
39	FRONT RIM -LH (AFTER MARKET RIM)	TBC	500
40	FRONT TYRE-LH (245/40 R18) <i>Act</i>	TBC	272
GRAND TOTAL		\$ 52,842.00	

For Premium Automobiles Pte Ltd



Authorized Signature

2699480

120923 92

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

5

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 27-May-19 CHANG 1 of 1 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	FRONT REINFORCEMENT BEAM	\$ 733.00	bt ✓ 586
GRAND TOTAL		\$ 733.00	

For Premium Automobiles Pte Ltd



Authorised Signature

by Tardikh.
27/5/19.

121919 92

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0407/2019/DY/GW
Date : 30-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian, Guo Qiang

You recommended 32 days

We took 40 days exclude 7 Sundays

and 2 PH - jb - 29 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Seah Li-Yen Jocelynn
Address : 15 Bloxhome Drive
Singapore 559710
Telephone : 98750369
Type of Claim : Own Damage Claims
Policy No. : 1800098340
Vehicle No : **SKR 6778 A**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : 16/8/2018
Engine No : CVK 063933
Chassis No : WAUZZZF44JA188316
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Mar-19
Place of Accident : Upper Paya Lebar Rd Underpass

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To carry out first measurement on car-liner	\$ 800.00	\$ 800.00
3	To remove and renew front windscreen.	S/N \$ 480.00	\$ 480.00
4	To remove and transfer, air con condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,000.00	\$ 1,000.00
6	To remove and transfer lhs front and rear door's multi locks systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 720.00	\$ 720.00
	SUB-TOTAL LABOUR CHARGES	: \$ 3,480.00	\$ 3,480.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 3,480.00
6	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carperts, electronic components and fuse trays.	S/N	\$ 1,400.00	\$ 1,400.00
7	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and central protection.	S/N	\$ 3,600.00	\$ 3,600.00
8	To renew passenger seat air bag and leather cover.	S/N	\$ 800.00	\$ 800.00
9	To suspend engine, remove and reinstall front suspension for car -o-liner repairs. Inspect for damages and renew accordingly.	S/N	\$ 2,800.00	\$ 2,800.00
10	To remove and reinstall rear exhaust silencer assy, rear suspension assy and fuel tank, for car-o-liner repairs. Inspect for damages.	S/N	\$ 2,800.00	\$ 2,800.00
	SUB-TOTAL LABOUR CHARGES	:	\$ 11,400.00	\$ 14,880.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 14,880.00
11	To place vehicle on car-o-liner.	S/N	\$ 1,800.00	\$ 1,800.00
12	To dismantle front bumper, lhs front fender, lhs front and rear doors. Inspect lhs wheel house and floor pan for damages. Cut out and weld lhs A-pillar, inner reinforcements, sill panel and inner web plates. Renew front lock carrier. Renew all damaged panels. Reinstall all parts removed.		\$ 12,600.00	\$ 10,500.00
13	To respray front bumper, lhs front fender, bonnet, lhs front and rear doors, door handles, lhs A-pillar, sill panel, door entrances and inner reinforcements. To carry out joint sealer works and stone chip treatment.		\$ 6,500.00	\$ 4,750.00
14	To renew lhs front and rear rims and lhs front tyre. To carry out wheel alignment.	S/N	\$ 320.00	\$ 320.00
14a	Added labour charges	S/N	\$ 11,500.00	\$ 6,310.00
15	To carry out diagnostic check.	S/N	\$ 576.00	\$ 576.00
TOTAL LABOUR CHARGES			\$ 48,176.00	\$ 39,136.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER SECURING STRIP	2 \$ 64.00	\$ 50.88
3	FRONT BUMPER GUIDE SECTION-LH	\$ 33.00	\$ 26.08
4	FRONT BUMPER GUIDE SECTION-RH	\$ 34.00	\$ 27.12
5	FRONT BUMPER GRILLE-CENTER	\$ 178.00	
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 191.00	\$ 152.40
7	FRONT AIR GUIDE-LH	\$ 56.00	\$ 44.40
8	FRONT AIR GUIDE GRILLE-LH/RH	2 \$ 246.00	\$ 98.00
9	FRONT FENDER-LH	\$ 700.00	\$ 559.60
10	FRONT FENDER ATTACHMENT PARTS-LH	\$ 183.00	\$ 146.40
11	FRONT FENDER BRACE-LH	\$ 107.00	\$ 85.60
12	FRONT FENDER END PLATE-LH	\$ 45.00	\$ 36.00
13	FRONT FENDER BRACKET-LH	\$ 32.00	\$ 25.20
14	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH	\$ 45.00	\$ 35.60
15	FRONT FENDER REAR BRACKET-LH	\$ 29.00	\$ 22.64
16	FRONT FENDER UPPER BRACKET-LH	\$ 31.00	\$ 24.16
17	FRONT FENDER CLOSING ELEMENT	\$ 30.00	\$ 23.76
18	FRONT FENDER PROTECTION FILM-LH	\$ 11.00	
19	FRONT WHEEL HOUSING LINER-LH	\$ 223.00	\$ 178.40
20	FRONT WHEEL HOSUING LINER ATTACHEMENT PART-LH	\$ 82.00	\$ 65.52
	SUB FRONT SPARE PARTS	\$ 4,319.00	\$ 3,200.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.