

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0407/2019/DY/GW
Date : 30-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian, Guo Qiang

*You recommended 32 days
We took 40 days exclude 7 Sundays
and 2 PH - jb - 29 Oct 19*

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Seah Li-Yen Jocelynn
Address : 15 Bloxhome Drive
Singapore 559710
Telephone : 98750369
Type of Claim : Own Damage Claims
Policy No. : 1800098340
Vehicle No : **SKR 6778 A**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : 16/8/2018
Engine No : CVK 063933
Chassis No : WAUZZZF44JA188316
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Mar-19
Place of Accident : Upper Paya Lebar Rd Underpass

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To carry out first measurement on car-liner	\$ 800.00	\$ 800.00
3	To remove and renew front windscreen.	S/N \$ 480.00	\$ 480.00
4	To remove and transfer, air con condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,000.00	\$ 1,000.00
6	To remove and transfer lhs front and rear door's multi locks systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 720.00	\$ 720.00
SUB-TOTAL LABOUR CHARGES		: \$ 3,480.00	\$ 3,480.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 3,480.00
6	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, floor carperts, electronic components and fuse trays.	S/N	\$ 1,400.00	\$ 1,400.00
7	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and central protection.	S/N	\$ 3,600.00	\$ 3,600.00
8	To renew passenger seat air bag and leather cover.	S/N	\$ 800.00	\$ 800.00
9	To suspend engine, remove and reinstall front suspension for car -o-liner repairs. Inspect for damages and renew accordingly.	S/N	\$ 2,800.00	\$ 2,800.00
10	To remove and reinstall rear exhaust silencer assy, rear suspension assy and fuel tank, for car-o-liner repairs. Inspect for damages.	S/N	\$ 2,800.00	\$ 2,800.00
SUB-TOTAL LABOUR CHARGES			\$ 11,400.00	\$ 14,880.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6778 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 14,880.00
11	To place vehicle on car-o-liner.	S/N	\$ 1,800.00	\$ 1,800.00
12	To dismantle front bumper, lhs front fender, lhs front and rear doors. Inspect lhs wheel house and floor pan for damages. Cut out and weld lhs A-pillar, inner reinforcements, sill panel and inner web plates. Renew front lock carrier. Renew all damaged panels. Reinstall all parts removed.		\$ 12,600.00	\$ 10,500.00
13	To respray front bumper, lhs front fender, bonnet, lhs front and rear doors, door handles, lhs A-pillar, sill panel, door entrances and inner reinforcements. To carry out joint sealer works and stone chip treatment.		\$ 6,500.00	\$ 4,750.00
14	To renew lhs front and rear rims and lhs front tyre. To carry out wheel alignment.	S/N	\$ 320.00	\$ 320.00
14a	<i>Added labour charges</i>	S/N	\$ 11,500.00	\$ 6,310.00
15	To carry out diagnostic check.	S/N	\$ 576.00	\$ 576.00
TOTAL LABOUR CHARGES			\$ 48,176.00	\$ 39,136.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER SECURING STRIP	2 \$ 64.00	\$ 50.88
3	FRONT BUMPER GUIDE SECTION-LH	\$ 33.00	\$ 26.08
4	FRONT BUMPER GUIDE SECTION-RH	\$ 34.00	\$ 27.12
5	FRONT BUMPER GRILLE-CENTER	\$ 178.00	
6	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 191.00	\$ 152.40
7	FRONT AIR GUIDE-LH	\$ 56.00	\$ 44.40
8	FRONT AIR GUIDE GRILLE-LH/RH	2 \$ 246.00	\$ 98.00
9	FRONT FENDER-LH	\$ 700.00	\$ 559.60
10	FRONT FENDER ATTACHMENT PARTS-LH	\$ 183.00	\$ 146.40
11	FRONT FENDER BRACE-LH	\$ 107.00	\$ 85.60
12	FRONT FENDER END PLATE-LH	\$ 45.00	\$ 36.00
13	FRONT FENDER BRACKET-LH	\$ 32.00	\$ 25.20
14	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH	\$ 45.00	\$ 35.60
15	FRONT FENDER REAR BRACKET-LH	\$ 29.00	\$ 22.64
16	FRONT FENDER UPPER BRACKET-LH	\$ 31.00	\$ 24.16
17	FRONT FENDER CLOSING ELEMENT	\$ 30.00	\$ 23.76
18	FRONT FENDER PROTECTION FILM-LH	\$ 11.00	
19	FRONT WHEEL HOUSING LINER-LH	\$ 223.00	\$ 178.40
20	FRONT WHEEL HOSUING LINER ATTACHEMENT PART-LH	\$ 82.00	\$ 65.52
SUB FRONT SPARE PARTS		\$ 4,319.00	\$ 3,200.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKR 6778 A**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 3,200.96
21	FRONT FENDER LINER LOWER COVER -LH		\$ 13.00	\$ 10.16
22	FRONT WHEEL ARC TRIM-LH		\$ 66.00	\$ 52.32
23	FRONT FENDER MOLDING-LH		\$ 32.00	
24	FRONT STONE CHIP GUARD-LH		\$ 46.00	\$ 36.64
25	LED HEADLIGHT-LH		\$ 7,087.00	\$ 5,669.60
26	LED HEADLIGHT POWER MODULE-LH		\$ 716.00	
27	LED HEADLIGHT CONTROL UNIT-LH		\$ 685.00	\$ 548.00
28	LED HEADLIGHT DRAIN HOSE-LH		\$ 32.00	
29	LED HEADLIGHT COMPENSATING PIECE	2	\$ 77.00	
30	LED HEADLIGHT ASSEMBLY SPACER	2	\$ 72.00	
31	LED HEADLIGHT LIFT CYLINDER-LH		\$ 192.00	\$ 153.20
32	LED HEADLIGHT LIFT CYLINDER BRACKET-LH		\$ 6.00	\$ 4.24
33	FRONT DOOR-LH		\$ 2,152.00	\$ 1,721.60
34	FRONT DOOR OUTER DOOR SEAL-LH		\$ 185.00	\$ 147.60
35	BONDNG AGENT		\$ 45.00	\$ 36.00
36	CLEANING SOLUTION		\$ 65.00	\$ 52.00
37	APPLICATOR		\$ 7.00	
38	FRONT DOOR ATTACHMENT PARTS-LH		\$ 488.00	\$ 390.00
39	FRONT DOOR HINGE HALF UPPER PART-LH UPPER		\$ 41.00	\$ 32.08
40	FRONT DOOR HINGE HALVES-LH UPPER		\$ 42.00	\$ 33.04
SUB FRONT SPARE PARTS			\$ 12,049.00	\$ 12,087.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKR 6778 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 12,087.44
	<i>c/f</i>		
41	FRONT DOOR HINGE HALF-LH LOWER	\$ 39.00	\$ 30.80
42	FRONT DOOR HINGE HALVES-LH LOWER	\$ 42.00	\$ 33.04
43	FRONT DOOR CATCH-LH	\$ 96.00	\$ 76.16
44	FRONT DOOR CATCH COVER-LH	\$ 13.00	\$ 10.40
45	FRONT DOOR SEAL INNET-LH	\$ 185.00	\$ 147.60
46	FRONT DOOR MOUNTING BAR-LH	\$ 149.00	\$ 118.80
47	FRONT DOOR HANDLE OUTSIDE GASKET-LH FRONT	\$ 4.00	\$ 3.20
48	FRONT DOOR HANDLE OUTSIDE GASKET-LH REAR	\$ 4.00	\$ 3.20
49	FRONT DOOR HANDLE EXTERIOR-LH	\$ 35.00	\$ 27.52
50	FORNT DOOR HANDLE SENSOR-LH	\$ 208.00	\$ 166.40
51	FRONT DOOR HANDLE TRIM PLATE-LH	\$ 80.00	\$ 63.52
52	FRONT DOOR HANDLE LOCK COVER-LH	\$ 6.00	\$ 4.08
53	FRONT DOOR LOCK-LH	\$ 394.00	\$ 314.80
54	FRONT DOOR INNER PANNEL COVER-LH	\$ 25.00	\$ 19.76
55	FRONT WINDOW GUDIE-LH	\$ 412.00	\$ 329.20
56	FRONT WINDOW GUDIE TRIM STRIP-LH	\$ 235.00	\$ 187.60
57	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH	\$ 280.00	\$ 224.00
58	FRONT B- PILLAR TRIM-LH	\$ 212.00	\$ 169.60
59	FRONT CONER TRIM-LH	\$ 41.00	\$ 32.80
60	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH	\$ 250.00	\$ 199.60
	SUB FRONT SPARE PARTS	\$ 2,710.00	\$ 14,249.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 14,249.52
61	FRONT WINDOW REGULATOR-LH		\$ 278.00	\$ 222.40
62	FRONT EXTERIOR MIRROR MOUNTING-LH		\$ 999.00	
63	FRONT MIRROR GLASS-LH		\$ 1,553.00	
64	FRONT MIRROR CAP-LH		\$ 220.00	\$ 175.60
65	FRONT TURN SIGNAL INDICATOR-LH		\$ 96.00	\$ 76.72
66	REAR DOOR-LH		\$ 2,152.00	\$ 1,721.60
67	REAR OUTER DOOR SEAL-LH		\$ 185.00	\$ 147.60
68	BONDING AGENT		\$ 45.00	\$ 35.92
69	CLEANING SOLUTION		\$ 65.00	\$ 51.68
70	APPLICATOR		\$ 7.00	
71	REAR DOOR SEALING STRIP-LH		\$ 15.00	\$ 11.68
72	REAR DOOR ATTACHMENT PARTS-LH		\$ 515.00	
73	REAR DOOR CATCH-LH		\$ 109.00	\$ 87.20
74	REAR DOOR SEAL, INNER-LH		\$ 201.00	
75	REAR WINDOW SLOT SEAL WITH TRIM STRIP-LH		\$ 335.00	\$ 267.60
76	REAR WINDOW GUIDE TRIM STRIP-LH		\$ 216.00	
77	REAR B PILLAR TRIM-LH		\$ 127.00	
78	REAR DOOR WINDOW-LH		\$ 265.00	
79	FRONT LOCK CARRIER MOUNTING		\$ 928.00	\$ 742.00
80	A/C DISCHARGE HOSE		\$ 310.00	\$ 248.00
	SUB FRONT SPARE PARTS		\$ 8,621.00	\$ 18,037.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 18,037.52
81	A/C RECEIVER DRIER		\$ 227.00	\$ 181.60
82	A/C COMPRESSOR HOSE		\$ 152.00	\$ 121.20
83	A/C HOSE AND TUBE ASSEMBLY		\$ 476.00	\$ 380.40
84	A/C O-SEAL RING	2	\$ 8.00	
85	A/C LINE O -RING	2	\$ 10.00	
86	FRONT FENDER PROTECTION FILM-LH		\$ 21.00	
87	FRONT FENDER TOP LEDGE COVER-LH		\$ 28.00	
88	FRONT FENDER LEDGE COVER-LH		\$ 56.00	
89	FRONT WIPER CROWL TRIM		\$ 89.00	
90	FRONT SECTIONAL PART-PILLAR A/B-LH		\$ 2,443.00	\$ 1,954.40
91	FRONT A-PILLAR-LH OUTER		\$ 976.00	\$ 780.80
92	WEB PLATE FOR SIDE MEMBER-LH		\$ 134.00	\$ 107.20
93	REINFORCEMENT FOR LOWER SIDE MEMBER-LH		\$ 329.00	\$ 262.80
94	FRONT SENSOR-INNER/ OUTER		\$ 231.00	\$ 184.80
95	FROTNT BUMPER WIRING SET		\$ 470.00	\$ 376.00
96	FANFARE- HIGH TONE LH		\$ 37.00	\$ 29.20
97	FANFARE MOUNT BRACKET-LH		\$ 26.00	\$ 20.80
98	FRONT UNDERTRAY		\$ 520.00	\$ 416.00
99	REAR UNDERTRAY		\$ 358.00	\$ 286.00
100	FRONT UNDERBODY TRIM-LH		\$ 37.00	\$ 29.44
	SUB FRONT SPARE PARTS		\$ 6,628.00	\$ 23,168.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKR 6778 A**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 23,168.16
101	UNDERBODYTRIM-LH		\$ 289.00	\$ 230.80
102	FRONT BUMPER FOAM FILLER PIECE		\$ 113.00	\$ 90.40
103	FRONT BUMPER CARRIER		\$ 733.00	
104	FRONT BUMPER SUPPORT-LH/RH	2	\$ 52.00	\$ 40.64
105	FRONT LOCK CARRIER BRACKET		\$ 125.00	\$ 100.00
106	FRONT SCUFF PLATE-LH		\$ 109.00	\$ 87.20
107	FRONT SUSPENSION SUBFRAME		\$ 1,726.00	\$ 1,380.80
108	ENGINE BRACKET HOLDER		\$ 430.00	\$ 343.60
109	FRONT LOWER CONTROL ARM-LH		\$ 491.00	\$ 392.40
110	FRONT SUSPENSION GUIDE-LH		\$ 861.00	\$ 688.40
111	FRONT UPPER CONTROL ARM-LH		\$ 466.00	\$ 372.80
112	REAR UPPER CONTROL ARM-LH		\$ 466.00	\$ 372.80
113	FRONT WHEEL BEARING HOUSING-LH		\$ 884.00	\$ 707.20
114	FRONT SWIVEL JOINT-LH		\$ 175.00	\$ 140.00
115	FRONT WHEEL HUB-LH		\$ 451.00	\$ 360.40
116	FRONT WHEEL BEARING WITH ASSEMBLY PARTS-LH	2	\$ 660.00	\$ 370.40
117	FRONT SUSPENSION FORKS-LH		\$ 239.00	\$ 190.80
118	FRONT STABILIZER SWAT BAR END LINK-LH	2	\$ 245.00	\$ 196.00
119	FRONT STABILIZER BAR		\$ 397.00	\$ 317.60
120	FRONT STABILIZER BAR BUSHING		\$ 20.00	\$ 15.76
SUB FRONT SPARE PARTS			\$ 8,932.00	\$ 29,566.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 29,566.16
121	FRONT STABILIZER BRAK CET		\$ 10.00	
122	FRONT SUSPENSION SHOCK ABSORBER TOP MOUNTING-LH		\$ 84.00	\$ 66.80
123	FRONT SUSPENSION SPRING SUPPORT-LH		\$ 56.00	\$ 44.56
124	FRONT SUSPENSION ABSORBER RUBBER STOP-LH		\$ 34.00	\$ 26.64
125	FRONT PROTECTIVE SLEEVE		\$ 8.00	\$ 6.40
126	FRONT PROTECTIVE CAP		\$ 4.00	\$ 3.20
127	FRONT SUSPENSION SHOCK SPACER-LH		\$ 28.00	\$ 22.32
128	FRONT SUSPENSION SPRING DISC LOWER-LH		\$ 36.00	\$ 28.80
129	FRONT GAS SHOCK ABSORBER-LH		\$ 276.00	\$ 220.40
130	FRONT COIL SPRING-LH		\$ 238.00	
131	FRONT DRIVE SHAFT-LH		\$ 2,422.00	\$ 1,937.60
132	FRONT WIRING SET FOR SPEED SENSOR -LH		\$ 224.00	\$ 178.80
133	FRONT HOSE BRAKE BRACKET-LH		\$ 25.00	
134	FRONT BRAKE HOSE BRAK CET-LH		\$ 25.00	
135	FRONT BRAKE CALIPER HOUSING-LH		\$ 246.00	\$ 340.40
136	FRONT BRAKE CALLIPER CARRIER-LH		\$ 221.00	\$ 176.80
137	FRONT BRAKE PADS WITH WEAR INDICATOR-LH		\$ 255.00	\$ 204.00
138	FRONT BRAKE DISC-LH		\$ 219.00	\$ 175.20
139	FRONT BRAKE DISC COVER PLATE-LH		\$ 106.00	\$ 84.40
140	FRONT BRAKE HOSE -LH		\$ 70.00	\$ 55.84
SUB FRONT SPARE PARTS			\$ 4,587.00	\$ 33,138.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 33,138.32
141	FRONT BRAKE HOSE CLIP-LH	2	\$ 4.00	
142	FRONT BRAKE PIPE FROM HYDRAULICS TO BRAKE HOSE-LH		\$ 50.00	\$ 39.44
143	FRONT BRAKE FLUID 1.0 LTR	2	\$ 59.00	\$ 46.56
144	STEERING WHEEL AIR BAG UNIT		\$ 3,141.00	\$ 2,512.80
145	FRONT DASHBOARD AIR BAG UNIT		\$ 4,019.00	\$ 3,215.20
146	ROUND CONNECTOR HSD WITH CABLE		\$ 241.00	\$ 192.80
147	SIDE AIRBAG UNIT-LH		\$ 1,391.00	\$ 1,112.80
148	SIDE AIRBAG WIRING HARNESS-LH		\$ 190.00	\$ 151.60
149	HEAD AIRBAG UNIT-LH/RH	2	\$ 3,416.00	\$ 2,732.80
150	AIR BAG CONTROL UNIT		\$ 1,927.00	\$ 1,541.60
151	FRONT AIR BAG CRASH SENSOR	3	\$ 1,145.00	\$ 915.60
152	FRONT DASHBOARD WITH AIR DUCT		\$ 4,838.00	\$ 3,870.40
153	FRONT CENTRAL CONSOLE TRIM PART		\$ 113.00	
154	FRONT A-PILLAR TRIM-LH UPPR /RH UPPER	2	\$ 374.00	\$ 298.40
155	FRONT GRAB HANDLE FOLDING-LH/RH	2	\$ 258.00	\$ 103.20
156	REAR GRAB HANDLE FOLDING-LH/RH	2	\$ 258.00	
157	MOULDED HEADLINING		\$ 1,751.00	\$ 1,400.80
158	THREE POINT AUTOMATIC SEAT-LH/RH	2	\$ 2,010.00	\$ 1,608.00
159	SEAT BEAT HEIGHT ADJUSTER	2	\$ 322.00	\$ 257.60
160	BACKREST COVER-RH		\$ 2,232.00	\$ 1,785.60
	SUB FRONT SPARE PARTS		\$ 27,739.00	\$ 54,923.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKR 6778 A**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 54,923.52
161	BACKREST FOR PADDING-RH		TBC	
162	FRONT WINDSCREEN	\$	1,040.00	\$ 832.00
163	FRONT WINDSCREEN GEL FOIL FOR RAIN SENOR	\$	128.00	\$ 102.40
164	CENTRAL PROTECTION	\$	485.00	\$ 388.00
165	WINDSCREEN SEALANT	S/N \$	200.00	\$ 200.00
166	ACRYLIC SEALANT	S.N \$	360.00	\$ 360.00
167	CAVITY WAX	S/N \$	280.00	\$ 280.00
168	STONE CHIP	S/N \$	360.00	\$ 360.00
169	FRONT CAR PLATE NO.	S/N \$	25.00	
170	Added parts - see attached	\$	733.00	\$ 586.00
171	Added parts - see attached	\$	260.00	\$ 214.00
172	Added parts - see attached	\$	42,082.00	\$ 11,448.92
173	Added parts - see attached	\$	2,056.80	\$ 1,645.49
174	SUNDRIES	\$	2,000.00	\$ 642.36
TOTAL SPARE PARTS			\$ 125,594.80	\$ 71,982.69
TOTAL LABOUR CHARGES			\$ 48,176.00	\$ 39,136.00
GRAND TOTAL			\$ 173,770.80	\$ 111,118.69

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

Jbi Road 1, Singapore 408699

: 6366 2323 Fax : 6841 1183

ail: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 1 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and reinstall dasboard inner frames, wire harness and all attachments.	\$ 1,800.00	\$ 1,800.00
2	To cut out and weld lhs inner wheel house, floor pan, fire wall lower section and reinforcements.	\$ 5,500.00	\$ 1,500.00
3	To reseal fire wall and floor pan section, respray inner wheel house, floor pans and inner panels.	\$ 2,600.00	\$ 1,650.00
4	To renew gear box assy and carry out adaptation. <i>(Oil sump and linkage to engine parts)</i>	\$ 1,200.00	\$ 960.00
5	To re-new front windscreen solar film S/N	\$ 400.00	\$ 400.00
TOTAL LABOUR CHARGE		\$ 11,500.00	\$ 6,310.00

For Premium Automobiles Pte Ltd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 2 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	FRONT FENDER END PLATE-LH	\$ 32.00	\$ 25.04
2	DRAIN HOSE FOR HEADLIGHT WASHER SYSTEM-LH	\$ 29.00	\$ 25.36
3	HEADLIGHT COMEPATING ELEMENT-LH	2 \$ 67.00	\$ 53.60
4	HEADLIGHT RETAINER PLATE SPACER-LH	2 \$ 67.00	\$ 53.60
5	HEADLIGHT SCREW ASSEMBLY SPACE-LH	2 \$ 74.00	\$ 59.20
6	FRONT FENDER TOP COVER-LH	\$ 28.00	\$ 22.24
7	FRONT FENDER LEDGE COVER-LH	\$ 52.00	\$ 41.52
8	SOCKET - JACK	\$ 5.00	\$ 32.40
9	HEXAGON HEAD BOLT	4 \$ 46.00	\$ 40.32
10	HEXAGON NUT	4 \$ 2.00	\$ 1.60
11	POP RIVET	4 \$ 3.00	\$ 2.88
12	HEXAGON BOLT	8 \$ 65.00	\$ 49.92
13	RETAINER FOR BRAKE HOSE-LH	\$ 25.00	\$ 19.40
14	JOINTED SHAFT-LH	\$ 34.00	\$ 26.88
15	REAR VIEW MIRROR	\$ 984.00	\$ 786.80
16	FRONT DOOR TRIM-LH	\$ 1,667.00	\$ 1,502.40
17	ENGINE MOUNTING-LH	\$ 377.00	\$ 301.60
18	ENGINE MOUNTING BRACKET-LH	\$ 149.00	\$ 119.20
19	ENGINE MOUNTING HOLDER SUPPORT	\$ 63.00	\$ 49.76
20	ENGINE AND GEARBOX FIXING PARTS	\$ 128.00	\$ 102.40
SUB-TOTAL SPARE PARTS		\$ 3,897.00	\$ 3,316.12

For Premium Automobiles Pte Ltd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

Quantity	Description	Unit Price	Amount
AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 3 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
Parts			
	<i>c/f</i>	\$ 3,897.00	\$ 3,316.12
21	ENGINE OIL SUMP-LOWER PART	\$ 311.00	\$ 248.40
22	ENGINE OIL SUMP-UPPER PART	\$ 507.00	\$ 405.60
23	HEXAGON SOCKET HEADBOLT	\$ 16.00	
24	ENGINE OIL LEVEL SENSOR SEAL RING	2 \$ 21.00	\$ 17.60
25	SILICONE SEALANT	\$ 55.00	\$ 46.48
26	SHAFT OIL SEAL	\$ 20.00	\$ 16.40
27	HIGH LUBIRICITY ENGINE OIL 5.0 LTR	1 \$ 180.00	\$ 215.60
28	CROSS MEMBER FOR WHEEL HOUSING LINER	\$ 62.00	\$ 49.28
29	WHEEL HOUSING LINER LENGTH EXTENSION-LH	\$ 277.00	\$ 221.60
30	FRONT FENDER REINFORCEMENT-LH	\$ 127.00	\$ 101.60
31	FRONT FENDER LOWER PLATE-LH	\$ 277.00	\$ 221.60
32	7 SPEED DUAL CLUTCH GEARBOX	\$ 27,830.00	
33	DUAL CLUTCH TRASMISSION FLUID 1.0 LTR	1 \$ 122.00	\$ 97.60
34	FRONT A-PILLAR OUTER-LH	\$ 976.00	
35	STEERING COLUMN CRUISE CONTROL	\$ 872.00	\$ 752.00
36	STEERING GEAR	\$ 5,939.00	\$ 4,751.20
37	FRONT TIE ROD END-LH	\$ 163.00	\$ 144.00
38	FRONT SPEED SENSOR	\$ 90.00	\$ 71.84
39	FRONT RIM -LH (AFTER MARKET RIM)	TBC	\$ 500.00
40	FRONT TYRE-LH (245/40 R18)	\$ 340.00	\$ 272.00
GRAND TOTAL		\$ 42,082.00	\$ 11,448.92

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 1 of 1 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Sealing flange / ABC	\$ 260.00	\$ 214.00
GRAND TOTAL		\$ 260.00	\$ 214.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. PA/OD/0407/2019/DY/GW Date 1-Jun-19 Service Advisor jb Pages 2 of 3 Regn No SKR 6778 A Model No A4 Sedan 2.0 TFSI	
Quantity	Description	Unit Price	Amount
Parts			
1	Steering under dash cover <i>MBC</i>	\$ 230.00	\$ 184.00
2	LHS B pillar lower cover <i>SCR</i>	\$ 140.00	\$ 112.00
3	LHS sill panel inner reinforcement <i>CBT</i>	\$ 457.00	\$ 365.60
4	LHS A pillare lower inner reinforcement	\$ 203.50	\$ 162.80
5	LHS curtain air bag connector <i>MBC</i>	\$ 173.50	\$ 138.80
6	LHS front door arm rest trim <i>Cont</i>	\$ 485.00	\$ 388.00
7	LHS front wheel spoiler <i>Mi's</i>	\$ 96.70	\$ 77.36
8	Dashboard air vent - centre <i>ML</i>	\$ 153.00	\$ 122.40
9	LHS rea door hinge - lower <i>RT</i>	\$ 41.30	\$ 33.04
10	Floorpan rubber plug x 4 <i>ML</i>	\$ 76.80	\$ 61.49
11			
		\$ 2,056.80	\$ 1,645.49

6/6 123020

123018

6/6 123019

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 12 December 2019 10:10 AM
To: Boo seng yak; Guo Qiang (LKKAuto); SUR; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SKSR6778A - OD AIG - SURVEYED 1 APR 19 - GUO QIANG

Dear Mr Boo,

Confirm repair cost limit \$110,000.00 before excess \$1600 and GST @ 40 days.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, 29 October 2019 6:02 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SKSR6778A - OD AIG - SURVEYED 1 APR 19 - GUO QIANG

Hi Adrian, Guo Qiang and all,

Revised estimate is attached. Photographs can be obtained from our Ubi office as file is very big.

Please confirm repair cost limit \$110,000.00 @40 days exclude 7 Sundays and 2 PH.'

Your early confirmation is well appreciated.

Best regards - jb