

Trans-cab Auto Services Pte Ltd

AAD1903-200

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5588C*Not Noted*
\$220k

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5588C

VF1ABL15AUC279380

RENAULT

LATITUDE

25.3.2019

TOKIO MARINE

30/9/2014

LIST

1	1	BUMPER COVER FRT	\$	1,259.42
2	1	BUMPER SPOILER FRT	\$	181.75
3	1	BUMPER ABSORBER FRT	\$	394.68
4	1	BUMPER RETAINER FRT LH	\$	151.41
5	1	BUMPER SUPPORT FRT	\$	123.88
6	1	BUMPER RETAINER FRT RH	\$	150.77
7	1	BUMPER SUPPORT FRT	\$	123.88
8	1	BUMPER UNDERTRAY FRT	\$	472.83
9	1	BUMPER GRILLE LOWER FRT	\$	266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	207.21
12	1	BUMPER BEAM FRT	\$	914.08
13	1	TOW COVER FRT	\$	28.61
14	1	RADIATOR GRILLE	\$	1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
16	1	RADIATOR GRILLE FRAME	\$	1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$	615.90
18	1	FRAME FULL SUPPORT BRACKET	\$	89.79
19	1	HEADLAMP LH	\$	1,184.43
20	1	HEADLAMP RH	\$	1,184.43
21	1	HEADLAMP PANEL FRT LH	\$	152.15
22	1	HEADLAMP PANEL FRT RH	\$	152.15

TOTAL	\$	11,148.30
10%	\$	1,114.83
	\$	10,033.47

Trans-cab Auto Services Pte Ltd**AAD1903-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5588C**Specical Nett**

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	}	X
2	1SET	BUMPER CLIP FRT	\$	5	66.00		
3	1	BUMPER BRACKET CLIP FRT LH	\$	5	12.00		
4	1	BUMPER SUPPORT CLIP FRT LH	\$	5	10.50		
5	1	BUMPER BRACKET CLIP FRT RH	\$	5	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	5	10.50		
7	1	TOW COVER FRT	\$	5	14.50		
8	1SET	RADIATOR GRILLE SCREW	\$	5	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	5	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	5	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	5	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	5	30.00		
21	1	Windscreen moulding	\$	7	100.00	}	
22	1SET	Front licence plate with holder	\$	nn	80.00		

TOTAL \$ 562.50**TOTAL PARTS \$ 10,595.97**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ nn 3,000.00 X

To apply paint protection system (PPS) maintain
and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 3,000.00 22a

To rust-proofing of the affected areas.

\$ nn 170.00 X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1903-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5588C

To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 X
To replace, refix and top up coolant for radiator	\$	170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X

TOTAL \$ 8,380.00**Over All Total \$ 18,975.97****(LUMP SUM) Repair Days****10 DAYS****1 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: