



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SGR 6644 A
TOYOTA VIOS

not added
other
1/5/19
2/4/19
the...
by

ATTN:			NO.	DESCRIPTION - PARTS	QTY	PRICE
			1	FRONT BONNET <i>1 X</i>	1	
			2	FRONT BONNET LOCK <i>1 X</i>	1	
			3	FRONT HEADLAMP L+R <i>0/5 one 1pc</i>	1	
			4	FRONT HEADLAMP BRACKET L+R <i>1 X</i>	1	
			5	FRONT GRILLE <i>1 X</i>	1	
			6	FRONT GRILLE LOGO <i>1 X</i>	1	
			7	FRONT BUMPER <i>Dis</i>	1	
			8	FRONT BUMPER RETAINER L+R <i>2pc</i>	2	
			9	FRONT BUMPER BRACKET L+R <i>?</i>	2	
			10	FRONT BUMPER FOG LAMP L+R <i>?</i>	2	
			11	FRONT BUMPER FOG LAMP GARNISH L+R <i>?</i>	2	
			12	FRONT BUMPER REINFORCEMENT BAR <i>3pc</i>	1	
			13	FRONT BUMPER SPONGE <i>1 X</i>	1	
			14	FRONT BUMPER UNDERCOVER <i>?</i>	1	
			15	FRONT FENDER L+R <i>0/5 buc 1pc</i>	2	
			16	FRONT FENDER COWLING L+R <i>0/5 to 1pc</i>	2	
			17	FRONT FENDER INNER PANEL L+R <i>?</i>	2	
			18	FRONT SUPPORT PANEL <i>3pc/2pc</i>	1	
			19	FRONT SUPPORT PANEL TOP GARNISH <i>1 X</i>	1	
			20	HORN <i>1 X</i>	1	
			21	WIPER WASHER TANK <i>?</i>	1	
			22	WIPER WASHER TANK MOTOR <i>?</i>	1	
			23	AIR CON CONDENSER <i>1 X</i>	1	
			24	HIGH PRESSURE HOSE <i>1 X</i>	1	
			25	LOW PRESSURE HOSE <i>1 X</i>	1	
			26	RADIATOR <i>1 X</i>	1	
			27	SUCTION PIPE <i>1 X</i>	1	
			28	DISCHARGE PIPE <i>1 X</i>	1	
			29	RADIATOR FAN COWLING <i>1 X</i>	1	
			30	RADIATOR FAN BLADE <i>1 X</i>	1	
			31	RADIATOR FAN MOTOR <i>1 X</i>	1	
			32	FRONT CHASSIS RH <i>1 X</i>	1	REPAIR
			32	FRONT ABSORBER RH <i>?</i>	1	
			33	FRONT LOWER ARM RH <i>?</i>	1	
			34	FRONT KNUCKLE RH <i>?</i>	1	
			35	FRONT KNUCKLE BEARING RH <i>?</i>	1	
			36	FRONT BEARING HUB RH <i>?</i>	1	
			37	FRONT STEERING RACK AND PINION ASSY <i>?</i>	1	

