



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL Ref : CS3/SMO18014013/Dvd3e2-1

50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWERSINGAPORE 048623

Date : 11-04-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 7778B	Veh. Inspected	FBE 909D
Policy No.	D18MTPV01002385	Coverage (\$)	0.00
Claim No.	CMTD1803265/THE	Excess (\$)	0.00
Assign From	THELMA CHOO	Assign Date	02/04/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CB1000	c.c	998
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	ZDCSC60C0CF066907	Colour	MULTI COLOUR
Odometer	38904	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	PIRELLI	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55 R17	PIRELLI	3 mm
L/H Rear Tyre			mm

4. Description of Damages

NO VISIBLE DAMAGE TO TP BIKE. REPORTED THAT OI REVERSED. SO SHOULD CONTACT AT TP TYRE ONLY. NEVER SAY WHICH SIDE FALL. NEED TO CHECK ON CONSISTENCY OF DAMAGE.

5. General Information

Accident Date	29/07/2018	Inspection Date	01/08/2018
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------