

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Apr-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1435 G

1 pc	Front n/s fender	\$	587.81
1 pc	Front n/s fender inner shield	\$	181.94
1 pc	Front n/s fender lamp	\$	32.10
1 pc	Front bumper	\$	811.11
1 pc	Front bumper n/s side bracke	\$	32.88
			\$ 1,645.84
Less 20%			\$ 329.17
			\$ 1,316.67

S/NETT

1 set	Front bumper clips	\$	48.00
1 set	Front n/s fender inner shield clips	\$	28.00
1 pc	Front n/s s fender sticker	\$	30.00
Sundry		\$	50.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00
To do wheel alignment		\$	80.00
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same		\$	600.00
To putty and spray painting on the front bumper, front n/s fender		\$	400.00
To apply rustproofing on repaired panels		\$	120.00
Total		\$	2,852.67

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- No item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ka/ra 10/4

2/4/19 12:42
3 hrs
P/P
Before Paint p/Lt