



Section A - Accident Details

Registration Number	SHD6356T
Case Reference Number	TAX/03/19/2146
Registration Date	23/10/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHIN CHOON LIANG
Type of Accident	Head to Rear
Accident Date and Time	30/3/2019 2:50 AM
Accident Reported Date and Time	30/3/2019 8:37 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	30/3/2019 4:34 AM
Replacement Vehicle Issued?	No
Job Card Number	24100834
Special Instruction to ARC, if any	TOWED \$90/ AIG - LKK
Prepared Date and Time	1/4/2019 9:53 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left/Right Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,170.00	\$1,230.00
Total Spray Cost	\$4,812.00	\$1,250.00
Total Spare Part Cost	\$22,273.58	\$5,247.43
Total Other Cost	\$3,326.00	\$720.00
TOTAL COST	\$32,581.58	\$8,447.43
Lump Sum Total	\$32,600.00	\$8,450.00 (L/S)
Number of Repair Days	12.0	11.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	01/04/2019 2:55 PM	01/04/2019 2:28 PM
Signature		
Remarks	Supplementary = 3 days	L/S REPAIR, PHOTO AFTER PAINT.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63655592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated: 18/09/2018

User ID: PohSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1909-0296	Invoice Number	
Quotation Date	18.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR TAIL LAMP PANEL	\$180.00	\$80.00
TO REPAIR REAR LH WHEEL HOUSE	\$300.00	\$150.00
TO REPAIR REAR PORTION	\$1,690.00	\$1,000.00
Total Labour	\$2,170.00	\$1,230.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR MEMBER, LH	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$100.00
TO RESPRAY TAIL LAMP PANEL LH	\$180.00	\$80.00
TO RESPRAY REAR LH FLOOR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR MEMBER, RH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER, LH	\$180.00	\$0.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY RIM	\$240.00	\$50.00
TO RESPRAY FUEL LID COVER	\$180.00	\$20.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$4,812.00	\$1,250.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$126.00	\$90.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757706
 FAX Number 63985552
 Estimator Telephone Number 68662623
 Accident Reporting Number 58662672

Date Generated : 16/09/2019

User ID : PohSuan

TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$50.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$250.00	\$250.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$50.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$30.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$60.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$40.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$3,326.00	\$720.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR SENSOR REVERSE	0.00	\$157.40	0.00	\$0.00	Replace	Check X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace X
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check X
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check X
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check X
		52592-47021	BUMPER SEAL, RR LH	1.00	\$88.90	25.00	\$66.68	Replace	Replace X
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check X
		58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	0.00	\$0.00	Replace	Check X
		17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Check X
		17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Check X
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace X
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace X
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace X
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace X
		56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1.00	\$27.30	25.00	\$20.48	Replace	Replace X
		64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	\$721.30	25.00	\$540.98	Replace	Replace X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63955592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/09/2019
User ID : PohSuan

		SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	✓
	52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	✓
	52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	✗
	52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	✗
	52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	✗
	68105-47122	TAILGATE DOOR GLASS	0.00	\$1,090.90	0.00	\$0.00	Replace	Not Given	✗
	68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	✗
	69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	✗
	68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Check	✗
	68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Check	✗
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check	✗
	69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	✗
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	✗
	69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Check	✗
	67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	✗
	67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check	✗
	82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Not Given	✗
	86790-47040	CAMERA ASSY, TELEVISION, RR	0.00	\$1,436.60	0.00	\$0.00	Replace	Not Given	✗
	84840-28040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$146.10	0.00	\$0.00	Replace	Check	✗
	75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	✓
	81271-53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Not Given	✗
		NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	✗
		NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	✗
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
	75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	✓
	75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
	76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	✗
	81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Check	✗
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	✗
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	✗
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	✗
	58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	✗
4006314		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	✗
	58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check	✗
	57604-47030	MEMBER SUB-ASSY, RR LH	0.00	\$174.10	0.00	\$0.00	Replace	Check	✗
	57603-47030	MEMBER SUB-ASSY, RR RH	0.00	\$174.10	0.00	\$0.00	Replace	Check	✗
	58303-47301	FLOOR PANEL RR/LH	0.00	\$102.00	0.00	\$0.00	Replace	Check	✗
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	✗

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757708
FAX Number: 63655592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated: 18/09/2019
User ID: PohSuan

	58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X
	58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Not Given	X
	58418-47070B0	BOX, DECK FLOOR, COVER LH	0.00	\$230.10	0.00	\$0.00	Replace	Not Given	X
	64997-47020	BOX, DECK FLOOR, LH	0.00	\$196.80	0.00	\$0.00	Replace	Not Given	X
	64910-47020-B0	COVER ASSY, TONNEAU	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X
	64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
	64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Check	X
	51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Check	X
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL, DISC	0.00	\$1,490.20	0.00	\$0.00	Replace	Not Given	X
		BREAKDOWN SIGN	0.00	\$35.00	0.00	\$0.00	Replace	Check	X
	64740-47031B2	PANEL ASSY, DECK LH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
	82161-47B22	WIRE, FLOOR	0.00	\$1,675.00	0.00	\$0.00	Replace	Not Given	X
	82162-47B20	WIRE, FLOOR, NO.2	0.00	\$1,305.40	0.00	\$0.00	Replace	Not Given	X
	61808-47061	PANEL SUB-ASSY, QTR WHEEL HOUSE	0.00	\$588.40	0.00	\$0.00	Replace	Check	X
	61606-47010	PANEL, QUARTER WHEEL HOUSE, OUTER LH	0.00	\$326.70	0.00	\$0.00	Replace	Check	X
	52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81561-47170	TAIL LAMP LH	1.00	\$548.40	10.00	\$493.56	Replace	Replace	X
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	61602-47091	FENDER RR/LH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	X
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
	65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X
	77350-47030	LID ASSY, FUEL	1.00	\$102.00	100.00	\$0.00	Replace	Repair	R
	77035-47090	CABLE SUB-ASSY, FUEL LID	0.00	\$63.90	0.00	\$0.00	Replace	Check	X
	77377-75010	RETAINER, FUEL LID CABLE	0.00	\$5.90	0.00	\$0.00	Replace	Check	X
	77300-52030	CAP ASSY, FUEL TANK	0.00	\$68.10	0.00	\$0.00	Replace	Not Given	X
	77201-47250	PIPE SUB-ASSY, FUEL NECK	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
	77226-47040	TUBE, FUEL TANK	0.00	\$36.10	0.00	\$0.00	Replace	Check	X
	77001-47120	TANK SUB-ASSY, FUEL	0.00	\$745.10	0.00	\$0.00	Replace	Check	X
	62720-47031	QUARTER GLASS RR/LH	1.00	\$168.10	25.00	\$126.08	Replace	Replace	X
		SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	X
6503707		TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace	X
	42611-47140	WHEEL, DISC	1.00	\$1,490.20	100.00	\$0.00	Replace	Repair	R
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R

	69060-47080	DOOR LOCK RR/LH	0.00	\$709.30	0.00	\$0.00	Replace	Check	X
	69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check	X
	68760-20122	DOOR HINGE UPPER RR/LH	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X
	68780-52031	DOOR HINGE LOWER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
	68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Check	X
Total				\$31,491.09		\$3,874.32			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		58311-47071	SPARE TYRE PANEL	1.00	\$667.70	25.00	\$500.78	Replace	Replace
		58303-47301	FLOOR PANEL RR/LH	1.00	\$102.00	25.00	\$76.50	Replace	Replace
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace
		57604-47030	MEMBER SUB-ASSY, RR LH	1.00	\$174.10	25.00	\$130.58	Replace	Replace
		58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace
		52018-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace
Total					3,579.90		2,684.97		

6559.29

- 20%

5247.43

+ 1230.00

+ 1970.00

8447.43

45 \$8450/-