



Case Details

Case Reference Number : TAX/03/19/2078
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6074G

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6288-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 17/03/2019 03:30 AM
 Vehicle Age(In Months) : 41

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair ▾	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair ▾	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check ▾	
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give ▾	
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give ▾	
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace ▾	
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair ▾	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check ▾	
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check ▾	
Total Spare Part Cost									2,789.66		Surveyor Total		511.62	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20	
Final Spare Part Cost									890.52		Final Sur Total		409.30	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	676.00	400	
Total:			676.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
Total:			936.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	890.52	409.30
Total Labour Cost	676.00	400.00
Total Spray Painting	936.00	450.00
Other	600.00	50.00
Overall Total	3,102.52	1,309.30
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,100.00	1,300.00

Estimator Assessment(\$)		Surveyor Assessment(\$)
Surveyor Approved Amount		1,300.00
No of Repair Days*	5	4
Remarks	-	L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	01/04/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: