



Poh Kin

Section A - Accident Details

Registration Number	SHD6074G
Case Reference Number	TAX/03/19/2078
Registration Date	23/10/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMED MASYADI BIN MASHUDI
Type of Accident	Side Swipe
Accident Date and Time	17/3/2019 11:30 AM
Accident Reported Date and Time	18/3/2019 10:58 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100832
Special Instruction to ARC, if any	TOS
Prepared Date and Time	30/3/2019 9:49 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



fr

lr

fr

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$936.00	\$450.00
Total Spare Part Cost	\$2,231.73	\$409.30
Total Other Cost	\$600.00	\$50.00
TOTAL COST	\$4,443.73	\$1,309.30
Lump Sum Total	\$4,450.00	\$1,300.00 (L/S)
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	01/04/2019 1:51 PM	01/04/2019 1:29 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER PAINT.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0121	Invoice Number	
Quotation Date	09.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$936.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$600.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check
		81519-47060	BRACKET, FR TURN UPPER RH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given
		81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace
		53801-47050	FENDER FRT/RH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check
		53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Check
Total					\$3,602.71		\$511.63		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

511.63
- 20%
409.30
+ 400.00
+ 500.00
1309.30
4/5 \$1300/-