



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3561Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	699.58	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	389.20	389.20
1	FRONT GRILLE LOGO (CONSISTENT)	NECESSARY	97.10	97.10
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	89.80	-
1	FRONT BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	42.98	-
1	FRONT BUMPER RETAINER RH (CONSISTENT)	NOT NECESSARY	42.98	-
	LESS 20% DISCOUNT		-272.33	-97.26
			1,089.31	389.04
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE WITH CASING (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET FRONT GRILLE CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT BUMPER ADS STICKER (SN) (CONSISTENT)	NECESSARY	180.00	100.00
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
			295.00	170.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		500.00	200.00
	RESPRAY FRONT BUMPER .		250.00	200.00
	TO STRAIGHTEN AND PANEL BEAT ON ACCIDENT AFFECTED AREAS.	NOT NECESSARY	250.00	-
			1,000.00	400.00
	GRAND TOTAL		2,384.31	959.04
	RECOMMENDED COST OF REPAIRS			959.04

Report Ref No. CC4/ASM19005800/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.