



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005800/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY

Date : 19-05-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 1978S	Veh. Inspected	SHB 3561Y
Policy No.	P1933649	Coverage (\$)	0.00
Claim No.	S9M01IR3	Excess (\$)	0.00
Assign From		Assign Date	03/04/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40 1.7	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU074918	Colour	YELLOW
Odometer	593909	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	5 mm
L/H Front Tyre	205/60 R16	TRIANGLE	5 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	5 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/03/2019	Inspection Date	03/04/2019
Survey held at	31 CORPORATION ROAD S 649825		
Repairer	DING AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------