

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

25/03/2019

Owner: JONATHAN TOH KOK HOW

ESTIMATE TO REPAIR HONDA VEZEL - SKX4860B

1pc front LH headlamp
1pc front LH headlamp lower bracket
1pc front LH headlamp top bracket
1pc front centre grille base
1pc front centre grille outer garnish
1pc front centre grille "HONDA" logo
1pc front bumper *801-17*
1pc front bumper RH side retainer
20pcs front bumper clip @\$5.00
1pc front bumper reinforcement
1pc front bumper LH fog cover
1pc front LH fender protector

less 20%

wiring
tuffkote
spray painting
labour charges
Total

*other 11am
(Karnath)*
Not withair
61 Sy 81650/s
Runny After Paint
2 days

SL	\$ 1,759.40	X
	\$ 45.00	X
	\$ 28.85	X
CM	\$ 542.20	✓
SL	\$ 385.00	X
na	\$ 58.85	X
B	\$ 927.50	✓
DIS	\$ 28.50	✓
na	\$ 100.00	✓
B	\$ 321.50	✓
SL	\$ 85.25	X
SL	\$ 195.00	X

\$ 4,477.05

\$ 895.41

\$ 3,581.64

\$ 60.00 *15%*
na \$ 60.00 X
\$ 600.00 *3501*
\$ 500.00 *2501*
\$ 4,801.64

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

