

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA7981Y

DATE: 28. Mar. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 27. Mar. 2019

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper ✓			\$553.00
10	Rear Bumper Clips ✓		\$2.20	\$22.00
1	Rear Bumper Sponge ?			\$103.50
2	Rear Bumper Reinforcement Brackets – RH/LH ?		\$80.00	\$160.60
1	Rear Bumper Reinforcement ?			\$428.40
1	Rear Bumper Undercover ✓			\$228.00
SUB TOTAL				\$1,495.50
LESS 20%				\$299.10
DISCOUNTED TOTAL				\$1,196.40
1	Reverse Sensor X			\$135.70
1	Rear Bumper Rubber Mat ✓			\$50.00
				Nett
				Nett
				\$185.70
Labour Charge				
1	Panel Beating			200
1	Spray Painting Charge			\$300.00
1	Remove/refix Reverse Sensor			\$300.00
				200
				\$120.00
				200
				\$720.00
TOTAL LABOUR				
ESTIMATE TOTAL				\$2,102.10
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng

Kalin 10/14

29/3/19 1020

2 hrs

45

At the Repair shop

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR

Signature:

Date:

ESTIMATE TOTAL