



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR ET2265A

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 32126
Reg No/Reg Date ET2265A / 18/06/2018
Date In/Mileage 09/04/2019 / 29045
Chassis No WDD2130452A455759
Engine No 27492031479282
Make/Model MB/MB E 250 2.0 SEDAN (W213) "EXCLUSIVE/
Colour/Trim 028 890 Cavansite B/ 048 B14 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WC000658	Credit	29/04/2019/ 22:28	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M_BPN5UN

POLICY NO/ACC DATE : 1800067076 // 29/03/2019
DRIVE IN- 30/03/2019 // TP-CAR NO: SKX97700 (CHINA TAIPING INSURANCE)
DATE IN/DATE SURVEY: 08-04-2019 // LLL TAUFIKH
BY/AUTHORIZED ON : CHONG BOON SEN // 08-04-2019

- X RIVETED NUT
- X REAR DRIVE UNIT TRUNK LID
- X REAR BOOT LID LOCK

4.00	3.75	00.00	
1.00	994.33	00.00	
1.00	289.27	00.00	

net ✓ 15.00 A
dis ✓ 994.33 A
bt ✓ 289.27 A

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett	1,298.60
7% GST on	1298.60
	90.90
Total Payable	1,389.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg