

INSURANCE

INS CASE OWNER:

Plater CC4 ASA 1900 5812, 4eb38

LKK
IDAC

Surveyor:

marcus

DOI:

ASSIGNMENT 1/4/19

Date/Time:

14/1/19

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No:

SKK 7878C

Name of Insured:

Mr. KUK SON

Insured Tel No:

HP:

7878/19

Excess Sec II :SS

D.O.A:

7878/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No:

Samozuk 107778

Policy No:

165568

Make / Model:

FERRARI

Place of Accident:

UTE

If NO, Driver Name / Age:

Driver Tel No:

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SKK 7878C

JRN 5372

SJT 84452

SMK 64



INSRS:
WSP:
Tel:
Liability:
RMKS: 01



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS: TP



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

SJT 84452 - 4
SKK 7878C - 4
Kamuk 1/19

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call OI:	7878/19
After call 1st to OI:	07-08-19
Documentation Check List: Handler Typist	
Notification 1st (if non-pickup)	
After call 1st to OI	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
I.TA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

01.05.19 4:30PM

UPDID ON CONFIRMED PROCEEDING - 01 INVOLVED BY 4 VEH (LOI) WAYS
THE LAST VEH. INFORM TP CLAIM AGREE TO SETTLE AND FURURE
ABOUT WLO ISSUE.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

43 \$58,000

(12 days) Reduction:

51

%

Email

Call

FINAL SETTLEMENT

Date/Time: 04/06/19

Confirm with: WARRIOR

Email

Call

Final Liability:

60

%

65

(Agreed / Assessed) BOLA S/N No:

741

If NO or B 28, Ass. Lia:

Repair Cost: (WLO) + E.TM + 43 \$57,457.90

4 VEH CL OI WLO

Loss of Rental (LOR) + 1605 \$51,364.25

(15 days) x 1100

Loss of Use (LOU):

85

15

x

days)

Loss of Income (LOI):

55

15

x

days)

LOR only: ☒ LOU only ☐ LOR + LOU ☐ LOR + LOU ☐

(Tick only one)

GIA/ITA Search: +300 \$52.00

Medical:

55

Disbursement: +55.00 \$55.00

(e.g. Tow/Independent)

Legal Cost:

55

1) Claim status: Normal/Reject/Private Settle

2) Report format: TP

3) Survey fee: +330

Total:

+10436.00

\$53,819.15

Global Sum \$5: 3,850

FINAL PAYMENT

Date/Time: 04/06/19

Confirm with: WARRIOR

Email

Call

Payee 1:

\$53,850

Name 1: ETHEL AWO PTE LTD

Payee 2: (Strike if N.A.):

\$5

Name 2:

Payee 3: (Strike if N.A.):

\$5

Name 3:

14/6/19

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 55784482at Workshop m/s styteak

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 18

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or NoLum Sum: 50 % 3 Val.: Yes or No
1/11/19

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 55784482 Yr Regn: 2/11/09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota corolla AHjcc 1598Colour: any A/C: Insured / Std / NI / NASp. Reading: 187/10 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EE106158707

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rjm / STD A/Rim or

Tyre Size: F: _____

R: 195/65-215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/3/19 D.O.I. 3/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.
The U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction 27A 97867m. nett 81442.28.200 (RED: 11.914.63 59%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair:

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip:

2) _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Vehicle:

SJT8445Z

Make & Model:

TOYOTA ALTIS

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Remarks
1	Front Bonnet			796.90	Rx
2	Front Bumper			821.40	Dis
3	Front Bumper Retainer Left & right	2	95.10	190.20	31
4	Front Bumper Clip			30.00SN	rec
5	Front Headlamp Left & right	2	745.60	1491.20	h/b/c era
6	Front Support Panel			836.70	Rx
7	Front Fog Lamp Left & right	2	314.80	629.60	11 X
8	Front Fog Lamp Garnish Left & right	2	248.20	496.40	17 X
9	Front Panel Lock			128.60	7 mi
10	Front Grille			373.80	CRA
11	Front Grille Emblem			48.00	rec
12	Front Bumper Reinforcement Frame			347.60	31
13	Reinforcement stay Left & right	2	98.60	197.20	Rx
14	Air Con Condenser			1321.90	Bent/pur
15	Air Con Condenser Pipe			518.50	11 X
16	Radiator			1780.40	11 X
17	Radiator fan & clowing			314.70	11 X
18	Radiator Coolant			50.00SN	11 X
19	Front number plate with casing			\$50.00 SN	31 40

S-N

S-N

4467

2 3 3

Labour for front portion					
1	Panel Beating <i>front portion</i>			\$ 600.00	<i>400</i>
2	Paint Work			\$ 800.00	<i>450</i>
3	Check Wiring			\$ 100.00	<i>20</i>

Vehicle:

SJT8445Z

Make & Model:

TOYOTA ALTIS

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Remarks
1	Rear Bootlid			954.60	20/Rec ✓
2	Rear Bootlid Inner Garnish			387.50	20/For ✓
3	Rear Bootlid Inner Lock			200.20	20/ ✓
4	Rear Bootlid Toyota Emblem			85.60	20/ ✓
5	Rear Bootlid "Corolla" Plate			65.90	20/ ✓
6	Rear Bootlid "Altis" Plate			68.70	20/ ✓
7	Rear Bootlid Reflector (Left & Right)	2	357.60	715.20	20/ ✓
8	Rear Bootlid Garnish Clip			30.00SN	17 X
9	Rear Bootlid 1.5 Plate			58.90	20/ ✓
10	Rear Bootlid Hingh Left & Right	2	95.70	191.40	20/20 ✓
11	Rear Bootlid Handle			385.70	20/20 ✓
12	Rear Number Plate With Casing			50.00SN	21 40 S.N
13	Rear Number Plate Lamp	2	52.70	105.40	17 X
14	Rear End Panel		695.10	880.90	3-5 MP ✓
15	Rear End Panel Rubber (Weather Stripe)			266.90	20/ ✓
16	Rear End Panel Stricker			46.20	17 X
17	Rear End Panel Inner Garnish		215.60	331.70	20/ ✓
18	Rear End Panel Garnish Stay	2			17 X
19	Rear Spare Tyre Boot Panel			980.90	TR X
20	Rear Tailamp (Left & Right)	2	414.80	829.60	20/ ✓
21	Rear Tailamp Inner Panel Left & Right	2	269.20	538.40	20/ 20/ 20/ 20/
22	Spare Tyre Top Cardboard			334.80	TR X
23	Rear Right Fender			1080.60	20 X

24	Rear Fender Inner Shield Left & Right	2	187.90	375.80	MAX
25	Rear Fender Inner Shield Left & Right Chip			460.00SN	MAX
26	Rear Bumper			459.50	D.S. ✓
27	Rear Bumper Retainer Left & Right	2	78.50	157.00	Sub ✓
28	Rear Bumper Reflector Left & right	2	68.20	136.40	O/S can be ✓
29	Rear Bumper Inner Sponge			108.60	To. ✓
30	Reverse Sencer			200.00SN	Sub ✓ S.N
31	Glass Selant			60.00SN	17X
32	Rear bumper brackets - @ 58.50			117.00	20/Sub ✓
33					
				50%	
					P-10767.80
					50%
					P- 5383.90
					sub - 350.00
					labour - 3240.00
					8973.90

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1318E

Vehicle Details

Vehicle No.: SJT8445Z

Vehicle to be Exported: No

Intended Deregistration Date: 05 Apr 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 3ZZ4943230

Chassis No.: MR053ZEE106158707

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$17,853.00

Original Registration Date: 02 Nov 2009

First Registration Date: 02 Nov 2009

Transfer Count: 1

Actual ARF Paid: \$17,853.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 01 Nov 2019

PARF Rebate Amount: \$8,926.00

Intended COE Rebate Details

COE Expiry Date: 01 Nov 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$15,019.00

COE Rebate Amount: \$860.00

Total Rebate Amount: \$9,786.00

The information contained herein is correct as at 03 Apr 2019

OK



MANDATE IA (S9M01IIK / SJT 8445Z)

Type

🔗 Question

Message

Liability: Insured involved in 4 vehicle chain collision insured was the last vehicle. Spoken to insured and he aware that his NCD may affected and AXA to settle at best. Settlement: Repair Cost : \$8,774.00 (w/GST)
Loss of Rental: \$1,605.00 (15days x \$100)(w/GST) Towing Fee: \$55.00 LTA Search: \$2.00 Total: \$10,436.00
Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (07/05/2019)

Reply

Re:MANDATE IA (S9M01IIK / SJT 8445Z)

Type

Question

Message

Please offer 85% at \$8870.60 Thanks.

« Service Request Details

Claim *

S9M01IHK

Reference

None 

Loss Date

28 March 2019

Report Date

29 Mar 2019 3:59:13 PM

Request Date

29 March 2019

Due Date

5 April 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Cancel	Cancel
--------	--------

Vehicle Information

Incident Vehicle Registration #

SJT8445Z

Make

TPVD TOYOTA

Model

COROLLA ALTIS 1.6 AUTO

STY76H

Primary Contact/Insured

HO KOK SEN
55 DUCHESS AVENUE, 269120, Singapore
64681098

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[My Claim](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

10/04/2019 10:01 AM

TYPE



SENT

2/4/19 4:01 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

RE: Please proceed inspection first without committing on liability

BODY

Dear Peter,Contents noted.Thank you



TYPE



SENT

2/4/19 3:22 PM

FROM

WANG Peter

SUBJECT

Please proceed inspection first without committing on liability

BODY

We are still waiting for additional documents to c...



TYPE



[Link](#) [Share](#) [Print](#) [Download](#) [Close](#)

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Please redirect the claimant to the insurer of the 3rd vehicle

BODY Dear Peter, Kindly advise.Thank you



TYPE 

SENT 1/4/19 3:10 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Please redirect the claimant to the insurer of the 3rd vehicle

BODY According to TP repairer the chain collision 1st v...



TYPE 

SENT 30/3/19 1:04 PM

FROM WANG Peter

SUBJECT Please redirect the claimant to the insurer of the 3rd vehicle

BODY





STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #01-03 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98827/04/19
Date: 23/04/2019
To: M/S AXA Insurance S'pore Pte.Ltd.
8 Shenton Way #27-01
AXA Tower
Singapore 068811
Attn: Motor Claim Dept

Dear Sir/Mdm,

Re: Claim of repair cost & loss of use for veh no.SJT 8445-Z

<u>No.</u>	<u>Description</u>	<u>Price</u>
1.	Lump Sum Repair Cost for Vehicle No. SJT 8445-Z	S\$8,774.00
2.	Loss of use for Rental Bill NR: 32096(S\$120X18Days) (12 Repair Days,Two Sunday And Four Waiting Days)	S\$2,311.20
3.	GIA Search Fee	S\$ 2.00
4.	Towing Fee(No:28515)	<u>S\$ 55.00</u>
Total :		<u>S\$11,142.20</u>

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 7 May 2019 3:03 PM
To: ORALSURGEON72@GMAIL.COM
Subject: ACCIDENT INVOLVING SKK 2828C AND SJT 8445Z ALONG CTE BEFORE BRADDELL RD EXIT TO AMK ON 28/03/2019

07 MAY 2019

HO HOK SEN

Dear Sir/ Mdm

OUR REF : CC4/ASM19005812/Ueb3
YOUR REF : SKK 2828C
ACCIDENT INVOLVING SKK 2828C AND SJT 8445Z ALONG CTE BEFORE BRADDELL RD EXIT TO AMK ON 28/03/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s STYTECH AUTO PTE LTD acting on behalf of the owner of SJT 8445Z against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, where your vehicle was involved in a four (4) vehicle chain collision and your vehicle was the last vehicle that rear-ended the other party JRN 5372 which in turn rear ended Third Party Vehicle SJT 8445Z which in turn had rear-ended the first vehicle which is SMK 6Y and we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Date: 28/03/19

M/S HVV Rental Pte Ltd
39, Woodlands Close
#03-62 S'pore 737854
Mega @ Woodlands

To: M/S STYTECH AUTO PTE LTD
2 Kaki Bukit Avenue 2 #01-03
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Mdm,


Repair Cost for Vehicle number SJT8445Z
Caused by accident dated on 28/03/19 involving vehicle(s) number SJT8445Z
JRN53724 SKK2828C at CTE

Our Company/I, HVV Rental Pte Ltd
vehicle number SJT 8445 Z hereby authorized you to liaise with the
insurance company and undertake all repairs & any other damages incurred as I am involved in the
accident dated on 28/03/19.

All legal & repair costs will be deducted from the proceeds of my claim and be released to M/S
STYTECH AUTO PTE LTD.

Thank you.

Yours faithfully,



A handwritten signature is written over a circular stamp. The stamp contains the text "STYTECH AUTO PTE LTD" around the perimeter and "S'pore" in the center.



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKK 2628C	(Insd veh)	Model: TOYOTA COROLLA ALTIS 1.6 AUTO
	SJT 8445Z	(TP veh)	
Date of Accident/ Time:	28/03/2019 / 16:30		

Repair Estimate	±\$	26,955.96	
Final Repair Cost	±\$		
Loss of Use	±\$		days at \$ per day
Rental (if any)	±\$		days at \$ per day
LTA / GIA Search Fee	±\$		
Others:	±\$		
Final Settlement Sum	±\$	8,850.00	Global Sum (All In)

Payee Name : STYTECH AUTO PTE LTD

Is Third Party Workshop GIA Registered? [] YES [x] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*) _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks:

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/i confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp
Name of Representative:
Date:



Signature of Witness / Workshop stamp (if applicable)
Name of Witness:
Date:



Signature of AXA's surveyor/representative:
Name of AXA's surveyor /Representative:
Date:



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #01-03 SINGAPORE 417921 (Kaki Bukit Auto hub)
TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
GST REG. NO: 201601539K CO. REG. NO: 201601539K

Our Ref: SAPL/98827/04/19
Date: 23/04/2019
To: M/S AXA Insurance S'pore Pte.Ltd.
8 Shenton Way #27-01 AXA Tower
S'pore 068811
Attn:Motor Claim Dept

Dear Sir/Mdm,

Re: Accident on 28/03/2019 Involving Vehicle Nos.SJT 8445-Z & JRN 5372 & SKK2828-C & SMK6-Y Along Central Wxpressway.

FINAL BILL FOR VEHICLE NO. SJT 8445-Z

<u>DESCRIPTION</u>	<u>PRICE</u>
Lump Sum Repair Cost For Veh No.SJT 8445-Z	S\$8,200.00
GST 7%	<u>S\$ 574.00</u>
	TOTAL: <u>S\$8,774.00</u>

Yours Faithfully,
STYTECH AUTO PTE LTD

Mr. Winston Teo
9685 8843



STYTECH AUTO PTE LTD

2 KAKI BUKIT AVE 2 #02-30 SINGAPORE 417921 (Kaki Bukit Auto hub)
 TEL: 6444-8125 FAX: 6445-3310 H/P: 9685 8843 Email: stytechent@singnet.com.sg
 GST REG. NO: 201601539K CO. REG. NO: 201601539K

NR No: 32096

SJT8445Z

Vehicle No: <u>SJTU8528M</u>	Make and Type: <u>TOYOTA ACTIS</u>
Date/Time Out: <u>28/03/19 7:05pm</u>	Date/Time In: <u>16/04/19 6:00pm</u>

Fuel Gauge EXTENSION CHARGES IS \$12.00 PER HOUR (SINGAPORE USE)
 DEPOSIT WILL BE FORFEITED IN ANY ACCIDENT/DAMAGE/FIRE & THEFT
 *NO RETURNING OF VEHICLE AFTER 6 PM & EVE / PUBLIC HOLIDAY

Hirer's Name: <u>HNV Rental Pte Ltd</u>	KM OUT									KM IN								
Hirer's Address:	RENTALS CHARGES										AMOUNT							
Tel:	18 Days at S\$ 120.00 per day										\$2160.00							
H/P:	Week at S\$ per week																	
Driver's Name: <u>MORGAN CHUA HUH TECK</u>	Month at S\$ per mth																	
Driver's Address: <u>Blk 932 YISHAN CENTRAL 1 #03-25</u>	Insurance fee to cover hired vehicle only																	
Tel: <u>90126132</u> I/C: <u>89244383C</u>	Delivery/Collection fee																	
Age: <u>1992</u>	Petro/Diesel																	
Driving Licence Date: <u>13/03/17</u> Class: <u>3</u>	Others																	
Additional Driver's Name:	Sub-Total																	
Driver's Address:	Add GST										7% \$151.20							
Tel:	Total Nett Charges										\$2311.20							
Age:	*Less Total Prepayment/Deposit Received																	
Driving Licence Date:	Balance Amount Due/Refundable																	
Class:	Add : EXTENSION CHARGES																	
Guarantor's Name:																		
Guarantor's Address:																		
Tel:																		
Occupation:																		

IMPORTANT NOTES

- * This vehicle is restricted to SINGAPORE only.
- * No refund will be given for early return or fuel left in vehicle.
- * Hirer is liable to pay all parking fees, traffic summons & other claims.
- * Hirer who carries the number of passengers or load exceeding the MPC label will have to take their own responsibilities & LTA summons.
- * In the event of vehicle breakdown due to no fuel, hirer is liable to pay \$50 service charge plus cost of fuel/diesel.
- * No replacement of vehicle in any accident, damage or loss.
- * Hirer is responsible for the first \$2000/- excess for collision/damage/ fire or theft to first party (i.e. STYTECH AUTO PTE LTD) vehicle (including windscreen) and also first \$2000/- excess for collision/damage/fire & theft to third party's vehicle for each and every accident & damage.

METHOD OF PAYMENT

☐ Cash ☐ Cheque No: ☐ Visa ☐ Bill Co.

Refund Received \$ _____ By Hirer x _____

* In the event of the rental vehicle is not return on the date due & no contact is made to inform our company of any changes & payment after one week due. Our Company will take action & repossess the vehicle & a service charge of \$120.00 are subject to the Hirer inclusive of the overdue charges with an additional interest of 3% per month.

I/We have read the terms and conditions of the rental agreement and agree thereto:-

Hirer's Signature

Guarantor's Signature

STYTECH AUTO PTE LTD
Signed By



24 Hours Towing Services

Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 28515

CASH SALE / JOB ORDER

Date:

28/3/19

Messrs:

Cash

车牌

Vehicle No.

SJT 84452

车型

Model No.

Toyota Altis

时间 (日/夜)

Time (day/night):

Day

联络号码

Contact No.

90126132

由

Location:

CTE Braddell Road

到

To:

Autohub #01-02

金额

Cash \$

55

其他

Others:

ERA \$5

经手人

Authorised By:

Pi

Tow Truck

Driver Name:

Pi HAD

☐ Jump Start/Changing of battery

☐ Tyre Replacement

☒ Accident/Breakdown

☐ Multi/Basement

☐ With Load/Cargo Box

☐ King Dolly

☐ Transport Charge

☐ Low Body Kit

☐ Door Opening Service

☐ Crane Up/Winch Out

☐ Collect Doc/Key

☐ Repo

☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在运行中如有任何损失或破坏,

一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility

for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-049264

Date of Request: 29/03/2019

Your Ref No:

Online Purchase

Styletech Auto Pte Ltd
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 29/03/2019
Enquiry By Teo CHoon Kiat Winston
TP Vehicle No. SKK2828C
Accident Date 28/03/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKK2828C	AXA Insurance Pte Ltd	08/07/2018-07/07/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-19-049264

Date of Request: 29/03/2019

Your Ref No:

Online Purchase

Stytech Auto Pte Ltd
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub
Singapore 417921

Dear Sir/Madam,

Enquiry Date 29/03/2019
Enquiry By Teo CHoon Kiat Winston
TP Vehicle No. SKK2828C
Accident Date 28/03/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK 2828C (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SJT 8445Z (TP veh)		(A)
Date of Accident:	28/03/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	26,863.96
Final Repair Cost	:	\$	8,774.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,605.00
	@85%		8,822.15
LTA / GIA Search Fee	:	\$	2.00

Others: Towing Fee	:	\$	55.00
--------------------	---	----	-------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,850.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability <u>85</u> (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No:
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	STYTECH AUTO PTE LTD	\$ 8,850.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

25/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19005812/Ueb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date : 25-06-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 2828C	Veh. Inspected	SJT 8445Z	
Policy No.	P1651568	Coverage (\$)	0.00	
Claim No.	S9M01IHK	Excess (\$)	0.00	
Assign From		Assign Date	02/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106158707	Colour	GREY	
Odometer	187180	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/03/2019	Inspection Date	03/04/2019	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 8445Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	796.90	-
1	FRONT BUMPER (CONSISTENT)	DISTORTED	821.40	566.10
2	FRONT BUMPER RETAINER LEFT & RIGHT @\$95.10 (CONSISTENT)	BENT	190.20	190.20
2	FRONT HEADLAMP LEFT & RIGHT @\$745.60 (CONSISTENT)	HOLDER CRACKED	1,491.20	1,491.20
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	836.70	-
2	FRONT FOG LAMP LEFT & RIGHT @\$314.80 (CONSISTENT)	NOT NECESSARY	629.60	-
2	FRONT FOG LAMP GARNISH LEFT & RIGHT @\$248.20 (CONSISTENT)	NOT NECESSARY	496.40	-
1	FRONT PANEL LOCK (CONSISTENT)	TWISTED	128.60	128.60
1	FRONT GRILLE (CONSISTENT)	CRACKED	373.80	373.80
1	FRONT GRILLE EMBLEM (CONSISTENT)	NECESSARY	48.00	48.00
1	FRONT BUMPER REINFORCEMENT FRAME (CONSISTENT)	BENT	347.60	347.60
2	REINFORCEMENT STAY LEFT & RIGHT @\$98.60 (CONSISTENT)	TO REPAIR SEE LABOUR	197.20	-
1	AIR CON CONDENSER (CONSISTENT)	BENT / PUNCTURE	1,321.90	1,321.90
1	AIR CON CONDENSER PIPE (CONSISTENT)	NOT NECESSARY	518.50	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	1,780.40	-
1	RADIATOR FAN & CLOWING (CONSISTENT)	NOT NECESSARY	314.70	-
1	REAR BOOTLID (CONSISTENT)	DENTED / BUCKLED	954.60	954.60
1	REAR BOOTLID INNER GARNISH (CONSISTENT)	DEFORMED / TORN	387.50	387.50
1	REAR BOOTLID INNER LOCK (CONSISTENT)	TWISTED	200.20	200.20
1	REAR BOOTLID TOYOTA EMBLEM (CONSISTENT)	NECESSARY	85.60	85.60
1	REAR BOOTLID 'COROLLA' PLATE (CONSISTENT)	NECESSARY	65.90	65.90
1	REAR BOOTLID 'ALTIS' PLATE (CONSISTENT)	NECESSARY	68.70	68.70
2	REAR BOOTLID REFLECTOR (LEFT & RIGHT) @\$357.60 (CONSISTENT)	CRACKED	715.20	715.20
1	REAR BOOTLID 1.6 EMBLEM (CONSISTENT)	NECESSARY	58.90	58.90

Report Ref No. CC4/ASM19005812/Ueb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BOOTLID HINGH LEFT & RIGHT @\$95.70 (CONSISTENT)	BENT / TWISTED	✓ 191.40	191.40
1	REAR BOOTLID HANDLE (CONSISTENT)	BENT / CRACKED	✓ 385.70	385.70
2	REAR NUMBER PLATE LAMP @\$52.70 (CONSISTENT)	NOT NECESSARY	✓ 105.40	-
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	✓ 880.90	695.10
1	REAR END PANEL RUBBER (CONSISTENT)	TWISTED	✓ 266.90	266.90
1	REAR END PANEL STRICKER (CONSISTENT)	NOT NECESSARY	✓ 46.20	-
1	REAR END PANEL INNER GARNISH (CONSISTENT)	TWISTED	✓ 331.70	215.60
2	REAR END PANEL GARNISH STAY (CONSISTENT) (NPA)	NO SUCH PARTS	-	-
1	REAR SPARE TYRE BOOT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 980.90	-
2	REAR TAILLAMP (LEFT & RIGHT) @\$414.80 (CONSISTENT)	CRACKED	✓ 829.60	829.60
2	REAR TAILLAMP INNER PANEL LEFT & RIGHT @\$269.20 (CONSISTENT)	O/S BENT	✓ 538.40	269.20
1	SPARE TYRE TOP CARDBOARD (CONSISTENT)	NOT NECESSARY	✓ 334.80	-
1	REAR RIGHT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 1,080.60	-
2	REAR FENDER INNER SHIELD LEFT & RIGHT @\$187.90 (CONSISTENT)	NOT NECESSARY	✓ 375.80	-
1	REAR BUMPER (CONSISTENT)	DISTORTED	✓ 459.50	459.50
2	REAR BUMPER RETAINER LEFT & RIGHT @\$78.50 (CONSISTENT)	BENT	✓ 157.00	157.00
2	REAR BUMPER REFLECTOR LEFT & RIGHT @\$68.20 (CONSISTENT)	O/S CRACKED	✓ 136.40	68.20
1	REAR BUMPER INNER SPONGE (CONSISTENT)	TORN	✓ 108.60	108.60
2	REAR BUMPER BRACKET @\$58.50 (CONSISTENT)	DENTED / BENT	✓ 117.00	117.00
	LESS 50% DISCOUNT		-	-5,383.90
			20,156.50	5,383.90
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIP (CONSISTENT) (SN)	NECESSARY	✓ 30.00	30.00
1	RADIATOR COOLANT (CONSISTENT) (SN)	NOT NECESSARY	✓ 50.00	-
1	FRONT NUMBER PLATE WITH CASING (CONSISTENT) (SN)	BENT	✓ 50.00	40.00
1	REAR BOOTLID GARNISH CLIP (CONSISTENT) (SN)	NOT NECESSARY	✓ 30.00	-

Report Ref No. CC4/ASM19005812/Ueb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE WITH CASING (CONSISTENT) (SN)	BENT	50.00	40.00
2	REAR FENDER INNER SHIELD LEFT & RIGHT CHIP (CONSISTENT) (SN)	NOT NECESSARY	60.00	-
1	REVERSE SENCER (CONSISTENT) (SN)	SHORTED	200.00	200.00
1	GLASS SEALANT (CONSISTENT) (SN)	NOT NECESSARY	60.00	-
			530.00	310.00
	LABOUR			
	PANEL BEATING (FRONT PORTION).INCLUSIVE OF THE REPAIR OF FRONT BONNET,FRONT SUPPORT PANEL AND REINFORCEMENT STAY LEFT & RIGHT .		600.00	400.00
	PAINT WORK.		800.00	450.00
	CHECK WIRING.		100.00	20.00
	REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TRANSFER BOOT FITTING.		150.00	60.00
	CHECK WIRING & FITTING REVERSE CAMERA.		150.00	50.00
	ANTI RUST PROOFING.		120.00	80.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE BOOT PANEL AND REAR RIGHT FENDER.		1,000.00	1,000.00
	SPRAY PAINTING WORKS.		1,200.00	1,100.00
	INTERIOR UPHOLSTERY.		150.00	80.00
			4,420.00	3,240.00
	GRAND TOTAL		25,106.50	8,933.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,200.00

Report Ref No. CC4/ASM19005812/Ueb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

