

Vehicle:

SJT8445Z

Make & Model:

TOYOTA ALTIS

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Remarks
1	Front Bonnet			796.90	Rx
2	Front Bumper	566.10		821.40	Dis —
3	Front Bumper Retainer Left & right	2	95.10	190.20	Set —
4	Front Bumper Clip			30.00 SN	rec — S.N
5	Front Headlamp Left & right	2	745.60	1491.20	holder are ✓
6	Front Support Panel			836.70	Rx
7	Front Fog Lamp Left & right	2	314.80	629.60	11 X
8	Front Fog Lamp Garnish Left & right	2	248.20	496.40	17 X
9	Front Panel Lock			128.60	7.00 —
10	Front Grille			373.80	CRA ✓
11	Front Grille Emblem			48.00	rec —
12	Front Bumper Reinforcement Frame			347.60	Set —
13	Reinforcement stay Left & right	2	98.60	197.20	Rx
14	Air Con Condenser			1321.90	Boat/pur ✓
15	Air Con Condenser Pipe			518.50	11 X
16	Radiator			1780.40	11 X
17	Radiator fan & clowing			314.70	11 X
18	Radiator Coolant			50.00 SN	11 X
19	Front number plate with casing			\$50.00 SN	Set 40 S.N

44674

2

Labour for front portion					
1	Panel Beating <i>front portion</i>			\$ 600.00	<i>400</i>
2	Paint Work			\$ 800.00	<i>450</i>
3	Check Wiring			\$ 100.00	<i>20</i>

Vehicle: SJT8445ZMake & Model: TOYOTA ALTIS

Chassis No: _____

S/N	Parts/Labour	QTY	Unit Price	Price	Remarks
1	Rear Bootlid			954.60	no/Buc ✓
2	Rear Bootlid Inner Garnish			387.50	De/For ✓
3	Rear Bootlid Inner Lock			200.20	7m ✓
4	Rear Bootlid Toyota Emblem			85.60	rec —
5	Rear Bootlid "Corolla" Plate			65.90	rec —
6	Rear Bootlid "Altis" Plate			68.70	rec —
7	Rear Bootlid Reflector (Left & Right)	2	357.60	715.20	cm —
8	Rear Bootlid Garnish Clip			30.00SN	17 X
9	Rear Bootlid 1.6 Plate			58.90	rec —
10	Rear Bootlid Hingh Left & Right	2	95.70	191.40	but/wi ✓
11	Rear Bootlid Handle			385.70	3d/cm —
12	Rear Number Plate With Casing			50.00SN	3d 40 S. ✓
13	Rear Number Plate Lamp	2	52.70	105.40	17 X
14	Rear End Panel		695.10	880.90	3-1500 —
15	Rear End Panel Rubber (Weather Stripe)			266.90	7m ✓
16	Rear End Panel Stricker			46.20	17 X
17	Rear End Panel Inner Garnish		215.60	331.70	7m ✓
18	Rear End Panel Garnish Stay	2			NS X
19	Rear Spare Tyre Boot Panel			980.90	TR X
20	Rear Tailamp (Left & Right)	2	414.80	829.60	cm —
21	Rear Tailamp Inner Panel Left & Right	2	269.20	538.40	0/5 Sep 8pc
22	Spare Tyre Top Cardboard			334.80	PM X
23	Rear Right Fender			1080.60	12 X

A

24	Rear Fender Inner Shield Left & Right	2	187.90	375.80	MAX
25	Rear Fender Inner Shield Left & Right Chip			\$60.00SN	MAX
26	Rear Bumper			459.50	Dis —
27	Rear Bumper Retainer Left & Right	2	78.50	157.00	Seal —
28	Rear Bumper Reflector Left & right	2	68.20	136.40	O/S cm 1/2
29	Rear Bumper Inner Sponge			108.60	To. —
30	Reverse Sencer			200.00SN	Seal — S.N
31	Glass Selant			60.00SN	17X
32	Rear bumper brackets - @ 58.50			117.00	20/Seal —
33					
				50%	
					P- 10767.80
					50%
					P- 5383.90
					S.N - 350.00
					labor - 3240.00
					8973.90

5

Labour for Rear Portion					
1	Remove & Refit Rear Windscreen			\$ 150.00	not X
2	Transfer Boot fitting			\$ 150.00	60
3	Check Wiring & Fitting Reverse Camera			\$ 150.00	50
4	Anti Rust Proofing			\$ 120.00	20
5	Penal Beating			\$ 1,000.00	✓
6	Spray Painting works			\$ 1,200.00	1100
7	Interior Upholstery			\$ 150.00	20

not Refit
n/c
2/5 ~~\$8200~~ ✓
3/4/19
12dy.

SJT84457

LKK Auto Consultancy finance notify
the Repairer of the following:

- To reserve car - after spray painting
- To reserve, damaged parts during reserve
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental repair must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: