

Hsiao Tony

INSURANCE: ONG TEE | CC Y/LPC1900 5814 Dph052 | LKK: 114/UN
 INS. CASE OWNER: BRYAN | DOI: 2/4/19 | Registered in Merimen: 114/UN

Surveyor: BRYAN | Date / Time: 114/UN
 Pre-assign / CCU / FTE: SKA 2250X




Insured Vehicle No.: SKA 2250X | Claim No.: 1811/19/4P05 (021602
 Name of Insured: SHEE WEE SHYONG | Policy No.:
 Insured Tel No.: _____ | HP: _____ | Make / Model: VOLKSWAGEN
 Excess Sec II :SS _____ | D.O.A.: 20/1/UN | Place of Accident: ORIENTAL BLVD.
 Is driver the owner? (YES / NO) _____ | Nature of Accident: _____
 If NO, Driver Name / Age: SHEE WEE MIN | OI GIA REPORT: YES / NO : _____ | TP GIA REPORT: YES / NO : _____
 Driver Tel No.: _____ | (V/L: YES / NO) _____ | Insured Liability: _____ % | Final ? Yes / No : _____

SKA 5723P



INSRS: _____
 WSP: Munni
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/Time	STAGE	DATE/PIC
10/4/19	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
13/05/19	Documentation Check List: Handler Typist	
14/5/19	Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>415</u>	SS <u>10,600.00</u> (<u>10</u> days) Reduction: <u>15,313.52/41%</u>		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>09-07-19</u>	Confirm with: <u>WILLIAM</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>15</u>			If NO or B 28. Ass. Lia:
Repair Cost: <u>1169</u>	SS <u>11,342.00</u>		
Loss of Rental (LOR):	SS <u>1,444.71</u> (<u>13</u> days) x <u>111.13</u>		
Loss of Use (LOU):	SS - (<u>5</u> x <u>13</u> days)		
Loss of Income (LOI):	SS <u>650.00</u> (<u>50</u> x <u>13</u> days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/> [Tick only one]			
GIA/LTA Search	SS <u>2.00</u>		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/Independent)		
Legal Cost:	SS -		
Total:	SS <u>13,468.71</u>	Global Sum SS: 13,000	
FINAL PAYMENT	Date/Time: <u>09-07-19</u>	Confirm with: <u>WILLIAM</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>13,000.00</u>	Name 1: <u>CHUNNI MOTOR WORK PTE LTD</u>	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

CONFIRM SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: 450

02 June 2024

Vehicle No: **SHA 5723 P** Date of Insp: **2016 June**

Type: Motor Cycle / Bus / Van / Lorry / Prime Mover /

Truck / Trailer or

Make: **Hyundai . I40** No: **1685**

Color: **Blue** Chrome / Silver / Black / Grey / White

Cap/Sealing: **391107** Plastic / Rubber / Metal

Engine: **D4FDGU626557**

CID: **KMHLB41UMGU090161**

Gen. Cond: Good / Fair / Poor / Damd

Steering: Free / Jammed / Leaked / Burnt or

Brake: In / Out / Jammed / Leaked / Burnt or

Mod: ABS / STD / ABS or

Tyre Size: F: **205/60 R 14**

R: **— 14 —**

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHISI / PIRI / SUMI /

TOYO / YOKO or **Wastecke**

Front: Good / Fair / Poor / Damd

RF Bal: **S** mm / **S.** mm

LF Bal: **S** mm / **S** mm


D.O.A: **29/03/2019** D.O.I: **02/04/2019**

Survey held at: **Chunni AMK**

Des. of Damages: Front / Rear / O/S / N/S / U/R / Rooftop or

o/s Body y o/s Rev

The IRC / Chassis frame / Body Structure affected due to collision.



Engine No: _____

Chassis No: _____

Make of Vehicle: _____

Model: _____

Year of Manufacture: _____

Color: _____

Capacity: _____

Engine Type: _____

Transmission: _____

Drive Shaft: _____

Steering: _____

Brake: _____

Mod: _____

Tyre Size: _____

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHISI / PIRI / SUMI / TOYO / YOKO or _____

Front: _____

RF Bal: _____

LF Bal: _____

D.O.A: _____

D.O.I: _____

Survey held at: _____

Des. of Damages: _____

The _____ / _____ / _____ affected due to collision.

Date / Time: _____ Action / Instruction: _____

Lowpac SKA 2250 X

13/05/19 Insured 2/S 10600/- with 10 days of rev

CL/S 10,600 / Rod \$8,313.52 / 44%

Reference: Life Policy No: Prelim. Report

Life: Final Report

Date / Time: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Inspection: _____

Add Fee: Life Insp:

Interview:

Inspection:

Workshop:

Report Format: _____

Lump Sum / R.R.P. or: _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19005814/Dpb3

Date: 08.04.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA5723P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.04.2019 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	18,913.52
Revised Estimate Amount	: S\$	13,341.60
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Body & O/S Rear Portion



Comments/Present Status:


Damages Consistent

Estimated normal period for repairs: 8 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

SHA 5723P

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,800.00 900/- ✓
	Spray Painting Charge			\$ 1,250.00 900/- ✓
	Wiring Charge			\$ 50.00 40/- ✓
	Tuff Kote			\$ 100.00 40/- ✓
	Towing Charge			\$ 50.00 40/- ✓
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/- ✓
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/- ✓
	Transfer of Door	\$	120.00	\$ 240.00 120/- ✓
	Remove/Refix Undercarriage (RR)			\$ 200.00 → 150/- ✓
	Rear Wheel Alignment			\$ 120.00 60/- ✓
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 } 150/- ✓
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
			2480.00 ✓	
	TOTAL LABOUR			\$ 5,160.00
	ESTIMATE TOTAL			\$ 18,913.52
	02/04/2019 @ 1008hrs		13341.60 ✓	
	LKA Auto			
	2/3 hrs @ 10 days		4/3 10600/- ✓	
				
	LKK Auto			
				
	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHA 5723 P
Technician:
Mileage: 391107
Time Printed 2.4.19 10:18 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-1°04'		-3°00' 3°00'
3°37'		-0°19' 5°41'
-0°09'		-1°30' 1°30'
14°51'		
13°47'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°22'		-3°00' 3°00'
4°13'		-0°19' 5°41'
-0°42'		-1°30' 1°30'
14°20'		
13°58'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°42'		-3°00' 3°00'
-0°36'		-3°00' 3°00'
0°32'		-3°00' 3°00'
-0°51'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°56'		-3°30' 2°30'
0°05'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°51'		-3°30' 2°30'
2°53'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°05'		-3°00' 3°00'
2°58'		-3°00' 3°00'
-1°24'		-3°00' 3°00'

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 1 April 2019 4:30 PM
To: Chunni Motor; MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021582 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]
Attachments: 01042019153944.pdf

P: Irene
Time: 4.37pm

Lonpac External - General

Without Prejudice


Dear Sir/Mdm

Please liaise with LKK Auto Consultants Pte Ltd for survey and assessment of liability.

Dear Nivitha

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Monday, 1 April, 2019 3:41 PM
To: MT_Claim_SG
Subject: Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19.

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Hsiao Tong (LKKAuto)


From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 9 April 2019 3:31 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; MT_Claim_SG; Hsiao Tong (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021602 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]
Attachments: Re: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P [External General]; ZheMin Shee shared "29032019 - 2250.mp4" with you; RE: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P [External General])

Lonpac External - General

Hi Shu Pei/Hsiao Tong

Please see attached for our Insured's emails for video and photographs.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Monday, 8 April, 2019 6:10 PM
To: ONG LI LI
Cc: Admin A; MT_Claim_SG; Hsiao Tong (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021602 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHA 5723P at M/s Chunni Motor Work Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>

Sent: Wednesday, 3 April 2019 12:25 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; MT_Claim_SG <mt_claim@lonpac.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Our Ref: 18/19/19/VP05/021602 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]

Lonpac External - General

Dear Shu Pei

Please take note of our correct claim no. above.

Attached is our Insured's GIA report that you have requested.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, 2 April, 2019 4:22 PM

To: ONG LI LI

Cc: Admin A; MT_Claim_SG; Hsiao Tong (LKKAuto)

Subject: RE: Our Ref: 18/19/19/VP05/021582 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 2 April 2019 8:00 AM

To: 'ONG LI LI' <llong@lonpac.com>; 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 18/19/19/VP05/021582 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Monday, 1 April 2019 4:30 PM

To: Chunni Motor <chunnimotor@gmail.com>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: Our Ref: 18/19/19/VP05/021582 Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19. [External General]

Lonpac External - General

Without Prejudice

Dear Sir/Mdm

Please liaise with LKK Auto Consultants Pte Ltd for survey and assessment of liability.

Dear Nivitha

fya


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]

Sent: Monday, 1 April, 2019 3:41 PM

To: MT_Claim_SG

Subject: Accident involving SHA 5723 P & SKA 2250 X along Orchard Boulevard on 29/03/19.

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Hsiao Tong (LKKAuto)

From: ZheMin Shee <sheezhemin@gmail.com>
Sent: Monday, 8 April 2019 6:37 PM
To: ONG LI LI
Subject: Re: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P [External General])
Attachments: image001.jpg; IMG_20190329_231550.jpg

Dear Ms Ong Li Li
Good day

Please be informed that videos are raw format downloaded from IRoad app through my phone, understand the IRoad viewer is required.

Attached is also the photo taken on the scene for damaged Taxi, which is only a dent in driver side door.

On Mon, 8 Apr 2019, 17:55 ONG LI LI, <llong@lonpac.com> wrote:

Lonpac External - General

Dear ZheMin

We acknowledge receipt of your email.

However, we are still trying to open and view the video files.

I shall update you again.

Thank you.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ZheMin Shee [mailto:sheezhemin@gmail.com]

Sent: Saturday, 6 April, 2019 3:55 PM

To: MT_Claim_SG

Subject: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P)

Dear Ms Ong Li Li

Below are all links for videos.

<https://www.dropbox.com/s/ndg1st2z7wg7icq/29032019%20-%202250.mp4?dl=0>

<https://www.dropbox.com/s/ai1sft6pblp9ix0/00000055.jdr?dl=0>

<https://www.dropbox.com/s/637knago2o01aqq/00000050.jdr?dl=0>

<https://www.dropbox.com/s/gmvs0jsd0aoxsv9/00000052.jdr?dl=0>

<https://www.dropbox.com/s/evytqmhdn2ugvcq/00000053.jdr?dl=0>

<https://www.dropbox.com/s/w1te4hjpdmwxtjt/00000051.jdr?dl=0>

<https://www.dropbox.com/s/som8w069idx90dk/00000054.jdr?dl=0>

Hsiao Tong (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 9 April 2019 10:13 AM
To: ZheMin Shee
Cc: MT_Claim_SG
Subject: RE: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P [External General])
Attachments: ZheMin Shee shared "29032019 - 2250.mp4" with you

Lonpac External - General

Dear ZheMin

We managed to download the MP4 video footage that you shared in dropbox in the attached email.


However, we are not able to view the video files' link in your email below as we do not have the IRoad viewer.

We have appointed surveyor to survey the Third party vehicle and we will forward the photographs of the taxi taken by you to them for review.

Thereafter, since liability is down, our appointed surveyor firm will proceed to negotiate and settle the third party claim at best possible terms.

Thank you.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ZheMin Shee [mailto:sheezhemin@gmail.com]
Sent: Monday, 8 April, 2019 6:37 PM
To: ONG LI LI
Subject: Re: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P [External General])

Dear Ms Ong Li Li
Good day

Please be informed that videos are raw format downloaded from IRoad app through my phone, understand the IRoad viewer is required.

Attached is also the photo taken on the scene for damaged Taxi, which is only a dent in driver side door.

On Mon, 8 Apr 2019, 17:55 ONG LI LI, <llong@lonpac.com> wrote:

Lonpac External - General

Dear ZheMin

We acknowledge receipt of your email.

However, we are still trying to open and view the video files.

I shall update you again.

Thank you.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ZheMin Shee [<mailto:sheezhemin@gmail.com>]

Sent: Saturday, 6 April, 2019 3:55 PM

To: MT_Claim_SG

Subject: Video Footage for Claim No. 18/19/19/VP05/021602 (Accident between SKA2250X & SHA5723P)

Dear Ms Ong Li Li

Below are all links for videos.

<https://www.dropbox.com/s/ndg1st2z7wg7icq/29032019%20-%202250.mp4?dl=0>

<https://www.dropbox.com/s/ai1sft6pblp9ix0/00000055.jdr?dl=0>

<https://www.dropbox.com/s/637knaqo2o01aqq/00000050.jdr?dl=0>

<https://www.dropbox.com/s/gmvs0jsd0aoxsv9/00000052.jdr?dl=0>

<https://www.dropbox.com/s/evytqmhdn2ugvcq/00000053.jdr?dl=0>

<https://www.dropbox.com/s/w1te4hjpdmwxtjt/00000051.jdr?dl=0>

<https://www.dropbox.com/s/som8w069idx90dk/00000054.jdr?dl=0>

CHUNNI MOTOR WORK
PTE LTD

Our Ref : SHA 5723 P (290319)

Your Ref : 18/19/19/VP05/021602

Date :

16 JUL 2019

LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25
Ubi Avenue 1
Singapore 408933

WITHOUT PREJUDICE

Attention : Asher Sng
Case Handler

Dear Sir/Madam

**ACCIDENT INVOLVING SHA 5723 P & SKA 2250 X ALONG ORCHARD BLVD TOWARDS
GRANGE ROAD ON 29-03-2019**

Your email of 09-07-2019 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the loss of rental & income during the period of repair) at a global sum of \$13,000.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHA 5723 P, Murali S/O Subramaniam's rights to claim damage for his injury against your insured, if any.

As requested, we return the attached Discharge Voucher duly executed together with all original documents for your kind attention.

Kindly expedite payment and forward us your cheque for the settlement sum of **\$13,000.00** made in favour of **M/s Chunni Motor Work Pte Ltd** as soon as possible.

Thank you.

Your faithfully

For **Chunni Motor Work Pte Ltd**

Claims Department

Enc



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19005814/Deb3s2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 26-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 2250X	Veh. Inspected	SHA 5723P
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021602	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	01/04/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU090161	Colour	BLUE
Odometer	391107	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	WEST LAKE	5 mm
L/H Front Tyre	205/60R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/03/2019	Inspection Date	02/04/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5723P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER (RH)	DENTED	4,736.80	2,020.20
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (RH)	BENT	2,201.10	2,201.10
1	FRONT DOOR (RH)	BUCKLED	2,256.40	2,256.40
1	FRONT DOOR GEAR / REGULATOR (RH)	NOT NECESSARY	250.60	-
1	FRONT DOOR POWER MOTOR, RH	NOT NECESSARY	296.40	-
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	ROCKER PANEL OUTER GARNISH (RH)	CUT / BENT	341.40	341.40
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	CUT / BENT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-3,334.13	-2,665.15
			13,336.52	10,660.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	REAR TYRE (RH) (SN)	SERVICEABLE	216.00	-
			417.00	201.00

Report Ref No. CC4/LPC19005814/Deb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,800.00	900.00
	SPRAY PAINTING CHARGE.		1,250.00	900.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE / REFIX UNDERCARRIAGE (RR)		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET REAR ABS SYSTEM. }		200.00	150.00
	RE-SET FRT & REAR POWER WINDOW SYSTEM. }		400.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	-
			5,160.00	2,480.00
	GRAND TOTAL		18,913.52	13,341.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,600.00

Report Ref No. CC4/LPC19005814/Deb3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.