



Steve (LKK) WL Pte Ltd
5/4/19 9.15am

Sompo Insurance Pte Ltd
50 Raffles Place, #05-01/06
Singapore Land Tower
Singapore 048623

4 days
LIS
Ry A/L sy

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	SKA933Y
Make / Model	MERCEDES/E200
Chassis number	WDD212042A183969
Accident date	27 March 2019
Reference	1903-48

Acknowledged by Repairer
Signature:

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER X R	1659.00
2	FRONT BUMPER SIDE RETAINER / BR (LH)	147.00
1	FRONT LH HEADLAMP X	3747.00
1	FRONT LH FENDER X R	1134.00
1	FRONT LH FENDER INNER SHIELD X	212.00
1	FRONT LH KNUCKLE ARM ? / BT	1368.00
1	FRONT LH KNUCKLE BEARING ? / NEC	794.00
1	FRONT LH UPPER TRAILING ARM X	561.00
1	FRONT LH LOWER ARM ?	545.00
1	FRONT LH ABS SENSOR X	392.00
		10559.00
	Less 10%	1059.90
		9499.10
	Balance C/F	9499.10
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	9499.10
1	RIM (WT (FL LH))	1200.00 ✓
1 BOT	BRAKE BUILD	60.00 20
1 SET	FRONT BUMPER CLIP	50.00 30
1 SET	FRONT FENDER INNER SHIELD CLIP	40.00 20
	Subtotal	1350.00
	Balance C/F	10849.10
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	10849.10
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	60.00 30
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00 X
3	CHECK FRONT WHEEL ALIGNMENT	150.00 60
4	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 ✓
5	PANEL BEATING ON AFFECTED AREAS	700.00 209
6	SPRAY PAINTING ON AFFECTED AREAS	700.00 490
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 20
	Subtotal	2460.00
	Grand total	13309.10