

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0422/2019/DY
Date : 2-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Choo Kwok Wah Allan
Address : 230 Westwood Avenue
#11-27
Singapore 648359
Telephone : HP +65 96887662
Type of Claim : Own Damage Claims
Policy No. : 1800070419
Vehicle No : **SMA 6649 E**
Model Code : Audi Q2 TFSI S TRONIC
Model / Year : Jun-18
Engine No : CHZ 673123
Chassis No : WAUZZZGA4JA066396
Mileage :
Date In : 1-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Mar-19
Place of Accident : Jurong West Ave 1 towards

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 6649 E

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	s/n \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500
3	To rep-spray rear bumper and lhs rear fender.	\$ 1,700.00 1,100
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>3,222.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 6649 E

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>Repair</i>	\$ 1,074.00	+
2	REAR BUMPER FIXING PARTS <i>Neu</i>	\$ 70.00	+
3	REAR BUMPER SPOILER <i>lt</i>	\$ 259.00	✓
4	REAR BUMPER TOWING EYE COVER <i>Neu</i>	\$ 39.00	+
5	REAR LIGHT REFLECTOR LH <i>Neu</i>	\$ 27.00	+
6	TAILLIGHT LH <i>Cracked.</i>	\$ 1,207.00	✓
7	TAILLIGHT TRIM LH <i>Neu</i>	NEC \$ 27.00	+
8	REAR BUMPER GUIDE SECTION LH <i>Neu</i>	\$ 49.00	+
9	REAR BUMPER SENSOR OUTER <i>3 Neu</i>	\$ 231.00	+
10	REAR BUMPER SEAL RING	4 \$ 12.00	+
11	REAR WHEEL ARCH COVERS REAR LH / RH <i>Neu</i>	NEC \$ 312.00	✓
12	REAR WHEEL ARCH CLIPS 14 <i>Neu</i>	NEC \$ 31.00	✓
13	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 3,738.00	
TOTAL LABOUR CHARGES		: \$ 3,222.00	
GRAND TOTAL		: <u>\$ 6,960.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *02/04/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorised Repairs, 04 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant