

DIORIMAGE ENTERPRISES PTE. LTD.
9 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0131/2019
DATE : 01-APR-2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
1 ANSON ROAD
15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : CHAN POH GEOK
ADDRESS : 41E LORONG L , TELOK KURAU
S(425458)
TELEPHONE NO : 97666190

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700019726-01
VEHICLE NO : SJB6399G
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y682926
CHASSIS NO : JF1SJ5KC5HG089969
MILEAGE : 1 KM
DATE IN : 01/04/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MOHAMED ISMAN BIN MOHAMED HEPBUN**
ACCIDENT DATE : 01/04/2019

Print Date : 02/04/2019
Print Time : 09:27:25

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJB6399G

Steve (LKK)
8322 8813

Mr Permalia 4/4/19 10.15am
P/P
5 days
Ry bef spray

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLK4497Z - CHINA TAIPING INSURED		
2	ZZ/001	CONDUCT TP CLAIM CN TAIPING DATE:29/03/2019 TIME: 1445HRS LOCATION:PIE TWDS TUAS 17KM BRIDGE		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER, END PANEL, FLOOR PAN & TAILGATE 1.5 560	2800.00	840 + 840 = 1680 ✓
4	ZZ/003	RESPRAY REAR BUMPER, END PANEL, FLOOR PAN & TAILGATE 1.5 840	2100.00	840 + 420 = 1260 (Rear panel, floor pan) ✓
5	ZZ/004	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR	900.00	×
6	ZZ/005	REMOVE & REFIX EXHAUST	150.00	×
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	×
8	ZZ/007	TRANSFER TAILGATE MECHANISM	150.00	×
9	ZZ/008	WHEEL ALIGNMENT	200.00	×
10	ZZ/009	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIR	400.00	×
11	ZZ/011	REMOVE & INSTALL REAR WINDSCREEN	300.00	×
12	ZZ/012	REMOVE & REFIX FUEL TANK	200.00	×
13	ZZ/013	TO CONDUCT REAR LIGHTING TEST	50.00	×
14	ZZ/014	TO CONDUCT PROTECTANT COATING	1500.00	×
15	ZZ/015	TO CONDUCT ANTI RUST COATING	580.00	300 ✓
16	ZZ/016	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	300.00	?
17	ZZ/017	TO SUPPLY & INSTALL REAR TINTED FILM	145.00	×
18	ZZ/018	SUNDRIES	100.00	20 ✓
19	ZZ/010	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	×
TOTAL LABOUR CHARGES			10125.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJB6399G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	DISC WHEEL AL 17	28111SG130	1500.00	X		
2	FLOOR PAN R R CP	52129SG0019P	432.00	?		
3	SKIRT COMPL R	5.2F 52401SG0109P	288.00	?		
4	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	✓	^ 00	
5	BRKT SD R RH	(1) 57707SG080	14.40	?		
6	BRKT SD R LH	57707SG090	14.40	?		
7	BEAM COMPL R EU	57711SG0219P	288.00	?	^ / 00	
8	COVER HOOK R	57731SG010NN	12.60	✓	MIS	
9	COVER BMPR R (EXHAUST)	57731SG060	14.40	X	^ / BR	
10	PANEL CPL R/G NA	60809SG0109P	1072.80	R X		
11	GLASS R/G	63019SG000	799.20	X		
12	LATCH&ACT ASSY RG	63032FG102	144.00	X		
13	RUBBER DAM GLS	-1 CAN USE SC000X2 63232SG000	14.40	X		
14	RUBBER R/G	63232SG010	12.60	X		
15	STRIKER R/G	63264AG100	21.60	X		
16	REFLEC AY RH	84281SC000	20.40	?		
17	REFLEX AY LH	84281SC010	20.40	?		
18	LENS & BODY COMPLJPL	84912SG111	432.00	X		
19	LENS & BODY COMPLRFR	84912SG121	432.00	X		
20	GARNISH AY RG, B	91111SG000	288.00	X		
21	PROTR R GARNISH	91713SG000	21.60	X		
22	PROTECTOR LWR SD	91713SG010	21.60	X		
23	PROTECTOR SD	91713SG020	4.32	X		
24	ORNAMENT R	93033SG001	79.20	✓	XEC	
25	LETTER MARK FORESTOR R	93079SG000	39.60	✓	NEC	

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	LETTER MK R SUB	93079SG030	64.80	✓ N/E C		
SUB TOTAL			6592.32	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1318.46	0.00	0.00	0.00
GRAND TOTAL			5273.86	0.00	0.00	0.00
OVERALL TOTAL			5273.86			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJB6399G

TOTAL LABOUR CHARGES	10125.00
TOTAL SPARE PARTS CHARGES	5273.86

GRAND TOTAL	15398.86 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.