

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC6004K151224

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower Singapore 068811

Date: 02-04-19

Vehicle No: GBC6004K

Model/Make: Nissan NV200

1.5L MT ABS Airbag 2WD 6DR

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>cut</i>	\$ 512.20	
2	Bumper Clips 12 pcs (@ S\$6.50 N) <i>new</i>	\$ 78.00	SN 40 S.N
3	Tail Lamp <i>pls</i>	\$ 319.70	N 500 S.N
4	"Corporate" Advertisement & Artwork <i>new</i>	\$ 600.00	SN 500 S.N
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	- 350
	To putty & spray painting & including touch up paint on accident affected	\$ 400.00	- 200

Total Parts & Labour of estimate for damaged vehicle

\$ 2,359.90

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-831.90
 50%
 P-415.95
 S.N - 540.00
 10km - 570.00
 1525.95

not Adhered
 LKK
 d/s 1500/
 Hdy.
 3/4/19
 Take photo of the repair