

REPAIR ESTIMATE*

VEHICLE NO : SHD 8584M

DATE 2/4/2019 13:46

MAKE :

MODEL : HYUNDAI i40

Like

PbyP
FWD

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille / out			\$ 1,110.10
	Front Bumper Cover / Rehd			\$ 1,052.20
	Front Bumper Grille (RH) X sm			\$ 93.60
	Front Bumper Bracket Top (RH) X sm			\$ 22.40
	Front Bumper Bracket (RH) X sm			\$ 24.60
	SUB TOTAL			\$ 2,302.90
	LESS 20%			\$ 460.58
	DISCOUNTED TOTAL			\$ 1,842.32
	Front Bumper Cover Advertisement Logo / sm			\$ 100.00
	Front Fender Advertisement Logo (RH) X sm			\$ 100.00
				\$ 200.00
	Labour Charge			
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 500.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 850.00
	ESTIMATE TOTAL			\$ 2,892.32

TOTAL LABOUR

ESTIMATE TOTAL

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

Kahin LKK

3/4/19 10 45 hrs.

2 Pys

PIP

Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

