

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 3 April 2019 2:06 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -COMFORTDELGRO ENGINEERING PTE LTD, DOA: 01/04/2019, SHC 8130U (TP VEHICLE), SLE 302K (OI VEHICLE)
Attachments: SHC 8130U GIA.pdf; SHC 8130U ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 8130U at M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 2/4/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Date/Time: 01.04.2019 15:34 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305283126

OMER
S
OMER NO.
ESS
(R)
(P)

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)


OUNT CARD NO.

REGN NO.:	SHC8130U	MILEAGE
MAKE :	HYUNDAI	FUEL E.....1/2.....IF
MODEL	I-40	DATE/TIME IN 01.04.2019 00:30
YR OF MANU	30.06.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU091556	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 01.04.2019
NATURE: 3P 01.04.19

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

Vehicle No.: SHC8130U LIMITS

Vehicle No.: SHC8130U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>11/4/19</u> Time Received: <u>0105</u>		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>Thor Siew Kan</u> Contact No. : <u>90899769</u> Vehicle No. : <u>SHC81304</u> Make / Model / Colour : <u>I40</u> Email :		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>hender Ave</u>		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Others: _____			

10. Odometer Reading : _____	11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested					
Fuel Level : <table border="1"><tr><td>F</td><td>1/4</td><td>1/2</td><td>3/4</td><td>E</td></tr></table>	F	1/4	1/2	3/4	E	
F	1/4	1/2	3/4	E		

Job Attended

12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input checked="" type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS TOWING		 #: Cracked X: Dented /: Scratched O: Missing Signature of Customer
Name of Driver : <u>Buy</u>		
Vehicle No. : <u>YN7337M</u>		
Time Dispatch : <u>0105</u>		
Time of Arrival : <u>0140</u>		
Time Completed : <u>0215</u>		

Cash Invoice Details (if applicable)

13. Cash Invoice No. :	
------------------------	--

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

<u>11/4/19</u> Date	<u>0140</u> Time	<u>[Signature]</u> Signature of Customer
------------------------	---------------------	---

14. WORKSHOP

Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard
-------------------------------	------------------------	------------------------------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 13:36
Date Of Accident	01/04/2019 00:30
Exact Location Of Accident	LENTOR AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8130U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	THOR SWEE KOON
NRIC No	S0178660A
Date Of Birth	16/01/1951
Occupation	OUTDOOR
Date Of Driving Pass	11/06/1969
Driving Experience	49 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90899769
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	444 09-1601 HOUGANG AVENUE 8
Postcode	530444
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	SENGKANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE302K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ABD RAHIM MUSA
NRIC/Passport Number	S2166090F
Contact Number	81553909

Address

Postcode

Insurance Company Name

Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name THOR SWEE KOON

Approximate Age 68

Injuries Sustain BACK

Injured person in which vehicle? SHC8130U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name PAX

Approximate Age

Injuries Sustain NOT SURE

Injured person in which vehicle? SHC8130U

Were seat belts worn?


Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report - T/20190401/2020

DECLARATION

I/We declare the foregoing particulars are true in every respect.

MFORT TRANSPORTATION PTE LTD
CO REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

S. R. M. P. O. H. V.
CSO
1/14/19



**SINGAPORE
POLICE FORCE**



T/20190401/2020

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 3

Report No. T/20190401/2020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/04/2019 09:51	Vide Report No.:	Station Diary No.: 24
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: THOR SWEE KOON		Address: APT BLK 444 HOUGANG AVENUE 8 #09-1601 SINGAPORE 530444	
ID Type / ID No.: NRIC NO / S0178660A		Contact No.: Home/Office: Mobile: 90899769	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 68	Date of Birth: 16/01/1951	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: TAXI DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/04/2019 00:30	Type of Location: Straight Road
Location: Along Road 1 LENTOR AVENUE Along Lentor Avenue towards yishun				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC8130U	Taxi					2
SLE302K						0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190401/2020

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3

Report No. T/20190401/2020

CONTINUATION OF REPORT

Driver			
Name	THOR SWEE KOON	ID No.	S0178660A
Related Vehicle	SHC8130U (Taxi)	Contact No.	90899769
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ABD RAHIM MUSA	ID No.	S2166090F
Related Vehicle	SLE302K	Contact No.	81553909
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 01/04/2019 at about 0030hrs, I was driving my comfort taxi bearing registration number SHC8130U along Lontor Avenue towards Yishun. As I was driving, the traffic light colour was red and as such I stopped my vehicle. When my vehicle was at a stationery position, there was a vehicle bearing registration number SLE302K which collided onto the rear of my vehicle. After the collision, my vehicle moved slightly forward and the driver of the said vehicle collided onto my vehicle for the second time. I then called for police and ambulance who arrived at my scene shortly later. Both my passenger was conveyed to KTHP. The rear of my vehicle bumper is quite damaged. I/C IO Sofian



SINGAPORE
POLICE FORCE



T/20190401/2020

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20190401/2020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 DALJIT SINGH

Signature Of Informant:

Date/Time:

01/04/2019 09:51

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMAD SHAHRIL BIN ABDULLAH

Contact No.: 65476083

Classification Of Case:

SN 035

Signature:

Authentication Stamp

NP168

Singapore Police Force

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

IS

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
 CTPL

CP/P

Singapore

LKK -

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/04/2019
Vehicle Reg. No.:	SHC8130U	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	30/06/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU652184	Chassis No:	KMHLB41UMGU091556
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	13,870.02
Miscellaneous Items	10.00
Labour	4,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	18,290.02
+ GST 7.00% (S\$)	1,280.30
Nett Amount (S\$)	19,570.32

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

00900

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2019)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC8130U/02/04/2019 08:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID <i>But</i>	20.00	0.00	*2,174.90 FL
2	1		*BOOTLID UPR LOCK <i>forward</i>	20.00	0.00	*102.60 FL
3	1		*BOOTLID LWR LOCK <i>x su</i>	20.00	0.00	*31.70 FL
4	1		*BOOTLID H EMBLEM <i>see</i>	20.00	0.00	*28.70 FL
5	1		*BOOTLID CRDI EMBLEM <i>see</i>	20.00	0.00	*27.90 FL
6	1		*BOOTLID I40 EMBLEM <i>see</i>	20.00	0.00	*27.90 FL
7	1		*BOOTLID LAMP <i>But</i> <i>CH</i> <i>one</i>	20.00	0.00	*565.60 FL
8	1		*BOOTLID MOULDING <i>see</i>	20.00	0.00	*85.00 FL
9	1		*BOOTLID LWR GARNIOSH <i>see</i>	20.00	0.00	*227.90 FL
10	1		*REAR BUMPER <i>But</i>	20.00	0.00	*553.00 FL
11	1		*REAR BUMPER REINFORCEMENT <i>see</i>	20.00	0.00	*428.40 FL
12	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH <i>But</i>	20.00	0.00	*160.60 FL
13	10		*REAR BUMPER CLIPS <i>see</i>	20.00	0.00	*22.00 FL
14	2		*REAR BUMPER SIDE BRKT RH/LH <i>see</i>	20.00	0.00	*71.20 FL
15	1		*REAR BUMPER SPONGE <i>see</i>	20.00	0.00	*103.50 FL
16	1		*REAR BUMPER UNDER COVER <i>see</i>	20.00	0.00	*228.00 FL
17	2		*TAILLAMP RH/LH <i>see</i>	20.00	0.00	*1,395.60 FL
18	1		*REAR END PANEL <i>But</i>	20.00	0.00	*526.70 FL
19	1		*REAR END PANEL GARNISH <i>see</i>	20.00	0.00	*57.70 FL
20	1		*REAR END LOWER PANEL <i>But</i>	20.00	0.00	*495.50 FL
21	1		*SPARE TYRE HOLDER <i>But</i>	20.00	0.00	*248.00 FL
22	1		*SPARE TYRE PANEL <i>But</i>	20.00	0.00	*852.80 FL
23	1		*SPARE TYRE CUSHION COVER <i>x su</i>	20.00	0.00	*209.10 FL
24	1		*SPARE TYRE FASTENER <i>see</i>	20.00	0.00	*28.50 FL
25	1		*REAR TOWING HOOK <i>x su</i>	20.00	0.00	*94.60 FL
26	1		*MEMBER ASSY-REAR FLOOR CENTRE <i>x rgr</i>	20.00	0.00	*570.40 FL
27	2		*EXHAUST INSULATOR <i>But</i> <i>torn</i>	20.00	0.00	*117.20 FL
28	2		*EXHAUST HANGER <i>x rgr</i>	20.00	0.00	*111.00 FL
29	1		*EXHAUST CENTRE PIPE <i>But</i>	20.00	0.00	*730.10 FL
30	2		*EXHAUST MUFFLER RH/LH <i>But</i>	20.00	0.00	*1,935.40 FL
31	2		*REAR FENDER RH/LH <i>CH</i> <i>But</i> <i>x rgr</i>	20.00	0.00	*4,342.80 FL
32	2		*REAR FENDER SHIELD RH/LH <i>x su</i>	20.00	0.00	*338.60 FL
33	1		*REAR WINDSCREEN MOULDING <i>see</i>	20.00	0.00	*60.00 FL
34	1		*BOOTLID COMFORTDELGRO & 65521111 STICKER <i>see</i>	0.00	0.00	*30.00 F
35	1		*REVERSE SENSOR <i>shut</i>	0.00	0.00	*135.70 F
36	1		*REAR BUMPER ADV.STICKER <i>x su</i>	0.00	0.00	*50.00 F
37	2		*REAR WINDSCREEN SEALANT <i>see</i>	0.00	0.00	*92.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

17,260.60

- List Item Discount on L Items (S\$)

3,390.58

Total Parts (S\$)

13,870.02

ComfortDelGro Engineering Pte Ltd/SHC8130U/02/04/2019 08:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
-----	-----	----------	-------------	-------	-------	--------

ComfortDelGro Engineering Pte Ltd/SHC8130U/02/04/2019 08:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	2,000.00 1,200
2	SPRAY PAINTING	New	1,600.00 1,400
3	WIRING CHECK	New	40.00 20
4	TUFF KOTE	New	200.00 100
5	TOWING FEE	New	60.00
6	R/I UPHOLSTERY ETC	New	150.00 50
7	R/I REAR WINDSCREEN	New	120.00 100
8	R/I REVERSE SENSOR	New	120.00 30
9	R/I EXHAUST SYSTEM	New	120.00 50
Gross Labour Cost (S\$)			4,410.00

ComfortDelGro Engineering Pte Ltd/SHC8130U/02/04/2019 08:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ka Loo (UCC)

2/4/19 1150hrs

5 Pys.

PRP

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ComfortDelGro Engineering Pte Ltd (Co. Reg No: 199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: Tokyo Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MK000342	Date of Loss:	01/04/2019
Vehicle Reg. No.:	SHC8130U	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	30/06/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU652184	Chassis No:	KMHLB41UMGU091556
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS**Amount**

Parts	792.72
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	792.72
+ GST 7.00% (S\$)	55.49
Nett Amount (S\$)	848.21
+ Previous Estimates (S\$)	19,570.32
Claim Total (S\$)	20,418.53

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC8130U/05/04/2019 17:59**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*EXHAUST FRONT — <i>Def</i>	20.00	0.00	*476.20 FL ~
2	1		*REAR FENDER EXTENSION LH — <i>Def</i>	20.00	0.00	*226.50 FL ~
3	1		*TAILLAMP CLIP LH — <i>me</i>	20.00	0.00	*3.60 FL ~
4	2		*BOOTLID HINGE RH/LH — <i>Def</i>	20.00	0.00	*284.60 FL ~

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	990.90
- List Item Discount on L Items (S\$)	198.18
Total Parts (S\$)	792.72

ComfortDelGro Engineering Pte Ltd/SHC8130U/05/04/2019 17:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SHC8130U/05/04/2019 17:59. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305283126
Date : 08/04/19

FINALIZATION FORM


To : LKK
Attn : KALVIN ANG


Fax :

Vehicle Reg No. : SHC8130U Date of Accident : 01-Apr-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: TOKIO MARINE --- SLE 302K
- The finalized amount shall be:
 - Spare Parts after List discount \$11,791.30
 - Labour Charges \$3,020.00
 - Total for Part-By-Part Repair Cost \$14,811.30**
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
- Estimated normal period for repairs: 5 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 9/4/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305283126
REGN NO : SHC8130U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 01.04.2019 00:30
ACCIDENT DATE : 01.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0577-G	BOOTLID	1	2,174.90	20.00	1,739.92
0002 04-01-0103-0721-G	BOOTLID UPR LOCK	1	102.60	20.00	82.08
0003 04-01-0103-0800-G	BOOTLID H EMBLEM	1	28.70	20.00	22.96
0004 04-01-0103-0786-G	BOOTLID CRDI EMBLEM	1	27.90	20.00	22.32
0005 04-01-0103-0787-G	BOOTLID I40 EMBLEM	1	27.90	20.00	22.32
0006 04-01-0103-0584-G	BOOTLID LAMP LH	1	565.60	20.00	452.48
0007 04-01-0103-0785-G	BOOTLID MOULDING	1	85.00	20.00	68.00
0008 04-01-0103-0784-G	BOOTLID LOWER GARNISH	1	227.90	20.00	182.32
0009 04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40
0010 04-01-0103-0740-G	REAR BUMPER REINFORCEMENT	1	428.40	20.00	342.72
0011 04-01-0103-0743-G	REAR BUMPER REIN-BRKT RH	1	80.30	20.00	64.24
0012 04-01-0103-0742-G	REAR BUMPER REIN-BRKT LH	1	80.30	20.00	64.24
0013 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305283126
 REGN NO : SHC8130U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 30.06.2016
 DATE/TIME IN : 01.04.2019 00:30
 ACCIDENT DATE : 01.04.2019

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT				
0014 04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	1	35.60	20.00	28.48	
0015 04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	35.60	20.00	28.48	
0016 04-01-0103-0739-G	REAR BUMPER SPONGE	1	103.50	20.00	82.80	
0017 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	
0018 04-01-0103-0585-A	TAILLAMP RH	1	697.80	20.00	558.24	
0019 04-01-0103-0581-A	TAILLAMP LH	1	697.80	20.00	558.24	
0020 04-01-0103-0696-G	REAR END PANEL	1	526.70	20.00	421.36	
0021 04-01-0103-1053-G	REAR END PANEL GARNISH	1	57.70	20.00	46.16	
0022 04-01-0103-2159-G	REAR END LOWER PANEL	1	495.50	20.00	396.40	
0023 02-01-0103-0055-G	EXHAUST INSULATOR LH	1	58.60	20.00	46.88	
0024 02-01-0103-0056-G	EXHAUST INSULATOR RH	1	58.60	20.00	46.88	
0025 02-01-0103-0078-G	EXHAUST FRONT**	1	476.20	20.00	380.96	

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305283126
 REGN NO : SHC8130U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 30.06.2016
 DATE/TIME IN : 01.04.2019 00:30
 ACCIDENT DATE : 01.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0026 02-01-0103-0053-G	EXHAUST MUFFLER LH	1	967.70	20.00	774.16
0027 02-01-0103-0054-G	EXHAUST MUFFLER RH	1	967.70	20.00	774.16
0028 04-01-0103-0576-G	REAR FENDER LH	1	2,171.40	20.00	1,737.12
0029 04-01-0103-0745-G	REAR WINDSCREEN MOULDING	1	60.00	20.00	48.00
0030 28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	15.00		15.00
0031 28-01-0103-0006-A	BOOTLID 65521111	1	15.00		15.00
0032 09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70
0033 05-01-0199-0032-A	WINDSCREEN AHESIVE-310ML	2	92.00		92.00
0034 04-01-0103-2158-G	SPARE TYRE HOLDER	1	248.00	20.00	198.40
0035 04-01-0103-0710-G	RR FENDER EXTENSION LH**	1	226.50	20.00	181.20
0036 04-01-0103-0830-G	SPARE TYRE PANEL	1	852.80	20.00	682.24
0037 04-01-0103-0695-G	SPARE TYRE FASTENER	1	28.50	20.00	22.80

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305283126
 REGN NO : SHC8130U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 30.06.2016
 DATE/TIME IN : 01.04.2019 00:30
 ACCIDENT DATE : 01.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0038 04-01-0103-0780-G	TAILLAMP CLIP LH**	1	3.60	20.00	2.88
0039 02-01-0103-0086-G	EXHAUST CENTRE PIPE	1	730.10	20.00	584.08
0040 04-01-0103-0712-G	BOOTLID HINGE LH**	1	142.30	20.00	113.84
0041 04-01-0103-0713-G	BOOTLID HINGE RH**	1	142.30	20.00	113.84

SUB-TOTAL : 11,791.30

JOB NATURE

0000 PB	PANEL BEATING	1200.00
0001 SP	SPRAYPAINT CHARGE	1400.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	100.00
0004 23-01	TOWING FEE	60.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305283126
REGN NO : SHC8130U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 01.04.2019 00:30
ACCIDENT DATE : 01.04.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0005 L	R/I UPHOLSTERY ETC	50.00				
0006 L	R/I REAR WINDSCREEN	100.00				
0007 L	R/I REVERSE SENSOR	30.00				
0008 L	R/I EXHAUST SYSTEM	50.00				
0009 20-05	TP MERIMEN	10.00				

SUB-TOTAL : 3,020.00

TOTAL : 14,811.30


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2019 08:38 Sendback Est	02 Apr 2019 08:54 S\$18,290.02	04 Apr 2019 11:08 Edit Adj Rpt	S\$14,811.30 Edit Estimates	S\$14,811.30 View Rpt		Pending for Survey Report Cancel Case
Supp #1	05 Apr 2019 17:58	05 Apr 2019 17:59 S\$792.72	05 Apr 2019 17:59			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CTPL , Co. Reg. No.: 199303821R									
Main Claimant: CTPL									
Vehicle Reg. No.: SHC8130U		Date of Loss: 01/04/2019 00:00 - :59 [33 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / M1902119		Policy/Cover Note No.: MK000342 (Third Party Only) Coverage: 25/02/2019 - 24/02/2020							
Vehicle Reg. No. (Insured): SLE302K		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 15/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC8130U (M1902119)

[SLE302K]

TP














































CTPL

Apr 1 2019 12:00AM

[CTPL]

ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	02/04/19 08:54	Repairer Estimates	1	Load HTM	
2	05/04/19 17:59	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	04/04/19 11:10	Accident Statement From: TP - Reg. No: SHC8130U, Claimant: COMFORT TRANSPORTATION PTE LTD	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	04/04/19 16:58	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	04/04/19 16:58	General View	1	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
				<input checked="" type="checkbox"/>
32	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
33	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
34	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/04/19 16:58	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	04/04/19 17:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	15/04/19 14:51	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	02/04/19 08:55	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 09:39	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19005862/K1TD3E2

Date: 18/04/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000342

Claimant Vehicle No : SHC8130U

Insured Vehicle No : SLE302K

Date of Loss: 01/04/2019

Nature of Claim: TP

Claim No: M1902119

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8130U

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU652184

Reg. Date: 30/06/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU091556

Colour: Blue

Odometer: 466613 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,662.74	11,791.30	2,871.44	19.58
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	4,410.00	3,010.00	1,400.00	31.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,082.74	14,811.30	4,271.44	22.38
+ GST 7.00/7.00% (S\$)	1,335.79	1,036.79	299.00	22.38
Nett Amount (S\$)	20,418.53	15,848.09	4,570.44	22.38

INSPECTION

Date of Assignment: 04/04/2019 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 02/04/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 5.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2019)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC8130U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
2	1		*BOOTLID UPR LOCK	Jammed	102.60 FL	*102.60 FL
3	1		*BOOTLID LWR LOCK	Serviceable	31.70 FL	*- FL
4	1		*BOOTLID H EMBLEM	Necessary	28.70 FL	*28.70 FL
5	1		*BOOTLID CRDI EMBLEM	Necessary	27.90 FL	*27.90 FL
6	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
7	1		*BOOTLID LAMP RH/LH	Cracked	565.60 FL	*565.60 FL
8	1		*BOOTLID MOULDING	Cut	85.00 FL	*85.00 FL
9	1		*BOOTLID LWR GARNIOSH	Cracked	227.90 FL	*227.90 FL
10	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
12	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH	Bent	160.60 FL	*160.60 FL
13	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
14	2		*REAR BUMPER SIDE BRKT RH/LH	Cracked	71.20 FL	*71.20 FL
15	1		*REAR BUMPER SPONGE	Torn	103.50 FL	*103.50 FL
16	1		*REAR BUMPER UNDER COVER	Cracked	228.00 FL	*228.00 FL
17	2		*TAILLAMP RH/LH	Necessary	1,395.60 FL	*1,395.60 FL
18	1		*REAR END PANEL	Buckled	526.70 FL	*526.70 FL
19	1		*REAR END PANEL GARNISH	Cracked	57.70 FL	*57.70 FL
20	1		*REAR END LOWER PANEL	Buckled	495.50 FL	*495.50 FL
21	1		*SPARE TYRE HOLDER	Buckled	248.00 FL	*248.00 FL
22	1		*SPARE TYRE PANEL	Buckled	852.80 FL	*852.80 FL
23	1		*SPARE TYRE CUSHION COVER	Not Necessary	209.10 FL	*- FL
24	1		*SPARE TYRE FASTENER	Cracked	28.50 FL	*28.50 FL
25	1		*REAR TOWING HOOK	Serviceable	94.60 FL	*- FL
26	1		*MEMBER ASSY-REAR FLOOR CENTRE	Repair	570.40 FL	*- FL
27	2		*EXHAUST INSULATOR	Torn	117.20 FL	*117.20 FL
28	2		*EXHAUST HANGER	Repair	111.00 FL	*- FL
29	1		*EXHAUST CENTRE PIPE	Bent	730.10 FL	*730.10 FL
30	2		*EXHAUST MUFFLER RH/LH	Bent	1,935.40 FL	*1,935.40 FL
31	1		*REAR FENDER RH/LH	N/S Buckled / O/S Repair	4,342.80 FL	*2,171.40 FL
32	2		*REAR FENDER SHIELD RH/LH	Serviceable	338.60 FL	*- FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
34	1		*BOOTLID COMFORTDELGRO & 65521111 STICKER	Necessary	30.00 F	*30.00 F
35	1		*REVERSE SENSOR	Shorted	135.70 F	*135.70 F
36	1		*REAR BUMPER ADV.STICKER	Not Necessary	50.00 F	*- F
37	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 F	*92.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Supplementary #1						
38	1		*EXHAUST FRONT	Bent	476.20 FL	*476.20 FL
39	1		*REAR FENDER EXTENSION LH	Buckled	226.50 FL	*226.50 FL
40	1		*TAILLAMP CLIP LH	Necessary	3.60 FL	*3.60 FL
41	2		*BOOTLID HINGE RH/LH	Bent	284.60 FL	*284.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **18,251.50** **14,674.70**
 - List Item Discount on L Items 20.00/20.00% (S\$) 3,588.76 2,883.40

Total Parts (S\$) **14,662.74** **11,791.30**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING	New	1,600.00	1,400.00
3	WIRING CHECK	New	40.00	20.00
4	TUFF KOTE	New	200.00	100.00
5	TOWING FEE	New	60.00	60.00
6	R/I UPHOLSTERY ETC	New	150.00	50.00
7	R/I REAR WINDSCREEN	New	120.00	100.00
8	R/I REVERSE SENSOR	New	120.00	30.00
9	R/I EXHAUST SYSTEM	New	120.00	50.00
Gross Labour Cost (S\$)			4,410.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >