

ASS. REC. BY:

REF: CS/CTI19005863/Uqd3

Special Instruction:

02

Supervisor: marcus

**ASSIGNMENT (Office)**

Minim

From (Person): Irene Tay Hui Ping of CTI

Date/Time: 3.4.19 10.26a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 73724

Insured: SLM 70564

at Workshop m/s AUTO N cars Service

Tel: 6555 2909

of BIR 1 Kaki Bukit Ave 6 #01-04

Policy No: DMPCSN 30350718011

Claim No: SNM 19D200013C02

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

D.O.A. 27.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 3.4.19 10.59a.m

Person Contacted: Tarla

Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SLC 73724 -X
	SLM 70564 -X

Surveyor

ASSIGNMENT

From: \_\_\_\_\_ Date: **9.4.2019**

Estimated Cost: \_\_\_\_\_

OD:  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLC 7372Y**

at Workshop m/s **AUTO N cars**

of **Blk 1 Kaki Bukit Ave 6 #01-90**

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: **2pm**

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: **J** Consistent? : Yes or No

Est. Repairs: **2** days Res.: Yes or No

Lum Sum, **1.31** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **"WP"**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **SLC 7372Y** Yr Regn: **5/16**

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **CA**

Make: **Subaru Forester** c.c. **1998**

Colour: **Grey** A/C:  Insured / Std / NI / NA

Sp. Reading: **49782** T/Radio:  Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **JF15JAK.856607238**

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi:  Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: **235/55-18**

BS / DUN / EXNOVA / GY / FS / LIZA /  MICOHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. **7** mm Rear R/Bal. **7** mm

L/Bal. **7** mm L/Bal. **7** mm

D.O.A. **27/12/18** D.O.I. **9/4/19**

Survey held at \_\_\_\_\_

Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or

**Rear**

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

16/4/19 Confirmed final by \$1168.00 with Darta. (Red 51938.64, 62%)

RECEIVED 16 APR 2019

Date/Time, File Pass to?  : Preli. Report

**16/4/19**  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: **2**

Resurvey No. of Trip: **2**

Add Fee:  : Site Insp (\$ ) S + RS. \$

: Interview (\$ ) Photos

: Tech. Invs (\$ ) Others

: Weekend (\$ )

Report Format: **MP-TP**

Lump Sum / I.B.I: (\$) **1168**

Survey Fee:	
Transportation:	
S + RS. \$	
Photos	
Others	
TOTAL	<b>220</b>

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2019 Sendback Est	29 Mar 2019 09:57 S\$3,106.64	03 Apr 2019 10:26 Assign				<b>New Assignment</b> Cancel Case

  

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

  

CLAIM SUBFOLDER DETAILS			
Insured:	TEO CHAI NGOH, ID: S1527302Z, Tel: +6598185472		
Main Claimant:	HAN RONG KWANG, ID: S8108654J		
Vehicle Reg. No.:	SLC7372Y	Date of Loss:	27/12/2018 10:00 - :59 [31 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200013C02	Policy/Cover Note No.:	DMPCSN30350718011
Vehicle Reg. No. (Insured):	SLM7056H	Policy No. (Claimant):	DMPPHQ18-002919
		Excess:	S\$0.00
Repairer:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/04/2019]		
Driver/Custodian (Insured):	TEO CHAI NGOH ( / Male), NRIC: S1527302Z, Tel: +6598185472 Email:		

  

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

  

ALL ASSOCIATED TASKS										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8654J
<b>Vehicle Details</b>	
Vehicle No.:	SLC7372Y
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	FA20A926813
Chassis No.:	JF1SJGK85GG072368
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$19,148.00
Original Registration Date:	25 May 2016
First Registration Date:	25 May 2016
Transfer Count:	0
Actual ARF Paid:	\$19,148.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2026
PARF Rebate Amount:	\$14,361.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$36,337.00
<b>Total Rebate Amount:</b>	<b>\$50,698.00</b>

The information contained herein is correct as at 09 Apr 2019

OK

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005868/UQD3N2

Date: 16/04/2019

**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30350718011
Claimant Vehicle No :	SLC7372Y	Insured Vehicle No :	SLM7056H
Date of Loss:	27/12/2018	Nature of Claim:	TP
		Claim No:	SNM19D200013C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLC7372Y	Engine No:	FA20A926813
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJGK85GG072368
Reg. Date:	25/05/2016 (Man. Year: )	Odometer:	49782 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,586.64	568.00	1,018.64	64.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	600.00	920.00	60.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>3,106.64</b>	<b>1,168.00</b>	<b>1,938.64</b>	<b>62.40</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>217.46</b>	<b>81.76</b>	<b>135.70</b>	<b>62.40</b>
<b>Nett Amount (\$\$)</b>	<b>3,324.10</b>	<b>1,249.76</b>	<b>2,074.34</b>	<b>62.40</b>

**INSPECTION**

Date of Assignment:	03/04/2019	Present Location:	Auto N Cars Services Pte Ltd (HQ)
Date Inspected:	09/04/2019	Inspected At:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2019)
<b>Parts:</b> M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC7372Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper	Dented/Deformed	710.00 FL	*710.00 FL
2	2		*Rear bumper retainer	Not Necessary	70.00 FL	*- FL
3	1		*Rear bumper underguard	No such part	135.00 FL	*- FL
4	1		*Rear bumper underguard LH reflector	Not Necessary	52.50 FL	*- FL
5	1		*Rear bumper reinforcement	Not Necessary	455.00 FL	*- FL
6	1		*Rear bumper tow hook cover	Serviceable	25.00 FL	*- FL
7	1		*Rear bumper paking sensor	Not Necessary	10.00 FL	*- FL
8	1		*Rear LH exhaust tailpipe	Serviceable	525.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,983.30</b>	<b>710.00</b>
- List Item Discount on L Items 20.00/20.00% (S\$)	396.66	142.00
<b>Total Parts (S\$)</b>	<b>1,586.64</b>	<b>568.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To knock and straighten rear portion. To remove and renew necessary parts. Cut and weld damaged panel. Adjust and realign the same	New	700.00	280.00
2	To putty and spray all affected areas	New	600.00	250.00
3	To install rear parking sensor	New	120.00	50.00
4	To check all wiring and lighting	New	100.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,520.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >