

ASS. REC. BY:

REF: CC/CT119005878/ R1vd3

Special Instruction:

Surveyor: RASU

ASSIGNMENT (Office)

mn/mn

From (Person): Irene Tay Hui Ping of CT1

Date/Time: 3.4.19 11.02 am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 6098C

Insured: GBH 4426M

at Workshop m/s Mov 4

Tel: 6262 3377

of 15 Yan Yoon Road, CNG Singapore

Policy No: DMKVS N18170318000

Claim No: SNM 19D 201415C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30.3.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 3.4.19 11.32 am

Person Contacted: Nabilah

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJK 6098C - X
	GBH 4426M - CS / CT119005866 / R1vd3 D.O.A - 30/3/2019
17/5/19	LS \$18,000 confirmed by email (Ref 18,124.04, 50%)

Rasul


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SYK 6098C**
 at Workshop n/s **MOVA**
 of **15, from youn to**
 Insured: **CTI**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SYK 6098C** Yr Regn: **2017 P85**
 Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **TOYOTA COROLLA ALTO** C.C: **1598**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MROS3REH104560117**
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ S/Rim / STD A/Rim or
 Tyre Size: F: **215/45ZR17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **30/03/19** D.O.I: **03/04/19**
 Survey held at **MOVA (from youn to)**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRt N/S & REAR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 APR 2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) **17/5 - typist**

Report Format: **maximen**
 Lump Sum / I.B.I: (\$) **18,000/-**

Days Of Repair: **32**

Resurvey No. of Trip: **2**

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee:

Transportation:

\$ = RM 52

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2019		03 Apr 2019 11:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	VERDECAS ENTERPRISE LLP, Co. Reg. No.: T14LL0564K			[Created by insurer]
Main Claimant:	MAHALINGAM GNANASEKARAN, ID: S2672942D			
Vehicle Reg. No.:	SJK6098C	Date of Loss:	30/03/2019 08:00 - :59 [25 Months and 2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D201415C02	Policy/Cover Note No.:	DMCVSN18170318000 (Comprehensive) Coverage: 25/05/2018 - 24/05/2019	
Vehicle Reg. No. (Insured):	GBH4426M	Policy No. (Claimant):	5088032110-02	
		Excess:	S\$0.00	
Repairer:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre, 629792 Boon Lay - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/04/2019]			
Driver/Custodian (Insured):	PANG CHIN TONG, ALVIN (FENG ZHENDONG) (33 / Male), NRIC: S8528605F Email:			
Adj Asg. Remarks:	kindly contact Nabilah - 6262 3377 to arrange for TP survey. Thank you.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

View All

Search Tasks

Create New Task

Complete

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 4 April 2019 9:19 AM
To: Billy
Cc: Veron Chen (LKKAUTO)
Subject: SJK 6098C DOA : 30/03/19

Hi Billy,

As spoken, the repair limit for this case is 18K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
PTE LTD

Save the Earth. Print only when necessary.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 17 May 2019 4:47 PM
To: Billy; SUR; Rasul (LKKAUTO)
Subject: RE: Re:SJK6098C-DOA: 30/3/2019

Dear Billy,

WITHOUT PREJUDICE

Close at Lump Sum Limit \$18,000.00 @ 32 days

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Billy <billy@moval.com.sg>
Sent: Friday, 17 May 2019 4:38 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re:SJK6098C

Hi Veron,

Attach after repair photos. Please help to close Lump Sum Limit \$18000.00 32days. Thank you.

Best Regard's
Billy Liaw

MOVA Automotive Pte Ltd

Tel: +65 62623377

Fax: +65 62643151



Connect with us on  

Veron Chen (LKKAUTO)

From: Billy <billy@nova.com.sg>
Sent: Saturday, 6 April 2019 9:31 AM
To: Rasul (LKKAUTO)
Cc: 'Jia Yu'
Subject: RE: SJK 6098C DOA : 30/03/19
Attachments: SJK6098C Toyota Altis 2017.pdf

Hi Sir,

Confirm Thank You.

Best Regard's
Billy Liaw

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: 04 April 2019 09:19
To: Billy
Cc: Veron Chen (LKKAUTO)
Subject: SJK 6098C DOA : 30/03/19

Hi Billy,

As spoken, the repair limit for this case is 18K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

- Cancer patient dies before receiving payout from case...
- Drowning to be made a crime punishable by jail, up to 5...
- Staff Neck & Shoulders

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

How it's Selling

Renew 12 Year Car: \$250 @ Degree @ \$6800 Per Yr Only



Yes, Come today - 202% Loan -
Monthly: \$200 (incl. GST)
Private Motors - Suzuki

• Free VCOM evaluation
• Free grooming and 1 month maintenance
• In-house workshop ensures quality service
• Member of SITA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

16 vehicles

Corolla Altis 1.6A

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Cost	Eng Cap	Mileage	Veh Type	Status
Search Selection	Corolla Altis 1.6A		Any	Any	2017	Any	Any	Any	Available
	Toyota Corolla Altis 1.6A Elegance		\$75,800	\$8,390 /yr	02-Feb-2017	1,598 cc	31,728 km	Sedan	Available
Facilitated Elegance Model: 1 Owner, Low Mileage Done, Agent Maintained. Flexible Loan Available, Trade In Welcome. Call Now For Viewing Appointment.									
Viewed: 07-Apr-2019 Tag: 2017 Toyota Corolla, 2017 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla									
	Toyota Corolla Altis 1.6A Elegance		\$76,800	\$8,460 /yr	22-Feb-2017	1,598 cc	17,000 km	Sedan	Available
1 Owner, Very Low Mileage Done At 17,000km, Accident Free, Always Service With Borneo Motor (Next Service At 24,000km), 5 Years Borneo Motor Warranty, Road Tax Till August 2019, Buy With Confidence!...									
Horizon Motoring Viewed: 05-Mar-2019 Tag: 2017 Toyota Corolla, 2017 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla									
	Toyota Corolla Altis 1.6A		\$80,000	\$9,010 /yr	06-Jan-2017	1,598 cc	43,000 km	Sedan	Available
1 Owner Car, Well Maintained By Agent, Price Negotiable, Consignment Unit! Trade In Welcome! Loan And Insurance Available! Call Now For Viewing Appointment!									
Prime Key Motoring Viewed: 06-Mar-2019 Tag: 2017 Toyota Corolla, 2017 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla									
	Toyota Corolla Altis 1.6A		\$74,800	\$8,180 /yr	13-Mar-2017	1,598 cc	19,800 km	Sedan	Available
Elegant White, Serviced By Agent, Agent Warranty Till March 2022, Low Maintenance Cost, One Owner Only, Accident Free, Very Well Maintained. Flexible In-House Loan Packages Available.									
Prime Motor & Leasing Viewed: 06-Mar-2019 Tag: 2017 Toyota Corolla, 2017 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla									
	SCT Auto Services Pte Ltd - Repair & Servicing								
SCT Auto Services is a one-stop repair centre with expertise in vehicle servicing, repairs, and spray painting.									
More info about this shop									
	Toyota Corolla Altis 1.6A Elegance		\$76,800	\$8,370 /yr	24-Mar-2017	1,598 cc	31,000 km	Sedan	Available
1 Owner Agent Unit, High Specs Model With Sports Bodykit, Keyless Entry, LED DRL, Navigation System & Driver's Electric Seats. 5 Years Manufacturer Warranty By Borneo Motors Till Mar 2022. Fully Serviced.									
Republic Auto Viewed: 13-Mar-2019 Tag: 2017 Toyota Corolla, 2017 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla									
	Toyota Corolla Altis 1.6A Elegance		\$76,800	\$8,340 /yr	05-Apr-2017	1,598 cc	25,050 km	Sedan	Available
High Specs Model, BEST Value! Vehicle Still Under Warranty By Borneo Motor 5 Years And Unlimited Mileages From The Date Of Purchase! Low Mileage Usage, Only Done 25,000 Km, Maintained And Service By B...									
Republic Auto Viewed: 04-Mar-2019 Tag: 2017 Toyota Corolla, 2017 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla									
	Toyota Corolla Altis 1.6A Elegance		\$77,800	\$8,400 /yr	26-Apr-2017	1,598 cc	19,799 km	Sedan	Available
One Lady Owner, Superb Low Mileage With New Car Smell. 5 Years Warranty By Borneo Motors. New Auspicious Number. Original Black Exterior Paintwork With Luxurious Beige Interior. Flexible Loan Packages...									

» **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2942D

Vehicle Details

Vehicle No.: SJK6098C
Vehicle to be Exported: Yes
Intended Deregistration Date: 01 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 CVT
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 1ZRY339344
Chassis No.: MR053REH104560117
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,990.00
Original Registration Date: 28 Feb 2017
First Registration Date: 28 Feb 2017
Transfer Count: 0
Actual ARF Paid: \$19,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Feb 2027
PARF Rebate Amount: \$14,992.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,889.00
COE Rebate Amount: \$40,256.00
Total Rebate Amount: \$55,248.00

The information contained herein is correct as at 01 Apr 2019

OK

74,000
55,248

18,752

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 15:07
Date Of Accident	30/03/2019 08:30
Exact Location Of Accident	ALONG MANDAI AVE TWDS SEMBAWANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK6098C
Insured/Policyholder	
Name Of Registered Owner	MAHALINGAM GNANASEKARAN
NRIC No	S2672942D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97850269
Alternative Phone No	OTHERS-83381849

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088032110-02
Cover Note Number	

Driver

Name of Driver	GNANASEKARAN VANI
NRIC No	S9371504G
Date Of Birth	13/09/1993
Occupation	INDOOR
Date Of Driving Pass	17/07/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83381849
Fax Number	
Contact Number	
Email Address	VANI13.MV@GMAIL.COM

Address	BLK 715 YISHUN STREET 71 #07-286
Postcode	760715
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH4426M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GX9261U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SDQ3280B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ran be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Namiah
alathura

Sketch Plan Pg. 2

SKETCH PLAN

Car A - SJK 6098C
 Car B - GBH 4426M
~~Car C - GX 96~~
 Car C - GX 9261U
 Car D - SDQ 3280B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SJK 6098C	ACCIDENT DATE & TIME: 30/3/2019 @ 8.20+
CONTACT NUMBER: 83381849	E-MAIL ADDRESS: van133@gmail.com
LOCATION: Mandai Ave towards Sembawang Road.	
Saturday Morning.	
Opp Crematorium hence cars were parked on either side of the road.	
I was on lane 2 & a car ^{was} parking on lane ³ and a portion of it was in lane 2 hence I slowed and came to a stop. A lorry hit me within a few seconds seconds. The force sent my car swerving. When I came to a stop my car nose had hit Car D. Driver's door was jammed and I came out of passenger's side door. Apparently, lorry had hit the rear right side of my car forcing me force forward to hit car C (causing it to hit car D) and the rear of my car swung forward swinging it to hit Car D.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
☐ Claim Own Policy ☒ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/TIN No.:

Natalah
 01/04/2019

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	RADIATOR GRILLE <i>Ch</i>	1	PC	564.20
2.	RADIATOR GRILLE TOP RUBBER <i>no</i>	1	PC	160.10
3.	RADIATOR GRILLE LOGO <i>see</i>	1	PC	48.00
4.	HEADLAMP ASSY RH & LH <i>Br</i>	2	PCS	2,795.00
5.	HEADLAMP LOWER BRACKET LH <i>Ch</i>	1	PC	78.80
6.	FRONT BUMPER <i>Br</i>	1	PC	458.90
7.	FRONT BUMPER SPONGE <i>cut</i>	1	PC	78.80
8.	FRONT BUMPER REINFORCEMENT <i>X</i>	1	PC	382.70
9.	FRONT BUMPER RETAINER RH & LH <i>see</i>	2	PCS	81.70
10.	FRONT BUMPER LOWER GRILLE - CENTER <i>X</i>	1	PC	155.00
11.	FRONT BUMPER CLIPS <i>see</i>	10	PCS	5.00
12.	FOG LAMP ASSY LH - CHECK <i>X</i>	1	PC	
13.	FOG LAMP GARNISH LH <i>see</i>	1	PC	91.90
14.	SUPPORT PANEL <i>Br</i>	1	PC	989.50
15.	BRACE PANEL <i>X</i>	1	PC	155.00
16.	AIR CON CONDENSER - CHECK <i>X</i>	1	PC	
17.	RADIATOR ASSY - CHECK <i>X</i>	1	PC	
18.	RADIATOR TOP BRACKET - CHECK <i>X</i>	1	PC	
19.	AIR CLEANER DUCT <i>Ch</i>	1	PC	171.00
20.	AIR CLEANER RESONATOR <i>Ch</i>	1	PC	103.40
21.	FUSE BOX BASE <i>X</i>	1	PC	111.70
22.	FRONT WIRE HARNESS - CHECK <i>X</i>	1	SET	
23.	FUSE BOX CENTER <i>X</i>	1	PC	209.10
24.	FRONT FENDER LH <i>Br</i>	1	PC	781.20
25.	FRONT FENDER INNER PANEL LH <i>repair</i>	1	PC	423.20
26.	FRONT FENDER COWLING LH <i>mis</i>	1	PC	200.90
27.	FRONT FENDER COWLING CLIPS <i>see</i>	10	PCS	5.00
28.	FRONT FENDER EMBLEM - DUAL VTI <i>see</i>	1	PC	40.00
29.	FRONT FENDER PROTECTOR LH - CHECK <i>X</i>	1	PC	
30.	FRONT FENDER CORNER GARNISH LH <i>Ch</i>	1	PC	35.00
31.	REAR DOOR RH <i>repair</i>	1	PC	1,100.00
32.	REAR DOOR TRIM BOARD RH - CHECK <i>X</i>	1	PC	
33.	REAR DOOR STICKER RH <i>X</i>	1	SET	40.00
34.	REAR DOOR LOCK RH <i>X</i>	1	PC	576.50
35.	REAR DOOR LOCK STRICKER RH <i>X</i>	1	PC	25.00
36.	ROOF SIDE PANEL RH <i>Br</i>	1	PC	333.00
37.	ROOF PANEL (REPAIR)	1	PC	
38.	ROOF LINING - CHECK <i>X</i>	1	PC	
39.	REAR WINDSCREEN GLASS <i>Br</i>	1	PC	741.90
40.	REAR WINDSCREEN GLASS MOULDING <i>see</i>	1	SET	95.00
41.	REAR FENDER RH & LH <i>Br</i>	2	PCS	986.80
42.	REAR FENDER COWLING RH & LH <i>Br LH-?/RH-DE</i>	2	PCS	45.00
43.	REAR FENDER AIR DUCT RH & LH <i>Br</i>	2	PCS	140.00
44.	REAR FENDER INNER PANEL RH <i>Br</i>	1	PC	395.70
45.	REAR FENDER INNER TRIM COVER RH <i>Br</i>	1	PC	759.00
46.	REAR FENDER INNER TRIM TOP GARNISH RH & LH <i>Br</i>	2	PCS	441.90
47.	REAR SPEAKER BOARD <i>Br</i>	1	PC	607.00
48.	REAR SPEAKER PANEL <i>Br</i>	1	PC	1,047.30
49.	REAR WHEEL HOUSING RH <i>Br</i>	1	PC	339.70
50.	REAR MUDFLAP RH <i>Br</i>	1	PC	111.70
51.	REAR CHASSIS MEMBER RH <i>Br</i>	1	PC	876.40

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- **XA017**

Page # :- 1 134506

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Move Building
 No. 22, Jalan Kilang,
 Singapore 189419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
52.	BOOT LID <i>BT</i>	1 PC	755.00	755.00
53.	BOOT LID HINGE RH & LH <i>BT</i>	2 PCS	68.00	136.00
54.	BOOT LID INNER TRIM <i>DE</i>	1 PC	515.00	515.00
55.	BOOT LID LOGO <i>nee</i>	1 PC	48.00	48.00
56.	BOOT LID EMBLEM - COROLLA <i>nee</i>	1 PC	49.00	49.00
57.	BOOT LID EMBLEM - ALTIS <i>nee</i>	1 PC	45.00	45.00
58.	BOOT LID CHROME MOULDING <i>CRA</i>	1 PC	233.70	233.70
59.	BOOT LID REFLECTOR RH & LH <i>BRO</i>	2 PCS	355.00	710.00
60.	BOOT LID LOCK <i>BT</i>	1 PC	382.50	382.50
61.	BOOT LID LOCK STRIKER <i>M</i>	1 PC	30.00	30.00
62.	BOOT LID WEATHERSTRIP <i>cut</i>	1 PC	185.00	185.00
63.	REAR NUMBER PLATE LAMP <i>X sue</i>	1 PC	55.00	55.00
64.	TAIL LAMP PANEL RH & LH - <i>LH-repair/RH-nee</i>	2 PCS	115.00	230.00
65.	TAIL LAMP ASSY RH & LH <i>BRO</i>	2 PCS	395.00	790.00
66.	TAIL LAMP CLIPS <i>nee</i>	4 PCS	10.00	40.00
67.	TAIL LAMP LOWER BRACKET RH & LH - <i>LH-MY/RH-CRA</i>	2 PCS	40.00	80.00
68.	REAR BUMPER <i>TORU</i>	1 PC	486.00	486.00
69.	REAR BUMPER SPONGE <i>X n</i>	1 PC	395.00	395.00
70.	REAR BUMPER RETAINER RH & LH <i>nee</i>	2 PCS	120.00	240.00
71.	REAR BUMPER REFLECTOR RH <i>BRO</i>	1 PC	58.00	58.00
72.	REAR BUMPER CLIPS <i>nee</i>	10 PCS	5.00	50.00
73.	REAR END PANEL <i>nee</i>	1 PC	590.00	590.00
74.	REAR END PANEL TOP COVER <i>DE</i>	1 PC	285.00	285.00
75.	SPARE TYRE BOARD <i>DE</i>	1 PC	295.00	295.00
76.	SPARE WHEEL PANEL <i>nee</i>	1 PC	797.00	797.00
77.	SPARE TYRE SPONGE <i>X n</i>	1 PC	333.10	333.10
78.	SPARE TYRE SPONGE RH & LH <i>X n</i>	2 PCS	179.10	358.20
79.	SPARE TYRE BOARD RH & LH - CHECK <i>X n</i>	2 PCS		
80.	SPARE WHEEL PANEL INSULATOR <i>nee</i>	1 PC	300.85	300.85
81.	REAR SPORT RIM RH <i>BT</i>	1 PC	1,645.10	1,645.10
82.	REAR WHEEL BEARING RH <i>nee</i>	1 PC	670.00	670.00
83.	REAR SHOCK ABSORBER RH <i>X sue</i>	1 PC	200.00	200.00
84.	REAR AXLE <i>X sue</i>	1 PC	2,850.00	2,850.00
85.	PETROL TANK - CHECK <i>X sue</i>	1 PC		
86.	REAR EXHAUST SILENCER <i>BT</i>	1 PC	939.00	939.00
87.	REAR EXHAUST HEAT COVER <i>BT</i>	1 PC	165.00	165.00
88.	REAR EXHAUST MOUNTINGS <i>nee</i>	3 PCS	41.70	125.10
89.	CENTER EXHAUST PIPE - CHECK	1 PC		
90.	REAR SEAT REST RH - CHECK	1 PC		
91.	REAR SEAT ASSY - CHECK	1 PC		
92.	REAR CHASSIS MEMBER LH (REPAIR)	1 PC		
93.	REAR SEAT BELT RH - CHECK	1 PC		
LIST TOTAL S\$				35,992.05
25% DISCOUNT S\$				-8,998.01
				26,994.04
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN GLASS SEALANT <i>nee</i>	1 PC	40.00	40.00
2.	REAR NUMBER PLATE <i>BT</i>	1 PC	40.00	40.00
3.	REVERSE SENSOR <i>nee</i>	1 SET	300.00	270.00

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- **XA017**

Page # :- 1 134506

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
4.	REAR TYRE RH <i>purchased</i>	1 PC	250.00	<i>700</i> 250.00 <i>700</i>
	SPECIAL NET TOTAL S\$			630.00
	LABOUR :			
	TOWING CHARGE WITH INVOICE			<i>receipt ?</i> 240.00
	TO CUT/WELD SUPPORT PANEL, FRONT FENDER INNER PANEL LH, REAR FENDER RH & LH, REAR FENDER INNER PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER LH, REAR SEAT PANEL, CENTER PILLAR RH, ROOF PANEL, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION.			<i>3600</i> 3,600.00
	SPRAY PAINT FRONT BUMPER, SUPPORT PANEL, FRONT FENDERS RH & LH, FRONT FENDER INNER PANEL LH, FRONT DOOR RH, CENTER PILLAR RH, ROOF PANEL, ROOF SIDE PANEL RH, REAR DOOR RH, REAR FENDERS RH & LH, REAR FENDER INNER PANEL RH, REAR SPEAKER PANEL, REAR SEAT PANEL, SPARE WHEEL PANEL, REAR CHASSIS MEMBERS, BOOT LID, REAR END PANEL, TAIL LAMP PANELS, REAR BUMPER (PEARL)			2,500.00
	REMOVE & REINSTALL AIR CON CONDENSER, PIPE, HOSE AND RECHARGE AIR CON GAS			<i>100</i> 120.00
	REMOVE & REINSTALL ROOF LINING, HANDLE, ROOM LAMP, SUN VISOR			<i>60</i> 80.00
	REMOVE & REINSTALL REAR SEAT, REAR SPEAKER BOARD, UPHOLSTERY, SIDE GARNISHES			<i>80</i> 160.00
	REMOVE & REINSTALL PETROL TANK, PIPE, HOSE			80.00 <i>60</i>
	REMOVE & REINSTALL LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING			<i>40</i> 60.00
	REMOVE & REINSTALL REAR AXLE, REAR UNDERCARRIAGE SUSPENSION			<i>150</i> 250.00
	REMOVE & REINSTALL DOOR INNER TRIM AND CHECK LOCKING SYSTEM			50.00
	REMOVE & REINSTALL WIRE HARNESS, FUSE BOX ASSY AND CHECK START			<i>100</i> 200.00
	TO APPLY SEAL ON WELDING JOINTS			<i>150</i> 200.00
	REMOVE & REFIT REVERSE SENSOR AND CHECK			

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- **XA017**

Page # :- 1 134506

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Move Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088664-2

No.	Description	Qty	U.Price	Amounts S\$
	FUNCTION			60.00
	DIAGNOSE AND CHECK SYSTEM AFTER REPAIR	100	180.00	180.00
	CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE	200	300.00	300.00
	COMPUTER WHEEL ALIGNMENT			60.00
	RUST PROOF AFFECTED AREAS	100	160.00	160.00
	LABOUR TOTAL S\$			8,500.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 36,124.04

GST @ 7 % 2,528.68

AMOUNT DUE S\$ 38,652.72

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Rasul
Hp 90010068
32 days
4/5
03/04/19 @ 1400 hrs
Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bulit Merah Lane 3,
#01-04/08/09/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-008864-2

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	RADIATOR GRILLE <i>CR</i>	1	PC 564.20	564.20
2.	RADIATOR GRILLE TOP RUBBER <i>no</i>	1	PC 160.10	160.10
3.	RADIATOR GRILLE LOGO <i>no</i>	1	PC 48.00	48.00
4.	HEADLAMP ASSY RH & LH <i>BR</i>	2	PCS 2,795.00	5,590.00
5.	HEADLAMP LOWER BRACKET LH <i>CR</i>	1	PC 70.80	70.80
6.	FRONT BUMPER <i>TORE</i>	1	PC 458.90	458.90
7.	FRONT BUMPER SPONGE <i>cut</i>	1	PC 78.80	78.80
8.	FRONT BUMPER REINFORCEMENT <i>X</i>	1	PC 382.70	382.70
9.	FRONT BUMPER RETAINER RH & LH <i>no</i>	2	PCS 81.70	163.40
10.	FRONT BUMPER LOWER GRILLE - CENTER <i>?</i>	1	PC 155.00	155.00
11.	FRONT BUMPER CLIPS <i>no</i>	10	PCS 5.00	50.00
12.	FOG LAMP ASSY LH - CHECK <i>?</i>	1	PC	
13.	FOG LAMP GARNISH LH <i>SCR</i>	1	PC 91.90	91.90
14.	SUPPORT PANEL <i>BA</i>	1	PC 989.50	989.50
15.	BRACE PANEL <i>X</i>	1	PC 155.00	155.00
16.	AIR CON CONDENSER - CHECK	1	PC	
17.	RADIATOR ASSY - CHECK	1	PC	
18.	RADIATOR TOP BRACKET - CHECK	1	PC	
19.	AIR CLEANER DUCT <i>CR</i>	1	PC 171.00	171.00
20.	AIR CLEANER RESONATOR <i>CR</i>	1	PC 103.40	103.40
21.	FUSE BOX BASE <i>?</i>	1	PC 111.70	111.70
22.	FRONT WIRE HARNESS - CHECK	1	SET	
23.	FUSE BOX CENTER <i>?</i>	1	PC 209.10	209.10
24.	FRONT FENDER LH <i>no</i>	1	PC 781.20	781.20
25.	FRONT FENDER INNER PANEL LH <i>repair</i>	1	PC 423.20	423.20
26.	FRONT FENDER COWLING LH <i>MS</i>	1	PC 200.90	200.90
27.	FRONT FENDER COWLING CLIPS <i>no</i>	10	PCS 5.00	50.00
28.	FRONT FENDER EMBLEM - DUAL VVT <i>no</i>	1	PC 40.00	40.00
29.	FRONT FENDER PROTECTOR LH - CHECK	1	PC	
30.	FRONT FENDER CORNER GARNISH LH <i>?</i>	1	PC 35.00	35.00
31.	REAR DOOR RH <i>repair</i>	1	PC 1,100.00	1,100.00
32.	REAR DOOR TRIM BOARD RH - CHECK	1	PC	
33.	REAR DOOR STICKER RH <i>X</i>	1	SET 40.00	40.00
34.	REAR DOOR LOCK RH <i>X</i>	1	PC 576.50	576.50
35.	REAR DOOR LOCK STRICKER RH <i>X</i>	1	PC 25.00	25.00
36.	ROOF SIDE PANEL RH <i>BT</i>	1	PC 333.00	333.00
37.	ROOF PANEL (REPAIR)	1	PC	
38.	ROOF LINING - CHECK	1	PC	
39.	REAR WINDSCREEN GLASS <i>no</i>	1	PC 741.90	741.90
40.	REAR WINDSCREEN GLASS MOULDING <i>no</i>	1	SET 95.00	95.00
41.	REAR FENDER RH & LH <i>no</i>	2	PCS 986.80	1,973.60
42.	REAR FENDER COWLING RH & LH <i>no</i>	2	PCS 45.00	90.00
43.	REAR FENDER AIR DUCT RH & LH <i>no</i>	2	PCS 140.00	280.00
44.	REAR FENDER INNER PANEL RH <i>no</i>	1	PC 395.70	395.70
45.	REAR FENDER INNER TRIM COVER RH <i>no</i>	1	PC 759.00	759.00
46.	REAR FENDER INNER TRIM TOP GARNISH RH & LH <i>no</i>	2	PCS	441.90
47.	REAR SPEAKER BOARD <i>no</i>	1	PC 607.00	607.00
48.	REAR SPEAKER PANEL <i>no</i>	1	PC 1,047.30	1,047.30
49.	REAR WHEEL HOUSING RH <i>no</i>	1	PC 339.70	339.70
50.	REAR MUDFLAP RH <i>no</i>	1	PC 111.70	111.70
51.	REAR CHASSIS MEMBER RH <i>BT</i>	1	PC 876.40	876.40

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/08/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088884-2

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 134506

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
52.	BOOT LID <i>BT</i>	1 PC	755.00	755.00
53.	BOOT LID HINGE RH & LH <i>BT</i>	2 PCS	68.00	136.00
54.	BOOT LID INNER TRIM <i>DE</i>	1 PC	515.00	515.00
55.	BOOT LID LOGO <i>nee</i>	1 PC	48.00	48.00
56.	BOOT LID EMBLEM - COROLLA <i>nee</i>	1 PC	49.00	49.00
57.	BOOT LID EMBLEM - ALTIS <i>nee</i>	1 PC	45.00	45.00
58.	BOOT LID CHROME MOULDING <i>CA</i>	1 PC	233.70	233.70
59.	BOOT LID REFLECTOR RH & LH <i>Bao</i>	2 PCS	355.00	710.00
60.	BOOT LID LOCK <i>BT</i>	1 PC	382.50	382.50
61.	BOOT LID LOCK STRIKER <i>BT</i>	1 PC	30.00	30.00
62.	BOOT LID WEATHERSTRIP <i>cut</i>	1 PC	185.00	185.00
63.	REAR NUMBER PLATE LAMP	1 PC	55.00	55.00
64.	TAIL LAMP PANEL RH & LH - <i>LH-repair/RH-nee</i>	2 PCS	115.00	230.00
65.	TAIL LAMP ASSY RH & LH <i>Bao</i>	2 PCS	395.00	790.00
66.	TAIL LAMP CLIPS <i>nee</i>	4 PCS	10.00	40.00
67.	TAIL LAMP LOWER BRACKET RH & LH - <i>LH-X/RH-CA</i>	2 PCS	40.00	80.00
68.	REAR BUMPER <i>TORN</i>	1 PC	486.00	486.00
69.	REAR BUMPER SPONGE <i>X</i>	1 PC	395.00	395.00
70.	REAR BUMPER RETAINER RH & LH <i>nee</i>	2 PCS	120.00	240.00
71.	REAR BUMPER REFLECTOR RH <i>Bao</i>	1 PC	58.00	58.00
72.	REAR BUMPER CLIPS <i>nee</i>	10 PCS	5.00	50.00
73.	REAR END PANEL <i>nee</i>	1 PC	590.00	590.00
74.	REAR END PANEL TOP COVER <i>DE</i>	1 PC	285.00	285.00
75.	SPARE TYRE BOARD <i>DE</i>	1 PC	295.00	295.00
76.	SPARE WHEEL PANEL <i>nee</i>	1 PC	797.00	797.00
77.	SPARE TYRE SPONGE	1 PC	333.10	333.10
78.	SPARE TYRE SPONGE RH & LH	2 PCS	179.10	358.20
79.	SPARE TYRE BOARD RH & LH - CHECK	2 PCS		
80.	SPARE WHEEL PANEL INSULATOR	1 PC	300.85	300.85
81.	REAR SPORT RIM RH <i>BT</i>	1 PC	1,645.10	1,645.10
82.	REAR WHEEL BEARING RH <i>nee</i>	1 PC	670.00	670.00
83.	REAR SHOCK ABSORBER RH	1 PC	200.00	200.00
84.	REAR AXLE	1 PC	2,850.00	2,850.00
85.	PETROL TANK - CHECK	1 PC		
86.	REAR EXHAUST SILENCER <i>BT</i>	1 PC	939.00	939.00
87.	REAR EXHAUST HEAT COVER <i>BT</i>	1 PC	165.00	165.00
88.	REAR EXHAUST MOUNTINGS <i>nee</i>	3 PCS	41.70	125.10
89.	CENTER EXHAUST PIPE - CHECK	1 PC		
90.	REAR SEAT REST RH - CHECK	1 PC		
91.	REAR SEAT ASSY - CHECK	1 PC		
92.	REAR CHASSIS MEMBER LH (REPAIR)	1 PC		
93.	REAR SEAT BELT RH - CHECK	1 PC		
LIST TOTAL S\$				31136.70 35,992.05
25% DISCOUNT S\$				7784.18 -8,998.01
				<u>23350.00</u> 26,994.04

SPECIAL NET ITEMS :

1.	REAR WINDSCREEN GLASS SEALANT <i>nee</i>	1 PC	40.00	40.00
2.	REAR NUMBER PLATE <i>BT</i>	1 PC	40.00	40.00
3.	REVERSE SENSOR <i>nee</i>	1 SET	300.00	220 300.00

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/05/06/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1 134506
Veh # :- SJK6098C
Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT
Estimate# :- CK418959
Claim # :-
ACC. Date :- 30/03/19
Terms :- C.O.D Days
Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
4.	REAR TYRE RH <i>punctured</i>	1 PC	250.00	250.00 700
	SPECIAL NET TOTAL S\$			630.00 475.00
	LABOUR :			
	TOWING CHARGE WITH INVOICE			240.00 receipt ?
	TO CUT/WELD SUPPORT PANEL, FRONT FENDER INNER PANEL LH, REAR FENDER RH & LH, REAR FENDER INNER PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER LH, REAR SEAT PANEL, CENTER PILLAR RH, ROOF PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION.			3,800.00 3600
	SPRAY PAINT FRONT BUMPER, SUPPORT PANEL, FRONT FENDERS RH & LH, FRONT FENDER INNER PANEL LH, FRONT DOOR RH, CENTER PILLAR RH, ROOF PANEL, ROOF SIDE PANEL RH, REAR DOOR RH, REAR FENDERS RH & LH, REAR FENDER INNER PANEL RH, REAR SPEAKER PANEL, REAR SEAT PANEL, SPARE WHEEL PANEL, REAR CHASSIS MEMBERS, BOOT LID, REAR END PANEL, TAIL LAMP PANELS, REAR BUMPER (PEARL)			2,500.00
	REMOVE & REINSTALL AIR CON CONDENSER, PIPE, HOSE AND RECHARGE AIR CON GAS			120.00 100
	REMOVE & REINSTALL ROOF LINING, HANDLE, ROOM LAMP, SUN VISOR			80.00 60
	REMOVE & REINSTALL REAR SEAT, REAR SPEAKER BOARD, UPHOLSTERY, SIDE GARNISHES			160.00 80
	REMOVE & REINSTALL PETROL TANK, PIPE, HOSE			80.00 60
	REMOVE & REINSTALL LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING			80.00 40
	REMOVE & REINSTALL REAR AXLE, REAR UNDERCARRIAGE SUSPENSION			250.00 150
	REMOVE & REINSTALL DOOR INNER TRIM AND CHECK LOCKING SYSTEM			50.00
	REMOVE & REINSTALL WIRE HARNESS, FUSE BOX ASSY AND CHECK START			200.00 100
	TO APPLY SEAL ON WELDING JOINTS			280.00 150
	REMOVE & REFIT REVERSE SENSOR AND CHECK			

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Buildit Merah Lane 3,
#01-04/05/06/07/08/09
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

02/04/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 134506

Veh # :- SJK6098C

Veh Model :- TOYOTA COROLLA ALTIS 1.6 CVT

Estimate# :- CK418959

Claim # :-

ACC. Date :- 30/03/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	FUNCTION			60.00
	DIAGNOSE AND CHECK SYSTEM AFTER REPAIR	1) PARTS 23350.50 2) WARE 4750.00 3) LABOUR 7650.00	100	180.00
	CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE	31471.50 - 6285.50 less 20%	200	300.00
	COMPUTER WHEEL ALIGNMENT	25125.00	100	60.00
	RUST PROOF AFFECTED AREAS			160.00
	LABOUR TOTAL S\$		7650.00	8,500.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 36,124.04

GST @ 7 % 2,528.68

AMOUNT DUE S\$ 38,652.72

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Rasul
Hp 96010068
32 days
4/8
03/04/19 @ 1400 hrs
Resurvey after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No. 13120344K

NO. 27277

Date: 30/3/19

CASH SALE / JOB ORDER

Messrs: CASH
车牌: SKJ 6098C 车型: TOYOTA
Vehicle No: SKJ 6098C Model No: TOYOTA
时间 (日/夜): DAY 联络号码: 91526858
Time (day/night): DAY Contact No: 91526858
由: madai rd
Location: madai rd
到: 2 pandan crescent
To: 2 pandan crescent
根額: \$240 - 其他: Others:
Cash S: \$240 - Others: Others:
经手人: AH Di Tow Truck: Alvin
Authorised By: AH Di Driver Name: Alvin

- ☐ Jump Start Changing of battery
- ☐ Tyre Replacement
- ☒ Accidents Breakdown
- ☐ Multi Basement
- ☐ With Load Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Reps
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对拖运之车辆, 在拖运中如有任何损坏或延误,
一概由车主自行承担。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility
for damages or other misadventure to your vehicle whilst being towed.

E. & O. E.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005878/R1VD3N2

Date: 24/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18170318000
Claimant Vehicle No :	SJK6098C	Insured Vehicle No :	GBH4426M
Date of Loss:	30/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201415C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK6098C	Engine No:	1ZRY339344
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104560117
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,624.04	21,825.66	5,798.38	20.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,500.00	7,650.00	850.00	10.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,124.04	29,475.66	6,648.38	18.40
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	36,124.04	18,000.00	18,124.04	50.17
+ GST 7.00/7.00% (S\$)	2,528.68	1,260.00	1,268.68	50.17
Nett Amount (S\$)	38,652.72	19,260.00	19,392.72	50.17

INSPECTION

Date of Assignment:	03/04/2019	
Date Inspected:	03/04/2019 Inspected At:	Mova Automotive Pte Ltd (FAN YOONG BRANCH) 15 Fan Yoong Road, CNG Singapore Centre Singapore 629792
Estimated Period of Repair:	32.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK6098C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	564.20 FL	*564.20 FL
2	1		*RADIATOR GRILLE TOP RUBBER	Necessary	160.10 FL	*160.10 FL
3	1		*RADIATOR GRILLE LOGO	Necessary	48.00 FL	*48.00 FL
4	2		*HEADLAMP ASSY RH & LH	Broken	5,590.00 FL	*5,590.00 FL
5	1		*HEADLAMP LOWER BRACKET LH	Cracked	78.80 FL	*78.80 FL
6	1		*FRONT BUMPER	Torn	458.90 FL	*458.90 FL
7	1		*FRONT BUMPER SPONGE	Cut	78.80 FL	*78.80 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	382.70 FL	*- FL
9	2		*FRONT BUMPER RETAINER RH & LH	Necessary	163.40 FL	*163.40 FL
10	1		*FRONT BUMPER LOWER GRILLE-CENTER	Serviceable	155.00 FL	*- FL
11	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
12	1		*FOG LAMP ASSY LH (NPA)	Serviceable	0.00 FL	*- FL
13	1		*FOG LAMP GARNISH LH	Scratched	91.90 FL	*91.90 FL
14	1		*SUPPORT PANEL	Bent	989.50 FL	*989.50 FL
15	1		*BRACE PANEL	Serviceable	155.00 FL	*- FL
16	1		*AIR CON CONDENSER (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*RADIATOR ASSY (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*RADIATOR TOP BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*AIR CLEANER DUCT	Cracked	171.00 FL	*171.00 FL
20	1		*AIR CLEANER RESONATOR	Cracked	103.40 FL	*103.40 FL
21	1		*FUSE BOX BASE	Serviceable	111.70 FL	*- FL
22	1		*SET FRONT WIRE HARNESS (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*FUSE BOX CENTER	Serviceable	209.10 FL	*- FL
24	1		*FRONT FENDER LH	Buckled	781.20 FL	*781.20 FL
25	1		*FRONT FENDER INNER PANEL LH	Repair	423.20 FL	*- FL
26	1		*FRONT FENDER COWLING LH	Missing	200.90 FL	*200.90 FL
27	10		*FRONT FENDER COWLING CLIPS	Necessary	50.00 FL	*50.00 FL
28	1		*FRONT FENDER EMBLEM-DUAL VVTI	Necessary	40.00 FL	*40.00 FL
29	1		*FRONT FENDER PROTECTOR LH (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*FRONT FENDER CORNER GARNISH LH	Cracked	35.00 FL	*35.00 FL
31	1		*REAR DOOR LH	Repair	1,100.00 FL	*- FL
32	1		*REAR DOOR TRIM BOARD RH (NPA)	Not Necessary	0.00 FL	*- FL
33	1		*SET REAR DOOR STICKER RH	Serviceable	40.00 FL	*- FL
34	1		*REAR DOOR LOCK RH	Serviceable	576.50 FL	*- FL
35	1		*REAR DOOR LOCK STRICKER RH	Serviceable	25.00 FL	*- FL
36	1		*ROOF SIDE PANEL RH	Bent	333.00 FL	*333.00 FL
37	1		*ROOF PANEL (NPA)	Repair	0.00 FL	*- FL
38	1		*ROOF LINING (NPA)	Not Necessary	0.00 FL	*- FL
39	1		*REAR WINDSCREEN GLASS	Broken	741.90 FL	*741.90 FL
40	1		*SET REAR WINDSCREEN GLASS MOULDING	Necessary	95.00 FL	*95.00 FL
41	2		*REAR FENDER RH & LH	Buckled	1,973.60 FL	*1,973.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	2		*REAR FENDER COWLING RH & LH	N/s Cracked/O/s Deformed	90.00 FL	*90.00 FL
43	2		*REAR FENDER AIR DUCT RH & LH	Deformed	280.00 FL	*280.00 FL
44	1		*REAR FENDER INNER PANEL RH	Buckled	395.70 FL	*395.70 FL
45	1		*REAR FENDER INNER TRIM COVER RH	Deformed	759.00 FL	*759.00 FL
46	2		*REAR FENDER INNER TRIM TOP GARNISH RH & LH	Deformed	441.90 FL	*441.90 FL
47	1		*REAR SPEAKER BOARD	Deformed	607.00 FL	*607.00 FL
48	1		*REAR SPEAKER PANEL	Deformed	1,047.30 FL	*1,047.30 FL
49	1		*REAR WHEEL HOUSING RH	Buckled	339.70 FL	*339.70 FL
50	1		*REAR MUDFLAP RH	Deformed	111.70 FL	*111.70 FL
51	1		*REAR CHASSIS MEMBER RH	Bent	876.40 FL	*876.40 FL
52	1		*BOOT LID	Bent	755.00 FL	*755.00 FL
53	2		*BOOT LID HINGE RH & LH	Bent	136.00 FL	*136.00 FL
54	1		*BOOT LID INNER TRIM	Deformed	515.00 FL	*515.00 FL
55	1		*BOOT LID LOGO	Necessary	48.00 FL	*48.00 FL
56	1		*BOOT LID EMBLEM-COROLLA	Necessary	49.00 FL	*49.00 FL
57	1		*BOOT LID EMBLEM-ALTIS	Necessary	45.00 FL	*45.00 FL
58	1		*BOOT LID CHROME MOULDING	Cracked	233.70 FL	*233.70 FL
59	2		*BOOT LID REFLECTOR RH & LH	Broken	710.00 FL	*710.00 FL
60	1		*BOOT LID LOCK	Bent	382.50 FL	*382.50 FL
61	1		*BOOT LID LOCK STRIKER	Bent	30.00 FL	*30.00 FL
62	1		*BOOT LID WEATHERSTRIP	Cut	185.00 FL	*185.00 FL
63	1		*REAR NUMBER PLATE LAMP	Serviceable	55.00 FL	*. FL
64	1		*TAIL LAMP PANEL RH & LH	O/s Buckled/N/s Repair	230.00 FL	*115.00 FL
65	2		*TAIL LAMP ASSY RH & LH	Broken	790.00 FL	*790.00 FL
66	4		*TAIL LAMP CLIPS	Necessary	40.00 FL	*40.00 FL
67	1		*TAIL LAMP LOWER BRACKET RH & LH	O/s Cracked/N/s Not Necessary	80.00 FL	*40.00 FL
68	1		*REAR BUMPER	Torn	486.00 FL	*486.00 FL
69	1		*REAR BUMPER SPONGE	Not Necessary	395.00 FL	*. FL
70	2		*REAR BUMPER RETAINER RH & LH	Necessary	240.00 FL	*240.00 FL
71	1		*REAR BUMPER REFLECTOR RH	Broken	58.00 FL	*58.00 FL
72	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
73	1		*REAR END PANEL	Buckled	590.00 FL	*590.00 FL
74	1		*REAR END PANEL TOP COVER	Deformed	285.00 FL	*285.00 FL
75	1		*SPARE TYRE BOARD	Deformed	295.00 FL	*295.00 FL
76	1		*SPARE WHEEL PANEL	Buckled	797.00 FL	*797.00 FL
77	1		*SPARE TYRE SPONGE	Not Necessary	333.10 FL	*. FL
78	2		*SPARE TYRE SPONGE RH & LH	Not Necessary	358.20 FL	*. FL
79	2		*SPARE TYRE BOARD RH & LH (NPA)	Not Necessary	-	*. FL
80	1		*SPARE WHEEL PANEL INSULATOR	Necessary	300.85 FL	*300.85 FL
81	1		*REAR SPORT RIM RH	Bent	1,645.10 FL	*1,645.10 FL
82	1		*REAR WHEEL BEARING RH	Necessary	670.00 FL	*670.00 FL
83	1		*REAR SHOCK ABSORBER RH	Serviceable	200.00 FL	*. FL
84	1		*REAR AXLE	Serviceable	2,850.00 FL	*. FL
85	1		*PETROL TANK (NPA)	Serviceable	0.00 FL	*. FL
86	1		*REAR EXHAUST SILENCER	Bent	939.00 FL	*939.00 FL
87	1		*REAR EXHAUST HEAT COVER	Bent	165.00 FL	*165.00 FL
88	3		*REAR EXHAUST MOUNTINGS	Necessary	125.10 FL	*125.10 FL
89	1		*CENTER EXHAUST PIPE (NPA)	Serviceable	0.00 FL	*. FL
90	1		*REAR SEAT REST RH (NPA)	Serviceable	0.00 FL	*. FL
91	1		*REAR SEAT ASSY (NPA)	Serviceable	0.00 FL	*. FL
92	1		*REAR CHASSIS MEMBER LH (NPA)	Repair	0.00 FL	*. FL
93	1		*REAR SEAT BELT RH (NPA)	Serviceable	0.00 FL	*. FL
94	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
95	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	1		*SET REVERSE SENSOR	Not Working	300.00 FS	*220.00 FS
97	1		*REAR TYRE RH (70%)	Punctured	250.00 FS	*175.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					36,622.05	28,942.55
- List Item Discount on L Items 25.00/25.00% (S\$)					8,998.01	7,116.89
Total Parts (S\$)					27,624.04	21,825.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE WITH INVOICE	New	240.00	240.00
2	TO CUT/WELD SUPPORT PANEL,FRONT FENDER INNER PANEL LH,REAR FENDER RH & LH,REAR FENDER INNER PANEL,KNOCK AND STRAIGHTEN REAR CHASSIS MEMBER LH,REAR SEAT PANEL,CENTER PILLAR RH,ROOF PANEL,REMOVE AND REPLACE ACCIDENT DAMAGED PARTS,REALIGN ALL CONNECTION	New	3,800.00	3,600.00
3	SPRAY PAINT FRONT BUMPER,SUPPORT PANEL,FRONT FENDERS RH & LH.FRONT FENDER INNER PANEL LH,FRONT DOOR RH.CENTER PILLAR RH,ROOF PANEL,ROOF SIDE PANEL RH,REAR DOOR RH,REAR FENDERS RH & LH,REAR FENDER INNER PANEL RH,REAR SPEAKER PANEL,REAR SEAT PANEL,SPARE WHEEL PANEL,REAR CHASSIS MEMBERS,BOOT LID,REAR END PANEL,TAIL LAMP PANELS,REAR BUMPER (PEARL)	New	2,500.00	2,500.00
4	REMOVE & REINSTALL AIR CON CONDENSER PIPE,HOSE AND RECHARGE AIR CON GAS	New	120.00	100.00
5	REMOVE & REINSTALL ROOF LINING,HANDLE,ROOM LAMP,SUN VISOR	New	80.00	60.00
6	REMOVE & REINSTALL REAR SEAT,REAR SPEAKER BOARD,UPHOLSTERY,SIDE GARNISHES	New	160.00	80.00
7	REMOVE & REINSTALL PETROL TANK,PIPE,HOSE	New	80.00	60.00
8	REMOVE & REINSTALL LUGGAGE COMPARTMENT INNER TRIM GARNISH,COVERING	New	60.00	40.00
9	REMOVE & REINSTALL REAR AXLE,REAR UNDERCARRIAGE SUSPENSION	New	250.00	150.00
10	REMOVE & REINSTALL DOOR INNER TRIM AND CHECK LOCKING SYSTEM	New	50.00	50.00
11	REMOVE & REINSTALL WIRE HARNESS,FUSE BOX ASSY AND CHECK START	New	200.00	100.00
12	TO APPLY SEAL ON WELDING JOINTS	New	200.00	150.00
13	REMOVE & REFIT REVERSE SENSOR AND CHECK FUNCTION	New	60.00	60.00
14	DIAGNOSE AND CHECK SYSTEM AFTER REPAIR	New	180.00	100.00
15	CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE	New	300.00	200.00
16	COMPUTER WHEEL ALIGNMENT	New	60.00	60.00
17	RUST PROOF AFFECTED AREAS	New	160.00	100.00
Gross Labour Cost (S\$)			8,500.00	7,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >