

RALLY PITSTOP

176 Sin Ming Drive
 #04-17 Sin Ming Autocare
 Singapore 575721
 Tel: 64516985
 Email: tar6985@hotmail.com

Not withonk
11 Sep @ 7
Resurvey After Paint
4-5 days

Date: 03-04-2019

To: Motor Claims Department

RE: Estimate repair cost of SKJ7171K

Your Insured: SKQ7808X

Dear Sir/Madam,
 Vehicle No: SKJ7171K
 Make Model: Audi A6
 Date of accident: 01-04-2019

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Rear bumper		<i>em</i> 1452.98 ✓
2	Rear bumper sensor	258.30	516.60 ✓
1	Rear bumper lower diffusion		438.20 ✓
1	Rear end panel		678.40 ✓
1	Rear reinforcement		548.10 ✓
1	Rear bumper sponge		238.10 ✓
1	Bootlid		<i>R</i> 1645.10 ✓
1	Weather stripe		<i>R</i> 258.10 X
	Sub-total before discount		5775.58
	Parts percentage discount 10%		577.56
	PARTS TOTAL		5198.02
	LABOUR CHARGES & MISC		
1	Labour to dismantle, panel beat, repair & replace rear bumper, rear reinforcement and all necessary parts		1000.00 ?
2	To putty and spray paint the accident damaged parts		800.00 600
3	To check wiring		50.00 200
	LABOUR TOTAL		1850.00
	LABOUR & PARTS TOTAL		7048.02

Regards,
 Terrence Lim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: