

(SIN 2010)

INS. CASE OWNER:

Dng 111

CC4 / LPC1900

5882, U^{KAB} 1/1/12

LKK:

IDAC:

Surveyor:

Marus

DOI:

ASSIGNMENT

4/4/2019

Date / Time:

2/4/19

Registered in Merimen:

Pre-assign / CCU / FTE

YN 2109m

Claim No.:

18/19/19/20001612

Policy No.:

218/1600 (1.663)

Make / Model:

Isuzu

Place of Accident:

UTE



Insured Vehicle No.:

T10MB U1M P000 BU

Name of Insured:

Insured Tel No.:

HP:

1/4/19

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

N. Khammyan

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SL 4169 R

INSRS:
WSP:
Tel:
Liability:
RMKS:

specialist.

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

SL 4169 R - f

YN 2109m - 18/19/19/20001612

Front to rear collision.

email liability clear

file pass to type mandate report

LOD

6/1/2020
Khammyan

File pass to mk to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

5/4/2019

Sent By:

LSP

Confirm with:

Confirm by:

Email ☐ Call ☐

FINALIZATION

Date/Time:

SS 16,611.04

(10 days) Reduction:

48%

Repair Cost:

PIP

FINAL SETTLEMENT

Date/Time:

13/12/19

Confirm with:

Karen

Email ☒ Call ☐

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

CU/687

SS 17,773.81

Loss of Rental (LOR):

SS 1,560

(13 days) X \$120

Loss of Use (LOU):

SS

(S - x - days)

Loss of Income (LOI):

SS

(S - x - days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow / Independent)

Legal Cost:

SS

Total:

SS 19,335.81

Global Sum SS:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

19,335.81

Confirm with:

SPECIALISTS MOTOR PTE LTD

Payee 1:

SS

Name 1:

SPECIALISTS MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$450

COPY SENT

(08/11/13) wef

REF:

ASS. REC. BY: *MCW*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

102

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLL4169R

Yr Regn:

2, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Subaru forester

C.C

1995

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

096326

T/Radio: Insured / Std / NI / NA

Eng/No:

JF15J5KCS66083764

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

1/4/19

D.O.I.

4/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear / A.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A 49803

(p/p 16,611.04 / Red \$14,040.58 / 46%)

(10 days + 2 Sunday + 1 PRS = 13 days)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19005882/Ufb3

Date: 05.04.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLL4169R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.04.2019 at the premises of M/s Specialists Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	30,297.32
Revised Estimate Amount	: S\$	16,633.50
"Check" Items Amount	: S\$	8,170.82
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 10 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

02nd April 2019

The Manager
Motor Claim Department
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

Date of Accident : 01st April 2019
Location : CTE Towards Bukit Timah Exit
Third Party Claim Vehicle No : YN 2109 M
Repair Cost For Vehicle No : SLL 4169 R Subaru Forester

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bonnet	202 1	882.40	\$ 882.40 ✓
2	Front bonnet hinge L&RH	2	48.30	\$ 96.60 X
3	Front bonnet insulation shield clips	scr 1 set	35.00	\$ 35.00 ✓
4	Front grille (top)	1	208.40	\$ 208.40 ✓
5	Front grille (bottom)	1	316.40	\$ 316.40 ✓
6	Front grille clips	1 set	35.00	\$ 35.00 ✓
7	Headlamp assy L&RH	holder 2	2,380.00	\$ 4,760.00 ✓
8	Headlamp lower bracket L&RH	2	49.30	\$ 98.60 ✓
9	Front bumper fascia	1	594.20	\$ 594.20 ✓
10	Front bumper clips	1	35.00	\$ 35.00 ✓
11	Front bumper towing cover	1	14.30	\$ 14.30 ✓
12	Front bumper reinforcement (outer)	1	140.30	\$ 140.30 ✓
13	Front bumper reinforcement	1	288.30	\$ 288.30 ✓
14	Front bumper side retainer L&RH	2	26.50	\$ 53.00 ✓
15	Front bumper fog lamp cover L&RH	2	79.20	\$ 158.40 X
16	Front bumper fog lamp assy L&RH	2	272.40	\$ 544.80 X
17	Headlamp nozzle cover L&RH	2	69.20	\$ 138.40 X
18	Headlamp nozzle pump assy L&RH	2	102.90	\$ 205.80 X
19	Front support panel	1	400.70	\$ 400.70 ✓
20	Front support bracket	1	72.90	\$ 72.90 X
21	Front support bracket clips	1 set	35.00	\$ 35.00 ✓
22	Radiator assy	1	792.80	\$ 792.80 X
23	Air con condenser	1	680.20	\$ 680.20 ✓
				\$10,586.50

Not Allowed
for
the party.
The party.
10 dy.

8576.80

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

02nd April 2019

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$10,586.50
24	Air filter air duct	11 1	231.10	\$ 231.10 X
25	Air filter air duct clips	1set	35.00	\$ 35.00
26	Front fender L&RH	0/5R 1/5RD 34C 2	300.60	\$ 601.20 PC
27	Front fender cowling L&RH	11 2	96.30	\$ 192.60 X
28	Front fender cowling clips L&RH	11 1set	35.00	\$ 35.00 X
29	Front fender side shield L&RH	11 2	25.00	\$ 50.00 X
30	Front fender side shield clips L&RH	11 2	30.00	\$ 60.00 X
31	Rear boot cover	30 1/5RD 1	1,072.90	\$ 1,072.90
32	Rear boot cover emblem (logo)	11 1	88.30	\$ 88.30
33	Rear boot cover emblem (Subaru)	11 1	72.30	\$ 72.30
34	Rear boot cover emblem (Forester)	11 1	72.30	\$ 72.30
35	Rear boot w/strip	11 1	120.80	\$ 120.80
36	Rear boot cover lock	11 1	176.40	\$ 176.40
37	Rear boot cover latch	11 1	38.92	\$ 38.92
38	Rear windscreen glass	11 1	888.20	\$ 888.20
39	Rear windscreen moulding	11 1	64.20	\$ 64.20
40	Rear no plate lamp	11 2	38.20	\$ 76.40
41	Rear no plate lamp garnish	11 1	160.40	\$ 160.40
42	Rear wiper blade	11 1	36.30	\$ 36.30
43	Rear wiper arm	11 1	63.20	\$ 63.20
44	Rear wiper motor assy	11 1	424.80	\$ 424.80
45	Rear boot cover inner board L&RH (top)	11 2	65.30	\$ 130.60
46	Rear boot cover inner board (centre)	11 1	264.20	\$ 264.20
47	Rear lamp assy L&RH	11 2	432.90	\$ 865.80
48	Rear end panel	11 1	288.30	\$ 288.30
49	Rear boot floor panel	11 1	432.40	\$ 432.40
50	Rear boot floor inner tray	11 1	100.80	\$ 100.80
51	Rear bumper fascia	11 1	600.40	\$ 600.40
52	Rear bumper clips	11 1set	55.00	\$ 55.00
53	Rear bumper reinforcement	11 1	420.40	\$ 420.40
54	Rear bumper towing cover	11 1	28.40	\$ 28.40
55	Rear bumper reflector L&RH	11 2	25.40	\$ 50.80 PC
56	Rear bumper bracket L&RH	11 2	20.30	\$ 40.60
57	Rear bumper side retainer L&RH	11 2	28.20	\$ 56.40
58	Rear exhaust silencer assy	11 1	668.20	\$ 668.20 X
59	Rear reverse camera	11 1	560.20	\$ 560.20 X
				\$19,709.32

2070

13374.50

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

02nd April 2019

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$19,709.32
60	Radiator coolant (s/net)	1	28.00	\$ 28.00
61	Front number plate (s/net)	1	50.00	\$ 50.00
62	Rear windscreen sealant (s/net)	1	60.00	\$ 60.00
63	Rear end panel sealer (s/net)	1	80.00	\$ 80.00
64	Rear bumper sensor (s/net)	1	380.00	\$ 380.00
65	Rear number plate (s/net)	1	50.00	\$ 50.00
66	Blackvue camera (s/net)	1	790.00	\$ 790.00
67	Rear windscreen solar film (s/net)	1	280.00	\$ 280.00
				<u>\$21,427.32</u>

Labour Charges :-

Towing fee	\$ 200.00
Cut out, renew, knocking & welding front bonnet, front fender L&RH, front support panel, remove & install all damage parts, straighten front chassis & re-align body	\$ 1,880.00
Remove & install radiator assy, engine cooling system & conduct pressure test	\$ 120.00
Remove & install air con condenser, vacuum & top up gas	\$ 120.00
Tuff-kote on damage parts	\$ 120.00
Spray painting on front damage parts	\$ 1,580.00
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, remove & install rear damage parts, straighten & re-align body	\$ 2,180.00
Remove & install rear windscreen glass	\$ 140.00
Remove & install rear seats, carpets, upholstery & etc	\$ 280.00
Remove & refix rear bumper sensor	\$ 80.00
Remove & install rear exhaust silencer	\$ 100.00
Tuff-kote on rear damage parts	\$ 120.00
Spray painting on damage parts	\$ 1,890.00
Check all lighting after repairs	\$ 60.00

Labour Charge

Total Amount

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Acknowledged by Repairs

Signature:

\$ 8,870.00

\$30,297.32

4660

30651.62*

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

02nd April 2019

The Manager
Motor Claim Department
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

Date of Accident : 01st April 2019
Location : CTE Towards Bukit Timah Exit
Third Party Claim Vehicle No : YN 2109 M
Repair Cost For Vehicle No : SLL 4169 R Subaru Forester

Supplementary Supply of Parts

No.	Particulars	Qty	Price	Amounts
1	Tyre bracket	Bent 1	15.50	\$ 15.50
2	Tyre bolt	Bent 1	25.80	\$ 25.80
3	Front grille lower bracket	Bent 1	26.40	\$ 26.40
4	Rear end panel inner garnish	Dis 1	40.30	\$ 40.30
5	Rear boot no plate garnish	one 1	210.30	\$ 210.30
6	Rear boot garnish seal	rel 1	21.60	\$ 21.60
7	Cover rear bumper	Re 1	14.40	\$ 14.40
				<u>\$ 354.30</u>

GST will be reflected in the final bills.

P-13728.80
202
P-10983.04
S.V-968.00
labur-4660.00
\$ 16611.04

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

02nd April 2019

The Manager
Motor Claim Department
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

Date of Accident : 01st April 2019
Location : CTE Towards Bukit Timah Exit
Third Party Claim Vehicle No : YN 2109 M
Repair Cost For Vehicle No : SLL 4169 R Subaru Forester

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bonnet	1	882.40	\$ 882.40 ✓
2	Front bonnet hinge L&RH	2	48.30	\$ 96.60 X
3	Front bonnet insulation shield clips	1set	35.00	\$ 35.00 ✓
4	Front grille (top)	1	208.40	\$ 208.40 ✓
5	Front grille (bottom)	1	316.40	\$ 316.40 ✓
6	Front grille clips	1set	35.00	\$ 35.00 ✓
7	Headlamp assy L&RH	2	2,380.00	\$ 4,760.00 ✓
8	Headlamp lower bracket L&RH	2	49.30	\$ 98.60 ✓
9	Front bumper fascia	1	594.20	\$ 594.20 ✓
10	Front bumper clips	1	35.00	\$ 35.00 ✓
11	Front bumper towing cover	1	14.30	\$ 14.30 ✓
12	Front bumper reinforcement (outer)	1	140.30	\$ 140.30 ✓
13	Front bumper reinforcement	1	288.30	\$ 288.30 ✓
14	Front bumper side retainer L&RH	2	26.50	\$ 53.00 ✓
15	Front bumper fog lamp cover L&RH	2	79.20	\$ 158.40 X
16	Front bumper fog lamp assy L&RH	2	272.40	\$ 544.80 X
17	Headlamp nozzle cover L&RH	2	69.20	\$ 138.40 >
18	Headlamp nozzle pump assy L&RH	2	102.90	\$ 205.80 ?
19	Front support panel	1	400.70	\$ 400.70 ?
20	Front support bracket	1	72.90	\$ 72.90 ?
21	Front support bracket clips	1set	35.00	\$ 35.00 ✓
22	Radiator assy	1	792.80	\$ 792.80 ?
23	Air con condenser	1	680.20	\$ 680.20 ?
				\$10,586.50

Not Allowed
OK
#55 subo party.
Whaphb. #1709
6/4/9
P/P #
10 dy.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

02nd April 2019

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$10,586.50
		1	231.10	\$ 231.10 ?
24	Air filter air duct	1set	35.00	\$ 35.00 ✓
25	Air filter air duct clips	2	300.60	\$ 601.20 ✓
26	Front fender L&RH	2	96.30	\$ 192.60 X
27	Front fender cowling L&RH	1set	35.00	\$ 35.00 X
28	Front fender cowling clips L&RH	2	25.00	\$ 50.00 X
29	Front fender side shield L&RH	2	30.00	\$ 60.00 X
30	Front fender side shield clips L&RH	1	1,072.90	\$ 1,072.90 ✓
31	Rear boot cover	1	88.30	\$ 88.30 ✓
32	Rear boot cover emblem (logo)	1	72.30	\$ 72.30 ✓
33	Rear boot cover emblem (Subaru)	1	72.30	\$ 72.30 ✓
34	Rear boot cover emblem (Forester)	1	120.80	\$ 120.80 ?
35	Rear boot w/strip	1	176.40	\$ 176.40 ✓
36	Rear boot cover lock	1	38.92	\$ 38.92 ?
37	Rear boot cover latch	1	888.20	\$ 888.20 ✓
38	Rear windscreen glass	1	64.20	\$ 64.20 ✓
39	Rear windscreen moulding	2	38.20	\$ 76.40 ?
40	Rear no plate lamp	1	160.40	\$ 160.40 ?
41	Rear no plate lamp garnish	1	36.30	\$ 36.30 ?
42	Rear wiper blade	1	63.20	\$ 63.20 ?
43	Rear wiper arm	1	424.80	\$ 424.80 ?
44	Rear wiper motor assy	2	65.30	\$ 130.60 ✓
45	Rear boot cover inner board L&RH (top)	1	264.20	\$ 264.20 ?
46	Rear boot cover inner board (centre)	2	432.90	\$ 865.80 ?
47	Rear lamp assy L&RH	1	288.30	\$ 288.30 ?
48	Rear end panel	1	432.40	\$ 432.40 ?
49	Rear boot floor panel	1	100.80	\$ 100.80 ?
50	Rear boot floor inner tray	1	600.40	\$ 600.40 ✓
51	Rear bumper fascia	1set	55.00	\$ 55.00 ✓
52	Rear bumper clips	1	420.40	\$ 420.40 ?
53	Rear bumper reinforcement	1	28.40	\$ 28.40 ✓
54	Rear bumper towing cover	2	25.40	\$ 50.80 1pc
55	Rear bumper reflector L&RH	2	20.30	\$ 40.60 ✓
56	Rear bumper bracket L&RH	2	28.20	\$ 56.40 ✓
57	Rear bumper side retainer L&RH	1	668.20	\$ 668.20 X
58	Rear exhaust silencer assy	1	560.20	\$ 560.20 ?
59	Rear reverse camera			\$19,709.32

Bus. Reg No: 199502604 E GST No: 19-9502604-E

02nd April 2019

GST will be reflected in the final bills.
Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

\$30,297.32

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9924D

Vehicle Details

Vehicle No.: SLL4169R
Vehicle to be Exported: No
Intended Deregistration Date: 04 Apr 2019
Vehicle Make: SUBARU
Vehicle Model: FORESTER 2.0I-L CVT AWD SR
Primary Colour: Brown
Manufacturing Year: 2016
Engine No.: FB20Y549077
Chassis No.: JF1SJ5KC5GG083764
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$15,690.00
Original Registration Date: 24 Feb 2017
First Registration Date: 24 Feb 2017
Transfer Count: 0
Actual ARF Paid: \$15,690.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Feb 2027
PARF Rebate Amount: \$11,767.00

Intended COE Rebate Details

COE Expiry Date: 23 Feb 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$48,209.00
COE Rebate Amount: \$38,036.00
Total Rebate Amount: \$49,803.00

The information contained herein is correct as at 04 Apr 2019

OK

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.88% P.A Low Interest@Gv
Finance. 2 Years Warranty.
\$3800 Down Monthly From \$738
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Subaru Forester

Advanced Search Submit

<

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Compare

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 3 April 2019 9:45 AM
To: cardoc@singnet.com.sg; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: FW: Our Ref: 181919VC00021612 ACCIDENT INVOLVING SLL4169R AND YN2109M ON 01/04/2019 AT CTE [External General]
Attachments: 0241_001.pdf; SLL4169R (1).JPG; SLL4169R (3).JPG; SLL4169R (5).JPG; SLL4169R (20).JPG; SLL4169R (21).JPG; SLL4169R (24).JPG

Lonpac External - General

Without Prejudice


Dear Irene

Please liaise with LKK Auto Consultants Pte Ltd for survey and assessment of liability.

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Specialists Motor Pte Ltd [mailto:cardoc@singnet.com.sg]
Sent: Wednesday, 3 April, 2019 9:03 AM
To: MT_Claim_SG
Subject: ACCIDENT INVOLVING SLL4169R AND YN2109M ON 01/04/2019 AT CTE

Without Prejudice

Dear Sir/ Madam

Please refer to the above matter.

Our client (SLL4169R) is claiming against your insured (YN2109M).


Kindly check for us the liability and arrange the surveyor to survey the vehicle SLL4169R at
Specialists Motor Pte Ltd
Blk 3018A, Ubi Road 1,
#01-24/25/26
Singapore 408711

Thanks & Regards

10.24am @ 3/4/19
vehicle in
Irene
pls call Irene / email
her for liability on urgent
basis.

Irene Ting
6747 2112

From: cardoc@singnet.com.sg [mailto:cardoc@singnet.com.sg]
Sent: Wednesday, 3 April, 2019 7:42 AM
To: CARDOC
Subject: Attached Image



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Friday, 5 April 2019 9:49 AM
To: 'Specialists Motor Pte Ltd'
Cc: Admin A; assignments
Subject: RE: Our Ref: 181919VC00021612 ACCIDENT INVOLVING SLL4169R AND YN2109M ON 01/04/2019 AT CTE [External General]

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/LPC19005882/Ufb3
Your Ref: SLL 4169R

Dear Sir/Madam,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 7 November 2019 11:45 AM
To: Specialists Motor Pte Ltd
Cc: Admin A
Subject: RE: Claim of GBH2531E and SLL4169R Our Ref: 19/19/19/VP05/021614 & Our Ref: 18/19/19/VC00/021612 [External General]

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We maintain settlement as follows as the same is reasonable and it is within the benchmark: -

1. Cost of Repair (w/GST)	\$ 17,773.81
2. Loss of Rental (13days x \$120.00)	\$ 1,560.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 19,335.81

Please re-consider and confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Specialists Motor Pte Ltd <cardoc@singnet.com.sg>
Sent: Tuesday, 8 October 2019 9:43 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Claim of GBH2531E and SLL4169R Our Ref: 19/19/19/VP05/021614 & Our Ref: 18/19/19/VC00/021612 [External General]

Without Prejudice

Dear Khanchna

Please refer to the above matter.

Your offer for the above claims S\$19,335.81 was accepted by our client.

Kindly let us have the DV and payments as soon as possible.

Thanks

Regards

Karen Ong

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Friday, December 13, 2019 2:47 PM
To: Specialists Motor Pte Ltd <cardoc@singnet.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Claim of YN2109M [LONPAC] and SLL4169R ON 01/04/2019

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

Saturdays should be working days for workshop.

We maintain settlement as follows as the same is reasonable and it is within the benchmark: -

1. Cost of Repair (w/GST)	\$ 17,773.81
2. Loss of Rental (13days x \$120.00)	\$ 1,560.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 19,335.81

Please re-consider and confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 17 December 2019 10:07 AM
To: spec
Cc: Admin A
Subject: RE: Claim of YN2109M [LONPAC] and SLL4169R ON 01/04/2019
Attachments: LONPAC DV.pdf

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

Thank you for the acceptance.

We attach herewith a copy of the DV.

Kindly send us (LKK) all the documents below for our necessary action: -

- **hardcopy of the DV**

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: spec <cardoc@singnet.com.sg>
Sent: Friday, 13 December 2019 3:17 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: RE: Claim of YN2109M [LONPAC] and SLL4169R ON 01/04/2019

Hi Khanchna,

Refer to your email above matter.

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLL4169R/1904046

Your Claim No: 18/19/VC00/021612

28th December 2019

WITHOUT PREJUDICE

The Manager
Motor Claim Dept.
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

**RE: ACCIDENT INVOLVING VEHICLES SLL 4169 R AND YN 2109 M ON 01ST APRIL 2019
AT 1615 HRS AT CTE TOWARDS BUKIT TIMAH EXIT**

Dear Sirs,

We refer to the above matters.

Attached a discharge voucher which was duly signed by the owner for your perusal.

Kindly let us have the payments as soon as possible.

Thanks

Regards


Karen Ong




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19005882/Uka3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 15-01-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2109M	Veh. Inspected	SLL 4169R	
Policy No.	2/18/VC00/101613	Coverage (\$)	0.00	
Claim No.	18/19/19/VC00/021612	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	03/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1SJ5KC5GG083764	Colour	BROWN	
Odometer	046326	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/60R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2019	Inspection Date	04/04/2019	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4169R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	BUCKLED	882.40	882.40
2	FRONT BONNET HINGE L&RH @ \$48.30	TO REPAIR SEE LABOUR	96.60	-
1	SET FRONT BONNET INSULATION SHIELD CLIPS	NECESSARY	35.00	35.00
1	FRONT GRILLE (TOP)	SCRATCHED / CRACKED	208.40	208.40
1	FRONT GRILLE (BOTTOM)	CRACKED	316.40	316.40
1	SET FRONT GRILLE CLIPS	NECESSARY	35.00	35.00
2	HEADLAMP ASSY L&RH @ \$2380.00	HOLDER CRACKED	4,760.00	4,760.00
2	HEADLAMP LOWER BRACKET L&RH @ \$49.30	CRACKED	98.60	98.60
1	FRONT BUMPER FASCIA	DENTED / TORN	594.20	594.20
1	FRONT BUMPER CLIPS	NECESSARY	35.00	35.00
1	FRONT BUMPER TOWING COVER	DEFORMED	14.30	14.30
1	FRONT BUMPER REINFORCEMENT (OUTER)	BENT	140.30	140.30
1	FRONT BUMPER REINFORCEMENT	DENTED	288.30	288.30
2	FRONT BUMPER SIDE RETAINER L&RH @ \$26.50	BENT	53.00	53.00
2	FRONT BUMPER FOG LAMP COVER L&RH @ \$79.20	NOT NECESSARY	158.40	-
2	FRONT BUMPER FOG LAMP ASSY L&RH @ \$272.40	NOT NECESSARY	544.80	-
2	HEADLAMP NOZZLE COVER L&RH @ \$69.20	NOT NECESSARY	138.40	-
2	HEADLAMP NOZZLE PUMP ASSY L&RH @ \$102.90	NOT NECESSARY	205.80	-
1	FRONT SUPPORT PANEL	BENT	400.70	400.70
1	FRONT SUPPORT BRACKET	NOT NECESSARY	72.90	-
1	SET FRONT SUPPORT BRACKET CLIPS	NECESSARY	35.00	35.00
1	RADIATOR ASSY	NOT NECESSARY	792.80	-
1	AIR CON CONDENSER	BENT / LEAKING	680.20	680.20
1	AIR FILTER AIR DUCT	NOT NECESSARY	231.10	-
1	SET FILTER AIR DUCT CLIPS	NECESSARY	35.00	35.00
2	FRONT FENDER L&RH @ \$300.60	O/S TO REPAIR SEE LABOUR / N/S DENTED	601.20	300.60
2	FRONT FENDER COWLING L&RH @ \$96.30	NOT NECESSARY	192.60	-
1	SET FRONT FENDER COWLING CLIPS L&RH	NOT NECESSARY	35.00	-

Report Ref No. CC4/LPC19005882/Uka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER SIDE SHIELD L&RH @ \$25.00	NOT NECESSARY	50.00	-
2	FRONT FENDER SIDE SHIELD CLIPS L&RH @ \$30.00	NOT NECESSARY	60.00	-
1	REAR BOOT COVER	BADLY DENTED	1,072.90	1,072.90
1	REAR BOOT COVER EMBLEM (LOGO)	NECESSARY	88.30	88.30
1	REAR BOOT COVER EMBLEM (SUBARU)	NECESSARY	72.30	72.30
1	REAR BOOT COVER EMBLEM (FOSTER)	NECESSARY	72.30	72.30
1	REAR BOOT W/STRIP	TWISTED	120.80	120.80
1	REAR BOOT COVER LOCK	TWISTED / JAMMED	176.40	176.40
1	REAR BOOT COVER LATCH	NOT NECESSARY	38.92	-
1	REAR WINDSCREEN GLASS	SHATTERED	888.20	888.20
1	REAR WINDSCREEN MOULDING	NECESSARY	64.20	64.20
2	REAR NO PLATE LAMP @ \$38.20	NOT NECESSARY	76.40	-
1	REAR NO PLATE LAMP GARNISH	CRACKED	160.40	160.40
1	REAR WIPER BLADE	NOT NECESSARY	36.30	-
1	REAR WIPER ARM	NOT NECESSARY	63.20	-
1	REAR WIPER MOTOR ASSY	NOT NECESSARY	424.80	-
2	REAR BOOT COVER INNER BOARD L&RH (TOP) @ \$65.30	CUT	130.60	130.60
1	REAR BOOT COVER INNER BOARD (CENTRE)	NOT NECESSARY	264.20	-
2	REAR LAMP ASSY L&RH @ \$432.90	NOT NECESSARY	865.80	-
1	REAR END PANEL	BADLY DENTED	288.30	288.30
1	REAR BOOT FLOOR PANEL	TO REPAIR SEE LABOUR	432.40	-
1	REAR BOOT FLOOR INNER TRAY	TORN	100.80	100.80
1	REAR BUMPER FASCIA	DISTORTED	600.40	600.40
1	SET REAR BUMPER CLIPS	NECESSARY	55.00	55.00
1	REAR BUMPER REINFORCEMENT	DISTORTED	420.40	420.40
1	REAR BUMPER TOWING COVER	TORN	28.40	28.40
2	REAR BUMPER REFLECTOR L&RH @ \$25.40	N/S CRACKED	50.80	25.40
2	REAR BUMPER BRACKET L&RH @ \$20.30	BENT	40.60	40.60
2	REAR BUMPER SIDE RETAINER L&RH @ \$28.20	BENT	56.40	56.40
1	REAR EXHAUST SILENCER ASSY	NOT NECESSARY	668.20	-
1	REAR REVERSE CAMERA	SERVICEABLE	560.20	-
1	TYRE BRACKET	BENT	15.50	15.50

Report Ref No. CC4/LPC19005882/Uka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE BOLT	BENT	25.80	25.80
1	FRONT GRILLE LOWER BRACKET	BENT	26.40	26.40
1	REAR END PANEL INNER GARNISH	DISTORTED	40.30	40.30
1	REAR BOOT NO PLATE GARNISH	CRACKED	210.30	210.30
1	REAR BOOT GARNISH SEAL	NECESSARY	21.60	21.60
1	COVER REAR BUMPER	DEFORMED	14.40	14.40
	LESS 20% DISCOUNT		-	-2,745.76
			20,063.62	10,983.04
	SPECIAL NETT ITEMS			
1	RADIATOR COOLANT (SN)	NECESSARY	28.00	28.00
1	FRONT NUMBER PLATE (SN)	BENT	50.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR END PANEL SEALER (SN)	NECESSARY	80.00	50.00
1	REAR BUMPER SENSOR (SN)	SHORTED	380.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
1	BLACKVUE CAMERA (SN)	DAMAGED	790.00	420.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	280.00	150.00
			1,718.00	968.00
	LABOUR			
	TOWING FEE.		200.00	120.00
	CUT OUT, RENEW, KNOCKING & WELDING FRONT BONNET, FRONT FENDER L&RH, FRONT SUPPORT PANEL, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN FRONT CHASSIS & RE-ALIGN BODY. INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGE L&RH AND O/S FRONT FENDER L&RH.		1,880.00	800.00
	REMOVE & INSTALL RADIATOR ASSY, ENGINE COOLING SYSTEM & CONDUCT PRESSURE TEST. }		120.00	100.00
	REMOVE & INSTALL AIR CON CONDENSER, VACUUM & TOP UP GAS. }		120.00	-
	TUFF-KOTE ON DAMAGE PARTS.		120.00	90.00
	SPRAY PAINTING ON FRONT DAMAGE PARTS.		1,580.00	1,100.00

Report Ref No. CC4/LPC19005882/Uka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Reg. No: 199607198R GST Reg. No: 19-3007198-R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CUT OUT, RENEW, KNOCKING & WELDING REAR BOOT COVER, REAR END PANEL, REAR BOOT FLOOR PANEL, REMOVE & INSTALL REAR DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY. INCLUSIVE OF THE REPAIR OF REAR BOOT FLOOR PANEL.	NOT NECESSARY	2,180.00	1,000.00
	REMOVE & INSTALL REAR WINDSCREEN GLASS.		140.00	120.00
	REMOVE & INSTALL REAR SEATS, CARPETS, UPHOLSTERY & ETC.		280.00	100.00
	REMOVE & REFIX REAR BUMPER SENSOR.		80.00	50.00
	REMOVE & INSTALL REAR EXHAUST SILENCER.		100.00	-
	TUFF-KOTE ON REAR BUMPER PARTS.		120.00	60.00
	SPRAY PAINTING ON REAR DAMAGE PARTS.		1,890.00	1,100.00
	CHECK ALL LIGHTING AFTER REPAIRS.		60.00	20.00
			8,870.00	4,660.00
GRAND TOTAL			30,651.62	16,611.04
RECOMMENDED COST OF REPAIRS				16,611.04

Report Ref No. CC4/LPC19005882/Uka3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.