

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8487 X

1 pc	o/s mirror Assy	Nec	\$	590.00
	<i>o/s Front Door x repair</i>		Less 10%	\$ 59.00
				<u>\$ 531.00</u>

S/NETT

1 set	o/s door stickers	Nec	\$	100.00
	Sundry		\$	50.00 2
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, etc		\$	550.00 200
	To putty and spray painting on front n/s door, o/s side mirror		\$	400.00 230
	To apply rustproofing on the repaired and replaced panels.		\$	120.00 4
			<u>\$</u>	<u>1,751.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kahin Uday

2/4/19 10:15h

2 Bys

4/s

After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: