

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

21-Jan-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1519 Z

1 pc	Front o/s fender ✓	\$	514.02
1 pc	Front o/s fender inner shield X	\$	176.72
		\$	690.74
	Less 20%	\$	138.14
		\$	552.60

S/NETT

1 pc	Front o/s fender sticker ✓	\$	60.00
1 pc	Front o/s fender inner shield clips X	\$	30.00

Sundry \$ ~~50.00~~ 200

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front o/s door etc

\$ ~~500.00~~ 200

To putty and spray painting on the front o/s fender, front o/s door X

\$ ~~400.00~~ 130

To apply rustproofing on the repaired and replaced panels

\$ ~~120.00~~ 130

Total \$ 1,712.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Li Mdey
2/4/19 1000h
2 hrs.
P/P
Before Part pld

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: