

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 7235L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	822.60	595.00
1	REAR BUMPER LOWER LIP	CUT	360.00	360.00
2	REAR BUMPER SIDE RETAINER @ \$89.60	NOT NECESSARY	179.20	-
1	REAR BUMPER REFLECTOR RH	CRACKED	233.50	233.50
1	REAR BUMPER REFLECTOR HOUSING RH	CRACKED	98.50	98.50
1	REAR BUMPER REINFORCEMENT	CRACKED	498.00	325.00
2	REAR BUMPER REINFORCEMENT BRACKET @ \$95.50	NOT NECESSARY	191.00	-
1	REAR END PANEL	NOT NECESSARY	544.60	-
1	REAR END PANEL TOP GARNISH	CRACKED	180.00	180.00
	LESS 10% DISCOUNT		-310.74	-179.20
			2,796.66	1,612.80
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	200.00	-
1	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	20.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			460.00	220.00
	<u>LABOUR</u>			
	PANEL BEATING, WELDING GRAZING, CUT, JOINT, STRAIGHTEN ALL AFFECTED PARTS.		1,200.00	300.00
	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS.		1,200.00	400.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		120.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
			2,890.00	780.00
	GRAND TOTAL		6,146.66	2,612.80

RECOMMENDED COST OF LUMP SUM REPAIRS		2,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/EQI19005887/Apb3s2





Report Ref No. CC6/EQI19005887/Apb3s2



**ADRIAN LING WAI PING** 

B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.