




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI19005887/Apb3s2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 30-10-2019		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 4320K	Veh. Inspected	SMJ 7235L
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM19HO00926/JT	Excess (\$)	0.00
	Assign From		Assign Date	02/04/2019
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KNAF3416MK5031290	Colour	WHITE
	Odometer	892	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	NEXEN	6 mm
	L/H Front Tyre	205/55 R16	NEXEN	6 mm
	R/H Rear Tyre	205/55 R16	NEXEN	6 mm
	L/H Rear Tyre	205/55 R16	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/03/2019	Inspection Date	02/04/2019
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	