

# LOH HENG

Automotive Repair Services  
Accident Insurance Claims

4-Feb-19

EQ Insurance Co

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. SJG6968M (Honda Civic)

S/N		Amount (\$\$)
<b>A</b>	<b>PART REPLACEMENT</b>	
	Rear bumper <i>CM</i>	\$ 695.00 ✓
	Rear right mudguard <i>B</i>	\$ 875.00 ✓
	Rear bumper retainer <i>CM</i>	\$ 46.00 ✓
	Mudguard lamp <i>Bu</i>	\$ 298.00 ✓
	<i>741</i>	
	Sub-Total	\$ 1,914.00
	Less: 20%	
	<b>Total</b>	<b>\$ 1,531.00</b>
<b>B</b>		
	To repair damaged on rear accident area. Cut and reweld mudguard, fix bumper.	
		\$ 880.00 <i>600</i>
	Remove and fix rear glass with sealant	
		\$ 140.00 ✓
	Remove upholstery, wiring, socket and refix.	
		\$ 180.00 <i>100</i>
	Respraying rear accident area.	\$ 650.00 <i>300</i>
	<b>GRAND TOTAL OF A &amp; B</b>	<b>\$ 3,381.00</b>

*COE expiring  
11-7-2028*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare  
Sin Ming Drive  
Singapore 575721  
Tel : 64532237 / 64530797  
Fax : 64556384