

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
Email : chris_chanbebe@hotmail.com

TRAYA
Poh kin

02nd APRIL 2019

TEO GARY
Blk 3020A Ubi Road 1
01-33
Singapore 408717

WP022298274722910

Accident date: 30.3.2019

Estimated repair cost for vehicle no:SGA899K PORSCHE BOXSTER S 3.4A '08

S/n	Qty	Items	U/price	Amount
1	1	Boxster S logo <i>new</i>		\$188.00 +
2	1	rear fan Assy <i>new</i>		\$683.00 +
3	1	Rear tail lamp-LH <i>coupled</i>		\$1,556.00 + 883
4	1	Rear bumper <i>2hd</i>		\$5,308.00 + 2859
5	1	Rear bumper clips <i>new</i>		\$50.00 -
6	2	Rear bumper side holder <i>new</i>	\$125.00	\$250.00 -
7	1	Rear bumper reinforcement <i>Back</i>		\$985.00 + 789
8	2	Rear bumper reinforcement damper <i>new</i>	\$455.00	\$910.00 +
9	4	Rear Bumper reverse sensor <i>2 pieces and</i>	\$320.00	\$1,280.00 + 640
10	4	Rear Bumper reverse sensor		\$2,216.00 +
11	1	Rear end panel <i>new</i>		\$50.00 +
12	1	Rear number plate <i>new</i>		\$558.00 +
13	1	reverse sensor wire <i>new</i>	\$218.00	\$436.00 +
14	2	Rear Exhaust chome pipe <i>new</i>	\$1,665.00	\$3,330.00 +
15	2	rear exhaust pipe	\$285.00	\$570.00 +
16	2	rear exhaust heat shield -side <i>new</i>	\$108.00	\$108.00 -
17	1	rear exhaust heat shield -side (frame) <i>coupled</i>		
Subtotal :-				\$18,478.00

5219.
469710

Labour charges

To Check Wiring System

~~\$100.00~~ 30.

to underseal

~~\$150.00~~ X

to perform diagnostic

~~\$200.00~~ 100

TO Remove & install rear reverse sensor

~~\$150.00~~ 60.

to remove & install rear exhaust system

740

~~\$450.00~~ X

Panel beating

~~\$1,000.00~~ 250

Spray painting

~~\$1,000.00~~ 300..

Subtotal :- \$3,050.00

Total:- \$21,528.00

total: 5437.10

4/s 43K

0304p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: