



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

02/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA.

Joy.

Accident date: 01/04/2019

Estimated repair cost for vehicle no: SLW981E HONDA ACCORD 2.4 A '09

CHASSIS: MRHCP26308P020483

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented.</i>		\$878.40	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$52.40	\$104.80	✓
3	1	Rear Boot Lid Emblem Logo <i>?</i>		\$29.10	✓
4	1	Rear Boot Lid Accord Logo <i>new</i>		\$35.00	✓
5	1	Rear Boot Lid 2.4 Logo		\$33.20	✓
6	1	Rear Boot Lid I-Vtec Logo		\$33.50	✓
7	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	✓
8	1	Rear Boot Lid Number Plate Garnish <i>Defend</i>		\$432.80	✓
9	2	Rear Boot Lid Side Reflector <i>new</i>	\$292.40	\$584.80	✓
10	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$210.90	✓
11	1	Rear Boot Lid Inner Rubber <i>lt</i>		\$185.00	✓
12	1	Rear Boot Lid Inner Trim Board <i>3M</i>		\$264.80	✓
13	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00	✓
14	2	Rear Tail Lamp <i>crackd</i>	\$336.70	\$673.40	✓
15	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	10
16	2	Rear Tail Lamp Lower Bracket <i>Bent</i>	\$53.60	\$107.20	50
17	2	Rear Tail Lamp Panel <i>Repair</i>	\$189.20	\$378.40	✓
18	1	Rear Bumper <i>Distorted</i>		\$709.10	✓
19	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00	30
20	2	Rear Bumper Side Retainer <i>new</i>	\$47.50	\$95.00	✓
21	1	Rear Bumper Reinforcement <i>Bent</i>		\$295.60	✓
22	2	Rear Bumper Mud Shield <i>3M</i>	\$93.80	\$187.60	✓
23	8	Rear Bumper Mud Shield Clip <i>new</i>	\$6.50	\$52.00	✓
24	4	Rear Bumper Reverse Sensor <i>Dented 2 pieces</i>	\$226.90	\$907.60	453.80
25	4	Rear Bumper Reverse Sensor Holder Bracket <i>new</i>	\$48.10	\$192.40	✓
26	4	Rear Bumper Reverse Sensor Rubber Seal <i>new</i>	\$12.50	\$50.00	✓
27	1	Rear End Panel <i>Dented</i>		\$317.40	✓
28	1	Rear End Panel Top Garnish <i>Defend</i>		\$197.70	✓

29	2	Rear Fender	Repair		\$1,294.50	X
30	2	Rear Fender Inner Trim Board	3 NP	\$163.50	\$327.00	X
31	16	Rear Fender Inner Trim Board Clip	5 NP	\$6.50	\$104.00	X
32	1	Rear Spare Tyre Panel	Repair		\$837.50	X
33	1	Rear Spare Tyre Panel Top Cover	torn		\$233.40	✓
34	2	Rear Spare Tyre Panel Top Side Sponge	Defunct	\$145.00	\$290.00	✓
35	1	Rear Spare Tyre Panel & End Panel Sealant	NP		\$450.00	✓
36	1	Rear Exhaust	3 NP		\$1,241.30	X
37	2	Rear Exhaust Mounting	1 NP	\$25.70	\$51.40	X

5243.30
4194.64

Subtotal :- \$11,970.80

Labour charges

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit cushion & trim board

~~\$280.00~~ 60

To remove & refit rear & center exhaust

~~\$380.00~~ X

To check wiring

~~\$100.00~~ 30

Tuff kote

2100

~~\$150.00~~ 60

Towing fee

~~\$150.00~~ X

Panel beating

~~\$1,600.00~~ 900

Spray painting

~~\$1,400.00~~ 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$4,160.00

Total:- \$16,130.80

total 6294.64

4/S: 51C (Nett Value)
06 Days.

SK.