

REPAIR ESTIMATE*

VEHICLE NO : SHC 2507G

MAKE :

MODEL : HYUNDAI IONIQ

DATE 3/4/2019

0830

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) X repair			\$ 1,768.30
	Rear Fender Inner Lining (RH) X			\$ 73.60
	Rear Windscreen Moulding X			\$ 28.20
	<i>Rear Bumper (RH) X repair</i>			
	<i>Rear Door (RH) X repair</i>			
	SUB TOTAL			\$ 1,870.10
	LESS 20%			\$ 374.02
	DISCOUNTED TOTAL			\$ 1,496.08
	Rear Windscreen Sealant X			\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (RH)			\$ 80.00
				\$ 126.00
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,170.00
	ESTIMATE TOTAL			\$ 3,792.08
	Kahin 1/11/14 N 3/4/19 1030hr 2 Pys. PIP After Repair photo			
	Acknowledged by Repairer Signature: Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.