

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412
Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Not Allowed
r/bk
p/p \$2028.67
3dy.

8/4/2019

M/S AXA INSURANCE

ESTIMATE REPAIR COST GB#4385Y KDY231-803

1	1 PC	TAILGATE
2	1 PC	TAILGATE LOWER MEMBER
3	1 PC	TAILGATE LOWER RED REFLECTOR
4	1 PC	TAILGATE DYNA STICKER
5	1 PC	NUMBER PLATE BRACKET
6	1 PC	NUMBER PLATE LAMP
7	2 PC	TAILLAMP
8	2 PC	TAILLAMP BRACKET
9	1 PC	TAILLAMP ROUND REFLECTOR
10	1 PC	BLACK TOOL BOX
11	2 PC	TAILGATE LOCK
12	1 PC	SPARE TYRE LOCK CHAIN PLATE

n	\$	1,079.90	X
n	\$	574.40	X
cre	\$	34.60	/
nu	\$	28.30	/
but	\$	123.86	/
11	\$	44.50	X
cm	\$	433.60	/
but	\$	251.20	/
11	\$	38.70	X
11	\$	398.90	X
n	\$	135.70	X
11	\$	225.70	X
	\$	3,369.36	
	\$	(842.34)	
	\$	2,527.02	

LESS 25%

871.56
2570
653.67

SPECIAL NETT :

13	1 PC	70KM/HR STICKER
14	1 PC	STEP BRACKET
15	1 PC	REAR NUMBER PLATE
16	1 PC	ARTWORK
17		TO SPRAY PAINTING
18		LABOUR CHARGE
19		REAR WIRING
20		TUFF KOTE

nu	\$	15.00	10
nu	\$	120.00	X
410	\$	40.00	15
	\$	380.00	280
	\$	800.00	450
	\$	1,000.00	600
	\$	30.00	20
11	\$	100.00	X
	\$	5,012.02	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL :

2028.67