



VAG Singapore Pte Ltd  
 48 Toh Guan Road East  
 #05-123, Enterprise Hub  
 Singapore 608586

Repair Estimate

Tel: 6267 9916  
 Fax: 6267 9313  
 www.avantage.sg

Date : 1st April 2019

Vehicle Num : SGD6895R

Make/Model : Golf Mk7 1.4TSI

Chassis No : WVVZZZAUZDW099064

S/N	PARTS	QTY	PRICE	TOTAL
1	Tow Cap Cover for rear bumper	1	\$ 30.00	\$ X 30.00
2	1 set of mounting parts for bumper	1	\$ 75.00	\$ ? 75.00
3	Rear Bumper	1	\$ 1,080.00	\$ de ✓ 1,080.00
4	Rear diffuser	1	\$ 375.00	\$ X 375.00
5	Left reflector	1	\$ 55.00	\$ X 55.00
6	Right reflector	1	\$ 55.00	\$ X 55.00
<b>TOTAL PARTS</b>				<b>\$ 1,670.00</b>
<b>TOTAL AMOUNT</b>				<b>\$ 1,670.00</b>
<b>MISCELLANEOUS ITEM</b>				
<b>LABOUR</b>				
1	Cover for bumper to rework cut-out for vehicle with park assist > including removal and assembly bumper, punch out of sensors			\$ 200 900.00
2	To perform surface preparation and spraypaint			\$ 200-250 680.00
3	To perform complete vehicle diagnostic check			\$ ✓ 90.00
4				
<b>TOTAL</b>				<b>\$ 3,340.00</b>
<b>GST 7%</b>				<b>\$ 233.80</b>
<b>GRAND TOTAL</b>				<b>\$ 3,573.80</b>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Tanfan 97495749/67418739  
 8/4/19 @ 4pm.  
 sur @ lkkauto.com.  
 02 days  
 Resurvey before paint.