



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE PTE LTD 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Teo Chuan Chin ADDRESS : BLK 504 JELAPANG ROAD #10-360 Singapore 670504 TEL : 97500970		WIP : 47864 EXCESS : DATE: 30-Mar-19	
VEH NO :	SKR7743T	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6GJ1031F0147005	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	9-Mar-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MGJ51-50-221ABB		\$ 1,206.20
2	RETAINER LHS	1	MGJR9-50-2J1		\$ 39.00
3	RETAINER RHS	1	MGJR9-50-2H1		\$ 39.00
4	BRACKET CENTER	1	MKD53-50-251		\$ 5.10
5	REFLECTOR LHS	1	MD350-51-5L0E		\$ 50.40
6	TOWING COVER LHS	1	MGJR9-50-EL164		\$ 23.70
7	TOWING COVER RHS	1	MGJR9-50-EK1 64		\$ 23.70
8	REAR REINFORCEMENT	1	MGHK1-50-260		\$ 512.60
9	RETAINER CENTER, SENSOR	2	MKD45-67-UC5A64		\$ 34.60
10	<u>SENSOR CENTER, SENSOR</u>	2	<u>MKD47-67-UC1 64</u>		\$ 387.80
12	TAPE PROTECTOR, SENSOR	4	MGS1D-50-EM1A		\$ 32.40
13	RIVET, REAR BUMPER	6	ML33X-13-209		\$ 16.80
14	GROMMET, REAR BUMPER	6	MH260-50-841		\$ 16.80
15	CLIP, REAR BUMPER	4	MB455-56-135		\$ 12.80
16	REAR END PANEL	1	MGHY1-70-75Z		\$ 666.70
17	TRIM, END PANEL	1	MGHK1-68-89XA		\$ 116.40
18	FASTENER, TRIM	10	MGJ21-68-885B02		\$ 28.00
19	SPONGE LHS, FLOOR PANEL	1	MGHK3-68-8F0A		\$ 248.00
20	SPONGE RHS, FLOOR PANEL	1	MGHK3-68-8E0A		\$ 149.40
21	ANTENNA, KEYLESS	1	MKD47-67-6NXA		\$ 105.80
22	CLIP, ANTENNA	1	MKD45-67-6NYA		\$ 2.50
23	ORNAMENT, MAZDA	1	MGHK1-51-711		\$ 27.50
24	ORNAMENT, 6	1	MGHK1-51-721		\$ 15.70
25	MASCOT, REAR	1	MGHK1-51-730		\$ 46.80
26	ORNAMENT, SKYACTIVE	1	MGHK1-51-771		\$ 71.10
27	GASKET LHS, BOOTLID LAMP	1	MGHK1-51-3J8A		\$ 50.00
28	GASKET RHS, BOOTLID LAMP	1	MGHK1-51-3H8A		\$ 50.00
29	GASKET LHS, TAILLAMP	1	MGHK1-51-163		\$ 27.70
30	GASKET RHS, TAILLAMP	1	MGHK1-51-153		\$ 27.70
31	INSULATOR HEAT, EXHAUST SILENCER	1	MG46F-56-451A		\$ 53.00
32	RIVET, INSULATOR	5	MB25D-56-398		\$ 10.00

		TOTAL PARTS	\$ 4,097.20
		LESS 10%	\$ 409.72
		TOTAL PARTS COST	\$ 3,687.48

Labour Description			
1		TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL. TO REPAIR BOOTLID, REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT. 660	\$ 4,290.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, BOOTLID, REAR FLOOR PANEL. 630	\$ 3,150.00
3	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS. /	NETT \$ 330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA. NN X	NETT \$ 330.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION. 330	\$ 990.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING NN X	\$ 350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. / X	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 150	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 180	\$ 350.00
10	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. NN X	NETT \$ 120.00
11	MZ-BR-SUNDRI	SUNDRIES. 10.	NETT \$ 100.00

5 Days.

before paint photos.

Guo Qup - 82880282

04/4/19.

TOTAL LABOUR	\$ -	\$ 10,510.00
TOTAL PARTS	\$ -	\$ 3,687.48
TOTAL	\$ -	\$ 14,197.48
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary work is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: