

**Hitachi Capital Asia Pacific Pte. Ltd.  
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
Tel : 64663022 Fax : 68966591  
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**VEHICLE ESTIMATE dated 02/04/2019**

INDIA INT'L INSURANCE  
ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 28/03/2019 @ 14:15  
VRN : SKX8053M  
MODEL : HONDA VEZEL 1.5  
TP VRN : SHA3823Y

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<b><u>PARTS REPLACEMENT</u></b>				
<b><u>1. Body Repair</u></b>				
1 REAR LH DOOR	1	\$ 880.00	\$ 880.00	<i>bf</i>
2 REAR LH DOOR STICKER	1	\$ 35.00	\$ 35.00	<i>na</i>
3 REAR LH DOOR WEATHERSTRIP	1	\$ 45.00	\$ 45.00	<i>?</i>
4 REAR LH DOOR WEATHERSTRIP	1	\$ 25.00	\$ 25.00	<i>?</i>
5 REAR LH DOOR WEATHERSTRIP	1	\$ 28.00	\$ 28.00	<i>?</i>
6 LH SIDE SKIRT	1	\$ 285.00	\$ 285.00	<i>cut</i>
7 REAR LH WHEELARCH	1	\$ 175.00	\$ 175.00	<i>cut</i>
8 ROCKER PANEL	1	\$ 245.00	\$ 245.00	<i>RP</i>
9 REAR LH RIM	1	\$ 813.00	\$ 813.00	<i>at</i>
			\$ 2,531.00	
<b>Discount -20%</b>			\$ 506.20	
			\$ 2,024.80	
<b>Special Nett</b>				
62 REAR LH TYRE	1	\$ 123.00	\$ 123.00	<i>X</i>
			\$ 123.00	
		<b>PARTS TOTAL</b>	\$ 2,147.80	

**2. Labour Charges**

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,250.00	<i>500</i>
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,000.00	<i>500</i>
Remove & Reinstall Cushions, Seats, Backrests, Inner Trim, Garnish, Roof Lining and/or Upholstery to Facilitate Repair	\$ 180.00	
Remove and Replace Rear LH Door Window Glass to Facilitate Repair	\$ 100.00	<i>60</i>
Dismantle and Transfer Door Fittings & Mechanisms to New Door	\$ 150.00	<i>60</i>
Cavity Treatment on New Parts	\$ 80.00	<i>30</i>
Conduct Water Seepage Test	\$ 120.00	<i>30</i>
	<b>LABOURS TOTAL</b>	\$ 2,880.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No. of repair days is allowed **7**

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Tanfir 97495749.*  
*wp*  
*10/4/19*  
*Resy before paint part by part.*  
*4 days.*  
*sure lth auto on.*

Grand Total : \$ 5,027.80  
Add 7% GST : \$ 351.95  
**Nett Total : \$ 5,379.75**



HITACHI CAPTIAL ASIA PACIFIC PTE LTD  
(MANAGER)

CUSTOMER SIGNATURE