



Joy

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZI007 / INDIA INTERNATIONAL	Document No:	SVO19023191
Chassis No:	MRHCR2630EP000032	Printed By:	ANIKKALAI
License No:	SKP5711J	Order Date:	11. April 2019
Mileage:	89379	Order Time:	2:10:18 PM
Engine No:	K24W31200877	Service Advisor:	ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: YUE XIAONING						
	OWNER INSURER: FWD						
	ACC DATE: 01/04/2019						
	SURVEYED BY: HWEE JIE / LKK						
	DATE: 10/04/2019						
	REF NO:						
	TP INSURER: INDIA INS						
	TP VEH: SHC8762X						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
71501-T2M-T10ZZ	FACERR.BUMPER	1	630.50	25	472.87	33.10	505.97
71593-T2A-A01	SPACERR.RR.BUMPER SIDE	1	12.20	25	9.15	0.64	9.79
71598-T2A-A01	SPACERL.RR.BUMPER SIDE	1	12.20	25	9.15	0.64	9.79
91505-TM8-003	CLIP.BUMPER	2	2.30	25	3.45	0.24	3.69
33555-T2A-A01	REFLECTOR ASSYL.RR.	1	20.30	25	15.22	1.07	16.29
71510-T2G-A00	GARNISH ASSYRR.BUMPER LOWER	1	159.80	25	119.85	8.39	128.24
71508-T2A-A00	PROTECTORRR.BUMPER SIDE	1	5.00	25	3.75	0.26	4.01
68500-T2M-Z10ZZ	LID COMPTRUNK	1	876.20	25	657.15	46.00	703.15
74865-T2A-003	WEATHERSTRIPTRUNK LID	1	71.30	25	53.47	3.74	57.21
75701-T2A-A02	EMBLEMH	1	26.70	25	20.02	1.40	21.42
75722-T2A-A01	EMBLEMRR.ACCORD	1	19.30	25	14.47	1.01	15.48
75725-TG2-K00	EMBLEMRR.I-VTEC	1	34.10	25	25.57	1.79	27.36
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
75731-T2A-W01	EMBLEMRR.2.4	1	11.60	25	8.70	0.61	9.31
33550-T2A-Y11	TAILLIGHT ASSYL.	1	538.40	25	403.80	28.27	432.07
66100-T2M-U00ZZ	PANEL COMPRR.	1	403.60	25	302.70	21.19	323.89
65680-T2M-T00ZZ	FRAME COMPL.RR.UPPER	1	134.80	25	101.10	7.08	108.18
39680-TV0-E11ZN	SENSOR ASSYPARKING	2	62.10	25	93.15	6.52	99.67
39681-T2A-Y11ZL	RETAINERPARKING SENSOR	2	23.70	25	35.55	2.49	38.04
75450-T2A-A01	OUTLET ASSYRR.AIR	1	60.70	25	45.52	3.19	48.71
	SUM PARTS:				2,442.79	171.00	2,613.79
BOSUN		1	20.00		20.00	1.40	21.40
	SUNDRIES						
BOMISC1	0671	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL REAR VIEW CAMERA (N)						
BA02R	0671	1	120.00		120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOMISC1		1	200.00		200.00	14.00	214.00
	RESET & INSTALL SMART ENTRY SYSTEM (N)						
BML02I		1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKBU02R	0671	1	1,650.00		1,650.00	115.50	1,765.50
	REMOVE & RENEW RR BUMPER & DAMAGE PARTS. ATTACHMENT ITEMS						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****0083E / MR YUE XIAONING
Chassis No: MRHCR2630EP000032
License No: SKP5711J
Mileage: 89379
Engine No: K24W31200877

Document No: SVO19023191
Printed By: ANIKKALAI
Order Date: 11. April 2019
Order Time: 2:10:18 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	SUPPLEMENTARY PARTS & LABOUR:-						
39680-TV0-E11ZN	SENSOR ASSYPARKING <i>Shorted</i>	2	62.10	25	93.15	6.52	99.67
39681-T2A-Y11ZL	RETAINERPARKING SENSOR <i>SCR</i>	2	23.70	25	35.55	2.49	38.04
75450-T2A-A01	OUTLET ASSYRR.AIR <i>CRK</i>	1	60.70	25	45.52	3.19	48.71
	SUM PARTS:				174.22	12.20	186.42
	TOTAL SGD				174.22	12.20	186.42

Total Payable (SGD)

186.42

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZI007 / INDIA INTERNATIONAL	Document No:	SVO19023191			
Chassis No:	MRHCR2630EP000032	Printed By:	ANIKKALAI			
License No:	SKP5711J	Order Date:	11. April 2019			
Mileage:	89379	Order Time:	2:10:18 PM			
Engine No:	K24W31200877	Service Advisor:	ANIKKA LAI SWEE KAM			
BP04R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	1,350.00	1,350.00	94.50	1,444.50
BOJSE	BODY JOINT SEALANT INNER FENDER	1	80.00	80.00	5.60	85.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00	560.00	39.20	599.20
BOBC	BODY UNDERSIDE COATING (N)	1	80.00	80.00	5.60	85.60
BKFE21R	CUT & RENEW RR L FENDER INNER PANEL INCLUDING FITTING ON ATTACHMENT ITEMS.	1	1,120.00	1,120.00	78.40	1,198.40
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	900.00	900.00	63.00	963.00
		SUM LABOUR:		6,460.00	452.20	6,912.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	0	180.00	0.00	0.00	0.00
		SUM EXT SERVICE:		0.00	0.00	0.00
		TOTAL SGD		8,902.79	623.20	9,525.99
		Total Payable (SGD)				9,525.99

GST Amount is calculated from individual line(s)

P/P \$8,902.79

8 days.