

AGS. REC. BY:

REF:

CC3/AG19005420/Atd302

Adrian
Munim

ASSIGNMENT

Front _____ Date _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 8200

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR. Seen: _____ Consistent?: Yes or No

Est. Repairs: 06/8/8 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ8750X Yr Regn: 2014 / DecType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 cc 1984Colour Grey A/C: Insured / Std / Nil / NASp. Reading 44255 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAUZZ24G3EN119807Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 225/55R17R: 225/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/04/19Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD AIG.

SKQ8750X-X

11/4 revert via munim, repair lump sum 16k

12/4 @ 11:33am - mandate approval limit 16k. inform by victor bah

mv: 90k.

12/4 @ 12:00pm - email premium authorise repair excess \$800

PV: 78.4k

Nett: 16.6k.

repair sum \$16,000 (Red: 24821 60%)
(6 days) 2

RECEIVED 23 APR 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 29/5 Typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

200

11

211

Denise Tay (LKKAUTO)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 10 April 2019 8:20 AM
To: Denise Tay (LKKAUTO); SUR
Cc: 'Claims Dept'
Subject: RE: OD CLAIM FOR SKQ 8750 X

Dear Denise,

We propose for 17K lumpsum.

Thank you.

Best regards,

Kelvin Khoo

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, 9 April, 2019 8:52 AM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; 'NORA ' <nora.khai@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SKQ 8750 X
Importance: High

Dear All,

Car survey on 3/4/2019.

Any update? Anyone following up? Try calling nobody pick up the call.

Please check if able to repair within \$15K all in.

We will not be responsible for any complaint.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 12 April 2019 12:08 PM
To: Claims Dept; SUR
Cc: Boo seng yak
Subject: RE: OD CLAIM FOR SKQ 8750 X

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKQ 8750X (Excess \$500/-)**. Repair limit at not exceeding \$ **\$16,000/-**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

We will still need the breakdown upon finalized as required by AIG.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 10 April 2019 11:42 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SKQ 8750 X

Dear Denise,

Kindly advise the repair cost at \$16K (before excess & GST) on part by part basis or Lump Sum basis?

Thank you.

Best regards,

Kelvin Khoo

Premium Automobiles Pte Ltd (Reg No 189902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Denise Tay (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 8 May 2019 3:54 PM
To: Adrian Ling (LKKAUTO); Denise Tay (LKKAUTO); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SKQ8750X - OD AIG - SURVEYED 3 APR 19
Attachments: WhatsApp Image 2019-05-08 at 15.39.50 (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.15 (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.16 (1) (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.16 (1) (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.16 (2) (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.16 (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.17 (1) (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.17 (2) (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.18 (1) (resize).jpeg; WhatsApp Image 2019-05-08 at 15.41.18 (resize).jpeg; PA04232019 - SKQ 8750 X - AUDI A6 C7 2.0 TFSI MU 4G - REAR LHS - OD (AIG).xls

hi Adrian and all,

Revised estimate and photographs attached.

Please confirm limit repair of \$16,000.00 @ 6 days of repairs (17,530.28)

Your early closure is really appreciated. *(Complaint customer)*

Best regards - jb

View Received Message

This mail is associated with :

***SKQ8750X (9861743733SG)**

OD

Mar 29 2019 6:00PM

[TEO SWEE HENG FREDERICK]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/04/2019 11:38 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16000.00) - SKQ8750X - Claim Handler: Loo, Tong Shing

Approved:16000.00:Repair limit not exceeding \$16,000.00. Re-Inspect and upload damage photos of LH headlamp. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Apr 2019

Preliminary Advice

Vehicle No	: SKQ8750X	Accident Date	: 29/03/2019
Make	: AUDI A6	Policy No.	: 1800003745-01
Assignment Date	: 03/04/2019	Excess	: S\$0.00
Date of Inspection	: 03/04/2019	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,821.00	
Revised Amount	:S\$	13,285.00	14,385
Check Items (Estimated)	:S\$	13,126.00	3024
Total	:S\$	26,411.00	32411
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	73,393.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,607.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pending repair cost from repairer

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:		Singapore NRIC
Owner ID:		6698F
Vehicle Details		
Vehicle No.:		SKQ8750X
Vehicle to be Exported:		Yes
Intended Deregistration Date:		03 Apr 2019
Vehicle Make:		AUDI
Vehicle Model:		A6 2.0 TFSI MU
Primary Colour:		Grey
Manufacturing Year:		2014
Engine No.:		CDN405195
Chassis No.:		WAUZZZ4G3EN119807
Maximum Power Output:		132.0 kW (177 bhp)
Open Market Value:		\$38,524.00
Original Registration Date:		31 Dec 2014
First Registration Date:		31 Dec 2014
Transfer Count:		0
Actual ARF Paid:		\$40,934.00
Intended PARF Rebate Details		
PARF Eligibility:		Yes
PARF Eligibility Expiry Date:		30 Dec 2024
PARF Rebate Amount:		\$30,700.00
Intended COE Rebate Details		
COE Expiry Date:		30 Dec 2024
COE Category:		E - Open Category
COE Period(Years):		10
QP Paid:		\$76,904.00
COE Rebate Amount:		\$42,693.00
Total Rebate Amount:		\$73,393.00

The information contained herein is correct as at 03 Apr 2019

OK

**Post FREE Ad to Sell Your Used Items!**

Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [3 Ways of Selling](#)

New 5 Years Renewal Coe Toyota Wish 1.8A

2.88% p.a Low Interest @ Gov
Finance 2 Years Warranty \$3800
Down Monthly From \$738
GVV 00000 P10 000 StarAd



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Save Search

Print

Sort by Date Posted 20 results/page

6 vehicles

Search

Audi A6

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Audi A6

Any

Any

2014

Any

Any

Any

Available

☐ Audi A6 Avant 2.0A TFSI MU

\$81,800

\$12,210 /yr

28-Feb-2014

1,984 cc

98,000 km

Stationwagon

Available

Graded B by **STA**

Reasonable Offer Will Be Consider! Consumer Who Want A Little Luxury In Their Family Wagon, The Audi A6 Avant Will Not Disappoint. Must Act Fast Before Its Gone.

Universe Motoring

Posted: 30-Mar-2019 Tags: 2014 Audi A6, 2014 Audi A6, Audi A6, Audi A6, Audi A6, Audi A6, Used Audi

PREMIUM AD☐ Audi A6 2.0A TFSI MU

\$83,955

\$12,320 /yr

14-May-2014

1,984 cc

87,000 km

Luxury

Available

Guarantee No Time Waste. 1 Ownership With Low Mileage Done. Very Well Maintained And Serviced By The Authorized Distributor. Almost New In Condition. High Loan Available. Viewing And Test Drive Are Mo...

Posted: 30-Mar-2019 Tags: 2014 Audi A6, 2014 Audi A6, Audi A6, Audi A6, Audi A6, Audi A6, Used Audi

PREMIUM AD☐ Audi A6 2.0A TFSI MU Ultra Edition

\$98,000

\$13,840 /yr

25-Aug-2014

1,984 cc

71,000 km

Luxury

Available

With Just 10% Driveway Today, This Ultra Edition Will Simply Amaze By Its Capabilities, Careful Owner With Full Servicing By Agent And Reputable Servworks Auto With Receipts Proof, Full LED Cockpit D...

Car Buyers Automotive Pte Ltd

Posted: 27-Mar-2019 Tags: 2014 Audi A6, 2014 Audi A6, Audi A6, Audi A6, Audi A6, Audi A6, Used Audi

PREMIUM AD☐ Audi A6 2.0A TFSI MU

\$89,800

\$12,500 /yr

18-Oct-2014

1,984 cc

78,112 km

Luxury

Available

Graded B by **STA**

1 Owner! Fully Agent Maintained Unit With Documented Service History! STA Certified Accident Free Quality Pre Owned For Peace Of Mind. Trade In And In House Financing Available! View Today!

Posted: 27-Mar-2019 Tags: 2014 Audi A6, 2014 Audi A6, Audi A6, Audi A6, Audi A6, Audi A6, Used Audi

**Monster Tune - Specialist for Audi Car repair, servicing & maintenance**

Full service custom tuning workshop with dealer-level diagnostic support, fleet management and performance modifications capability.

[More info about this shop](#)

☐ Audi A6 2.0A TFSI MU

\$91,800

\$12,420 /yr

09-Dec-2014

1,984 cc

-

Luxury

Available

2.18% Interest! Worry About Getting A Pre-Owned Car? We Provide 1 Year Warranty For Your Peace Of Mind! 1 Owner! Major Servicing Done By Previous Owner! Flexible Loan Available, High Approval Rate! Hi...

AL Autocar Pte Ltd

Posted: 25-Mar-2019 Tags: 2014 Audi A6, 2014 Audi A6, Audi A6, Audi A6, Audi A6, Audi A6, Used Audi

PREMIUM AD☐ Audi A6 2.0A TFSI MU

\$96,888

\$13,190 /yr

29-Dec-2014

1,984 cc

55,000 km

Luxury

Available

Genuine Low Mileage Unit, Owned By A Single Car Enthusiastic With Tracked Records From Agent Since Day 1. Responsive MTM Stage 1 Tuned Up. Irresistible To Its Superb Condition. Perfectly Well Balanced...

Posted: 20-Mar-2019 Tags: 2014 Audi A6, 2014 Audi A6, Audi A6, Audi A6, Audi A6, Audi A6, Used Audi

PREMIUM AD

UNPUBLISHED NEW

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/04/2019 20:05
Date Of Accident	29/03/2019 18:00
Exact Location Of Accident	LENTOR AVENUE NEAR YISHUN AVE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKQ8750X
Insured/Policyholder	
Name Of Registered Owner	TEO SWEE HENG FREDERICK
NRIC No	S1636698F
Email Address	FREDTEO.KF@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82000002
Alternative Phone No	OTHERS-82000002
Vehicle Particulars	
Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU 4G
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800003745-01
Cover Note Number	
Driver	
Name of Driver	TEO SWEE HENG FREDERICK
NRIC No	S1636698F
Date Of Birth	28/10/1964
Occupation	INDOOR
Date Of Driving Pass	02/06/1983
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82000002
Fax Number	
Contact Number	OTHERS-82000002
Email Address	FREDTEO.KF@GMAIL.COM

Address	91 YISHUN AVENUE 1 #08-17
Postcode	769135
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG LENTOR AVENUE, NEAR YISHUN AVE 1, PLANNING TO TURN RIGHT INTO YISHUN AVE 1, WHEN THE GREEN LIGHT CAME ON, I SAW THE VEHICLE IN FRONT OF ME GETTING READY TO MOVE, I FOLLOWED BUT THE GREEN LIGHT DID NOT INCLUDE THE RED ARROW POINTING TO RIGHT SO THE VEHICLE IN FRONT DID NOT MOVE. BUT I DID. SO I BANGED ONTO THE BACK OF THE VEHICLE IN FRONT OF ME. WHEN I GOT OUT OF THE CAR, I REALISED THERE WAS ANOTHER VEHICLE IN FRONT OF THE CAR I BANGED ONTO. I.E. 3 CAR CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG3172G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD SHAFIE BIN ZULKIFLY
NRIC/Passport Number	S8540347H
Contact Number	87502736
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBD9850J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Nora Khai
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN 

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG LENSEL AVENUE, NEAR TURN
 AVE 1, PLANNING TO TURN RIGHT INTO
 YISHAN AVE 1.
 WHEN THE GREEN LIGHT CAME ON, I SAW
 THE VEHICLE IN FRONT OF ME ~~STARTING~~
 BEGINNING READY TO MOVE, I FOLLOWED.
 BUT THE GREEN LIGHT DID NOT INCLUDE
 THE RED ARROW POINTING TO RIGHT, SO
 THE VEHICLE IN FRONT DID NOT MOVE.
 BUT I DID, SO I RANLED ONTO
 THE BACK OF THE VEHICLE IN FRONT OF
 ME.
 WHEN I GOT OUT OF THE CAR,
 I REALISED THERE WAS ANOTHER VEHICLE
 IN FRONT OF THE CAR I RANLED ONTO
 I.E. 3 CAR CRASH COLLISION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: **Nora Khai**
 SAK/TFM No.:

Accident Photo



AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TEO SWEE HENG FREDERICK
Period of Insurance : 23 Jan 2019 To 22 Jan 2020
Engine No. : CDN405195
Chassis No. : WAUZZZ4G3EN119807

Vehicle No. : SKQ8750X
Policy No. : 1800003745-01
Endorsement No. :
Issued Date : 07 Jan 2019

ABOUT THE COVER

Make/Model : AUDI A6 C7 2.0 TFSI MU
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2014
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TEO SWEE HENG FREDERICK - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125249

PREMIUM LEASING -JTWH
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1636698F



Name

TEO SWEE HENG FREDERICK



张瑞兴

Race

CHINESE

Date of Birth

28-10-1984

Country of Birth

SINGAPORE

Sex

M



2881673



NRIC No. S1636698F



Blood Group

B+


Date of issue

27-12-1994

91 YISHUN AVENUE 1 #08-17
SINGAPORE 769135

S1636698F

30/10/2013



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0423/2019/KK
Date	:	2-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Teo Swee Heng Frederick
Address	:	91 Yisun Avenue 1 #08-17 Singapore 769135
Telephone	:	HP +65 82000002
Type of Claim	:	Own Damage Claims
Policy No.	:	1800003745-01
Vehicle No	:	SKQ 8750 X
Model Code	:	Audi A6 C7 2.0 TFSI MU 4G
Model / Year	:	Dec-14
Engine No	:	CDN 405195
Chassis No	:	WAUZZZ4G3EN119807
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	29-Mar-19
Place of Accident	:	Lentor Avenue Near Yisun Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 8750 X

S/N	Nature of Jobs	Estimated Charges
1	To remove , check and reinstall front wire harness for headlight , horns ,outside temperature sensor , headlight washer assy and front parking aid. s/n	\$ 480.00 ✓
2	To remove and transfer aircon condenser , radiator , charge air cooler , electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system. Renew accordingly. s/n	\$ 1,200.00 ? +
3	To dismantle and renew front bumper , both front fender , bonnet and both headlight. Renew front lock carrier and align to position. Reogarnize crash management components. Reinstall all parts removed. ✓ ✓ ✓	\$ 7,000.00 1500 excluding lock carrier. ✓
4	To respray front bumper , both front fender and bonnet. ✓	\$ 3,600.00 2200 ✓
5	To carry out diagnostic check. s/n	\$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 12,472.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	\$ 2,443.00	✓ 1954.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 249.00	*
3	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 172.00	*
4	FRONT BUMER SPOILER <i>new</i>	\$ 227.00	*
5	RADIATOR GRILLE <i>new</i>	\$ 1,227.00	✓ 981.60
6	RADIATOR GRILLE COVER <i>new</i>	\$ 33.00	✓ 26.08
7	FRONT BUMPER TRIM COVER <i>new</i>	\$ 90.00	?
8	FRONT BUMPER END CAP <i>new</i>	\$ 130.00	*
9	FRONT BUMER FOG LAMP COVER - RH <i>new</i>	\$ 139.00	*
10	FRONT BUMPER END CAP - LH <i>new</i>	\$ 36.00	*
11	FOAM FILLER PIECE <i>new</i>	\$ 90.00	?
12	FRONT REINFORCEMENT BEAM <i>new</i>	\$ 754.00	?
13	FRONT BUMOER COVER <i>new</i>	\$ 112.00	✓ 89.20
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 34.00	*
15	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 34.00	*
16	FRONT BUMPER BRACKET HOLDER - LH <i>new</i>	\$ 237.00	?
17	FRONT BUMPER BRACKET HOLDER - RH <i>new</i>	\$ 237.00	?
18	SIGN "CAUTION" <i>new</i>	\$ 13.00	✓ 9.76
19	AIR CONDITIONER STICKER <i>new</i>	\$ 18.00	✓ 14.00
20	FRONT BUMPER SENSOR <i>new</i>	2 \$ 462.00	*
SUB TOTAL SPARE PARTS		\$ 6,737.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET <i>Dented</i>	\$ 4,965.00	✓ 3972
22	BONNET ATTACHMENT PARTS <i>Not New</i>	\$ 130.00 ?	
23	LID HINGE - LH <i>See in</i>	\$ 146.00	+
24	LID HINGE - RH	\$ 146.00	+
25	GAS FILLED STRUT <i>See in</i>	2 \$ 217.00	+
26	STRUT BALL STUD <i>See in</i>	2 \$ 38.00	+
27	BONNET CATCH HOOK <i>Best</i>	\$ 90.00	? 101.60
28	BONNET LOCK BAR <i>See in</i>	2 \$ 90.00	?
29	BONNET SAFETY CATCH HOOK <i>See in</i>	\$ 16.00	?
30	MICRO-SWITCH LID LOCK <i>See in</i>	2 \$ 391.00	?
31	MICRO SWITCH <i>See in</i>	2 \$ 133.00	?
32	ENGINE BONNET INSULATOR <i>See in</i>	\$ 289.00	+
33	SIGNAL HORN HIGH TONE - LH <i>See in</i>	\$ 168.00	+
34	SIGNAL HORN LOW TONE - RH	\$ 262.00	+
35	SPRING SHACKLE - LH <i>See in</i>	\$ 43.00	+
36	FRONT FENDER - LH <i>Repair</i>	\$ 1,269.00	+
37	FRONT FENDER ATTACHMENT PARTS - LH <i>See in</i>	\$ 38.00	+
38	FRONT FENDER STONE GUARD FILM - LH <i>See in</i>	\$ 110.00	✓ 89
39	FRONT FENDER - RH <i>Repair</i>	\$ 1,269.00	+
40	FRONT FENDER ATTACHMENT PARTS - RH <i>See in</i>	\$ 38.00	+
SUB TOTAL SPARE PARTS		\$ 9,848.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FRONT FENDER STONE GUARD FILM - RH <i>New</i>	\$ 110.00	✓ 88
42	HEADLAMP MOUNTING BEAM - LH <i>New</i>	\$ 107.00	?X
43	HEADLAMP MOUNTING BEAM - RH <i>Damaged</i>	\$ 107.00	✓ 85 60
44	HEADLIGHT GAS DISCHARGE LAMP - LH <i>Cracked</i>	\$ 3,050.00	✓ 2440
45	HEADLIGHT GAS DISCHARGE LAMP - RH <i>Cracked</i>	\$ 3,050.00	✓ 2440
46	HEADLIGHT WASHER COVER CAP - LH <i>New</i>	\$ 52.00	?
47	HEADLIGHT WASHER COVER CAP - RH <i>New</i>	\$ 52.00	?
48	COOLANT RADIATOR LOCK CARRIER <i>New</i>	\$ 1,140.00	?
49	A/C CONDENSER <i>New</i>	\$ 689.00	?
50	COOLANT COOLER <i>New</i>	\$ 394.00	?
51	RADIATOR RUBBER BUSH - UPPER <i>New</i>	2 \$ 12.00	+
52	RADIATOR RUBBER BUSH - CENTER <i>New</i>	2 \$ 18.00	+
53	RADIATOR RUBBER BUSH - LOWER <i>New</i>	2 \$ 24.00	+
54	READY-MIX COOLANT <i>New</i>	4 \$ 84.00	?
55	AIR GUIDE - LH <i>New</i>	\$ 29.00	+
56	AIR GUIDE - RH <i>New</i>	\$ 29.00	+
57	AIR GUIDE COVER - UPPER CENTRE <i>New</i>	\$ 27.00	+
58	TWIN FAN RING <i>New</i>	\$ 237.00	+
59	RADIATOR FAN <i>New</i>	\$ 811.00	+
60	RADIATOR FAN CONTROL UNIT <i>New</i>	\$ 778.00	+
SUB TOTAL SPARE PARTS		\$ 10,800.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	FRONT BUMPER FOG LAMP COVER - LH <i>new</i>	\$ 139.00	<i>✓</i>
62	FRONT NO PLATE <i>Bent</i>	S/N \$ 25.00	<i>✓</i>
63	SUNDRIES <i>new</i>	\$ 800.00	<i>224</i>
TOTAL SPARE PARTS		: \$ 28,349.00	
TOTAL LABOUR CHARGES		: \$ 12,472.00	
GRAND TOTAL		: \$ 40,821.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

41673.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Ling

Surveyed Date

: 03/04/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 06 Days. (excluding lock carter)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0423/2019/KK
Date : 2-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
6 days exclude 1 PH & 1 Sunday
jb 7 May 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Teo Swee Heng Frederick
Address : 91 Yisun Avenue 1
#08-17
Singapore 769135
Telephone : HP +65 82000002
Type of Claim : Own Damage Claims
Policy No. : 1800003745-01
Vehicle No : **SKQ 8750 X**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : Dec-14
Engine No : CDN 405195
Chassis No : WAUZZZ4G3EN119807
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Mar-19
Place of Accident : Lentor Avenue Near Yisun Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 8750 X

S/N	Nature of Jobs	Estimated Charges			
1	To remove , check and reinstall front wire harness for headlight , horns ,outside temperature sensor , headlight washer assy and front parking aid.	s/n	\$ 480.00	\$	480.00
2	To remove and transfer aircon condenser , radiator , charge air cooler , electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system. Renew accordingly.	s/n	\$ 1,200.00		
3	To dismantle and renew front bumper , both front fender , bonnet and both headlight. Renew front lock carrier and align to position. Reogarnize crash management components. Reinstall all parts removed.		\$ 7,000.00	\$	1,500.00
4	To respray front bumper , both front fender and bonnet.		\$ 3,600.00	\$	2,200.00
5	To carry out diagnostic check.	s/n	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,472.00	\$	4,372.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,443.00	\$ 1,954.40
2	FRONT BUMPER FIXING PARTS	\$ 249.00	
3	FRONT BUMPER CLOSING ELEMENT	\$ 172.00	
4	FRONT BUMER SPOILER	\$ 227.00	
5	RADIATOR GRILLE	\$ 1,227.00	\$ 981.60
6	RADIATOR GRILLE COVER	\$ 33.00	\$ 26.08
7	FRONT BUMPER TRIM COVER	\$ 90.00	
8	FRONT BUMPER END CAP	\$ 130.00	
9	FRONT BUMER FOG LAMP COVER - RH	\$ 139.00	
10	FRONT BUMPER END CAP - LH	\$ 36.00	
11	FOAM FILLER PIECE	\$ 90.00	
12	FRONT REINFORCEMENT BEAM	\$ 754.00	
13	FRONT BUMOER COVER	\$ 112.00	\$ 89.20
14	FRONT BUMPER GUIDE SECTION - LH	\$ 34.00	
15	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	
16	FRONT BUMPER BRACKET HOLDER - LH	\$ 237.00	
17	FRONT BUMPER BRACKET HOLDER - RH	\$ 237.00	
18	SIGN "CAUTION"	\$ 13.00	\$ 9.76
19	AIR CONDITIONER STICKER	\$ 18.00	\$ 14.00
20	FRONT BUMPER SENSOR	2 \$ 462.00	
	SUB TOTAL SPARE PARTS	\$ 6,737.00	\$ 3,075.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	3,075.04
21	BONNET	\$	4,965.00	\$ 3,972.00
22	BONNET ATTACHMENT PARTS	\$	130.00	
23	LID HINGE - LH	\$	146.00	
24	LID HINGE - RH	\$	146.00	
25	GAS FILLED STRUT	2 \$	217.00	
26	STRUT BALL STUD	2 \$	38.00	
27	BONNET CATCH HOOK	\$	90.00	\$ 101.60
28	BONNET LOCK BAR	2 \$	90.00	
29	BONNET SAFETY CATCH HOOK	\$	16.00	
30	MICRO-SWITCH LID LOCK	2 \$	391.00	
31	MICRO SWITCH	2 \$	133.00	
32	ENGINE BONNET INSULATOR	\$	289.00	
33	SIGNAL HORN HIGH TONE - LH	\$	168.00	
34	SIGNAL HORN LOW TONE - RH	\$	262.00	
35	SPRING SHACKLE - LH	\$	43.00	
36	FRONT FENDER - LH	\$	1,269.00	
37	FRONT FENDER ATTACHMEN PARTS - LH	\$	38.00	
38	FRONT FENDER STONE GUARD FILM - LH	\$	110.00	\$ 88.00
39	FRONT FENDER - RH	\$	1,269.00	
40	FRONT FENDER ATTACHMENT PARTS - RH	\$	38.00	
	SUB TOTAL SPARE PARTS	:	\$ 9,848.00	\$ 7,236.64

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SKQ 8750 X

		Damage Parts & Prices		
S/N	Parts Description		S/NETT	REMARKS
		c/f	\$	7,236.64
41	FRONT FENDER STONE GUARD FILM - RH		\$ 110.00	\$ 88.00
42	HEADLAMP MOUNTING BEAM - LH		\$ 107.00	
43	HEADLAMP MOUNTING BEAM - RH		\$ 107.00	\$ 85.60
44	HEADLIGHT GAS DISCHARGE LAMP - LH		\$ 3,050.00	\$ 2,440.00
45	HEADLIGHT GAS DISCHARGE LAMP - RH		\$ 3,050.00	\$ 2,440.00
46	HEADLIGHT WASHER COVER CAP - LH		\$ 52.00	
47	HEADLIGHT WASHER COVER CAP - RH		\$ 52.00	
48	COOLANT RADIATOR LOCK CARRIER		\$ 1,140.00	
49	A/C CONDENSER		\$ 689.00	
50	COOLANT COOLER		\$ 394.00	
51	RADIATOR RUBBER BUSH - UPPER	2	\$ 12.00	
52	RADIATOR RUBBER BUSH - CENTER	2	\$ 18.00	
53	RADIATOR RIBBER BUSH - LOWER	2	\$ 24.00	
54	READY-MIX COOLANT	4	\$ 84.00	
55	AIR GUIDE - LH		\$ 29.00	
56	AIR GUIDE - RH		\$ 29.00	
57	AIR GUIDE COVER - UPPER CENTRE		\$ 27.00	
58	TWIN FAN RING		\$ 237.00	
59	RADIATOR FAN		\$ 811.00	
60	RADIATOR FAN CONTRO UNIT		\$ 778.00	
	SUB TOTAL SPARE PARTS	:	\$ 10,800.00	\$ 12,290.24

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 8750 X

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	12,290.24
61	FRONT BUMPER FOG LAMP COVER - LH		\$ 139.00	
62	FRONT NO PLATE	S/N	\$ 25.00	\$ 25.00
63	<i>Added parts -see attached</i>		\$ 1,051.00	\$ 840.80
64	SUNDRIES		\$ 800.00	\$ 2.24
	TOTAL SPARE PARTS	:	\$ 28,349.00	\$ 13,158.28
	TOTAL LABOUR CHARGES	:	\$ 12,472.00	\$ 4,372.00
	GRAND TOTAL	:	\$ 40,821.00	\$ 17,530.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0423/2019/KK 2-May-19 Glory Tan 1 of 1 SKQ 8750 X Audi A6 C7 2.0 TFSI MU 4G
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Control unit for LED headlight. <i>Qty 1</i>	\$ 1,051.00	\$ 840.80 ✓
		<u>\$ 1,051.00</u>	<u>\$ 840.80</u>
<u>LABORS</u>			
	TOTAL	\$ 1,051.00	\$ 840.80

Adrian Ling

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1187

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
7B Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/0010423/2019/REK
Date 2-May-18
Service Advisor Glory Tan
Pages 1 of 1
Regn No SKD 8750 X
Model No Audi A6 C7 2.0 TFSI H&J 4C

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Control unit for LED headlights. <i>Damaged</i>	\$ 1,051.00	✓

\$ 1,051.00

LABORS

TOTAL \$ 1,051.00

For Premium Automobiles Pte Ltd

Adrian Ling
AL

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKQ 8750 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0423/2019/MAS

23 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKQ 8750 X, Audi A6 C7 2.0 TFSI

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SKQ 8750 X**, claimant, **Mr. Teo Swee Heng Frederick**, please find the related document per attached.

1. A copy of the Original invoice no. 85013756 – S\$16,264.00
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKQ 8750 X



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone: 6386 2223
Main Telex: 6472 3723

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6386 2223
Telex: 6472 3723

Ubi Service Centre
95 Ubi Road 1
Singapore 408723
Telephone: 6386 2223
Telex: 6472 3723

Customer Service
Service Appointment
Service Information
Service Loan Service
customer.care@premiumauto.com.sg

6386 2223
9828 1233

INS TAX INVOICE
Company Reg No. 199902271W
GST Reg. No. 199902271W

Page 1 14:27

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013756 Date: 10/05/2019 Order: SKQ8750X Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKQ8750X Regn Date: 31/12/2014 Mileage: 49739 WIP NO: 48460

Model: A6 C7 2.0 TFSI Chassis: WAUZZZ4G3EN119807 Engine: CDN 405195 Dept: U

VSF No:

You have been assisted by:- UB-Jiayee (138)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT repair basis as agreed	16,000.00	1.00	16,000.00
Q	EXC	Insurance Excess/Liability	-800.00	1.00	-800.00

Parts 0.00
Labour 0.00
Sublet 16,000.00
Menus 0.00
Lubricant 0.00

Sub-Total 15,200.00
7% GST 1,064.00
Grand Total 16,264.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKQ 8750 X

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0423/2019/KK
3 May 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A6 C7 2.0 TFSI
Vehicle Chassis No. : WAUZZZ4G3EN119807
Vehicle Regn No. : **SKQ 8750 X**
Vehicle Mileage : 49739 KM
Vehicle Owner : Mr. Teo Swee Heng Frederick
Certificate No : 1800003745-01
Own Damage Excess : S\$856.00 (Inclusive 7% GST)
Accident Date : 29 March 2019
Place : Lentor Avenue Near Yisun Ave 1
Repair Cost : \$ 16,264.00
WIP No. : 48460
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :


Time :

Date :



3/5/19 @ 6pm

3/5/19



AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TEO SWEE HENG FREDERICK
 Period of Insurance : 23 Jan 2019 To 22 Jan 2020
 Engine No. : CDN405195
 Chassis No. : WAUZZZ4G3EN119807

Vehicle No. : SKQ8750X
 Policy No. : 1800003745-01
 Endorsement No. :
 Issued Date : 07 Jan 2019

ABOUT THE COVER

Make/Model : AUDI A6 C7 2.0 TFSI MU
 Engine Capacity/Tonnage : 1,984.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2014
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TEO SWEE HENG FREDERICK - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125249

PREMIUM LEASING -JTWH
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2019 10:27		03 Apr 2019 16:58 Edit Adj Rpt	S\$16,000.00 Edit Estimates	S\$16,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TEO SWEE HENG FREDERICK , ID: S1636698F, Tel: +6582000002, Email: FREDTEO.KF@GMAIL.COM									
Vehicle Reg. No.: SKQ8750X		Date of Loss: 29/03/2019 18:00 - :59 [50 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 9861743733SG		Policy/Cover Note No.: (Comprehensive)							
		Excess: S\$800.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/04/2019]									
Driver/Custodian: TEO SWEE HENG FREDERICK (54 / Male), NRIC: S1636698F, Tel: +6582000002 Email: FREDTEO.KF@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (12/04/2019): Alert - Adj Mandate Approved (S\$16000.00) - SKQ8750X - Claim Handler: Loo, Tong ... - AIG_SG (04/04/2019): SKQ8750X / OD / 29/03/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ8750X (9861743733SG)
OD
Mar 29 2019 6:00PM
[TEO SWEE HENG FREDERICK]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser v		
Assessment Reports												1 per page v		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	11/04/19 16:30	Adjuster Immediate Advice												Load HTM			
2	11/04/19 16:50	Adjuster Immediate Advice												Load HTM			
Photos/Images												3 per page v		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	04/04/19 10:16	General View												Load JPG	☒		
2	04/04/19 10:16	General View												Load JPG	☒		
3	04/04/19 10:16	General View												Load JPG	☒		
4	04/04/19 10:16	General View												Load JPG	☒		
5	04/04/19 10:16	General View												Load JPG	☒		
6	04/04/19 10:16	General View												Load JPG	☒		
7	04/04/19 10:16	General View												Load JPG	☒		
8	04/04/19 10:16	General View												Load JPG	☒		
9	04/04/19 10:16	General View												Load JPG	☒		
10	04/04/19 10:16	General View												Load JPG	☒		
11	04/04/19 10:16	General View												Load JPG	☒		
12	04/04/19 10:16	General View												Load JPG	☒		
13	04/04/19 10:16	General View												Load JPG	☒		
14	04/04/19 10:16	General View												Load JPG	☒		
15	04/04/19 10:16	General View												Load JPG	☒		
16	04/04/19 10:16	General View												Load JPG	☒		
17	04/04/19 10:16	General View												Load JPG	☒		
18	04/04/19 10:16	General View												Load JPG	☒		
19	04/04/19 10:16	General View												Load JPG	☒		
20	04/04/19 10:16	General View												Load JPG	☒		
21	04/04/19 10:16	General View												Load JPG	☒		
22	04/04/19 10:16	General View												Load JPG	☒		
23	04/04/19 10:16	General View												Load JPG	☒		
24	04/04/19 10:16	General View												Load JPG	☒		
25	04/04/19 10:16	General View												Load JPG	☒		
26	04/04/19 10:16	General View												Load JPG	☒		
27	04/04/19 10:16	General View												Load JPG	☒		
28	04/04/19 10:16	General View												Load JPG	☒		
29	04/04/19 10:16	General View												Load JPG	☒		
30	04/04/19 10:16	General View												Load JPG	☒		
31	04/04/19 10:16	General View												Load JPG	☒		
32	04/04/19 10:16	General View												Load JPG	☒		
33	04/04/19 10:16	General View												Load JPG	☒		
34	08/05/19 17:35	Reinspection Photo												Load JPG	☒		

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
35	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
36	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
37	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
38	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
39	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
40	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
41	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
42	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
43	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
44	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
45	08/05/19 17:35	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/04/19 10:15	Driver's Driving License and NIRC	 Load PDF		
2	04/04/19 10:15	Certificate of Insurance	 Load PDF		
3	04/04/19 10:15	Singapore Accident Statment	 Load PDF		
4	04/04/19 10:36	SG CAR MART AND LTA CARD	 Load PDF		
5	11/04/19 16:47	ESTIMATE	 Load PDF		
6	14/06/19 12:56	Workshop Invoice	 Load PDF		
7	14/06/19 12:56	Discharge Voucher	 Load PDF		
8	14/06/19 14:13	Supplementary	 Load PDF		

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/04/19 20:29	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/04/19 20:26	Accident Photo	 Load JPG	☒	
2	01/04/19 20:26	Accident Photo	 Load JPG	☒	
3	01/04/19 20:26	Accident Photo	 Load JPG	☒	
4	01/04/19 20:26	Accident Photo	 Load JPG	☒	
5	01/04/19 20:26	Accident Photo	 Load JPG	☒	
6	01/04/19 20:26	Accident Photo	 Load JPG	☒	
7	01/04/19 20:26	Accident Photo	 Load JPG	☒	
8	01/04/19 20:26	Accident Photo	 Load JPG	☒	
9	01/04/19 20:26	Accident Photo	 Load JPG	☒	
10	01/04/19 20:26	Accident Photo	 Load JPG	☒	
11	01/04/19 20:29	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	01/04/19 20:22	Sketch Plan	 Load JPG	☒	
2	01/04/19 20:22	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19005920/ATD3E2

Date: 14/06/2019

REFERENCE

Insured/Claimant: TEO SWEE HENG FREDERICK

Policy No:

Date of Loss: 29/03/2019

Nature of Claim: OD Claim No: 9861743733SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ8750X**
Make & Model: AUDI A6, 2.0 TFSI MU (A)
Reg. Date: 31/12/2014 (Man. Year: 2014)
Colour: Grey
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CDN405195
Chassis No: WAUZZZ4G3EN119807
Odometer: 49255 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,201.40	13,158.28	16,043.12	54.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,472.00	4,372.00	8,100.00	64.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,673.40	17,530.28	24,143.12	57.93
Approved Total (Overridden) (S\$)		16,000.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	40,873.40	15,200.00	25,673.40	62.81
+ GST 7.00/7.00% (S\$)	2,861.14	1,064.00	1,797.14	62.81
Nett Amount (S\$)	43,734.54	16,264.00	27,470.54	62.81

INSPECTION

Date of Assignment: 03/04/2019

Date Inspected: 03/04/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,443.00 FS	*1,954.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	249.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	172.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
5	1		*RADIATOR GRILLE	Cracked	1,227.00 FS	*981.60 FS
6	1		*RADIATOR GRILLE COVER	Cracked	33.00 FS	*26.08 FS
7	1		*FRONT BUMPER TRIM COVER	Not Necessary	90.00 FS	*- FS
8	1		*FRONT BUMPER END CAP	Not Necessary	130.00 FS	*- FS
9	1		*FRONT BUMPER FOG LAMP COVER - RH	Not Necessary	139.00 FS	*- FS
10	1		*FRONT BUMPER END CAP - LH	Not Necessary	36.00 FS	*- FS
11	1		*FOAM FILLER PIECE	Not Necessary	90.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	754.00 FS	*- FS
13	1		*FRONT BUMPER COVER	Damaged	112.00 FS	*89.20 FS
14	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	34.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	34.00 FS	*- FS
16	1		*FRONT BUMPER BRACKET HOLDER - RH	Not Necessary	237.00 FS	*- FS
17	1		*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
18	1		*AIR CONDITIONER STICKER	Necessary	18.00 FS	*14.00 FS
19	2		*FRONT BUMPER SENSOR	Not Necessary	462.00 FS	*- FS
20	1		*BONNET	Dented	4,965.00 FS	*3,972.00 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	130.00 FS	*- FS
22	1		*LID HINGE - LH	Not Necessary	146.00 FS	*- FS
23	1		*LID HINGE - RH	Not Necessary	146.00 FS	*- FS
24	2		*GAS FILLED STRUT	Not Necessary	217.00 FS	*- FS
25	2		*STRUT BALL STUD	Not Necessary	38.00 FS	*- FS
26	1		*BONNET CATCH HOOK	Bent	101.60 FS	*101.60 FS
27	2		*BONNET LOCK BAR	Not Necessary	90.00 FS	*- FS
28	1		*BONNET SAFETY CATCH HOOK	Not Necessary	16.00 FS	*- FS
29	2		*MICRO-SWITCH LID LOCK	Not Necessary	391.00 FS	*- FS
30	2		*MICRO SWITCH	Not Necessary	133.00 FS	*- FS
31	1		*ENGINE BONNET INSULATOR	Not Necessary	289.00 FS	*- FS
32	1		*SIGNAL HORN HIGH TONE - LH	Not Necessary	168.00 FS	*- FS
33	1		*SIGNAL HORN LOW TONE - RH	Not Necessary	262.00 FS	*- FS
34	1		*SPRING SHACKLE - LH	Not Necessary	43.00 FS	*- FS
35	1		*FRONT FENDER - LH	Repair	1,269.00 FS	*- FS
36	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	38.00 FS	*- FS
37	1		*FRONT FENDER STONE GUARD FILM - LH	Necessary	110.00 FS	*88.00 FS
38	1		*FRONT FENDER - RH	Repair	1,269.00 FS	*- FS
39	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	38.00 FS	*- FS
40	1		*FRONT FENDER STONE GUARD FILM - RH	Necessary	110.00 FS	*88.00 FS
41	1		*HEADLAMP MOUNTING BEAM - LH	Not Necessary	107.00 FS	*- FS
42	1		*HEADLAMP MOUNTING BEAM - RH	Damaged	107.00 FS	*85.60 FS
43	1		*HEADLIGHT GAS DISCHARGE LAMP - LH	Cracked	3,050.00 FS	*2,440.00 FS
44	1		*HEADLIGHT GAS DISCHARGE LAMP - RH	Cracked	3,050.00 FS	*2,440.00 FS
45	1		*HEADLIGHT WASHER COVER CAP - LH	Not Necessary	52.00 FS	*- FS
46	1		*HEADLIGHT WASHER COVER CAP - RH	Not Necessary	52.00 FS	*- FS
47	1		*COOLANT RADIATOR LOCK CARRIER	Not Necessary	1,140.00 FS	*- FS
48	1		*A/C CONDENSER	Not Necessary	689.00 FS	*- FS
49	1		*COOLANT COOLER	Not Necessary	394.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*RADIATOR RUBBER BUSH - UPPER	Not Necessary	12.00 FS	*- FS
51	2		*RADIATOR RUBBER BUSH - CENTER	Not Necessary	18.00 FS	*- FS
52	2		*RADIATOR RUBBER BUSH - LOWER	Not Necessary	24.00 FS	*- FS
53	4		*READY-MIX COOLANT	Not Necessary	84.00 FS	*- FS
54	1		*AIR GUIDE - LH	Not Necessary	29.00 FS	*- FS
55	1		*AIR GUIDE - RH	Not Necessary	29.00 FS	*- FS
56	1		*AIR GUIDE COVER - UPPER CENTRE	Not Necessary	27.00 FS	*- FS
57	1		*TWIN FAN RING	Not Necessary	237.00 FS	*- FS
58	1		*RADIATOR FAN	Not Necessary	811.00 FS	*- FS
59	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	778.00 FS	*- FS
60	1		*FRONT BUMPER FOG LAMP COVER - LH	Not Necessary	139.00 FS	*- FS
61	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
62	1		*SUNDRIES	Necessary	800.00 FS	*2.24 FS
63	1		*CONTROL UNIT FOR LED HEADLIGHT	Damaged	840.80 FS	*840.80 FS
64	1		*FRONT BUMPER BRACKET HOLDER - LH	Not Necessary	237.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	29,201.40	13,158.28
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGE AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM. RENEW ACCORDINGLY	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	1,500.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER AND BONNET	New	3,600.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,472.00	4,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >