

Form No. 10

REF: CS / INC19005929/64d3

Special Instruction

Surveyor: Guanqiang

ASSIGNMENT (Office)

From/Person: Annie Koh

of INC

Date/Time: 3/4/2019 @ 9.43am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SGF 1590S

Insured: SGG 5105D

at Workshop no: Thiam Heng Huat  
of 176 Sin Ming Drive # 05-14

Tel: 8263 6295

Policy No: \_\_\_\_\_ Claim No: MT/1038156-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A: 30/03/2019  
(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time: 10:17am 3/4/19 Person Contacted: Steven

Vehicle  IN  OFF

Date/Time	Action/Instruction (✓) Estimate
	SGF 1590S - X
	SGG 5105D - MJA/MSI09021413/K1 D.O.A - 23/09/2009

SYMPHONY

62.

REF: INC

6749B

ASSIGNMENT

(-2021)


From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Thiam Heng Huat  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SGF1590S Yr Regn: 03 Apr 2006  
 Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mit Lancer 1.6 cc 1584  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 543882 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JMYSTCS 3A 6U 008021  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In Order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In Order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

<input checked="" type="radio"/>	
N/S	O/S
<input checked="" type="radio"/>	

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$13K  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 8 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Tyre Size: F: 195/60 R15  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Roadstone  
 Front Rear  
 R/Bal. 5 mm 5 mm  
 L/Bal. 5 mm 5 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 03-04-19  
 Survey held at w/s 12:30 pm  
 Des. of Damages:  Frt. /  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
03/4 finalized \$4000 with Ah Di (red: 17039.90; 80%)  
 RECEIVED 10 APR 2019  
  
9/4/2019

Date/Time, File Pass to?  Preli. Report  
 Final Report  
 1) 10/4 Typist  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: TP  
 Lump Sum / I.B.I. (\$) 4000  
 Days Of Repair: 8  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech. Invs (\$ )  Weekend (\$ )  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_

## Nivitha (LKK Auto)

---

**From:** Annie Koh <annie.koh@income.com.sg>  
**Sent:** Wednesday, 3 April 2019 9:43 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** SUR  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 03/04/2019

Re-send

Warmest Regards

Annie Koh  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 3 April 2019 9:38 AM  
**To:** Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 03/04/2019

Dear Annie,

Thank you for the assignment.

Please be informed that XE 2773D (LEE KUAN HWA) is not in the workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Annie Koh [mailto:annie.koh@income.com.sg]  
**Sent:** Wednesday, 3 April 2019 9:32 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>  
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1	HELENA TAN	MT/1036593-002	XE2773D	LEE KUAN HWA MOTOR SERVICE	24 SUNGAI KADUT STREET 4 SUNGAI KADUT INDUSTRIAL ESTATE SINGAPORE 729050	Siew Chen / 6269 9192	10:00-12:00	SMF4403J	19/3/19
2	DAVID PHUA	MT/1038186-002	SGF1590S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGG5105D	30/3/19
3	FIONA SHEN	MT/1038371-002	SKQ2664B	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLM2152X	29/3/19

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh  
Senior Admin Assistant, Motor Insurance  
T +65 6430 7899  
[www.income.com.sg](http://www.income.com.sg)



---

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/04/2019 16:26
Date Of Accident	30/03/2019 12:05
Exact Location Of Accident	CLEMENTI ROAD TOWARDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGF1590S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JASIN BIN NASIMAN
NRIC No	S0216749B
Email Address	JASIN.NGASIMAN@KGMELAKA.MOSQUE.ORG.SG
Mobile Phone No	(LOCAL) +65-96645065
Alternative Phone No	OTHERS-NOPHONE

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MT100544
Cover Note Number	

### Driver

Name of Driver	JASIN BIN NASIMAN
NRIC No	S0216749B
Date Of Birth	14/05/1948
Occupation	INDOOR
Date Of Driving Pass	27/06/1977
Driving Experience	41 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96645065
Fax Number	
Contact Number	OTHERS.NOPHONE

Address	BLK 650 SENJA LINK #04-08
Postcode	670650
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN. NOTE: VEHICLE REPAIR AT OWNER PREFERRED WORKSHOP.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGG5015D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NIZAM

NRIC/Passport Number

Contact Number

91833814

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

JASIN BIN NASIMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGF1590S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time: 1-4-2019

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 1-4-2019

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 30-03-2019 Time: 12:03pm Location: CEMENT 1 ROAD TOWARDS A.Y.E  
 Veh A: SGF1590S Veh B: SGG501SD No of pax: 1 Weather: Clear/dry Rain/Wet  
 SKETCH PLAN Veh C: SLE270T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- TRAFFIC WAS HEAVY
- AT THE RED TRAFFIC LIGHT JUNCTION, THERE WERE MANY CARS STOPPED IN FRONT OF MY VEHICLE.
- MY CAR SGF1590S(A) WAS ALSO STOPPED. SUDDENLY SGG501SD(B) BANGED INTO THE REAR OF MY VEHICLE SGF1590S(A)
- AS A RESULT MY VEHICLE SGF1590S(A) WAS PUSHED FORWARD AT VEHICLE SLE270T(C)

VEHICLE B = NA

VEHICLE C = MR NIZAM = 918 33814 (HP)

ACCIDENT SITE PHOTO = YES

Remarks: Please forward a copy of my efile accident report to:

My workshop :  
 Email address : thiamhenghust@gmail.com  
 & myself :  
 Email address : jasin.ngasiman@kgmelaka.masque.org.sg  
 I/Phone :


Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

OWNER/DRIVER WAP 6645065

  
 Policyholder's Signature

  
 Driver's Signature  
 (If driver is not the policyholder)



Date & Time: 1-4-2019

Date & Time: 1-4-2019

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6749B
Vehicle No.:	SGF1590S
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	4G18HC4452
Chassis No.:	JMYSTCS3A6U008021
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,295.00
Original Registration Date:	03 Apr 2006
First Registration Date:	03 Apr 2006
Transfer Count:	0
Actual ARF Paid:	\$14,625.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	02 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$9,204.00
<b>Total Rebate Amount:</b>	<b>\$9,204.00</b>
<p>Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.</p>	

The information contained herein is correct as at 03 Apr 2019

OK

## ▶ Lancer Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Mitsubishi Lancer 1.6A GLX</b> (COE till 04/2021)	<b>\$13,800</b>	\$6,760 /yr	18-Apr-2006	1,584 cc	-	ABWIN (1994) Pte Ltd	<b>Available</b>
100% Loan Available, In House Loan A Very Good Car For Trusted And Durable Call Now To View. Office No. - - Kin Meng - 92282214   Yap - 92795559							
<b>Mitsubishi Lancer 1.6A GLX</b> (COE till 05/2021)	<b>\$15,000</b>	\$6,940 /yr	28-Jun-2006	1,584 cc	-	SG Car Consign Pte Ltd	<b>Available</b>
After You Make Some Comparison Of The Prices And Depreciation Of Most Lancer, You'll Find That This Lancer Is Of Low Depreciation And Has The Best Value For Your Money. Owned By Executive Owner Sellin... Office No. - 61000200 Danny Loh - 97622873   Joey Kwan - 87158050   Andy Tay - 94891030							
<b>Mitsubishi Lancer 1.6M GLX</b> (COE till 05/2021)	<b>\$14,000</b>	\$6,480 /yr	10-Jul-2006	1,584 cc	-	Monster Motors Pte Ltd	<b>Available</b>
Cheap And Modded Lancer. S90 Throttle Body, Open Pod Hurricane Filter, Drift Racing Exhaust. Mods Will Go With The Car. WhatsApp Or Call To Book An Appointment For Viewing! Loans And Trade-ins Availab... Office No. - - Enzo - 97598881   Ryan - 92325669							
<b>Mitsubishi Lancer 1.6A GLX</b> (COE till 08/2021)	<b>\$16,000</b>	\$6,630 /yr	12-Sep-2006	1,584 cc	125,364 km	Corsica Trading	<b>Available</b>
Low Mileage, Well Maintained And Regularly Serviced, Sports Rims, Leather Seats, Reverse Sensor, No Repairs Needed. Office No. - 67775005 Woo Kok Wah - 90086666   Mr Kelvin Goh - 96786666							
<b>Mitsubishi Lancer 1.6M GLX</b> (COE till 10/2021)	<b>\$16,800</b>	\$6,650 /yr	12-Oct-2006	1,584 cc	190,000 km		<b>Available</b>
Regular Servicing, Driven By Lady Owner, Careful Driver, Interior And Exterior Well Taken Care, Test Drive With No Obligation. Office No. - - Jerina - 91811664   Saik Nural - 90076873							
<b>Mitsubishi Lancer 1.6M GLX</b> (COE till 08/2021)	<b>\$24,000</b>	\$9,940 /yr	18-Oct-2006	1,584 cc	190,000 km	Car Empire Automobiles Pte Ltd	<b>Available</b>
Very Low Petrol Consumption Easy Maintenance! Well Maintained By Previous Owner Tuned Before For Better Fuel Consumption. High Loan Available. Office No. - 69097310 Samuel - 97222822   Soon - 97379527   Lucas Lim - 87506761   Sean - 90120468							
<b>Mitsubishi Lancer 1.6M GLX</b> (COE till 11/2021)	<b>\$18,688</b>	\$7,140 /yr	15-Nov-2006	1,584 cc	-		<b>Available</b>
100% Accident Free And Serviced Regularly. Stock Condition Without Any Modification. Office No. - - Martin Foo - 88118855							
<b>Mitsubishi Lancer 1.6A GLX</b> (COE till 12/2021)	<b>\$16,800</b>	\$6,190 /yr	19-Dec-2006	1,584 cc	-	Mr Benz Traders	<b>Available</b>
2 Owners Only. Original Car Paintwork! Extremely Well Maintained! Low Mileage. Accident-Free. Don't Miss This Beauty! Kindly Call Our Friendly Sales Person For Viewing The Car Now. Office No. - 63461282 Bernard Foong - 96609891   Chester Lee - 90676766   Ansel Tan - 98607949   Stanley - 90012123							
<b>Mitsubishi Lancer 1.6A GLX</b> (COE till 02/2022)	<b>\$20,800</b>	\$7,290 /yr	09-Feb-2007	1,584 cc	-	Car Guru.Com Pte Ltd	<b>Available</b>
Smooth Engine, Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now B... Office No. - 67639595 Lawrence - 92228747   Jimmy - 90079944							

# Thiam Heng Huat

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Vehicle model: Mitsubishi Lancer GLX

Number plate: SGF15905

List items			
No.	Description	Unit	Amount
1	Front bumper / ee.	1	\$ 460.00
2	Front bumper retainers L+R@\$28.00 - ee	2	\$ 56.00
3	Front bumper lower spoiler / CAA.	1	\$ 330.00
4	Radiator grille X NN	1	\$ 230.00
5	Radiator grille "Mitsubishi Diamond" emblem / ee.	1	\$ 55.00
6	Front bumper lower grille X NN	1	\$ 156.00
7	Front bumper reinforcement X BT	1	\$ 185.00
8	Front Bumper impact absorber X	1	\$ 95.00
9	Front foglamps L+R@\$125.00 X NN	2	\$ 250.00
10	Front foglamps garnish L+R@\$80.00 X NN	2	\$ 160.00
11	Front licence plate garnish / ee.	1	\$ 45.00
12	Headlamps L+R@\$520.00 X NN	2	\$ 1,040.00
13	Front fenders L+R@\$580.00 X repair.	2	\$ 1,160.00
14	Front fenders inner cowlings L+R@\$120.00 X	2	\$ 240.00
15	Front support panel X NN	1	\$ 198.00
16	Front support panel top garnish X	1	\$ 58.00
17	Bonnet X repair	1	\$ 370.00
18	Bonnet hinges L+R@\$26.00 X NN	2	\$ 52.00
19	Bonnet insulator X NN	1	\$ 189.00
20	A/C condenser X	1	\$ 580.00
21	Rear bumper / ee.	1	\$ 460.00
22	Rear bumper lower spoiler / O/S.	1	\$ 330.00
23	Rear bumper side retainers L+R@28.00 / ee.	2	\$ 56.00
24	Rear Bumper reinforcement / BT	1	\$ 185.00
25	Rear Bumper impact absorber X NN	1	\$ 95.00
26	Rear fenders L+R@\$620.00 X repair.	2	\$ 1,240.00
27	Rear fender inner cowling L+R@\$120.00 / ee.	2	\$ 240.00
28	Taillamps L+R@\$480.00 / CAA.	2	\$ 960.00
29	Taillamps seal sponge L+R@\$18.00 X NN	2	\$ 36.00
30	Taillamps panel L+R@\$80.00 X repair.	2	\$ 160.00
31	End panel / Bnc.	1	\$ 380.00
32	End Panel top garnish / ee.	1	\$ 145.00
33	Bootlid / BT	1	\$ 520.00
34	Bootlid spoiler X NN	1	\$ 290.00
35	Bootlid spoiler 3rd brake lamp X NN	1	\$ 86.00
36	Bootlid no. plate garnish X repair	1	\$ 79.00
37	Bootlid keylock cylinder X NN	1	\$ 85.00

794.4

38	Bootlid licence plate lamp L+R@\$85.00	X NN	2	\$	170.00
39	Boot weatherstrip	/ Twi	1	\$	105.00
40	Bootlid "LANCER" emblem	/	1	\$	23.00
41	Bootlid "GLX" emblem	/	1	\$	18.00
42	Bootlid "Mitsubishi Diamond" emblem	/ m.c.	1	\$	55.00
43	Bootlid inner trim	X NN	1	\$	145.00
44	Bootlid top lock	/ BT	1	\$	122.00
45	Bootlid lock striker	X NN	1	\$	53.00
46	Rear fender inner trim L+R@\$95.00	X X NN	2	\$	190.00
47	Rear floor panel	X Repair X	1	\$	480.00
48	Spare tyre	X	1	\$	120.00
49	Spare tyre lock	X NN	1	\$	45.00
50	Spare tyre top board	/ CIA	1	\$	125.00
51	Rear exhaust assy	X Repair	1	\$	350.00
52	Rear exhaust mountings@\$16.00	X	4	\$	64.00
53	Rear exhaust heat shield inner	X NN	1	\$	45.00
54	Rear exhaust heat shield outer	X NN	1	\$	45.00
				Subtotal	\$ 13,411.00
				Discount	10%
				Total	\$ 12,069.90

4629.4  
420.46

Special nett items

No.	Description	Unit	Amount
1	End panel top garnish clips	1 set	\$ 80.00
2	Rear Bumper clips	1 set	\$ 80.00
3	Reverse sensors	1 set	\$ 280.00
4	End panel sealant	1	\$ 120.00
5	Floor panel sealant	1	\$ 180.00
6	Rear number plate and frame	1 set	\$ 55.00
7	Front number plate and frame	1 set	\$ 55.00
8	Rear windscreen sealant	1	\$ 100.00
9	Rear windscreen moulding	1	\$ 120.00
10	Bootlid inner trim clips	1 set	\$ 80.00
11	Bootlid no. plate garnish clips	1 set	\$ 80.00
12	Bootlid outer handle clips	1 set	\$ 80.00
13	Rear fenders inner trim clips	1 set	\$ 80.00
14	Rear fenders inner cowling clips	1 set	\$ 80.00
15	Radiator coolant	1	\$ 60.00
16	Front bumper clips	1 set	\$ 80.00
17	Front fender inner cowling clips	1 set	\$ 80.00
18	Front support top panel garnish clips	1 set	\$ 80.00
19	Taillamp clips LH/RH	1 set	\$ 80.00
20	Sundries	1	\$ 60.00
			Total \$ 1,910.00

20  
40  
200  
40  
X  
40  
40  
10  
40  
30  
40  
500

Labour			
No.	Description	Unit	Amount
1	To dismantle / renew the rear accident portion. To panel beat, reshape, orientate, straighten and align repair / replacement	1	\$ 1,600.00
2	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.	1	\$ 60.00
3	To remove and refit interior upholstery to facilitate the repair.	1	\$ 180.00
4	To remove and refit bootlid components replace, check and re-adjust the close gap and alignment and water seepage.	1	\$ 200.00
5	To remove and replace rear windscreen to facilitate the repair.	1	\$ 180.00
6	To remove and refit, straighten and re-adjust exhaust pipe and replace exhaust silencer	1	\$ 200.00
7	To apply undercoating on the accident repair and replaced panel for rust protection.	1	\$ 100.00
8	Supply spray paint material and to respray bootlid and spoiler, rear end panel, both rear fenders, rear floor panel and other affected area / panel.	1	\$ 1,600.00
9	To dismantle / renew the front accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	1	\$ 1,200.00
10	To remove and refit a/c condenser to facilitate repair. To perform pressure test and confirm on the a/c temperature.	1	\$ 180.00
11	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions	1	\$ 60.00
12	To remove and replace radiator to facilitate repair. To perform pressure test and confirm on the cooling system.	1	\$ 180.00
13	To apply undercoating on the accident repair and replaced panel for rust protection.	1	\$ 120.00
14	Supply spray paint material and necessary items to respray bonnet, front bumper, front support panel, headlamp panel, both front fenders and other affected area / panel.	1	\$ 1,200.00
		<b>Total</b>	<b>\$ 7,060.00</b>
		<b>Grand Total</b>	<b>\$ 21,039.90</b>

800  
30.  
60  
x  
x } NN  
x }  
60  
1000.  
200  
x } NN  
x }  
x }  
600.

2750  
2470.46  
229.5400

8 Days.  
Lumpsum Repair.  
After repair photos -  
Gno Riang - 82880282  
03/4/19.

**L&L Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19005929/Gtd3s2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 10-04-2019



ATTN: DAVID PHUA

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGG 5105D	Veh. Inspected	SGF 1590S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1038186-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	03/04/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER 1.6	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JMYSTCS3A6U008021	Colour	BLUE
Odometer	543882 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60R15	ROADSTONE	5 mm
L/H Front Tyre	195/60R15	ROADSTONE	5 mm
R/H Rear Tyre	195/60R15	ROADSTONE	5 mm
L/H Rear Tyre	195/60R15	ROADSTONE	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	30/03/2019	Inspect Date / Time	03/04/2019 ( 12:30 PM )
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 1590S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	460.00	460.00
2	FRONT BUMPER RETAINERS L+R @ \$28.00	DEFORMED	56.00	56.00
1	FRONT BUMPER LOWER SPOILER	CRACKED	330.00	330.00
1	RADIATOR GRILLE	NOT NECESSARY	230.00	-
1	RADIATOR GRILLE "MITSUBISHI DIAMOND" EMBLEM	NECESSARY	55.00	55.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	156.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	185.00	185.00
1	FRONT BUMPER IMPACT ABSORBER	NOT NECESSARY	95.00	-
2	FRONT FOGLAMPS L+R @ \$125.00	NOT NECESSARY	250.00	-
2	FRONT FOGLAMPS GARNISH L+R @ \$80.00	NOT NECESSARY	160.00	-
1	FRONT LICENCE PLATE GARNISH	DEFORMED	45.00	45.00
2	HEADLAMPS L+R @ \$520.00	NOT NECESSARY	1,040.00	-
2	FRONT FENDERS L+R @ \$580.00	TO REPAIR SEE LABOUR	1,160.00	-
2	FRONT FENDERS INNER COWLINGS L+R @ \$120.00	NOT NECESSARY	240.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	198.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	58.00	-
1	BONNET	TO REPAIR SEE LABOUR	370.00	-
2	BONNET HINGES L+R @ \$26.00	NOT NECESSARY	52.00	-
1	BONNET INSULATOR	NOT NECESSARY	189.00	-
1	A/C CONDENSER	NOT NECESSARY	580.00	-
1	REAR BUMPER	DEFORMED	460.00	460.00
1	REAR BUMPER LOWER SPOILER	DISTORTED	330.00	330.00
2	REAR BUMPER SIDE RETAINERS L+R @ \$28.00	DEFORMED	56.00	56.00
1	REAR BUMPER REINFORCEMENT	BENT	185.00	185.00
1	REAR BUMPER IMPACT ABSORBER	NOT NECESSARY	95.00	-
2	REAR FENDERS L+R @ \$620.00	TO REPAIR SEE LABOUR	1,240.00	-
2	REAR FENDER INNER COWLING L+R @ \$120.00	DEFORMED	240.00	240.00
2	TAILLAMPS L+R @ \$480.00	CRACKED	960.00	794.40
2	TAILLAMPS SEAL SPONGE L+R @ \$18.00	NOT NECESSARY	36.00	-

Report Ref No. CS/INC19005929/Gtd3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAILLAMPS PANEL L+R @ \$80.00	TO REPAIR SEE LABOUR	160.00	-
1	END PANEL	BUCKLED	380.00	380.00
1	END PANEL TOP GARNISH	DEFORMED	145.00	145.00
1	BOOTLID	BENT	520.00	520.00
1	BOOTLID SPOILER	NOT NECESSARY	290.00	-
1	BOOTLID SPOILER 3RD BRAKE LAMP	NOT NECESSARY	86.00	-
1	BOOTLID NO. PLATE GARNISH	NOT NECESSARY	79.00	-
1	BOOTLID KEYLOCK CYLINDER	NOT NECESSARY	85.00	-
2	BOOTLID LICENCE PLATE LAMP L+R @ \$85.00	NOT NECESSARY	170.00	-
1	BOOT WEATHERSTRIP	TWISTED	105.00	105.00
1	BOOTLID "LANCER" EMBLEM	NECESSARY	23.00	23.00
1	BOOTLID "GLX" EMBLEM	NECESSARY	18.00	18.00
1	BOOTLID "MITSUBISHI DIAMOND" EMBLEM	NECESSARY	55.00	55.00
1	BOOTLID INNER TRIM	NOT NECESSARY	145.00	-
1	BOOTLID TOP LOCK	BENT	122.00	122.00
1	BOOTLID LOCK STRIKER	NOT NECESSARY	53.00	-
2	REAR FENDER INNER TRIM L+R @ \$95.00	NOT NECESSARY	190.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	480.00	-
1	SPARE TYRE	NOT NECESSARY	120.00	-
1	SPARE TYRE LOCK	NOT NECESSARY	45.00	-
1	SPARE TYRE TOP BOARD	CRACKED	125.00	125.00
1	REAR EXHAUST ASSY	TO REPAIR SEE LABOUR	350.00	-
4	REAR EXHAUST MOUNTINGS @ \$16.00	NOT NECESSARY	64.00	-
1	REAR EXHAUST HEAT SHIELD INNER	NOT NECESSARY	45.00	-
1	REAR EXHAUST HEAT SHIELD OUTER	NOT NECESSARY	45.00	-
	LESS 10% DISCOUNT		-1,341.10	-468.94
			12,069.90	4,220.46
	<b>SPECIAL NETT ITEMS</b>			
1	SET END PANEL TOP GARNISH CLIPS (SN)	DEFORMED	80.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	40.00
1	SET REVERSE SENSORS (SN)	DAMAGED	280.00	200.00

Report Ref No. CS/INC19005929/Gtd3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL SEALANT (SN)	NECESSARY	120.00	40.00
1	FLOOR PANEL SEALANT (SN)	NOT NECESSARY	180.00	-
1	SET REAR NUMBER PLATE AND FRAME (SN)	SCRATCHED	55.00	40.00
1	SET FRONT NUMBER PLATE AND FRAME (SN)	BENT	55.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET BOOTLID NO. PLATE GARNISH CLIPS (SN)	NECESSARY	80.00	10.00
1	SET BOOTLID OUTER HANDLE CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET REAR FENDERS INNER TRIM CLIPS (SN)	NECESSARY	80.00	40.00
1	SET REAR FENDERS INNER COWLING CLIPS (SN)	NECESSARY	80.00	30.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	40.00
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET FRONT SUPPORT TOP PANEL GARNISH CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET TAILLAMP CLIPS LH/RH (SN)	NOT NECESSARY	80.00	-
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
			1,910.00	500.00
	<b>LABOUR</b>			
	TO DISMANTLE / RENEW THE REAR ACCIDENT PORTION. TO PANEL BEAT, RESHAPE, ORIENTATE, STRAIGHTEN AND ALIGN REPAIR / REPLACEMENT. INCLUSIVE OF THE REPAIR OF FRONT FENDERS L+R, BONNET, REAR FENDERS L+R, TAILLAMPS PANEL L+R, REAR FLOOR PANEL AND REAR EXHAUST ASSY.		1,600.00	800.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.		60.00	30.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.		180.00	60.00
	TO REMOVE AND REFIT BOOTLID COMPONENT REPLACE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.	NOT NECESSARY	200.00	-
	TO REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE THE REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE EXHAUST SILENCER.	NOT NECESSARY	200.00	-

Report Ref No. CS/INC19005929/Gtd3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.		100.00	60.00
	SUPPLY SPRAY PAINT MATERIAL AND T RESPRAY BOOTLID AND SPOILER, REAR END PANEL, BOTH REAR FENDERS, REAR FLOOR PANEL AND OTHER AFFECTED AREA / PANEL.		1,600.00	1,000.00
	TO DISMANTLE / RENEW THE FRONT ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.		1,200.00	200.00
	TO REMOVE AND REFIT A/C CONDENSER TO FACILITATE REPAIR. TO PERFORM PRESSURE TEST AND CONFIRM ON THE A/C TEMPERATURE.	NOT NECESSARY	180.00	-
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.	NOT NECESSARY	60.00	-
	TO REMOVE AND REPLACE RADIATOR TO FACILITATE REPAIR. TO PERFORM PRESSURE TEST AND CONFIRM ON THE COOLING SYSTEM.	NOT NECESSARY	180.00	-
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.	NOT NECESSARY	120.00	-
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, HEADLAMP PANEL, BOTH FRONT FENDERS AND OTHER AFFECTED AREA / PANEL.		1,200.00	600.00
			7,060.00	2,750.00
<b>GRAND TOTAL</b>			<b>21,039.90</b>	<b>7,470.46</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>4,000.00</b>

Report Ref No. CS/INC19005929/Gtd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.